

INS. CASE OWNER:

Sharon

CC 3/CT118000433

Kes 352

LKK:

IDAC:

ASSIGNMENT

Surveyor:

KENNETH

DOI:

05/01/18

Date / Time:

05/01/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGD 6152B

Name of Insured:

CHUA KWA KUANG

Insured Tel No.:

HP: 9617 0742

Excess Sec II :S\$

D.O.A: 26/12/14

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SNM18D00037C02/LK1C05

Policy No.:

DMPCSN2023781705

Make / Model:

HYUNDAI GETZ - 1.1 5000

Place of Accident:

PIE TOWARDS AIRPORT ROAD
(SEPORE THOMSON EXIT)

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHC 59355



INSRS:

WSP: Trans-GS (AMK)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHC 59355 - CC3/AXA11015252/Kg1C3K2 D.O.A: 28/11/14
 - CC4/AXA15020230/H117352 D.O.A: 28/11/14
 - CC5/FL16022905/Kg1C3K2 D.O.A: 30/11/14
 SGD 6152B - NAICT11015252/K4 D.O.A: 14/07/17

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

26/01/18 (Aur)

FILE REVIEW: REJECT CLAIM TP LOST CONTROL.

2/2/18

SEEK APPROVAL TO REJECT TP CLAIM.

2/2/18

MANDATE APPROVE TO REJECT TP CLAIM.

2/2/18

EMAIL TO WSP TO REJECT CLAIM.

02/02/18

FILE PASS TO TYPIST

Based on index TP security
in lost control.

Reject Case

By (staff): Aur

Approved by: Oliver

Date: 2/2/18

RECEIVED 07 FEB 2018

PRELIMINARY ADVICE

Date/Time: 25/01/18

Sent By:

Shirley Kiew

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.: 36

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

TP LOST CONTROL AT OLD PARKED VEH.

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

(\$ x days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle (up)

2) Report Format:

3) Survey fee:

TP 400

COPY SENT 02/02/18

ASS. REC. BY:

REF:

C711

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

8/11 File pass to Customer

PIP: \$47,559.65 (RED: \$118,374.23) 7% Exclude (CHECK ITEM \$45,159.30)

Veh No:

SHC59351

Yr Regn:

06, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Celta

c.c

1995

Colour

M. White / R

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC - 281660

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal:

7

mm

Rear

R/Bal:

3

mm

L/Bal:

7

mm

L/Bal:

3

mm

D.O.A.

28/12/17

D.O.I.

3/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear, O/S Btr & N/S Rear

The U/C / Chassis frame & Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18000433/Kes3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date : 08-01-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGD 6152B	Veh. Inspected	SHC 5935J	
Policy No.	DMPCSN3033781705	Coverage (\$)	0.00	
Claim No.	SNM18D00037C02/2	Excess (\$)	0.00	
Assign From		Assign Date	08/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/12/2017	Inspection Date	05/01/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J*Not Authorised***AAD1801-024***Presumed B4 painting*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5935J
VF1ABL15AUC281660
RENAULT
LATITUDE
26.12.2017
CHINA TAIPING

		PART	LIST	
1	1	BUMPER COVER FRT	\$	<i>Nil</i> 1,259.42 —
2	1	BUMPER SPOILER FRT	\$	<i>Nil</i> 181.75 —
3	1	BUMPER ABSORBER FRT	\$	<i>Nil</i> 394.68 —
4	1	BUMPER RETAINER FRT LH	\$	<i>CM</i> 151.41 —
5	1	BUMPER SUPPORT FRT	\$	<i>Nil</i> 123.88 —
6	1	BUMPER RETAINER FRT RH	\$	<i>CM</i> 150.77 —
7	1	BUMPER SUPPORT FRT	\$	<i>Nil</i> 123.88 —
8	1	BUMPER UNDERTRAY FRT	\$	<i>Nil</i> 472.83 —
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Nil</i> 266.80 —
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Nil</i> 207.21 —
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Nil</i> 207.21 —
12	1	BUMPER BEAM FRT	\$	<i>B</i> 914.08 —
13	1	TOW COVER FRT	\$	<i>Nil</i> 28.61 —
14	1	RADIATOR GRILLE	\$	<i>CM</i> 1,707.78 —
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Nil</i> 225.36 —
16	1	RADIATOR GRILLE FRAME	\$	<i>B</i> 1,353.75 —
17	1	FRAME FULL SUPPORT PANEL	\$	<i>B</i> 615.90 —
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>B</i> 89.79 —
19	1	FRONT BRACE PANEL	\$	<i>B</i> 177.22 —
20	1	HORN	\$	<i>Nil</i> 314.17 —
21	1	HORN BRACKET	\$	<i>B</i> 40.45 —
22	1	HEADLAMP RH	\$	<i>B</i> 1,184.43 —
23	1	HEADLAMP PANEL FRT RH	\$	<i>Nil</i> 152.15 —
24	1	HEADLAMP HARNESS	\$	928.29 ?
25	1	BONNET	\$	<i>B</i> 1,941.63 —
26	1	BONNET INSULATOR	\$	<i>Sm</i> 405.73 ✗
27	1	BONNET STRUT LH	\$	<i>Pr</i> 88.61 —
28	1	BONNET STRUT RH	\$	<i>Pr</i> 88.61 —
29	1	BONNET HINGE LH	\$	<i>Pr</i> 348.31 —

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

30	1	BONNET HINGE RH	\$	B ₁	348.31	✓
31	1	BONNET LOCK	\$	B ₁	305.48	✓
32	1	BONNET CABLE	\$		119.19	?
33	1	BONNET CABLE COVER	\$	M ₁	161.03	✓
34	1	BONNET SEAL OUTER	\$	M ₁	92.36	✓
35	1	BONNET SEAL INNER	\$	M ₁	157.28	✓
36	1	FENDER PANEL FRT RH	\$	B ₁	783.83	✓
37	1	WHEELARCH FRT RH	\$	Z ₁	278.84	✓
38	1	FENDER BRACKET LOWER RH	\$	B ₁	15.79	✓
39	1	FENDER INSULATOR RH	\$	S ₁	130.84	X
40	1	FENDER PANEL FRT LH	\$	B ₁	783.83	✓
41	1	WHEELARCH FRT LH	\$	C _M	278.84	✓
42	1	FENDER BRACKET LOWER LH	\$	n	15.79	X
43	1	FENDER INSULATOR LH	\$	S ₁	130.84	✓
44	1	WIPER RESERVOIR	\$	R ₁	348.25	✓
45	1	WIPER RESERVOIR NECK	\$	R ₁	136.11	✓
46	1	WIPER RESERVOIR MOTOR	\$	S ₁	270.06	X
47	1	AIR CLEANER LOWER	\$	C _M	271.26	✓
48	1	AIR CLEANER HOSE	\$	C _M	76.14	✓
49	1	AUTO COMPUTER	\$		5,032.17	?
50	1	STEERING PUMP ELECTRIC	\$	R ₁	2,306.90	✓
51	1	STEERING PINION RACK	\$		4,413.11	?
52	1	ENGINE HARNESS	\$		4,084.54	?
53	1	SUBFRAME OUTER FRT	\$		2,652.45	?
54	1	SUBFRAME BRACKET OUTER RH	\$		92.36	?
55	1	ENGINE MOUNTING H	\$		552.55	?
56	1	FUSE BOX	\$		987.39	?
57	1	ENGINE MOUNTING RH	\$		552.55	?
58	1	ENGINE MOUNTING LOWER	\$		562.42	?
59	1	ENGINE MOUNTING UPPER	\$		592.02	?
60	1	VEHICLE HARNESS PASS ROOM	\$		10,003.86	?
61	1	AIR CLEANER BOX	\$		464.20	?
62	1	TURBO DUCT	\$		1,027.80	?
63	1	OIL PAN ASSEMBLY	\$		2,283.91	?
64	1	A/C CONDENSER	\$	B ₁	2,020.37	✓
65	1	A/C CONDENSER GARNISH RH UPPER	\$	C _M	39.67	✓
66	1	A/C CONDENSER GARNISH RH	\$	C _M	59.60	✓
67	1	A/C PIPE CONDENSER TO COMPRESSOR	\$		208.39	?
68	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$		658.72	?

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

69	1	A/C PIPE COMPRESSOR	\$	334.29 X
70	1	A/C PIPE	\$	658.72 X
71	1	A/C COMPRESSOR	\$	2,684.61 X
72	1 Oil	AIR COOLER	\$	792.60
73	1 Oil	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13 ?
74	1 Oil	AIR INTERCOOLER HOSE (Short)	\$	375.14 ?
75	1	TRANSMISSION COOLER	\$	1,219.30 ?
76	1	TRANSMISSION COOLER PAD	\$	17.96 ?
77	1	RADIATOR	\$	1,202.20
78	2	RADIATOR STUD UPPER	\$	14.41 X
79	2	RADIATOR BUSH UPPER	\$	50.12 X
80	2	RADIATOR MTG LOWER	\$	55.85 X
81	1	RADIATOR FAN COWLING	\$	820.54 ?
82	1	RADIATOR FAN MOTOR LH	\$	967.36 ?
83	1	RADIATOR FAN MOTOR RH	\$	1,479.46 ?
84	1	RADIATOR TANK	\$	324.62 ?
85	1	RADIATOR HOSE UPPER	\$	240.56 ?
86	1	RADIATOR HOSE LOWER	\$	491.18 ?
87	1	RADIATOR TANK HOSE	\$	61.18 ?
88	1	WINDSCREEN FRT	\$	1,364.06 X
89	1	SEATBELT LH	\$	2,937.80 X
90	1	SEATBELT RH	\$	2,925.37 X
91	1	SEATBELT BUCKLE LH	\$	984.13 X
92	1	SEATBELT BUCKLE RH	\$	949.80 X
93	1	PASSENGER AIRBAG	\$	3,412.40 X
94	1	STEERING AIRBAG	\$	2,525.75 X
95	1	AIRBAG COMPUTER	\$	1,259.82 X
96	1	AIRBAG SENSOR	\$	724.63 X
97	1	ROTARY SWITCH	\$	1,253.11 X
98	1	DASHBOARD	\$	4,900.54 X
99	1	BUMPER COVER REAR	\$	1,108.46
100	1	BUMPER LOWER REAR	\$	768.84
101	1	BUMPER BRACKET CTR REAR	\$	113.47 X
102	1	BUMPER BRACKET SIDE LH REAR	\$	135.97 X
103	1	BUMPER BRACKET CTR LH REAR	\$	44.99 X
104	1	BUMPER BRACKET SIDE RH REAR	\$	135.97
105	1	BUMPER BRACKET CTR RH REAR	\$	44.99
106	1	BUMPER BEAM REAR	\$	777.52 X
107	1	BUMPER BEAM BRACKET LH REAR	\$	225.95 X

Trans-cab Auto Services Pte Ltd

AAD1801-024

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

108	1	BUMPER BEAM BRACKET RH REAR	\$	R	225.95 X
109	1	FENDER PANEL REAR RH	\$	Bz	3,299.13 ✓
110	1	WHEELARCH REAR RH	\$	Bz	543.47 ✓
111	1	FENDER PANEL INNER TRIM REAR RH	\$	Return	671.45 ✓
112	1	FENDER PANEL REAR LH	\$	Bz	3,299.13 ✓
113	1	WHEELARCH REAR LH	\$	Sn	543.47 X
114	1	FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45 X
115	1	LOWER ARM REAR RH	\$	Bz	905.99 ✓
116	1	KUCKLE ARM REAR RH	\$	Bz	736.67 ✓
117	1	ABSORBER REAR RH	\$		389.75 ?
118	1	ABSORBER BOLT REAR RH	\$		52.10 ?
119	1	ABSORBER DUST COVER REAR RH	\$		92.16 ?
120	1	DOOR PANEL REAR RH	\$	Bz	2,844.66 ✓
121	1	DOOR SEAL REAR RH	\$	Sn	187.08 X
122	1	DOOR PANEL FRT RH	\$	Bz	2,844.66 ✓
123	1	DOOR HINGE UPPER RH	\$	R	261.28 X
124	1	DOOR HINGE LOWER RH	\$	R	300.55 X
125	1	DOOR CHECK FRT RH	\$	Sn	194.77 X
126	1	DOOR CHECK BOLT	\$	Sn	22.69 X
127	1	DOOR LOCK FRT RH	\$	R	908.75 X
128	1	DOOR CATCH FRT RH	\$	R	131.23 X
129	1	DOOR HANDLE OUTER FRT RH	\$	Tu	477.76 ✓
130	1	DOOR HANDLE COVER FRT RH	\$	Sn	13.22 X
131	1	DOOR HANDLE MODULE FRT RH	\$	Sn	133.60 X
132	1	DOOR REGULATOR FRT RH	\$		505.19 ?
133	1	DOOR REGUALTOR MOTOR FRT RH	\$		796.46 ?
134	1	DOOR REGULATOR GUIDE FRT RH	\$		120.97 ?
135	1	DOOR GLASS FRT RH	\$	Shatter	625.96 ✓
136	1	DOOR FINISHER FRT RH	\$		515.06 ?
137	1	DOOR MOULDING FRT RH	\$	Sn	176.82 X
138	1	DOOR FINISHER CLIP KIT FRT RH	\$	Sn	90.97 X
139	1	DOOR CASING FRT RH	\$	Sn	1,509.06 X
140	1	DOOR CASING LIGHT	\$	Sn	82.49 X
141	1	DOOR GRAB HANDLE FRT RH	\$	Sn	210.96 X
142	1	DOOR MIRROR RH	\$	Sn	1,725.73 X
143	1	DOOR WEATHERSTRIP FRT RH	\$	Sn	410.27 X
144	1	DOOR SEAL LOWER FRT RH	\$	Sn	91.17 X
145	1	DOOR GLASS RUNNER SEAL FRT RH	\$	Sn	626.36 X
146	1	DOOR WAIST SEAL OUTER FRT RH	\$	Sn	291.27 X

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

147	1	DOOR WAIST SEAL INNER FRT RH	\$	122.15	X
148	1	DOOR PANEL REAR RH	\$	2,844.66	X
149	1	DOOR GUIDE REAR RH	\$	176.82	X
150	1	DOOR HINGE UPPER RH	\$	274.50	X
151	1	DOOR HINGE LOWER RH	\$	300.55	X
152	1	DOOR CHECK REAR RH	\$	203.06	X
153	1	DOOR LOCK REAR RH	\$	908.75	
154	1	DOOR GRAB HANDLE REAR RH	\$	210.96	X
155	1	DOOR HANDLE OUTER REAR RH	\$	126.49	X
156	1	DOOR HANDLE CAP REAR RH	\$	35.52	X
157	1	DOOR HANDLE COVER REAR RH	\$	13.22	X
158	1	DOOR HANDLE MODULE REAR RH	\$	133.60	X
159	1	DOOR FINISHER REAR RH	\$	423.10	X
160	1	DOOR WHEATHESTRIIP REAR RH	\$	410.66	
161	1	DOOR SEAL REAR RH	\$	162.02	7
162	1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69	
163	1	DOOR MOULDING REAR RH	\$	176.82	
164	1	FENDER PANEL REAR RH	\$	3,299.13	X
165	1	FENDER PANEL INNER TRIM REAR	\$	671.45	X
166	1	WHEELARCH REAR RH	\$	543.47	X
167	1	LOWER ARM RH L70Y	\$	685.76	X
168	1	KUNCKLE ARM RH L70Y	\$	846.98	X
169	1	KUNCKLE HUB+BEARING RH	\$	497.69	X
170	1	KUNCKLE ARM SHIELD RH	\$	131.43	7
171	1	KUNCKLE ARM PLATE RH	\$	174.05	7
172	1	ABSORBER FRT RH	\$	360.54	7
173	1	ABSORBER MOUNTING KIT RH	\$	440.66	7
174	1	ABSORBER DUST COVER	\$	228.72	7
175	1	STABILIZER BAR FRT L70Y	\$	604.65	7
176	1	STABILIZER LINK FRT L70Y	\$	117.22	7
177	1	BRAKE CALIPER FRT RH L70Y	\$	656.94	X
178	1	BRAKE CALIPER BRACKET FRT RH L70Y	\$	555.12	X
179	1	ABS SENSOR FRT RH L70Y	\$	255.75	X
180	1	DRIVESHAFT RH	\$	1,747.45	7
181	1	ROCKER PANEL INNER GARNISH RH	\$	466.51	X
182	1	ROCKER PANEL INNER LH	\$	1,024.79	X
183	1	DOOR PANEL FRT RH	\$	2,844.66	X
184	1	DOOR HINGE UPPER RH	\$	261.28	X
185	1	DOOR HINGE LOWER RH	\$	300.55	X

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

186	1	DOOR CHECK FRT RH	\$	194.77	}
187	1	DOOR CHECK BOLT	\$	22.69	
188	1	DOOR LOCK FRT RH	\$	908.75	
189	1	DOOR CATCH FRT RH	\$	131.23	
190	1	DOOR HANDLE OUTER FRT RH	\$	477.76	
191	1	DOOR HANDLE COVER FRT RH	\$	13.22	
192	1	DOOR HANDLE MODULE FRT RH	\$	133.60	
193	1	DOOR REGULATOR FRT RH	\$	505.19	
194	1	DOOR REGULATOR MOTOR FRT RH	\$	796.46	
195	1	DOOR REGULATOR GUIDE FRT RH	\$	120.97	
196	1	DOOR GLASS FRT RH	\$	625.96	
197	1	DOOR FINISHER FRT RH	\$	515.06	
198	1	DOOR MOULDING FRT RH	\$	176.82	
199	1	DOOR FINISHER CLIP KIT FRT RH	\$	90.97	
200	1	DOOR CASING FRT RH	\$	1,509.06	
201	1	DOOR CASING LIGHT	\$	82.49	
202	1	DOOR GRAB HANDLE FRT RH	\$	210.96	
203	1	DOOR MIRROR RH	\$	1,725.73	
204	1	DOOR WEATHERSTRIP FRT RH	\$	410.27	
205	1	DOOR SEAL LOWER FRT RH	\$	91.17	
206	1	DOOR GLASS RUNNER SEAL FRT RH	\$	626.36	
207	1	DOOR WAIST SEAL OUTER FRT RH	\$	291.27	

TOTAL	\$	157,604.43
10%	\$	15,760.44
	\$	141,843.98

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	—
2	1SET	BUMPER CLIP FRT	\$	66.00	—
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00	<
6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	X
7	1	TOW COVER FRT	\$	14.50	✓
8	1SET	RADAIOR GRILLE SCREW	\$	16.00	✓
9	1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	X
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	✓

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
13	1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	—
14	1SET	WHEELARCH CLIP FRT RH	\$	na	29.40	—
15	1	CAP HUB RH FRT	\$	na	35.00	—
16	1	CAP HUB RH REAR	\$	na	35.00	—
17	1	RIM RH REAR	\$	na	385.00	—
18	1	TYRE RH REAR	\$	na	330.00	308in
19	1SET	BUMPER RR CLIP	\$	na	66.00	—
20	1SET	BUMPER BEAM BOLT	\$	na	22.22	—
21	1SET	PARKING AID	\$	na	600.00	X
22	1	BUMPER BRACKET CLIP CTR REAR	\$	na	15.00	X
23	1	BUMEPB BRACKET SIDE CLIP LH REAR	\$	na	12.00	X
24	1	BUMEPB RETAINER CLIP LH REAR	\$	na	10.40	X
25	1	BUMEPB BRACKET SIDE CLIP RH REAR	\$	na	12.00	X
26	1	BUMEPB RETAINER CLIP RH REAR	\$	na	10.40	X
27	1SET	BOOT FINISHER CLIP	\$	na	25.10	X
28	1	Rear boots sticker "Trans-cab"	\$	na	30.00	X
29	1	Rear boots sticker "6555-3333"	\$	na	30.00	X
30	1	FENDER PANEL INNER TRIM CLIP REAR RH	\$	na	22.00	X
31	1	FENDER PANEL INNER TRIM CLIP REAR LH	\$	na	22.00	X
32	1SET	WHEELARCH CLIP LH RR	\$	na	32.34	—
33	1SET	WHEELARCH CLIP RH RR	\$	na	32.34	—
34	2	REAR WINDSCREEN SEALANT	\$	na	80.00	40in
35	1	WINDSCREEN MOULDING	\$	na	100.00	—
36	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	30in
37	1	EXHAUST MOUNTING REAR	\$	na	65.50	X
38	1	EXHAUST BRACKET REAR	\$	na	22.22	X
39	1SET	FRONT LICENCE PLATE WITH HOLDER	\$	na	80.00	X
40	1	DOOR STICKER "6555-3333" RH	\$	na	80.00	X
41	1	DOOR STICKER 'Trans-cab' RH	\$	na	80.00	X
42	1	DOOR STICKER 'Chassis' RH	\$	na	30.00	X
43	1	LOWER ARM BOLT	\$	na	34.14	X
44	1	LOWER ARM NUT	\$	na	19.93	X
45	1	ABSORBER BOLT	\$	na	44.01	X
46	1	ABSORBER NUT	\$	na	17.56	X
47	1	BRAKE DISC SCREW FRT	\$	na	15.20	X
48	1	KUNCKLE ARM BOLT LH	\$	na	14.21	X
49	1	BRAKE CALIPER BRACKET BOLT FRT RH	\$	na	19.93	X

Trans-cab Auto Services Pte Ltd

AAD1801-024

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

TOTAL \$ 2,971.90**TOTAL PARTS \$ 144,815.88****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2600 7,500.00
Towing Fees.	\$	120.00 500
To apply paint protection system (PPS) maintain and enhancement	\$	380.00 X
Putty and spray painting of the affected portion.	\$	1880 6,000.00
To rust-proofing of the affected areas.	\$	170.00 1500
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 1200
To check steering geometry and computer wheel alignment	\$	220.00 600
To transfer of tire, rim and on wheel balancing.	\$	170.00 200
To Check Electrical Lighting Concerned.	\$	170.00 400
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 2500
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	~ 170.00	X
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	380.00	1201
To reinstall rear bumper parking sensor.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00	} 801
To repair and realign rear exhaust pipe.	\$	170.00	
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00	X
To lift-up engine with gear box and refit.	\$	440.00	?
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	?
To remove and refit air bag system and reset.	\$	480.00	?
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	601

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

To vacuum, replace, refix and recharge air condenser	\$	380.00 1001
To replace, refix and top up coolant for radiator	\$	170.00 501
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 501
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 X
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 1201

TOTAL \$ 21,110.00**Over All Total \$ 165,925.88⁶****LUMP SUM (REPAIR)****30 DAYS***28 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:



Airfo
Consultants
Pte Ltd

Company Registration No. 199607198R

511 UBI AVE L #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933. TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI18000433/Kes3

Date: 25.01.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 5935J

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05.01.2018 at the premises of M/s Trans-Cab Auto Services Pte Ltd (Ang Mo Kio) and have the following to report:-

Workshop Estimate Amount	: S\$	165,925.88
Revised Estimate Amount	: S\$	47,551.65
"Check" Items Amount	: S\$	45,159.20
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Rear Portion, O/S Front portion,
N/S Rear Portion and Body Structure affected due to collision



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 28.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

1259.42	928.29	52.00	12.00	2600.00	4900.00
181.75	405.73	66.00	10.50	50.00	70.00
394.68	119.19	14.50	12.00	1980.00	380.00
151.41	130.84	16.00	10.50	150.00	4020.00
123.88	15.79	70.00	69.00	120.00	20.00
150.77	130.84	30.50	20.00	60.00	260.00
123.88	270.06	29.40	30.00	20.00	160.00
472.83	5032.17	35.00	99.00	40.00	150.00
266.80	4413.11	35.00	600.00	250.00	130.00
207.21	4084.54	385.00	15.00	60.00	130.00
207.21	2652.45	231.00	12.00	120.00	170.00
914.08	92.36	66.00	10.40	60.00	140.00
28.61	552.55	22.22	12.00	80.00	350.00
1707.78	987.39	32.34	10.40	60.00	170.00
225.36	552.55	32.34	25.10	100.00	380.00
1353.75	562.42	40.00	30.00	50.00	170.00
615.90	592.02	100.00	30.00	50.00	260.00
89.79	10003.86	30.00	22.00	120.00	110.00
177.22	464.20		22.00		240.00
314.17	1027.80		40.00		130.00
40.45	2283.91	1287.30	70.00	5970.00	380.00
1184.43	208.39		65.50		440.00
152.15	658.72		22.22		440.00
1941.63	334.29		80.00		480.00
88.61	658.72		80.00		320.00
88.61	2684.61		80.00		280.00
348.31	1014.13		30.00		120.00
348.31	375.14		34.14		120.00
305.48	1219.30		19.93		170.00
161.03	17.96		44.01		50.00
92.36	14.41		17.56		
157.28	50.12		15.20		15140.00
783.83	55.85		14.21		
278.84	820.54		19.93		
15.79	967.36				
783.83	1479.46	1684.60			
278.84	324.62				
348.25	240.56				
136.11	491.18				
271.26	61.18				
76.14	2937.80				
2306.90	2925.37				
2020.37	984.13				
39.67	949.80				
59.60	3412.40				
792.60	2525.75				
1202.20	1259.82				
1364.06					
1108.46	724.63				
768.84	1253.11				

135.97	4900.54
44.99	113.47
3299.13	135.97
543.47	44.99
671.45	777.52
3299.13	225.95
905.99	225.95
736.67	543.47
2844.66	671.45
2844.66	389.75
477.76	52.10
625.96	92.16
908.75	187.08
410.66	261.28
334.69	300.55
176.82	194.77

22.69
908.75
131.23
13.22
133.60
505.19
796.46
120.97

44771.50 515.06
176.82

157604.43 90.97
44771.50 1509.06
112832.93 82.49
210.96

2971.90
1287.30
1684.60

21110.00
5970.00
15140.00

44771.50 1725.73
4477.15 410.27
40294.35 91.17
1287.30 626.36
5970.00 291.27

122.15
2844.66
47551.65

928.29
119.19

5032.17

4413.11

4084.54

2652.45

552.55 + 92.36

987.39

552.55

562.42

592.02

10003.86

464.20

1027.80

2283.91

CHECK ITEM

543.47	208.39
685.76	658.72
846.98	1014.13
497.69	375.14
131.43	1219.30
174.05	17.96
360.54	820.54
440.66	967.36
228.72	1479.46
604.65	324.62
117.22	240.56
656.94	491.18
555.12	61.18
255.75	389.75
1747.45	52.10
466.51	92.16
1024.79	505.19
2844.66	796.46
261.28	120.97
300.55	515.06
194.77	162.02
22.69	131.43
908.75	174.05
131.23	360.54
477.76	440.66
13.22	228.72
133.60	604.65
505.19	117.22
796.46	1747.45
120.97	
625.96	48573.42
515.06	4857.34
176.82	43716.08
90.97	440.00
1509.06	440.00
82.49	480.00
210.96	45076.08
1725.73	
410.27	
91.17	
626.36	
291.27	
112832.90	

48,665.78

486658

43799.20

45,159.20

45159.20

revised & check amount wrong.
 kindly recheck. IQ
 stamp HOKED - 22/1/18.

Shirley Hiew (LKK Auto)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Thursday, 25 January 2018 5:27 PM
To: Shirley Hiew (LKK Auto); Asher Sng (LKKAuto); Vic (LKKAuto); Admin A; Hsiao Tong (LKKAuto)
Cc: Sharon Han; Alfred Toh; Adeline Chng; Chee So Chow; Hwang Shiang Yi
Subject: RE: Direct Settlement - Accident Involving SGD6152B (OI : SNM18D00037C02/2) AND SHC5935J (TP : LKK REF - CC3/CTI18000433/Kes3) on 26/12/2017
Attachments: CHEONGHOH LAW ACTING FOR INSURED.pdf; KSCGP ACTING FOR SKK6830T.pdf; REPORT OF SKK6830T.pdf; MCHM17171158-SGD6152B.pdf

LKK REF - CC3/CTI18000433/Kes3
CTI REF - SNM18D00037C02/2 (SGD6152B)

Dear Shirley/Asher

We refer to your email of even date pertaining to the above matter.

Attach herewith:

1. Letter from M/s CheongHoh Law Corpn (acting for Insured)
2. Email from M/s KSCGP Juris LLP (acting for SKK6830T)
3. Accident Report of SKK6830T
4. Insured's Accident Report (SGD6152B)

Based on the information received till date, Insured should not be responsible for the damages sustained by SHC5935J.

We await your advice/findings on the investigation in due course.

Our Sharon (Adeline) shall be in-charge for this claim.

Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID : +65 6389 6183
FAX: +65 6224 7175/6224 7478
Email: claimsdept@sg.cntaiping.com
alfred.toh@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Thursday, January 25, 2018 11:06 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Sharon Han <sharon.han@sg.cntaiping.com>
Cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SGD6152B (OI : SNM18D00037C02/2) AND SHC5935J (TP : LKK REF - CC3/CTI18000433/Kes3) on 26/12/2017

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 5935J at M/s Trans-Cab Auto Services Pte Ltd - Ang Mo Kio.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 2 February 2018 12:55 PM
To: Shirley Hiew (LKK Auto); Ng Wai Yin; 'Jasmine Tan'; claims@transcab.com.sg
Cc: Admin A; Vic (LKKAuto)
Subject: RE: TCS REF: AAD1801-024--Accident involving SGD6152B, SKK6830T & SHC5935J on 26.12.17 *** LKK REF: CC3/CTI18000433/Kes3
Attachments: SKETCH PLAN (SGD 6152B).pdf

Without Prejudice

Hi Jasmine,

We refer to the above matter.

We attached here with a copy of our insured's accident statement for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client lost control of his vehicle and collided into our insured vehicle which stationary at the road shoulder.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 10 January 2018 10:53 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; 'Jasmine Tan' <jasminetan@transcab.com.sg>; claims@transcab.com.sg;
Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>
Subject: RE: TCS REF: AAD1801-024--Accident involving SGD6152B, SKK6830T & SHC5935J on 26.12.17 *** LKK REF: CC3/CTI18000433/Kes3

Dear Wai Yin,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Asher,

For your information and necessarily action please.

To check availability of the case handler , you may contact the undersigned.

"Wishes you a Merry Christmas & Happy New Year 2018"

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin [<mailto:waiyin.ng@transcab.com.sg>]

Sent: Tuesday, 9 January 2018 11:58 AM

To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>; Admin A <admin-a@lkkauto.com>; claims@transcab.com.sg; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>

Subject: RE: TCS REF: AAD1801-024--Accident involving SGD6152B, SKK6830T & SHC5935J on 26.12.17 *** LKK REF: CC3/CTI18000433/Kes3

WITHOUT PREJUDICE

Dear Mei Kwan

Enclosed is the video footage for your investigation.

Brief Details.

On 26/12/2017 at about 0015hours, I was driving alone in my taxi bearing a registration number, SHC9535J. I was driving along Pan Island Expressway towards Airport, along Stevens Road.

On I was driving on the second lane. Suddenly I felt an impact coming from the rear of my vehicle. Due to the impact, I lost control of the vehicle and swerved all the road shoulder on the left. I lost conscious then. When I woke up, I saw that there were other vehicles on the left and right of my vehicles. I do not know what happened and what had collided me from the rear.

I was then conveyed to Tan Tock Seng Hospital by ambulance. I was given 18 days of Hospitalization Leave. I had suffered injuries on my head, chest and also on the right side of my arm. I was then informed by Traffic Police to make a traffic accident report. I do not know what happened but I have an in-vehicle camera installed. I do not know what are the damages to my vehicle.

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg

**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]**Sent:** Tuesday, January 09, 2018 10:39 AM**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>**Cc:** 'Jasmine Tan' <jasminetan@transcab.com.sg>; Admin A <admin-a@lkkauto.com>; claims@transcab.com.sg; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>**Subject:** RE: TCS REF: AAD1801-024--Accident involving SGD6152B, SKK6830T & SHC5935J on 26.12.17 *** LKK REF:

CC3/CTI18000433/Kes3

Dear Wai Yin,

We refer to the above matter.

Please provide us CCTV footage for this case.

I was then conveyed to Tan Tock Seng Hospital by ambulance. I was given 18 days of Hospitalization Leave. I had suffered injuries on my head, chest and also on the right side of my arm. I was then informed by Traffic Police to make a traffic accident report. I do not know what happened but I have an in-vehicle camera installed. I do not know what are the damages to my vehicle.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin [<mailto:waiyin.ng@transcab.com.sg>]**Sent:** Monday, 8 January, 2018 5:03 PM**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>**Cc:** 'Jasmine Tan' <jasminetan@transcab.com.sg>; Admin A <admin-a@lkkauto.com>**Subject:** TCS REF: AAD1801-024--Accident involving SGD6152B, SKK6830T & SHC5935J on 26.12.17

WITHOUT PREJUDICE

Dear Shirley

Refer to our tele-conversation moment ago.

We are claiming against the owner of SGD 6152B (China Taiping Insurance), enclosed is the LTA search for your attention.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake; please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CT118000433/Kes3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 07-02-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGD 6152B	Veh. Inspected	SHC 5935J
Policy No.	DMPCSN3033781705	Coverage (\$)	0.00
Claim No.	SNM18D00037C02/2	Excess (\$)	0.00
Assign From		Assign Date	05/01/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF1ABL15AUC281660	Colour	METALLIC WHITE / RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	GITI	7 mm
L/H Front Tyre	215/60R16	LING LONG	7 mm
R/H Rear Tyre	215/60R16	LING LONG	3 mm
L/H Rear Tyre	215/60R16	LING LONG	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION, O/S FRONT PORTION AND N/S REAR PORTION. THE UNDERCARRIAGE AND BODY STRUCTURE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	26/12/2017	Inspection Date	05/01/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	28 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 11

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5935J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT	MISSING	1,259.42	1,259.42
1	BUMPER SPOILER FRT	MISSING	181.75	181.75
1	BUMPER ABSORBER FRT	MISSING	394.68	394.68
1	BUMPER RETAINER FRT LH	CRACKED	151.41	151.41
1	BUMPER SUPPORT FRT	MISSING	123.88	123.88
1	BUMPER RETAINER FRT RH	CRACKED	150.77	150.77
1	BUMPER SUPPORT FRT	MISSING	123.88	123.88
1	BUMPER UNDERTRAY FRT	MISSING	472.83	472.83
1	BUMPER GRILLE LOWER FRT	MISSING	266.80	266.80
1	BUMPER FOG LAMP GRILLE LH	MISSING	207.21	207.21
1	BUMPER FOG LAMP GRILLE RH	MISSING	207.21	207.21
1	BUMPER BEAM FRT	BENT	914.08	914.08
1	TOW COVER FRT	MISSING	28.61	28.61
1	RADIATOR GRILLE	CRACKED	1,707.78	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	RADIATOR GRILLE FRAME	BROKEN	1,353.75	1,353.75
1	FRAME FULL SUPPORT PANEL	BROKEN	615.90	615.90
1	FRAME FULL SUPPORT BRACKET	BENT	89.79	89.79
1	FRONT BRACE PANEL	BENT	177.22	177.22
1	HORN	DENTED	314.17	314.17
1	HORN BRACKET	BENT	40.45	40.45
1	HEADLAMP RH	BROKEN	1,184.43	1,184.43
1	HEADLAMP PANEL FRT RH	DISTORTED	152.15	152.15
1	HEADLAMP HARNESS	* CHECK	928.29	-
1	BONNET	BENT	1,941.63	1,941.63
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	PUNCTURE	88.61	88.61
1	BONNET STRUT RH	PUNCTURE	88.61	88.61
1	BONNET HINGE LH	BENT	348.31	348.31
1	BONNET HINGE RH	BENT	348.31	348.31
1	BONNET LOCK	BENT	305.48	305.48

Report Ref No. CC3/CTI18000433/Kes3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 11

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET CABLE	* CHECK	119.19	-
1	BONNET CABLE COVER	MISSING	161.03	161.03
1	BONNET SEAL OUTER	MISSING	92.36	92.36
1	BONNET SEAL INNER	MISSING	157.28	157.28
1	FENDER PANEL FRT RH	BENT	783.83	783.83
1	WHEELARCH FRT RH	TORN	278.84	278.84
1	FENDER BRACKET LOWER RH	BENT	15.79	15.79
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	FENDER PANEL FRT LH	BENT	783.83	783.83
1	WHEELARCH FRT LH	CRACKED	278.84	278.84
1	FENDER BRACKET LOWER LH	TO REPAIR SEE LABOUR	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	WIPER RESERVOIR	DENTED	348.25	348.25
1	WIPER RESERVOIR NECK	DENTED	136.11	136.11
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	AIR CLEANER LOWER	CRACKED	271.26	271.26
1	AIR CLEANER HOSE	CRACKED	76.14	76.14
1	AUTO COMPUTER	* CHECK	5,032.17	-
1	STEERING PUMP ELECTRIC	DENTED	2,306.90	2,306.90
1	STEERING PINION RACK	* CHECK	4,413.11	-
1	ENGINE HARNESS	* CHECK	4,084.54	-
1	SUBFRAME OUTER FRT	* CHECK	2,652.45	-
1	SUBFRAME BRACKET OUTER RH	* CHECK	92.36	-
1	ENGINE MOUNTING H	* CHECK	552.55	-
1	FUSE BOX	* CHECK	987.39	-
1	ENGINE MOUNTING RH	* CHECK	552.55	-
1	ENGINE MOUNTING LOWER	* CHECK	562.42	-
1	ENGINE MOUNTING UPPER	* CHECK	592.02	-
1	VEHICLE HARNESS PASS ROOM	* CHECK	10,003.86	-
1	AIR CLEANER BOX	* CHECK	464.20	-
1	TURBO DUCT	* CHECK	1,027.80	-
1	OIL PAN ASSEMBLY	* CHECK	2,283.91	-

Report Ref No. CC3/CTI18000433/Kes3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 11

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	A/C CONDENSER	BENT	2,020.37	2,020.37
1	A/C CONDENSER GARNISH RH UPPER	CRACKED	39.67	39.67
1	A/C CONDENSER GARNISH RH	CRACKED	59.60	59.60
1	A/C PIPE CONDENSER TO COMPRESSOR	* CHECK	208.39	-
1	A/C PIPE CONDENSER TO EXPENSION VALVE	* CHECK	658.72	-
1	A/C PIPE COMPRESSOR	SERVICEABLE	334.29	-
1	A/C PIPE	SERVICEABLE	658.72	-
1	A/C COMPRESSOR	SERVICEABLE	2,684.61	-
1	OIL COOLER	PUNCTURE	792.60	792.60
1	OIL INTERCOOLER HOSE (LONG)	* CHECK	1,014.13	-
1	OIL INTERCOOLER HOSE (SHORT)	* CHECK	375.14	-
1	TRANSMISSION COOLER	* CHECK	1,219.30	-
1	TRANSMISSION COOLER PAD	* CHECK	17.96	-
1	RADIATOR	PUNCTURE	1,202.20	1,202.20
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING	* CHECK	820.54	-
1	RADIATOR FAN MOTOR LH	* CHECK	967.36	-
1	RADIATOR FAN MOTOR RH	* CHECK	1,479.46	-
1	RADIATOR TANK	* CHECK	324.62	-
1	RADIATOR HOSE UPPER	* CHECK	240.56	-
1	RADIATOR HOSE LOWER	* CHECK	491.18	-
1	RADIATOR TANK HOSE	* CHECK	61.18	-
1	WINDSCREEN FRT	CRACKED	1,364.06	1,364.06
1	SEATBELT LH	SERVICEABLE	2,937.80	-
1	SEATBELT RH	SERVICEABLE	2,925.37	-
1	SEATBELT BUCKLE LH	SERVICEABLE	984.13	-
1	SEATBELT BUCKLE RH	SERVICEABLE	949.80	-
1	PASSENGER AIRBAG	SERVICEABLE	3,412.40	-
1	STEERING AIRBAG	SERVICEABLE	2,525.75	-
1	AIRBAG COMPUTER	SERVICEABLE	1,259.82	-
1	AIRBAG SENSOR	SERVICEABLE	724.63	-

Report Ref No. CC3/CTI18000433/Kes3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 11

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ROTARY SWITCH	SERVICEABLE	1,253.11	-
1	DASHBOARD	SERVICEABLE	4,900.54	-
1	BUMPER COVER REAR	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR	BUCKLED	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER BRACKET CTR LH REAR	SERVICEABLE	44.99	-
1	BUMPER BRACKET SIDE RH REAR	DISTORTED	135.97	135.97
1	BUMPER BRACKET CTR RH REAR	DISTORTED	44.99	44.99
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	FENDER PANEL REAR RH	BENT	3,299.13	3,299.13
1	WHEELARCH REAR RH	BENT	543.47	543.47
1	FENDER PANEL INNER TRIM REAR RH	DEFORMED	671.45	671.45
1	FENDER PANEL REAR LH	BUCKLED	3,299.13	3,299.13
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	LOWER ARM REAR RH	BENT	905.99	905.99
1	KNUCKLE ARM REAR RH	BENT	736.67	736.67
1	ABSORBER REAR RH	* CHECK	389.75	-
1	ABSORBER BOLT REAR RH	* CHECK	52.10	-
1	ABSORBER DUST COVER REAR RH	* CHECK	92.16	-
1	DOOR PANEL REAR RH	BENT	2,844.66	2,844.66
1	DOOR SEAL REAR RH	SERVICEABLE	187.08	-
1	DOOR PANEL FRT RH	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT RH	SERVICEABLE	194.77	-
1	DOOR CHECK BOLT	SERVICEABLE	22.69	-

Report Ref No. CC3/CTI18000433/Kes3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 11

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR LOCK FRT RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH	TO REPAIR SEE LABOUR	131.23	-
1	DOOR HANDLE OUTER FRT RH	JAMMED	477.76	477.76
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	* CHECK	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	* CHECK	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	* CHECK	120.97	-
1	DOOR GLASS FRT RH	SHATTERED	625.96	625.96
1	DOOR FINISHER FRT RH	* CHECK	515.06	-
1	DOOR MOULDING FRT RH	SERVICEABLE	176.82	-
1	DOOR FINISHER CLIP KIT FRT RH	SERVICEABLE	90.97	-
1	DOOR CASING FRT RH	SERVICEABLE	1,509.06	-
1	DOOR CASING LIGHT	SERVICEABLE	82.49	-
1	DOOR GRAB HANDLE FRT RH	SERVICEABLE	210.96	-
1	DOOR MIRROR RH	SERVICEABLE	1,725.73	-
1	DOOR WEATHERSTRIP FRT RH	SERVICEABLE	410.27	-
1	DOOR SEAL LOWER FRT RH	SERVICEABLE	91.17	-
1	DOOR GLASS RUNNER SEAL FRT RH	SERVICEABLE	626.36	-
1	DOOR WAIST SEAL OUTER FRT RH	SERVICEABLE	291.27	-
1	DOOR WAIST SEAL INNER FRT RH	SERVICEABLE	122.15	-
1	DOOR PANEL REAR RH	REPEATED	2,844.66	-
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR RH	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH	TORN	908.75	908.75
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-

Report Ref No. CC3/CTI18000433/Kes3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 11

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR WEATHERSTRIP REAR RH	CUT	410.66	410.66
1	DOOR SEAL REAR RH	* CHECK	162.02	-
1	DOOR WAIST SEAL OUTER REAR RH	DENTED	334.69	334.69
1	DOOR MOULDING REAR RH	DENTED	176.82	176.82
1	FENDER PANEL REAR RH	REPEATED	3,299.13	-
1	FENDER PANEL INNER TRIM REAR	REPEATED	671.45	-
1	WHEELARCH REAR RH	REPEATED	543.47	-
1	LOWER ARM RH L70Y	REPEATED	685.76	-
1	KNUCKLE ARM RH L70Y	REPEATED	846.98	-
1	KNUCKLE HUB+BEARING RH	REPEATED	497.69	-
1	KNUCKLE ARM SHIELD RH	* CHECK	131.43	-
1	KNUCKLE ARM PLATE RH	* CHECK	174.05	-
1	ABSORBER FRT RH	* CHECK	360.54	-
1	ABSORBER MOUNTING KIT RH	* CHECK	440.66	-
1	ABSORBER DUST COVER	* CHECK	228.72	-
1	STABILIZER BAR FRT L70Y	* CHECK	604.65	-
1	STABILIZER LINK FRT L70Y	* CHECK	117.22	-
1	BRAKE CALIPER FRT RH L70Y	SERVICEABLE	656.94	-
1	BRAKE CALIPER BRACKET FRT RH L70Y	SERVICEABLE	555.12	-
1	ABS SENSOR FRT RH L70Y	SERVICEABLE	255.75	-
1	DRIVESHAFT RH	* CHECK	1,747.45	-
1	ROCKER PANEL INNER GARNISH RH	NO SUCH PARTS	466.51	-
1	ROCKER PANEL INNER LH	TO REPAIR SEE LABOUR	1,024.79	-
1	DOOR PANEL FRT RH	REPEATED	2,844.66	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT RH	SERVICEABLE	194.77	-
1	DOOR CHECK BOLT	SERVICEABLE	22.69	-

Report Ref No. CC3/CT118000433/Kes3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 11

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR LOCK FRT RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH	TO REPAIR SEE LABOUR	131.23	-
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	TO REPAIR SEE LABOUR	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	DOOR GLASS FRT RH	SERVICEABLE	625.96	-
1	DOOR FINISHER FRT RH	SERVICEABLE	515.06	-
1	DOOR MOULDING FRT RH	SERVICEABLE	176.82	-
1	DOOR FINISHER CLIP KIT FRT RH	NOT NECESSARY	90.97	-
1	DOOR CASING FRT RH	SERVICEABLE	1,509.06	-
1	DOOR CASING LIGHT	SERVICEABLE	82.49	-
1	DOOR GRAB HANDLE FRT RH	SERVICEABLE	210.96	-
1	DOOR MIRROR RH	SERVICEABLE	1,725.73	-
1	DOOR WEATHERSTRIP FRT RH	SERVICEABLE	410.27	-
1	DOOR SEAL LOWER FRT RH	SERVICEABLE	91.17	-
1	DOOR GLASS RUNNER SEAL FRT RH	SERVICEABLE	626.36	-
1	DOOR WAIST SEAL OUTER FRT RH	SERVICEABLE	291.27	-
	LESS 10% DISCOUNT		-15,760.44	-4,477.15
			141,843.96	40,294.35
	SPECIAL NETT ITEMS			
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NECESSARY	52.00	52.00
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	MISSING	14.50	14.50
1	SET RADIATOR GRILLE SCREW (SN)	NECESSARY	16.00	16.00

Report Ref No. CC3/CTI18000433/Kes3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:8 of 11

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NECESSARY	70.00	70.00
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NECESSARY	30.50	30.50
1	SET WHEELARCH CLIP FRT RH (SN)	NECESSARY	29.40	29.40
1	CAP HUB RH FRT (SN)	DENTED	35.00	35.00
1	CAP HUB RH REAR (SN)	DENTED	35.00	35.00
1	RIM RH REAR (SN)	DENTED	385.00	385.00
1	TYRE RH REAR (30%) (SN)	PUNCTURE	330.00	231.00
1	SET BUMPER RR CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BEAM BOLT (SN)	NECESSARY	22.22	22.22
1	SET PARKING AID (SN)	SERVICEABLE	600.00	-
1	BUMPER BRACKET CLIP CTR REAR (SN)	NOT NECESSARY	15.00	-
1	BUMPER BRACKET SIDE CLIP LH REAR (SN)	NOT NECESSARY	12.00	-
1	BUMPER RETAINER CLIP LH REAR (SN)	NOT NECESSARY	10.40	-
1	BUMPER BRACKET SIDE CLIP RH REAR (SN)	NOT NECESSARY	12.00	-
1	BUMPER RETAINER CLIP RH REAR (SN)	NOT NECESSARY	10.40	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	25.10	-
1	REAR BOOTS STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	REAR BOOTS STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	FENDER PANEL INNER TRIM CLIP REAR RH (SN)	NOT NECESSARY	22.00	-
1	FENDER PANEL INNER TRIM CLIP REAR LH (SN)	NOT NECESSARY	22.00	-
1	SET WHEELARCH CLIP LH RR (SN)	NECESSARY	32.34	32.34
1	SET WHEELARCH CLIP RH RR (SN)	NECESSARY	32.34	32.34
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	65.50	-
1	EXHAUST BRACKET REAR (SN)	TO REPAIR SEE LABOUR	22.22	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	DOOR STICKER "6555-3333" RH (SN)	SERVICEABLE	80.00	-

Report Ref No. CC3/CTI18000433/Kes3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:9 of 11

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR STICKER 'TRANS-CAB' RH (SN)	SERVICEABLE	80.00	-
1	DOOR STICKER 'CHASSIS' RH (SN)	SERVICEABLE	30.00	-
1	LOWER ARM BOLT (SN)	SERVICEABLE	34.14	-
1	LOWER ARM NUT (SN)	SERVICEABLE	19.93	-
1	ABSORBER BOLT (SN)	SERVICEABLE	44.01	-
1	ABSORBER NUT (SN)	SERVICEABLE	17.56	-
1	BRAKE DISC SCREW FRT (SN)	SERVICEABLE	15.20	-
1	KNUCKLE ARM BOLT LH (SN)	SERVICEABLE	14.21	-
1	BRAKE CALIPER BRACKET BOLT FRT RH (SN)	SERVICEABLE	19.93	-
			2,971.90	1,287.30
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FENDER BRACKET LOWER LH, BUMPER BEAM REAR, BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR LOCK FRT RH, DOOR CATCH FRT RH, DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, ROCKER PANEL INNER LH, DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR LOCK FRT RH, DOOR CATCH FRT RH, DOOR REGULATOR FRT RH }		7,500.00	2,600.00
	AND EXHAUST BRACKET REAR. }		-	-
	TOWING FEES.		120.00	50.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	1,980.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	150.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.		170.00	20.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	40.00

Report Ref No. CC3/CTI18000433/Kes3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:10 of 11

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.		380.00	250.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGAGGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	60.00
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING. }		380.00	-
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		380.00	120.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. }		280.00	80.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE. }		170.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	* CHECK	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	* CHECK	440.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	* CHECK	480.00	-
	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.		380.00	60.00
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.		380.00	100.00
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.		170.00	50.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-

Report Ref No. CC3/CTI18000433/Kes3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:11 of 11

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	120.00
			21,110.00	5,970.00
	GRAND TOTAL		165,925.86	47,551.65
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$45,159.20 NETT)			47,551.65

Report Ref No. CC3/CTI18000433/Kes3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.