



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18000467/Aea3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 20-03-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 8184P	Veh. Inspected	SLQ 5063D
Policy No.	DMCVSN3086751700	Coverage (\$)	0.00
Claim No.	SNM18D00134/C02/3	Excess (\$)	0.00
Assign From		Assign Date	08/01/2018
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 120I	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	WBAUL52060VE84777	Colour	SILVER
Odometer	102513	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45R17	PIRELLI	6 mm
L/H Front Tyre	225/45R17	PIRELLI	6 mm
R/H Rear Tyre	225/45R17	PIRELLI	6 mm
L/H Rear Tyre	225/45R17	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/01/2018	Inspection Date	08/01/2018
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 5063D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
2	REAR NUMBER PLATE LAMP	NOT NECESSARY	130.00	-
1	REAR BUMPER	DISTORTED	1,245.00	1,245.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	30.00
2	REAR BUMPER SIDE HOLDER	DAMAGED	276.00	276.00
1	REAR BUMPER TOW COVER	MISSING	22.00	22.00
1	REAR BUMPER REINFORCEMENT	BENT	435.00	435.00
1	REAR BUMPER INNER FRAME	CRACKED	158.00	158.00
4	REVERSE SENSOR	DAMAGED	1,020.00	1,020.00
2	TAIL LAMP	CRACKED	760.00	760.00
2	TAIL LAMP PANEL	DENTED	590.00	590.00
1	REAR END PANEL	DISTORTED	658.00	658.00
1	REAR END PANEL TOP GARNISH	DEFORMED	128.00	128.00
1	BOOTLID	DISTORTED	1,285.00	1,285.00
1	BOOTLID LOCK	DAMAGED	186.00	186.00
1	BOOTLID WEATHERSTRIPE	CUT	198.00	198.00
2	BOOTLID HINGES	BENT	170.00	170.00
2	BOOTLID DAMPER	NOT NECESSARY	310.00	-
1	BOOTLID REFLECTOR	CRACKED	276.00	276.00
1	BOOTLID INNER TRIM BOARD	NOT NECESSARY	295.00	-
1	SET BOOTLID INNER TRIM BOARD CLIPS	NECESSARY	50.00	30.00
1	BMW LOGO	NECESSARY	65.00	65.00
1	120I EMBLEM	NECESSARY	89.00	89.00
1	BATTERY TERMINAL	ACTIVATED	220.00	220.00
1	REAR EXHAUST PIPE	NOT NECESSARY	926.00	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	56.00	-
2	REAR FENDER INNER TRIM	DEFORMED	716.00	716.00
1	SET REAR FENDER INNER TRIM CLIPS	NECESSARY	60.00	60.00
2	SEAT BELT BUCKLE	ACTIVATED	650.00	650.00
	LESS 10% DISCOUNT		-1,102.40	-926.70
			9,921.60	8,340.30

Report Ref No. CC6/CTI18000467/Aea3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>SPECIAL NETT ITEMS</b>				
1	REAR NUMBER PLATE (SN)	BENT	30.00	30.00
1	REAR NUMBER PLATE HOLDER (SN)	DEFORMED	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
			140.00	130.00
<b>LABOUR</b>				
	TO KNOCKING OUT REAR PORTION & RENEW ABOVE PARTS.		1,500.00	1,200.00
	TO PUTTY & SPRAY UP PAINT WORKS.		1,200.00	800.00
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO UNDERSEAL.		150.00	60.00
	TO REMOVE UPHOLSTERY.		150.00	100.00
	TO REMOVE EXHAUST PIPE.	NOT NECESSARY	150.00	-
	TO TRANSFER BOOTLID FITTINGS.		150.00	100.00
	TO RESET AIR BAG CONFIGURATION.		350.00	250.00
	TO RESET OVER-ALL PROTECTION.		550.00	400.00
	TO PERFORM DIAGNOSTIC TEST.		200.00	120.00
			4,450.00	3,060.00
<b>GRAND TOTAL</b>			<b>14,511.60</b>	<b>11,530.30</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>9,000.00</b>

Report Ref No. CC6/CTI18000467/Aea3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.