

283	FRONT BUMPER NEW PART PAINT K1R	13.0	
1746	R/DOOR MIRROR HSG NEW PART PAINT K1R	3.0	
2185	L/SILL MOULDING NEW PART PAINT K1R	7.0	
2186	R/SILL MOULDING NEW PART PAINT K1R	7.0	
2583	REAR BUMPER NEW PART PAINT K1R	14.0	
471	BONNET REPAIR PAINTING >50%	41.0	
741	L/F WING REPAIR PAINTING >50%	16.0	
742	R/F WING REPAIR PAINTING >50%	16.0	
1211	L/INN SIDE MEMBER SURFACE PAINT	5.0	
3481	L/R WING SURFACE PAINT	8.0	
3482	R/R WING SURFACE PAINT	8.0	
LABOUR COST - PAINT			
	TIME(PAINT)	230.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	260.0	
	Total Paintwork Labour	26.0HRS	\$1,196.00
MATERIAL COST - PAINT			
	New Part Painting		Cost Price
	New Part Painting - Plastic K1R		\$167.18
	Material-Constant Main Work Metal		\$197.29
	Surface-/Blend Paint		\$28.60
	Repair Painting		\$116.78
	Material-Const Main Work Plastic		\$98.75
	Total Excluding Pearlescent Uplift		\$9.00
	Pearlescent Uplift @ 0.0%		\$617.60
	Total Paint Material Cost		\$0.00
			\$617.60

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
260	1	FRT NO PLATE BRKT	52114 06100		0%	50.00*
283	1	FRONT BUMPER	52119 06951		0%	220.00*
297	1	L/FOG LAMP COVER	52040 06110		0%	80.00*
298	1	R/FOG LAMP COVER	52030 06110		0%	80.00*
301	1	L/F OUTER SENSOR	89341 33180B0		0%	165.00*
302	1	R/F OUTER SENSOR	89341 33180B0		0%	165.00*
303	1	L/PARK AID SENS CVR	89348 33080A0		0%	18.00*
304	1	R/PARK AID SENS CVR	89348 33080A0		0%	18.00*
317	1	L/F UPP BUMPER BRKT	52536 06110		0%	45.00*
318	1	R/F UPP BUMPER BRKT	52535 06120		0%	45.00*
340	1	BUMPER SUPPORT	52021 06080		0%	150.00*
344	1	FRT BUMPER ABSORBER	52611 06180		0%	65.00*
410	1	GRILLE	53101 06270		0%	170.00*
412	1	CTR BUMPER GRILLE	53112 06160		0%	80.00*
471	1	BONNET	53301 06140		0%	360.00*
475	1	L/BONNET HINGE	53420 33180		0%	40.00*
476	1	R/BONNET HINGE	53410 33180		0%	40.00*
481	1	BONNET INSULATION	53341 06210		0%	95.00*
493	1	LOWER BONNET LOCK	53510 06160		0%	55.00*
497	1	L/BONNET DAMPER	53450 06060		0%	120.00*
498	1	R/BONNET DAMPER	53440 06070		0%	120.00*

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SNM17D07299C01

Assessment Number: KKHC0208

Version: LKKAUTOC/2

Date Calculated: 12/10/2018 03:07

Full Report - V1

Registration: SCR8873P

Printed: 12/10/2018 10:08

500	1	CONTROL CABLE	53630 06140	0%	60.00*
527	1	BONNET FRONT SEAL	53381 06090	0%	45.00*
561	1	LEFT HEADLAMP ASSY	81150 06630	0%	1,300.00*
562	1	RIGHT HEADLAMP ASSY	81110 06630	0%	1,300.00*
637	1	L/F FOG LAMP CPL	81220 06052	0%	110.00*
638	1	R/F FOG LAMP CPL	81210 06052	0%	110.00*
741	1	L/F WING	53802 06170	0%	185.00*
742	1	R/F WING	53801 06160	0%	185.00*
767	1	L/WING MOULDING	53826 06060	0%	45.00*
768	1	R/WING MOULDING	53825 06060	0%	45.00*
841	1	L/WHEELHOUSE SHELL	53876 06100	0%	65.00*
842	1	R/WHEELHOUSE SHELL	53875 06100	0%	65.00*
988	1	LOCK CARRIER STRUT	53208 06070	0%	45.00*
1009	1	FRONT PANEL	53201 06160	0%	220.00*
1118	1	R/F WHEELHOUSE CPL	53701 06150	0%	195.00*
1169	1	L/RADIATOR AIR GUIDE	53294 06110	0%	55.00*
1170	1	R/RADIATOR AIR GUIDE	53293 06120	0%	55.00*
1203	1	L/F BUMPER REINF	57118 06080	0%	65.00*
1212	1	R/INN SIDE MEMBER	57027 06051	0%	590.00*
1392	1	AIR GUIDE TRIM	55708 06130	0%	145.00*
1401	1	WINDSCREEN	56101 06431	0%	420.00*
1411	1	WINDSCREEN BOND KIT	PZ49I 00C1131	0%	38.18U
1415	2	CLIP FASTENING	56115 30120	0%	4.76U
1416	2	CLIP FASTENING	56116 22050	0%	3.96U
1436	1	WASHER CONTAINER	85315 06190	0%	95.00*
1453	1	L/F WIPER ARM	85221 06100	0%	95.00*
1454	1	R/F WIPER ARM	85211 06100	0%	95.00*
1457	1	L/F WIPER BLADE	85222 33250	0%	60.00*
1458	1	R/F WIPER BLADE	85212 53081	0%	60.00*
1738	1	R/DOOR MIRROR	87910 06322A0	0%	420.00*
2185	1	L/SILL MOULDING	75852 06903	0%	195.00*
2186	1	R/SILL MOULDING	75851 06903	0%	195.00*
2583	1	REAR BUMPER	52159 06923	0%	260.00*
3011	1	BADGE "VVT-I" L	75443 06260	0%	18.00*
3012	1	BADGE "VVT-I" R	75443 06540	0%	18.00*
4331	1	INSTRUMENT PNL TRIM	55401 06161C0	0%	600.00*
4455	1	COMPRESSOR	88310 06280	0%	580.00*
4465	1	CONDENSER	88460 06220	0%	375.00*
4481	1	COMPR/CONDENSER TUBE	88711 06340	0%	165.00*
4482	1	COND/EVAPORATOR PIPE	88710 06271	0%	195.00*
4483	1	COMPR/EVAP TUBE	88712 06180	0%	185.00*
4485	1	FRT PIPE COMPR/COND	88715 06080	0%	115.00*
7011	1	FRT AXLE CARRIER	51100 06100	0%	980.00*
7017	1	L/F SUSPN BUFFER	52213 06130	0%	80.00*
7018	1	R/F SUSPN BUFFER	52213 06130	0%	80.00*
7025	1	L/R BUFFER	52216 06110	0%	80.00*
7026	1	R/R BUFFER	52216 06110	0%	80.00*
7027	1	L/F CONTROL ARM BUSH	52211 06130	0%	80.00*
7028	1	R/F CONTROL ARM BUSH	52211 06130	0%	80.00*
7029	1	L/R CONTROL ARM BUSH	52217 06090	0%	80.00*
7030	1	R/R CONTROL ARM BUSH	52215 06110	0%	80.00*
7053	1	L/LWR AXLE STEERING	48069 06140	0%	145.00*

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SNM17D07299C01

Full Report - V1

Assessment Number: KKHC0208

Registration: SCR8873P

Version: LKKAUTOC/2

Printed: 12/10/2018 10:08

Date Calculated: 12/10/2018 03:07

7054	1	R/LWR AXLE STEERING	48068 06140	0%	145.00*
7065	1	L/CARRIER JOINT	43340 09130	0%	75.00*
7066	1	R/CARRIER JOINT	43330 09710	0%	75.00*
7069	1	L/SEAT W/OUT SPRING	48471 41010	0%	35.00*
7070	1	R/SEAT W/OUT SPRING	48471 41010	0%	35.00*
7077	1	L/F STRUT	48520 09K90	0%	215.00*
7078	1	R/F STRUT	48510 09S30	0%	215.00*
7081	1	L/F STEERING KNUCKLE	43212 06230	0%	185.00*
7082	1	R/F STEERING KNUCKLE	43211 06230	0%	185.00*
7091	1	L/UPP SUPP MOUNTING	48609 06170	0%	80.00*
7092	1	R/UPP SUPP MOUNTING	48609 06170	0%	80.00*
7101	1	L/F DAMPER BUFFER	48331 33032	0%	25.00*
7102	1	R/F DAMPER BUFFER	48331 33032	0%	25.00*
7117	1	L/F WHEEL BEARING	90363 C0002	0%	75.00*
7118	1	R/F WHEEL BEARING	90363 C0002	0%	75.00*
7131	1	L/F WHEEL HUB	43502 06110	0%	175.00*
7132	1	R/F WHEEL HUB	43502 06110	0%	175.00*
7241	1	ABS BRAKE UNIT	44050 06090	0%	4,100.00*
7761	1	RADIATOR	16400 0H291	0%	400.00*
7767	1	RADIATOR SHROUD	16711 0H150	0%	125.00*
7769	1	L/UPP RADIATOR BRKT	16523 0H040	0%	18.00*
7770	1	R/UPP RADIATOR BRKT	16523 0H040	0%	18.00*
7771	1	L/LWR RADIATOR BRKT	16535 0H040	0%	18.00*
7772	1	R/LWR RADIATOR BRKT	16535 0H040	0%	18.00*
7773	1	LWR RADIATOR HOSE	16572 0H140	0%	40.00*
7776	1	UPPER RADIATOR HOSE	16571 0H160	0%	35.00*
7787	1	EXPANSION TANK	16470 0H090	0%	105.00*
7789	1	L/FAN MOTOR	16363 02120	0%	180.00*
7790	1	R/FAN MOTOR	16363 0H170	0%	180.00*
7793	1	L/BLOWER FAN	16361 0H190	0%	80.00*
7794	1	R/BLOWER FAN	16361 0H200	0%	80.00*
8041	1	OIL FILTER	90915 YZZJ2	0%	18.00*
8067	1	SUMP	12101 0H080	0%	115.00*
8375	1	AIR INTAKE HOSE	17750 0H090	0%	70.00*
8391	1	AIR FILTER ASSY	17700 0H131	0%	280.00*
8626	1	FRONT ENGINE STRUT	12309 0H090	0%	145.00*
8677	1	RR CTR ENGINE MNTG	12372 0H110	0%	135.00*
8678	1	UPPER ENGINE BRACKET	12362 0V020	0%	145.00*
8679	1	FRT CTR SILENTBLOCK	12361 0H110	0%	145.00*
8781	1	L/ENGINE COVER	51442 06120	0%	75.00*
8782	1	R/ENGINE COVER	51441 06130	0%	75.00*
8797	1	FRONT HEAT SHIELD	25586 28090	0%	130.00*
8801	1	EXHAUST MANIFOLD	25051 28330	0%	2,650.00*
8805	1	EXHAUST INSULATION	17167 28060	0%	265.00*
8811	1	FRONT LAMBDA PROBE	89467 33080	0%	165.00*
8815	1	FRONT EXHAUST PIPE	17410 0H240	0%	195.00*
8823	1	EXHAUST PIPE	17420 0H210	0%	220.00*
8834	1	REAR SILENCER	17430 0H230	0%	230.00*
9113	1	L/R STRG KNUCKLE	42305 06180	0%	220.00*
9114	1	R/R STRG KNUCKLE	42304 06200	0%	220.00*
9181	1	L/R WHEEL HUB CPL	42460 06040	0%	300.00*
9182	1	R/R WHEEL HUB CPL	42450 06060	0%	300.00*

9325	1	L/R TOWING STRUT	48780 06060	0%	145.00*
9385	1	L/R TRAILING ARM FRT	48710 06050	0%	155.00*
9386	1	R/R TRAILING ARM FRT	48710 06050	0%	155.00*
9631	1	BATTERY HOLDER	74431 06050	0%	45.00*
9645	1	L/HORN	86510 06101	0%	60.00*
9646	1	R/HORN	86520 06091	0%	60.00*
9660	1	FUSE BOX	82740 33020	0%	220.00*
9662	1	LOWER FUSE BOX COVER	82663 33070	0%	120.00*
1000	1	FRT TOW CVR	Renew	0%	12.00*
1000	1	FRT PARKING SEN WIRE	Renew	0%	1,350.00*
1000	1	BONNET CHROME	Renew	0%	75.00*
1000	1	BONNET STOPPER LH	Renew	0%	12.00*
1000	1	BONNET STOPPER RH	Renew	0%	12.00*
1000	1	FRT SUP TOP STOP LH	Renew	0%	15.00*
1000	1	FRT SUP TOP STOP RH	Renew	0%	15.00*
1000	1	FRT SUPP TOP GARNISH	Renew	0%	110.00*
1000	1	OUTSIDE TEMP SENSOR	Renew	0%	85.00*
1000	1	WING SHIELD BRKT LH	Renew	0%	6.50*
1000	1	WING SHIELD BRKT RH	Renew	0%	6.50*
1000	1	FRT WING INN BRKT LH	Renew	0%	50.00*
1000	1	FRT WING INN BRKT RH	Renew	0%	50.00*
1000	1	BATTERY TOP BRKT	Renew	0%	30.00*
1000	1	WIPER SIDE GAR LH	Renew	0%	30.00*
1000	1	WIPER SIDE GAR RH	Renew	0%	30.00*
1000	1	RR FLOOR UNDERCOVER	Renew	0%	90.00*
1000	1	SKIRT CHROME MLD LH	Renew	0%	95.00*
1000	1	SKIRT CHROME MLD RH	Renew	0%	95.00*
1000	1	FLOOR PNL LWR GAR LH	Renew	0%	235.00*
1000	1	FLOOR PNL LWR GAR RH	Renew	0%	235.00*
1000	1	ENG UNDERCOVER LH	Renew	0%	95.00*
1000	1	ENG UNDERCOVER RH	Renew	0%	95.00*
1000	1	'O' RING-BIG	Renew	0%	15.00*
1000	1	'O' RING -SMALL	Renew	0%	12.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost

(5 %)

Sundry Parts

(Fixed)

Total Parts

\$30,209.90

\$1,510.50

\$100.00

\$31,820.40

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT NUMBER PLATE SPECIALIST	0%	\$40.00
AUDATEX FEES SPECIALIST		\$42.00
AIR CON GAS SPECIALIST	0%	\$50.00
ANTI FREEZE SPECIALIST		\$20.00
BRAKE OIL @2LX\$10 SPECIALIST	0%	\$20.00
ENGINE OIL @4.5LX\$20 SPECIALIST		\$90.00
WHEEL ALIGNMENT SPECIALIST	0%	\$80.00
FRT TYRE LH SPECIALIST		\$220.00
FRT TYRE RH SPECIALIST	0%	\$220.00
REAR TYRE RH SPECIALIST		\$220.00

FRT RIM RH	SPECIALIST	0%	\$520.00
FRT WS SEALANT	SPECIALIST		\$40.00
FRT WS DAMP SEAL	SPECIALIST	0%	\$20.00
ERP BRACKET	SPECIALIST		\$26.00
PRIVATE HIRE	SPECIALIST	0%	\$25.00
STICKER			
OIL SUMP SEALANT	SPECIALIST		\$40.00
Total Extras			\$1,673.00

Final Calculation

Total Parts		\$31,820.40
Labour		
Total Panel/Mechanical	\$2,290.80	
Total Paintwork	\$1,196.00	
Total Visual Alignment work	\$55.20	
Total Labour		\$3,542.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$1,673.00	
Total of Additional Costs		\$1,673.00
Total Paint/Material Costs		\$617.60
Repair Costs Excludes GST		\$37,653.00
Deductions		
Deduction for Excess (Fixed)	-\$1,000.00	
Total Deductions		-\$1,000.00
Grand Total Excludes GST (After Deduction)		\$36,653.00
GST @ 7 %		\$2,565.71
Grand Total Includes GST (After Deduction)		\$39,218.71

Assessment Notes

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2018	08 Jan 2018	09 Jan 2018	\$522,500.00	\$522,500.00		Pending for Survey Report
	Sendback Est	11:48	15:31	Edit Estimates	View Rpt		Cancel Case
		\$554,967.69	Edit Adj Rpt				

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS	
Insured:	EMING VEHICLES, Co. Reg. No.: 53366056D, Tel: +6591830887
Vehicle Reg. No.:	SCR8873P
Date of Loss:	28/12/2017 03:00 - :59 [43 Months and 22 Days From LTA Reg Date (Man Yr)]
Policy/Cover Note No.:	DMHCSN1748561700 (Comprehensive) Coverage: 13/07/2017 - 12/07/2018
Excess:	S\$1,000.00
Reparer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 18/01/2018]
Driver/Custodian:	CHONG EE MING CHRISTOPHER (30 / Male), NRIC: S8741068D, Tel: +6591830887
Adj Asg. Remarks:	PLEASE PROCEED TO CONDUCT SURVEY / REVERT / CHECK ECONOMICAL FOR REPAIR / CONDUCT SITE INSPECTION AND INTERVIEW DRIVER. EXCESS OF \$1,000.00 APPLIES.

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
- CHINA_TAIPING (02/02/2018): Alert - Adj Mandate Approved (\$522500.00) - SCR8873P - Claim Handler: Jowyn Tay - CHINA_TAIPING (12/01/2018): Alert - Adj Mandate Maintained - SCR8873P - Claim Handler: Jowyn Tay		

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SCR8873P (SNM17D07299C01)

OD

Dec 28 2017 3:00AM

[EMING VEHICLES]

K Kim Hin Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On		Thumbnail		Print
1	08/01/18 11:48	K Kim Hin Auto Pte Ltd (HQ) Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	11/01/18 14:16	Adjuster Immediate Advice		Load HTM	
2	30/01/18 11:44	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	☒
No	Finalized On		Thumbnail		Print
1	08/01/18 11:43	K Kim Hin Auto Pte Ltd (HQ) Accident Photo		Load JPG	☒
2	08/01/18 11:43	Accident Photo		Load JPG	☒
3	08/01/18 11:43	Accident Photo		Load JPG	☒
4	08/01/18 11:43	Accident Photo		Load JPG	☒
5	08/01/18 11:43	Accident Photo		Load JPG	☒
6	08/01/18 11:43	Accident Photo		Load JPG	☒
7	08/01/18 11:43	Accident Photo		Load JPG	☒
8	08/01/18 11:43	Accident Photo		Load JPG	☒
9	08/01/18 11:43	Accident Photo		Load JPG	☒
10	08/01/18 11:43	Accident Photo		Load JPG	☒
11	08/01/18 11:43	Accident Photo		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail		Print
1	11/01/18 14:33	General View		Load JPG	☒
2	11/01/18 14:33	General View		Load JPG	☒
3	11/01/18 14:33	General View		Load JPG	☒
4	11/01/18 14:33	General View		Load JPG	☒
5	11/01/18 14:33	General View		Load JPG	☒
6	11/01/18 14:33	General View		Load JPG	☒
7	11/01/18 14:33	General View		Load JPG	☒
8	11/01/18 14:33	General View		Load JPG	☒
9	11/01/18 14:33	General View		Load JPG	☒
10	11/01/18 14:33	General View		Load JPG	☒
11	11/01/18 14:33	General View		Load JPG	☒
12	11/01/18 14:33	General View		Load JPG	☒
13	11/01/18 14:33	General View		Load JPG	☒
14	11/01/18 14:33	General View		Load JPG	☒
15	11/01/18 14:33	General View		Load JPG	☒
16	11/01/18 14:33	General View		Load JPG	☒
17	11/01/18 14:33	General View		Load JPG	☒
18	11/01/18 14:33	General View		Load JPG	☒
19	11/01/18 14:33	General View		Load JPG	☒
20	11/01/18 14:33	General View		Load JPG	☒
21	11/01/18 14:33	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
22	11/01/18 14:33	General View	 Load JPG	☒
23	11/01/18 14:33	General View	 Load JPG	☒
24	11/01/18 14:33	General View	 Load JPG	☒
25	11/01/18 14:33	General View	 Load JPG	☒
26	11/01/18 14:33	General View	 Load JPG	☒
27	11/01/18 14:33	General View	 Load JPG	☒
28	11/01/18 14:33	General View	 Load JPG	☒
29	11/01/18 14:33	General View	 Load JPG	☒
30	11/01/18 14:33	General View	 Load JPG	☒
31	11/01/18 14:33	General View	 Load JPG	☒
32	11/01/18 14:33	General View	 Load JPG	☒
33	11/01/18 14:33	General View	 Load JPG	☒
34	11/01/18 14:33	General View	 Load JPG	☒
35	11/01/18 14:33	General View	 Load JPG	☒
36	11/01/18 14:33	General View	 Load JPG	☒
37	11/01/18 14:33	General View	 Load JPG	☒
38	11/01/18 14:33	General View	 Load JPG	☒
39	11/01/18 14:33	General View	 Load JPG	☒
40	11/01/18 14:33	General View	 Load JPG	☒
41	11/01/18 14:33	General View	 Load JPG	☒
42	11/01/18 14:33	General View	 Load JPG	☒
43	11/01/18 14:33	General View	 Load JPG	☒
44	11/01/18 14:33	General View	 Load JPG	☒
45	11/01/18 14:34	General View	 Load JPG	☒
46	11/01/18 14:34	General View	 Load JPG	☒
47	11/01/18 14:34	General View	 Load JPG	☒
48	11/01/18 14:34	General View	 Load JPG	☒
49	11/01/18 14:34	General View	 Load JPG	☒
50	11/01/18 14:34	General View	 Load JPG	☒
51	11/01/18 14:34	General View	 Load JPG	☒
52	11/01/18 14:34	General View	 Load JPG	☒
53	11/01/18 14:34	General View	 Load JPG	☒
54	11/01/18 14:34	General View	 Load JPG	☒
55	11/01/18 14:34	General View	 Load JPG	☒
56	11/01/18 14:34	General View	 Load JPG	☒
57	11/01/18 14:34	General View	 Load JPG	☒
58	11/01/18 14:34	General View	 Load JPG	☒
59	11/01/18 14:34	General View	 Load JPG	☒
60	11/01/18 14:34	General View	 Load JPG	☒
61	11/01/18 14:34	General View	 Load JPG	☒
62	11/01/18 14:34	General View	 Load JPG	☒
63	11/01/18 14:34	General View	 Load JPG	☒
64	11/01/18 14:34	General View	 Load JPG	☒
65	11/01/18 14:34	General View	 Load JPG	☒
66	11/01/18 14:34	General View	 Load JPG	☒
67	11/01/18 14:34	General View	 Load JPG	☒
68	11/01/18 14:34	General View	Load JPG	☒
69	11/01/18 14:34	General View	Load JPG	☒
70	11/01/18 14:34	General View	Load JPG	☒
71	11/01/18 14:34	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
72	11/01/18 14:34	General View	 Load JPG	☒
73	11/01/18 14:34	General View	 Load JPG	☒
74	11/01/18 14:34	General View	 Load JPG	☒
75	11/01/18 14:34	General View	 Load JPG	☒
76	11/01/18 14:34	General View	 Load JPG	☒
77	11/01/18 14:34	General View	 Load JPG	☒
78	11/01/18 14:34	General View	 Load JPG	☒
79	11/01/18 14:34	General View	 Load JPG	☒
80	11/01/18 14:34	General View	 Load JPG	☒
81	11/01/18 14:34	General View	 Load JPG	☒
82	11/01/18 14:34	General View	 Load JPG	☒
83	11/01/18 14:34	General View	 Load JPG	☒
84	11/01/18 14:34	General View	 Load JPG	☒
85	11/01/18 14:34	General View	 Load JPG	☒
86	11/01/18 14:34	General View	 Load JPG	☒
87	11/01/18 14:34	General View	 Load JPG	☒
88	11/01/18 14:34	General View	 Load JPG	☒
89	11/01/18 14:34	General View	 Load JPG	☒
90	11/01/18 14:34	General View	 Load JPG	☒
91	11/01/18 14:34	General View	 Load JPG	☒
92	11/01/18 14:34	General View	 Load JPG	☒
93	11/01/18 14:34	General View	 Load JPG	☒
94	11/01/18 14:34	General View	 Load JPG	☒
95	11/01/18 14:34	General View	 Load JPG	☒
96	11/01/18 14:34	General View	 Load JPG	☒
97	11/01/18 14:34	General View	 Load JPG	☒
98	11/01/18 14:34	General View	 Load JPG	☒
99	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
100	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
101	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
102	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
103	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
104	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
105	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
106	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
107	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
108	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
109	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
110	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
111	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
112	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
113	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
114	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
115	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
116	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
117	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
118	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
119	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
120	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
121	21/03/18 11:49	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
122	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
123	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
124	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
125	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
126	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
127	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
128	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
129	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
130	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
131	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
132	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
133	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
134	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
135	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
136	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
137	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
138	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
139	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
140	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
141	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
142	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
143	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
144	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
145	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
146	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
147	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
148	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
149	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
150	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
151	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
152	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
153	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
154	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
155	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
156	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
157	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
158	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
159	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
160	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
161	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
162	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
163	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
164	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
165	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
166	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
167	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
168	21/03/18 11:49	Reinspection Photo	Load JPG	☒
169	21/03/18 11:49	Reinspection Photo	Load JPG	☒
170	21/03/18 11:49	Reinspection Photo	Load JPG	☒
171	21/03/18 11:49	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
172	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
173	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
174	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
175	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
176	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
177	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
178	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
179	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
180	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
181	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
182	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
183	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
184	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
185	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
186	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
187	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
188	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
189	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
190	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
191	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
192	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
193	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
194	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
195	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
196	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
197	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
198	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
199	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
200	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
201	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
202	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
203	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
204	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
205	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
206	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
207	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
208	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
209	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
210	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
211	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
212	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
213	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
214	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
215	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
216	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
217	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
218	21/03/18 11:49	Reinspection Photo	Load JPG	☒
219	21/03/18 11:49	Reinspection Photo	Load JPG	☒
220	21/03/18 11:49	Reinspection Photo	Load JPG	☒
221	21/03/18 11:49	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
222	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
223	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
224	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
225	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
226	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
227	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
228	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
229	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
230	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
231	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
232	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
233	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
234	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
235	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
236	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
237	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
238	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
239	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
240	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
241	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
242	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
243	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
244	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
245	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
246	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
247	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
248	21/03/18 11:49	Reinspection Photo	 Load JPG	☒
249	21/03/18 11:50	Reinspection Photo	 Load JPG	☒
250	21/03/18 11:50	Reinspection Photo	 Load JPG	☒
251	21/03/18 11:50	Reinspection Photo	 Load JPG	☒
252	21/03/18 11:50	Reinspection Photo	 Load JPG	☒
253	21/03/18 11:50	Reinspection Photo	 Load JPG	☒
254	21/03/18 11:50	Reinspection Photo	 Load JPG	☒
255	21/03/18 11:50	Reinspection Photo	 Load JPG	☒
256	21/03/18 11:50	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	08/01/18 11:36	E-filed GIA report	 Load PDF	
2	08/01/18 11:42	ACRA	 Load PDF	
3	08/01/18 11:42	Certificate of Insurance	 Load PDF	
4	08/01/18 11:42	Log card (if available)	 Load PDF	
5	08/01/18 11:42	Driver's NRIC	 Load PDF	
6	08/01/18 11:42	TRANSFER FEE	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/01/18 14:16	ESTIMATE	 Load PDF	
2	11/01/18 14:16	REVISED AUDATEX	 Load PDF	
3	29/01/18 12:12	SCR 8873P INTERVIEW REPORT	 Load PDF	
4	22/10/18 16:42	Investigation Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118000550/DQD3E2

Date: 22/10/2018

REFERENCE

Insured/Claimant: EMING VEHICLES Policy No: DMHCSN1748561700
Date of Loss: 28/12/2017 Nature of Claim: OD Claim No: SNM17D07299C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCR8873P**
Make & Model: TOYOTA CAMRY, 2.5 (A) Engine No: 2ARU131457
Reg. Date: 06/05/2014 (Man. Year: 2014) Chassis No: MR053AK5004007612
Colour: Silver Odometer: 70811 km
Engine Capacity: 2494 cc
Market Value/New Car Price: S\$92,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50,357.29	33,493.40	16,863.89	33.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,610.40	4,159.60	450.80	9.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	54,967.69	37,653.00	17,314.69	31.50
Approved Total (Overridden) (S\$)		22,500.00		
- Excess (S\$)	0.00	1,000.00	-1,000.00	
(S\$)	54,967.69	21,500.00	33,467.69	60.89
+ GST 7.00/7.00% (S\$)	3,847.74	1,505.00	2,342.74	60.89
Nett Amount (S\$)	58,815.43	23,005.00	35,810.43	60.89

INSPECTION

Date of Assignment: 09/01/2018 Present Location:
Date Inspected: 10/01/2018 Inspected At:

K Kim Hin Auto Pte Ltd (HQ)
K Kim Hin Auto Pte Ltd (HQ)
160 Sin Ming Drive #02-20, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 18.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 22 Oct 2018)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SCR8873P)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*ABS BRAKE UNIT	Cut	4,100.00 F	*4,100.00 F
2	1	NA	*AIR FILTER ASSY	Distorted	280.00 F	*280.00 F
3	1	NA	*AIR GUIDE TRIM	Cut	145.00 F	*145.00 F
4	1	NA	*AIR INTAKE HOSE	Distorted	70.00 F	*70.00 F
5	1	NA	*BADGE "VVT-I" L	Necessary	18.00 F	*18.00 F
6	1	NA	*BADGE "VVT-I" R	Necessary	18.00 F	*18.00 F
7	1	NA	*BATTERY	Repeated	0.00 F	*- F
8	1	NA	*BATTERY HOLDER	Bent	45.00 F	*45.00 F
9	1	NA	*BATTERY TOP BRKT	Bent	30.00 F	*30.00 F
10	1	NA	*BONNET	Bent	360.00 F	*360.00 F
11	1	NA	*BONNET CHROME	Dented	75.00 F	*75.00 F
12	1	NA	*BONNET FRONT SEAL	Necessary	45.00 F	*45.00 F
13	1	NA	*BONNET INSULATION	Distorted	95.00 F	*95.00 F
14	1	NA	*BONNET STOPPER LH	Necessary	12.00 F	*12.00 F
15	1	NA	*BONNET STOPPER RH	Necessary	12.00 F	*12.00 F
16	1	NA	*BUMPER SUPPORT	Bent	150.00 F	*150.00 F
17	1	NA	*CLIP FASTENING	Necessary	4.88 F	*4.76 F
18	1	NA	*CLIP FASTENING	Necessary	3.96 F	*3.96 F
19	1	NA	*COMPR/CONDENSER TUBE	Bent	165.00 F	*165.00 F
20	1	NA	*COMPR/EVAP TUBE	Bent	185.00 F	*185.00 F
21	1	NA	*COMPRESSOR	Broken	580.00 F	*580.00 F
22	1	NA	*COND/EVAPORATOR PIPE	Bent	195.00 F	*195.00 F
23	1	NA	*CONDENSER	Bent	375.00 F	*375.00 F
24	1	NA	*CONTROL CABLE	Cut	60.00 F	*60.00 F
25	1	NA	*CRANKSHAFT PULLEY	Serviceable	215.00 F	*- F
26	1	NA	*CTR BUMPER GRILLE	Missing	80.00 F	*80.00 F
27	1	NA	*DRIVE BELT TENSIONER	Not Necessary	155.00 F	*- F
28	1	NA	*ELECTRIC FUEL PUMP	Serviceable	195.00 F	*- F
29	1	NA	*ENG OIL FILTER HSING	Not Necessary	95.00 F	*- F
30	1	NA	*ENG UNDERCOVER LH	Missing	95.00 F	*95.00 F
31	1	NA	*ENG UNDERCOVER RH	Missing	95.00 F	*95.00 F
32	1	NA	*ENGINE CONTROL UNIT	Not Necessary	7,100.00 F	*- F
33	1	NA	*EXHAUST INSULATION	Dented	265.00 F	*265.00 F
34	1	NA	*EXHAUST MANIFOLD	Dented	2,650.00 F	*2,650.00 F
35	1	NA	*EXHAUST PIPE	Dented	220.00 F	*220.00 F
36	1	NA	*EXPANSION TANK	Distorted	105.00 F	*105.00 F
37	1	NA	*FLOOR PNL LWR GAR LH	Distorted	235.00 F	*235.00 F
38	1	NA	*FLOOR PNL LWR GAR RH	Distorted	235.00 F	*235.00 F
39	1	NA	*FRONT BUMPER	Torn	220.00 F	*220.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1	NA	*FRONT ENGINE STRUT	Bent	145.00 F	*145.00 F
41	1	NA	*FRONT ENGINE SUPPORT	Serviceable	135.00 F	*- F
42	1	NA	*FRONT EXHAUST PIPE	Dented	195.00 F	*195.00 F
43	1	NA	*FRONT HEAT SHIELD	Bent	130.00 F	*130.00 F
44	1	NA	*FRONT LAMBDA PROBE	Dented	165.00 F	*165.00 F
45	1	NA	*FRONT NUMBER PLATE	Not Necessary	18.00 F	*- F
46	1	NA	*FRONT PANEL	Dented	220.00 F	*220.00 F
47	1	NA	*FRONT STABILISER	Not Necessary	195.00 F	*- F
48	1	NA	*FRT AXLE CARRIER	Bent	980.00 F	*980.00 F
49	1	NA	*FRT BUMPER ABSORBER	Missing	65.00 F	*65.00 F
50	1	NA	*FRT CTR SILENTBLOCK	Torn	145.00 F	*145.00 F
51	1	NA	*FRT NO PLATE BRKT	Missing	50.00 F	*50.00 F
52	1	NA	*FRT PARKING SEN WIRE	Distorted	1,350.00 F	*1,350.00 F
53	1	NA	*FRT PIPE COMPR/COND	Bent	115.00 F	*115.00 F
54	1	NA	*FRT SUP TOP STOP LH	Missing	15.00 F	*15.00 F
55	1	NA	*FRT SUP TOP STOP RH	Missing	15.00 F	*15.00 F
56	1	NA	*FRT SUPP TOP GARNISH	Distorted	110.00 F	*110.00 F
57	1	NA	*FRT TOW CVR	Missing	12.00 F	*12.00 F
58	1	NA	*FRT WING INN BRKT LH	Distorted	50.00 F	*50.00 F
59	1	NA	*FRT WING INN BRKT RH	Distorted	50.00 F	*50.00 F
60	1	NA	*FUEL TANK	Not Necessary	800.00 F	*- F
61	1	NA	*FUSE BOX	Distorted	220.00 F	*220.00 F
62	1	NA	*GRILLE	Missing	170.00 F	*170.00 F
63	1	NA	*INSTRUMENT PNL TRIM	Cracked	600.00 F	*600.00 F
64	1	NA	*L/BLOWER FAN	Distorted	80.00 F	*80.00 F
65	1	NA	*L/BONNET DAMPER	Bent	120.00 F	*120.00 F
66	1	NA	*L/BONNET HINGE	Bent	40.00 F	*40.00 F
67	1	NA	*L/BUMPER BOOT	Not Necessary	130.00 F	*- F
68	1	NA	*L/CARRIER JOINT	Bent	75.00 F	*75.00 F
69	1	NA	*L/DRIVE SHAFT CPL	Not Necessary	480.00 F	*- F
70	1	NA	*L/ENGINE COVER	Distorted	75.00 F	*75.00 F
71	1	NA	*L/F AXLE CARRIER	Not Necessary	75.00 F	*- F
72	1	NA	*L/F BUMPER REINF	Bent	65.00 F	*65.00 F
73	1	NA	*L/F CONTROL ARM BUSH	Torn	80.00 F	*80.00 F
74	1	NA	*L/F DAMPER BUFFER	Torn	25.00 F	*25.00 F
75	1	NA	*L/F FOG LAMP CPL	Missing	110.00 F	*110.00 F
76	1	NA	*L/F OUTER SENSOR	Missing	165.00 F	*165.00 F
77	1	NA	*L/F STABI ROD	Not Necessary	75.00 F	*- F
78	1	NA	*L/F STABILISER BUSH	Not Necessary	30.00 F	*- F
79	1	NA	*L/F STEERING KNUCKLE	Bent	185.00 F	*185.00 F
80	1	NA	*L/F STRUT	Bent	215.00 F	*215.00 F
81	1	NA	*L/F SUSPN BUFFER	Bent	80.00 F	*80.00 F
82	1	NA	*L/F UPP BUMPER BRKT	Distorted	45.00 F	*45.00 F
83	1	NA	*L/F WHEEL BEARING	Dented	75.00 F	*75.00 F
84	1	NA	*L/F WHEEL HUB	Dented	175.00 F	*175.00 F
85	1	NA	*L/F WHEELHOUSE CPL	Repair	195.00 F	*- F
86	1	NA	*L/F WING	Bent	185.00 F	*185.00 F
87	1	NA	*L/F WIPER ARM	Bent	95.00 F	*95.00 F
88	1	NA	*L/F WIPER BLADE	Cut	60.00 F	*60.00 F
89	1	NA	*L/FAN MOTOR	Bent	180.00 F	*180.00 F
90	1	NA	*L/FOG LAMP COVER	Missing	80.00 F	*80.00 F
91	1	NA	*L/HORN	Bent	60.00 F	*60.00 F
92	1	NA	*L/LWR AXLE STEERING	Bent	145.00 F	*145.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
93	1	NA	*L/LWR RADIATOR BRKT	Bent	18.00 F	*18.00 F
94	1	NA	*L/PARK AID SENS CVR	Missing	18.00 F	*18.00 F
95	1	NA	*L/R BUFFER	Bent	80.00 F	*80.00 F
96	1	NA	*L/R CONTROL ARM BUSH	Torn	80.00 F	*80.00 F
97	1	NA	*L/R DAMPER	Not Necessary	25.00 F	*- F
98	1	NA	*L/R EXHAUST RUBBER	Not Necessary	35.00 F	*- F
99	1	NA	*L/R FRONT AXLE BRKT	Not Necessary	75.00 F	*- F
100	1	NA	*L/R SPRING LEG	Not Necessary	185.00 F	*- F
101	1	NA	*L/R STABI ROD	Not Necessary	80.00 F	*- F
102	1	NA	*L/R STRG KNUCKLE	Dented	220.00 F	*220.00 F
103	1	NA	*L/R TOWING STRUT	Missing	145.00 F	*145.00 F
104	1	NA	*L/R TRAILING ARM FRT	Bent	155.00 F	*155.00 F
105	1	NA	*L/R TRAILING ARM RR	Not Necessary	125.00 F	*- F
106	1	NA	*L/R TYRE	Not Necessary	143.00 F	*- F
107	1	NA	*L/R WHEEL	Not Necessary	110.38 F	*- F
108	1	NA	*L/R WHEEL HUB CPL	Dented	300.00 F	*300.00 F
109	1	NA	*L/RADIATOR AIR GUIDE	Distorted	55.00 F	*55.00 F
110	1	NA	*L/SEAT W/OUT SPRING	Bent	35.00 F	*35.00 F
111	1	NA	*L/SILL MOULDING	Broken	195.00 F	*195.00 F
112	1	NA	*L/UPP RADIATOR BRKT	Bent	18.00 F	*18.00 F
113	1	NA	*L/UPP SUPP MOUNTING	Bent	80.00 F	*80.00 F
114	1	NA	*L/WHEELHOUSE SHELL	Missing	65.00 F	*65.00 F
115	1	NA	*L/WING COVER PANEL	Serviceable	45.00 F	*- F
116	1	NA	*L/WING MOULDING	Missing	45.00 F	*45.00 F
117	1	NA	*LEFT HEADLAMP ASSY	Cracked	1,300.00 F	*1,300.00 F
118	1	NA	*LOCK CARRIER STRUT	Bent	45.00 F	*45.00 F
119	1	NA	*LOWER BONNET LOCK	Bent	55.00 F	*55.00 F
120	1	NA	*LOWER ENGINE SUPPORT	Not Necessary	135.00 F	*- F
121	1	NA	*LOWER FUSE BOX COVER	Distorted	120.00 F	*120.00 F
122	1	NA	*LWR RADIATOR HOSE	Distorted	40.00 F	*40.00 F
123	1	NA	**O' RING -SMALL	Necessary	12.00 F	*12.00 F
124	1	NA	**O' RING-BIG	Necessary	15.00 F	*15.00 F
125	1	NA	*OIL FILTER	Necessary	18.00 F	*18.00 F
126	1	NA	*OIL STRAINER	Serviceable	75.00 F	*- F
127	1	NA	*OUTSIDE TEMP SENSOR	Missing	85.00 F	*85.00 F
128	1	NA	*POWER STEERING CPL	Not Necessary	590.00 F	*- F
129	1	NA	*R/BLOWER FAN	Distorted	80.00 F	*80.00 F
130	1	NA	*R/BONNET DAMPER	Bent	120.00 F	*120.00 F
131	1	NA	*R/BONNET HINGE	Bent	40.00 F	*40.00 F
132	1	NA	*R/BUMPER BOOT	Not Necessary	130.00 F	*- F
133	1	NA	*R/CARRIER JOINT	Bent	75.00 F	*75.00 F
134	1	NA	*R/DOOR MIRROR	Cracked	420.00 F	*420.00 F
135	1	NA	*R/DRIVE SHAFT CPL	Not Necessary	540.00 F	*- F
136	1	NA	*R/ENGINE COVER	Distorted	75.00 F	*75.00 F
137	1	NA	*R/F AXLE CARRIER	Not Necessary	75.00 F	*- F
138	1	NA	*R/F CONTROL ARM BUSH	Torn	80.00 F	*80.00 F
139	1	NA	*R/F DAMPER BUFFER	Torn	25.00 F	*25.00 F
140	1	NA	*R/F FOG LAMP CPL	Missing	110.00 F	*110.00 F
141	1	NA	*R/F OUTER SENSOR	Missing	165.00 F	*165.00 F
142	1	NA	*R/F STABI ROD	Not Necessary	75.00 F	*- F
143	1	NA	*R/F STABILISER BUSH	Not Necessary	30.00 F	*- F
144	1	NA	*R/F STEERING KNUCKLE	Bent	185.00 F	*185.00 F
145	1	NA	*R/F STRUT	Bent	215.00 F	*215.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
146	1	NA	*R/F SUSPN BUFFER	Bent	80.00 F	*80.00 F
147	1	NA	*R/F UPP BUMPER BRKT	Distorted	45.00 F	*45.00 F
148	1	NA	*R/F WHEEL BEARING	Dented	75.00 F	*75.00 F
149	1	NA	*R/F WHEEL HUB	Dented	175.00 F	*175.00 F
150	1	NA	*R/F WHEELHOUSE CPL	Bent	195.00 F	*195.00 F
151	1	NA	*R/F WING	Bent	185.00 F	*185.00 F
152	1	NA	*R/F WIPER ARM	Cracked	95.00 F	*95.00 F
153	1	NA	*R/F WIPER BLADE	Missing	60.00 F	*60.00 F
154	1	NA	*R/FAN MOTOR	Bent	180.00 F	*180.00 F
155	1	NA	*R/FOG LAMP COVER	Missing	80.00 F	*80.00 F
156	1	NA	*R/HORN	Bent	60.00 F	*60.00 F
157	1	NA	*R/INN SIDE MEMBER	Bent	590.00 F	*590.00 F
158	1	NA	*R/LWR AXLE STEERING	Bent	145.00 F	*145.00 F
159	1	NA	*R/LWR RADIATOR BRKT	Bent	18.00 F	*18.00 F
160	1	NA	*R/PARK AID SENS CVR	Missing	18.00 F	*18.00 F
161	1	NA	*R/R BUFFER	Bent	80.00 F	*80.00 F
162	1	NA	*R/R CONTROL ARM BUSH	Torn	80.00 F	*80.00 F
163	1	NA	*R/R DAMPER	Not Necessary	25.00 F	*- F
164	1	NA	*R/R EXHAUST RUBBER	Not Necessary	35.00 F	*- F
165	1	NA	*R/R FRONT AXLE BRKT	Not Necessary	75.00 F	*- F
166	1	NA	*R/R SPRING LEG	Not Necessary	185.00 F	*- F
167	1	NA	*R/R STABI ROD	Not Necessary	80.00 F	*- F
168	1	NA	*R/R STRG KNUCKLE	Dented	220.00 F	*220.00 F
169	1	NA	*R/R TRAILING ARM FRT	Bent	155.00 F	*155.00 F
170	1	NA	*R/R TRAILING ARM RR	Not Necessary	125.00 F	*- F
171	1	NA	*R/R TYRE	Not Necessary	143.00 F	*- F
172	1	NA	*R/R WHEEL	Not Necessary	110.38 F	*- F
173	1	NA	*R/R WHEEL HUB CPL	Dented	300.00 F	*300.00 F
174	1	NA	*R/RADIATOR AIR GUIDE	Distorted	55.00 F	*55.00 F
175	1	NA	*R/SEAT W/OUT SPRING	Bent	35.00 F	*35.00 F
176	1	NA	*R/SILL MOULDING	Broken	195.00 F	*195.00 F
177	1	NA	*R/UPP RADIATOR BRKT	Bent	18.00 F	*18.00 F
178	1	NA	*R/UPP SUPP MOUNTING	Bent	80.00 F	*80.00 F
179	1	NA	*R/WHEELHOUSE SHELL	Missing	65.00 F	*65.00 F
180	1	NA	*R/WING COVER PANEL	Serviceable	45.00 F	*- F
181	1	NA	*R/WING MOULDING	Missing	45.00 F	*45.00 F
182	1	NA	*RADIATOR	Bent	400.00 F	*400.00 F
183	1	NA	*RADIATOR SHROUD	Distorted	125.00 F	*125.00 F
184	1	NA	*REAR BUMPER	Deformed	260.00 F	*260.00 F
185	1	NA	*REAR EXHAUST RUBBER	Not Necessary	35.00 F	*- F
186	1	NA	*REAR HEAT SHIELD	Not Necessary	80.00 F	*- F
187	1	NA	*REAR SILENCER	Dented	230.00 F	*230.00 F
188	1	NA	*REAR TOWING STRUT	Not Necessary	145.00 F	*- F
189	1	NA	*RIGHT FRONT DOOR	Not Necessary	0.00 F	*- F
190	1	NA	*RIGHT HEADLAMP ASSY	Cracked	1,300.00 F	*1,300.00 F
191	1	NA	*RR CTR ENGINE MNTG	Torn	135.00 F	*135.00 F
192	1	NA	*RR FLOOR UNDERCOVER	Distorted	90.00 F	*90.00 F
193	1	NA	*SKIRT CHROME MLD LH	Cut	95.00 F	*95.00 F
194	1	NA	*SKIRT CHROME MLD RH	Cut	95.00 F	*95.00 F
195	1	NA	*SPECIALIST AIR CON GAS	Necessary	50.00 FS	*50.00 FS
196	1	NA	*SPECIALIST ANTI FREEZE	Necessary	20.00 FS	*20.00 FS
197	1	NA	*SPECIALIST AUDATEX FEES		42.00 FS	*42.00 FS
198	1	NA	*SPECIALIST BATTERY	Not Necessary	180.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
199	1	NA	*SPECIALIST BRAKE OIL @2LX\$10	Necessary	20.00 FS	*20.00 FS
200	1	NA	*SPECIALIST ENGINE OIL @4.5LX\$20	Necessary	90.00 FS	*90.00 FS
201	1	NA	*SPECIALIST ERP BRACKET	Necessary	26.00 FS	*26.00 FS
202	1	NA	*SPECIALIST FRT NUMBER PLATE	Necessary	40.00 FS	*40.00 FS
203	1	NA	*SPECIALIST FRT RIM LH	Not Necessary	520.00 FS	*- FS
204	1	NA	*SPECIALIST FRT RIM RH	Cut	520.00 FS	*520.00 FS
205	1	NA	*SPECIALIST FRT TYRE LH	Cut	220.00 FS	*220.00 FS
206	1	NA	*SPECIALIST FRT TYRE RH	Cut	220.00 FS	*220.00 FS
207	1	NA	*SPECIALIST FRT WS DAMP SEAL	Necessary	20.00 FS	*20.00 FS
208	1	NA	*SPECIALIST FRT WS SEALANT	Necessary	40.00 FS	*40.00 FS
209	1	NA	*SPECIALIST FRT WS SOLAR FILM	Not Necessary	220.00 FS	*- FS
210	1	NA	*SPECIALIST OIL SUMP SEALANT	Necessary	40.00 FS	*40.00 FS
211	1	NA	*SPECIALIST PRIVATE HIRE STICKER	Necessary	25.00 FS	*25.00 FS
212	1	NA	*SPECIALIST REAR RIM LH	Not Necessary	520.00 FS	*- FS
213	1	NA	*SPECIALIST REAR RIM RH	Not Necessary	520.00 FS	*- FS
214	1	NA	*SPECIALIST REAR TYRE LH	Not Necessary	220.00 FS	*- FS
215	1	NA	*SPECIALIST REAR TYRE RH	Cut	220.00 FS	*220.00 FS
216	1	NA	*SPECIALIST WHEEL ALIGNMENT	Necessary	80.00 FS	*80.00 FS
217	1	NA	*SUMP	Dented	115.00 F	*115.00 F
218	1	NA	*SUNDRY PARTS	Necessary	100.00 FS	*100.00 FS
219	1	NA	*UPPER ENGINE BRACKET	Torn	145.00 F	*145.00 F
220	1	NA	*UPPER FUSE BOX COVER	Serviceable	75.00 F	*- F
221	1	NA	*UPPER RADIATOR HOSE	Distorted	35.00 F	*35.00 F
222	1	NA	*V-BELT	Not Necessary	120.00 F	*- F
223	1	NA	*WASHER CONTAINER	Distorted	95.00 F	*95.00 F
224	1	NA	*WATER PUMP PULLEY	Not Necessary	125.00 F	*- F
225	1	NA	*WINDSCREEN	Cracked	420.00 F	*420.00 F
226	1	NA	*WINDSCREEN BOND KIT	Necessary	38.18 F	*38.18 F
227	1	NA	*WING SHIELD BRKT LH	Distorted	6.50 F	*6.50 F
228	1	NA	*WING SHIELD BRKT RH	Distorted	6.50 F	*6.50 F
229	1	NA	*WIPER LINKAGE CPL	Serviceable	215.00 F	*- F
230	1	NA	*WIPER SIDE GAR LH	Missing	30.00 F	*30.00 F
231	1	NA	*WIPER SIDE GAR RH	Missing	30.00 F	*30.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	48,147.56	31,982.90
+ Margin on L,N Items 5.00/5.00% (\$\$)	2,209.73	1,510.50
Total Parts (\$\$)	50,357.29	33,493.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	1,196.00	1,196.00
2	Total Paint Materials	New	617.60	617.60
3	Total Panel/Mechanical Labour	New	2,796.80	2,346.00
Gross Labour Cost (\$\$)			4,610.40	4,159.60

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

