

REPAIR ESTIMATE*

VEHICLE NO : SHC 3347U

DATE 6/1/2018 12:18

MAKE :

MODEL : HYUNDAI SONATA

LKK/Kawin

L/Sun

Like

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>Dented</i>			\$ 538.80 ✓
	Front Bumper Bracket (LH) <i>2nd</i>			\$ 20.10 X
	Headlamp (LH) ?			\$ 797.90 ?
	Front Fender (LH) <i>Dented</i>			\$ 593.00 ✓
	Front Fender Shield (LH) <i>dymed</i>			\$ 86.00 ✓
	SUB TOTAL			\$ 2,035.80
	LESS 20%			\$ 407.16
	DISCOUNTED TOTAL			\$ 1,628.64
	Labour Charge			
	Panel Beating			\$ 560.00 400/r
	Spray Painting Charge			\$ 400.00 360/r
	Wiring Charge			\$ 50.00 20/r
	Tuff Kote			\$ 50.00 30/r
	TOTAL LABOUR			\$ 1,060.00
	ESTIMATE TOTAL			\$ 2,688.64
08/01/2018 @ 1500m Wia Antuan 2/22m 1/ryu 2 dpp LKK Auto 8 Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • As prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				