



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
Ms TOH POH LIAN Blk 729 Tampines St 71 #09-43 Singapore 520729 Contact No Mobile: 96989867	Cust No/Name	/Ms Toh Poh Lian
	Reg No/Reg Date	SLQ432E / 27/06/2017
	Date In/Mileage	08/01/2018/ 0
	Chassis No	JMYSRCY1AGU006871
	Engine No	4A92CP5274
	Make/Model	MIT/16MY LANCER EX 1.6 (F52)
	Colour/Trim	U02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No					
CSM00001	Cash	08/01/2018/ 20:08	DS	218 / MarsLer	50264					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount		
S	MIPNT88088	TO CHECK LIGHTING & WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS								60 80.00
S	MIPNT88088	TO REMOVE AND RE-INSTALL REAR CAPERTING & TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS								300 600.00
S	MIPNT88088	TO SUPPLY AND REPLACE REAR REVERSE SENSOR								✓ 280.00
S	MIPNT88088	TO SUPPLY AND REPLACE REAR NUMBER PLATE WITH FRAME								✓ 50.00
S	MIPNT88088	TO REPLACE REAR BUMPER, REINFORCEMENT, ETC -REPAIR REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS								600 2400.00
S	MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS								420 1680.00
P	JJ6410B832	FACE, RR BUMPER	?			1.00	852.00	10.00	766.80	
M	JJ6410A436XA-X42	COVER, REAR BUMPER	x NN			1.00	37.00	10.00	33.30	
P	JJMU488006	CLIP, RR BUMPER	=			5.00	2.00	10.00	9.00	
P	JJMR200300	CLIP, BUMPER	=			5.00	2.00	10.00	9.00	
M	JJ6410C543	LH BRKT, R/BMPR FACE	=			1.00	16.00	10.00	14.40	
M	JJ6410C544	RH BRKT, R/BMPR FACE	=			1.00	16.00	10.00	14.40	
M	JJ6410B929	REINFORCEMENT, RR BUM	?			1.00	220.00	10.00	198.00	
M	JJ6410B028	UPR REINFORCEMENT, RR	?			1.00	85.00	10.00	76.50	
Z	NOTES									
ACCIDENT ON 08/01/2018 ALONG CHANGI GENERAL HOSPITAL B2 CARPARK										
OWNER CLAIMING THIRD PARTY										
REQUIRED REPLACEMENT CAR										
TP : SHA3401G TP INS : India										
3 Days.										

Confirm & accepted by	before paint photos.	Parts	1,121.40
		Labour	0.00
		Standard Menu	0.00
		Specialist Job	5,090.00
		Others (Lub, etc)	0.00
		Sundry	0.00
		Total (w/o GST)	6,211.40

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.