## COMFORTDELGRO ENGINEERING PTE LTD **REPAIR ESTIMATE\***

REPAIR ESTIMATE*  VEHICLE NO: SHC 1614L		DATE 8/4/2018 14:55				MX	
MAKE MODEL	: : HYUNDAI SONATA	1	$\mathcal{I}\mathcal{N}$	NIC			
Qty	Parts Description/ Labour	Туре	U	nit Price	A	Amount	
	Rear Bumper a cotonal				\$	578.40	~
	Rear Bumper Reinforcement SVC				\$	483.30	×
	Rear Bumper Clip				\$	22.00	-
	Rear Bumper Sponge &				\$	137.40	X
i	Rear Bumper Under Cover 🗫 .				\$	185.80	X
	Rear Bumper Protector (LH/RH)		\$	38.00	\$	76.00	×
					<u> </u>		
	SUB TOTAL				\$	1,482.90	
	LESS 20%				\$	296.58	
	DISCOUNTED TOTAL				\$	1,186.32	
	Rear Bumper Reverse Sensor				\$	135.70	Nett L
	Rear Bumper Advertisement Logo				\$		Nett -
	Rear Fender Advertisement Logo (LH/RH)		\$	100.00	\$	200.00	
			,				
					\$	385.70	
					ļ		
	Labour Charge		Ì		_	250.00	1950
	Panel Beating				\$	350.00 200.00	
	Spray Painting Charge				\$	50.00	180
	Wiring Charge Remove/Refix Reverse Sensor				\$	120.00	
	Remove/Renx Reverse Sensor				"	1,200.00	401
	TOTAL LABOUR				\$	720.00	
	ESTIMATE TOTAL				\$	2,292.02	
	2/5mm 2 days.						
	LIGA ALA						6
	, le				Ì		
	2 2 1		2				2
	= 14m = 24/1.				Ì		
	JEC AND						
	$\vee$						
	//						
				<u> </u>			_
	This is an initial estimate based on a visual inspection of the						
	be prepared after the vehicle is surveyed by a motor Surve	yor appoi	ted by the	he insurance co	mpar	ıy	_