



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2015 HONDA JAZZ 1.5 (SCX366H)

Date of Loss

January 8, 2018

Time of Loss

1.20

Loss Description

SCX366H (INSD) C/W SLQ4860B (TP)

Comment

Workshop Details

Total Rebate Amount

40327

Nett Loss Amount

\$20,173.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

07/16/2018



Days of work completion *

187



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SCX366H

Purchase Date

mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

06/19/2015



Mileage

25389

Age of Vehicle

2

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2015

ASSESSMENT INFO...

2015

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

GABRIEL, CHONG JUN WEI

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... HONDA

ASSESSMENT INFO... HONDA

CATEGORY Model

POLICY INFORMAT... JAZZ 1.5

ASSESSMENT INFO... JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2W

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JHMGK5850FX203193

CATEGORY Date of Birth

FNOL INFORMATI... April 14, 1995

POST SURVEY INF... mm/dd/yyyy



CATEGORY Age

FNOL INFORMATI... 23

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... JHMGK5850FX203193

CATEGORY Engine No

POLICY INFORMAT... L15B31000587

ASSESSMENT INFO... L15B31000587

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1498

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 60500

FNOL INFORMATI... 2

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF... ▼

CATEGORY License Issue Date

FNOL INFORMATI... January 1, 2016

POST SURVEY INF... mm/dd/yyyy 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... mm/dd/yyyy 

CATEGORY Address

FNOL INFORMATI... 49 JALAN HAJI SALAM, 468834,
Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S9512628F

POST SURVEY INF...

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

01/11/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

800

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

185/55R16

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

185/55R16

Front left side

DUNLOP6mm

Front right side

DUNLOP6mm

Rear left side

DUNLOP6mm

Rear right side

DUNLOP6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes ☐ No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			PASSENGER AIR BAG			Damaged	1640.3		20		1312.24	Review
		2	1			STEERING AIR BAG			Damaged	2236.8		20		1789.44	Review
		3	1			STEERING AIR BAG COIL SPRING			Damaged	268.9		20		215.12	Review
		4	1			STEERING AIR BAG SENSOR			Damaged	223.8		20		179.04	Review
		5	1			FRONT N/S CHASSIS A/BAG SENSOR			Damaged	223.8		20		179.04	Review
		6	1			AIR BAG CONTROL UNIT			Damaged	806.7		20		645.36	Review
		7	2			FRONT SAFETY BELT			Damaged	445.9		20		713.44	Review
		8	1			GEAR LEVEL CENTRE CONSOLE			Cracked	205.5		20		164.4	Review
		9	1			FRONT INSTRUMENT PANEL			Cracked	718.5		20		574.8	Review
		10	1			N/S DASHBOARD LOWER COVER			Serviceable	0	0	0	0	0	Deny
		11	1			FRONT WINDSCREEN GLASS			Cracked	1469.2		20		1175.36	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART:)
		12	1			FRONT W/S GLASS MOULDING			Necessary	145		20		116	Review
		13	1			FRONT WIPER GARNISH			Cracked	173.2		20		138.56	Review
		14	1			BONNET			Buckled	527		20		421.6	Review
		15	1			BONNET INSULATOR			Damaged	86		20		68.8	Review
		16	1			O/S BONNET GARNISH			Cut	40.1		20		32.08	Review
		17	1			BONNET INNER LOCK			Bent	87.7		20		70.16	Review
		18	2			BONNET HINGE			Bent	24.9		20		39.84	Review
		19	2			FRONT FENDER			Buckled	406.6		20		650.56	Review
		20	1			FRONT N/S FENDER SIDE SUPPORT			Bent	85.2		20		68.16	Review
		21	1			FRONT N/S FENDER INNER GARNISH			Broken	36.3		20		29.04	Review
		22	1			FRT N/S FENDER INNER PANEL - IN			Damaged	92.5		20		74	Review
		23	1			FRT N/S FENDER INNER PANEL - OUT			Damaged	70		20		56	Review
		24	1			FRT N/S INNER PANEL SUPPORT (IN			Damaged	30.2		20		24.16	Review
		25	1			FRT N/S INNER PANEL SUPPORT (O)			Damaged	45.2		20		36.16	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		26	1			FRONT N/S CHASSIS MEMBER			Bent	466.7		20		373.36	Review
		27	1			N/S CHASSIS MEMBER OUTER PANEL			Bent	105.5		20		84.4	Review
		28	1			FRONT N/S FENDER INNER SHIELD			Deformed	76.8		20		61.44	Review
		29	1			ENGINE UNDER COVER COMPLETE			Deformed	180.6		20		144.48	Review
		30	1			FRONT N/S QUATER GLASS			Damaged	208.6		20		166.88	Review
		31	1			FRT N/S QUATER GLASS MOULDING			Necessary	55.5		20		44.4	Review
		32	1			FRONT N/S SIDE SKIRT			Deformed	363.6		20		290.88	Review
		33	1			N/S ROCKER PANEL			Buckled	232.3		20		185.84	Review
		34	1			FRONT N/S DOOR			Repair	0	0	0	0	0	Deny
		35	2			FRONT N/S DOOR HINGE			Serviceable	0	0	0	0	0	Deny
		36	1			FRONT N/S DOOR FRAME TAPE			Serviceable	0	0	0	0	0	Deny
		37	1			REAR N/S DOOR			Buckled	703.4		20		562.72	Review
		38	1			REAR N/S DOOR TAPE			Necessary	15.4		20		12.32	Review

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PART)
		39	1			REAR N/S DOOR GLASS REGULATOR GEAR			Broken	151.8		20		121.44	Review
		40	2			HEADLAMP			Broken	1118.6		20		1789.76	Review
		41	1			N/S HEADLAMP BRACKET			Bent	23.6		20		18.88	Review
		42	1			N/S HEADLAMP ADJUSTER SENSOR			Damaged	279.6		20		223.68	Review
		43	1			FRONT SUPPORT PANEL			Bent	376.3		20		301.04	Review
		44	1			RADIATOR - AUTO			Cut	1187.4		20		949.92	Review
		45	1			RADIATOR FAN COWLING			Serviceable	0	0	0	0	0	Deny
		46	1			RADIATOR FAN MOTOR			Serviceable	0	0	0	0	0	Deny
		47	1			RADIATOR FAN BLADE			Serviceable	0	0	0	0	0	Deny
		48	1			RADIATOR TOP HOSE			Serviceable	0	0	0	0	0	Deny
		49	1			RADIATOR LOWER HOSE			Serviceable	0	0	0	0	0	Deny
		50	1			AIR CON CONDENSER			Cut	704.4		20		563.52	Review
		51	1			AIR CON CONDENSER FAN COWLING			Serviceable	0	0	0	0	0	Deny
		52	1			AIR CON CONDENSER FAN MOTOR			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		53	1			AIR CON CONDENSER FAN BLADE			Serviceable	0	0	0	0	0	Deny
		54	1			AIR CON SUCTION HOSE			Serviceable	0	0	0	0	0	Deny
		55	1			AIR CON DISCHARGE HOSE			Bent	141.9		20		113.52	Review
		56	1			AIR CON LIQUID PIPE			Serviceable	0	0	0	0	0	Deny
		57	1			FRONT BUMPER FASCIA			Damaged	494.7		20		395.76	Review
		58	1			FRONT BUMPER LOWER LIP			Deformed	56.3		20		45.04	Review
		59	1			FRONT N/S BUMPER SIDE RETAINER			Damaged	10.4		20		8.32	Review
		60	1			FRONT BUMPER REINFORCEMENT			Bent	219.4		20		175.52	Review
		61	1			FRONT BUMPER LOWER GRILLE			Deformed	27.5		20		22	Review
		62	1			FRT BUMPER NO. PLATE GARNISH			Deformed	50.9		20		40.72	Review
		63	1			FRONT BUMPER N/S SIDE GUIDE			Deformed	10.8		20		8.64	Review
		64	1			FRONT BUMPER N/S FOG LAMP			Dented	261.9		20		209.52	Review
		65	1			FRONT BUMPER N/S DAY LAMP			Damaged	180.6		20		144.48	Review
		66	1			FRONT BUMPER N/S FOGLAMP COVER			Missing	23.3		20		18.64	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
		67	1			RADIATOR GRILLE ASSY			Cracked	288.9		20		231.12	Review
		68	6			RADIATOR GRILLE CLIP			Necessary	3.2		20		15.36	Review
		69	1			RADIATOR GRILLE TOP COVER			Deformed	11.8		20		9.44	Review
		70	1			LH ENGINE MOUNTING			Damaged	108.2		20		86.56	Review
		71	1			LH ENGINE MOUNTING BRACKET			Bent	34.8		20		27.84	Review
		72	1			RH ENGINE MOUNTING			Damaged	124		20		99.2	Review
		73	1			REAR MOUNTING			Bent	108.2		20		86.56	Review
		74	1			FRONT N/S SHOCK ABSORBER			Bent	292.6		20		234.08	Review
		75	1			FRONT N/S LOWER ARM			Bent	151.8		20		121.44	Review
		76	1			FRONT N/S KNUCKLE ARM			Bent	187.4		20		149.92	Review
		77	1			FRONT N/S KNUCKLE BEARING HUP			Bent	138.3		20		110.64	Review
		78	1			FRONT N/S WHEEL BEARING			Bent	79.5		20		63.6	Review
		79	1			FRONT STABILIZA BAR			Bent	169.9		20		135.92	Review
		80	1			FRONT N/S STABILIZA BAR LINK			Bent	43.1		20		34.48	Review

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		81	1			FRONT N/S DRIVE SHAFY			Bent	961.6		20		769.28	Review
		82	1			STEERING RACK N PINION			Bent	1148.7		20		918.96	Review
		83	1			FRONT ENGINE CROSS MEMBER			Bent	740		20		592	Review
		84	1			WIRE HARNESSL			Serviceable	0	0	0	0	0	Deny
		85	1			FRONT N/S SPORT RIM			Cut	819.6		20		655.68	Review

Labour

Add

Approve

Deny

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
		1		TO TOWING	60	0	0	Reviewing		1
		2		TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM	80	0	0	Reviewing		1
		3		TO REMOVE & RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	100	0	0	Reviewing		1
		4		TO REMOVE ROOF LINING, FRONT AND REAR SEATS, TRIM BOARD AND CARPET	80	0	0	Reviewing		1
		5		TO REMOVE AIR CON CONDENSER, PIPES AND DRIER, VACUUM AND TO RECHARGE GAS	100	0	0	Reviewing		1
		6		TO REMOVE AND RENEW FRONT INSTRUMENT PANEL ASSY, TO REWIRING AND TRANSFER INSTRUMENT FITTINGS	200	0	0	Reviewing		1
		7		TO REMOVE AND LIFT UP ENGINE ASSY	350	0	0	Reviewing		1

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
 	8		TO DISMANTLE AND LOWER FRONT UNDERCARRIAGE	250	0	0	Reviewing		1
 	9		TO CHECK AND ADJUST WHEEL ALIGNMENT	60	0	0	Reviewing		1
 	10		TO CHECK CHASSIS ALIGNMENT	250	0	0	Reviewing		1
 	11		TO PUTTY AND SPRAY REPLACED PARTS	1500	0	0	Reviewing		1
 	12		TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS	2000	0	0	Reviewing		1
 	13		TO REMOVE FRONT WEEKEND NO. PLATE RESEAL AND SEND FOR INSPECTION	100	0	0	Reviewing		1
 	14		TO REMOVE, RENEW FRONT SEAT BELT, STEERING AIR BAG, PASSENGER AIR BAG, AIR BAG SENSOR, AIR BAG CONTROL UNIT, AIR BAG SENSOR WIRE, DIAGNOSTIC & RESET AIR BAG SYSTEM	250	0	0	Reviewing		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF
REPAIR : 20
DAYS

Reviewing



2

FRONT W/S
GLASS
SEALANT

Reviewing

60

NECESSARY



3

ERP IU
BRACKET

Reviewing

25

NECESSARY



4

FRONT N/S
QUATER
GLASS
SEALANT

Reviewing

30

NECESSARY



5

RADIATOR
COOLANT

Reviewing

30

NECESSARY



6

AUTO GEAR
BOX OIL -
2PCS

Reviewing

40

NECESSARY



	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		7	FRONT WEEKEND PLATE WITH BOX	Reviewing	50	NECESSARY	
		8	FRONT N/S TYRE	Reviewing	150	CUT	
		9	N/S LOWER RESONATOR BOX (DISC 20%)	Reviewing	70.16	CRACKED (SUPPLEMENTARY)	
		10	N/S STABILIZA BAR BRACKET (DISC 20%)	Reviewing	7.6	BENT (SUPPLEMENTARY)	
		11	N/S STABILIZA BAR BRACKET BUSH(DISC 20%)	Reviewing	9.28	BENT (SUPPLEMENTARY)	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$25,244.60			Claim Amount	\$25,244.60			

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$5,380.00	\$5,380.00
Miscellaneous	\$472.04	\$472.04
Excess	-\$800.00	-\$800.00

Submit for Review

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	FINAL LUMP SUM	Reviewing	20000	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount

\$19,200.00

Claim Amount

\$19,200.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$20,000.00	\$20,000.00
Excess	-\$800.00	-\$800.00

Submit for Review