

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118000588/KQBE2

Date: 09/05/2018

REFERENCE

Insured/Claimant:	LEE BOON PENG	Policy No:	DMPCSN1720931700
Date of Loss:	08/01/2018	Nature of Claim:	OD
		Claim No:	SNM18D00138C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG2552G		
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (180BHP) (A)	Engine No:	CNC173177
Reg. Date:	28/09/2016 (Man. Year: 2016)	Chassis No:	WAUZZZ8R7HA020141
Colour:	Metallic Grey	Odometer:	15374 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$159,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,433.00	3,579.75	1,853.25	34.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,029.25	850.25	179.00	17.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,462.25	4,430.00	2,032.25	31.45
- Excess (\$\$)	0.00	250.00	-250.00	
(\$\$)	6,462.25	4,180.00	2,282.25	35.32
+ GST 7.00/7.00% (\$\$)	452.36	292.60	159.76	35.32
Nett Amount (\$\$)	6,914.61	4,472.60	2,442.01	35.32

INSPECTION

Date of Assignment:	10/01/2018 Present Location:	K Kim Hin Auto Pte Ltd (HQ)
Date Inspected:	11/01/2018 Inspected At:	160 Sin Ming Drive #02-20, Sin Ming AutoCity
		Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 May 2018)

Parts: M1-SUV AUDI Q5 2.0 TFSI Quattro (180BHP) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLG2552G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*CONDENSER (WCP)	Serviceable	400.00 F	*- F
2	1	NA	*FRONT BUMPER (WCP)	Buckled	800.00 F	*800.00 F
3	1	NA	*FRONT BUMPER SPOILER (WCP)	Repair	210.00 F	*- F
4	1	NA	*FRT BUMPER FILLING (WCP)	Cracked	60.00 F	*60.00 F
5	1	NA	*FRT BUMPER SUPPORT (WCP)	Bent	280.00 F	*280.00 F
6	1	NA	*FRT LWR BUMPER COVER (WCP)	Missing	65.00 F	*65.00 F
7	1	NA	*GRILLE (WCP)	Cracked	640.00 F	*640.00 F
8	1	NA	*H/LAMP WASHER VALVE (WCP)	Serviceable	120.00 F	*- F
9	1	NA	*L/F AIR GUIDE GRILLE (WCP)	Cracked	180.00 F	*180.00 F
10	1	NA	*L/F FOG LAMP CPL (WCP)	Serviceable	100.00 F	*- F
11	1	NA	*L/F INNER SENSOR (WCP)	Dented	115.00 F	*115.00 F
12	1	NA	*L/F OUT BUMPER BRKT (WCP)	Serviceable	20.00 F	*- F
13	1	NA	*L/F OUTER SENSOR (WCP)	Serviceable	115.00 F	*- F
14	1	NA	*L/HEADLAMP MOUNTING (WCP)	Cracked	70.00 F	*70.00 F
15	1	NA	*L/HEADLAMP MOUNTING (WCP)	Cracked	55.00 F	*55.00 F
16	1	NA	*L/RADIATOR AIR GUIDE (WCP)	Serviceable	45.00 F	*- F
17	1	NA	*LEFT HEADLAMP ASSY (WCP)	MTG Cracked	990.00 F	*990.00 F
18	1	NA	*NOZZLE HOSE (WCP)	Serviceable	115.00 F	*- F
19	1	NA	*PARKING SENSOR WIRE (WCP)	Serviceable	185.00 F	*- F
20	1	NA	*R/F INNER SENSOR (WCP)	Serviceable	115.00 F	*- F
21	1	NA	*R/F OUT BUMPER BRKT (WCP)	Repair	20.00 F	*- F
22	1	NA	*R/F OUTER SENSOR (WCP)	Serviceable	115.00 F	*- F
23	1	NA	*R/RADIATOR AIR GUIDE (WCP)	Serviceable	45.00 F	*- F
24	1	NA	*SPECIALIST ANTIFREEZE 4 LTR	Not Necessary	48.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1	NA	*SPECIALIST AUDATEX FEE		42.00 FS	*42.00 FS
26	1	NA	*SPECIALIST FRT NUMBER PLATE	Dented	40.00 FS	*20.00 FS
27	1	NA	*SPECIALIST TOP UP AIRCON GAS	Not Necessary	100.00 FS	*- FS
28	1	NA	*SUNDRY PARTS	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	5,190.00	3,417.00
+ Margin on L,N Items 5.00/5.00% (\$\$)	243.00	162.75
Total Parts (\$\$)	5,433.00	3,579.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	368.00	363.40
2	Total Paint Materials	New	123.05	123.45
3	Total Panel/Mechanical Labour	New	538.20	363.40
Gross Labour Cost (S\$)			1,029.25	850.25

Report was unsubmitted during this print-out.

< END OF ESTIMATES >