


FAX Number : 63685592  
Estimator Telephone Number : 66662623  
Accident Reporting Number : 66662672

## SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1339C  
Ref. No : BUS/01/18/1002  
Reg. Date : 01/01/1900  
Vehicle Type : BUS -12M  
Make : MAN  
Model : MAN  
Name of Driver : Yang Yunie  
Type of Accident : SIDE SWIPE  
Date / Time of Accident : 02/01/2018 06:20:00 PM  
Accident Reported Date / Time : 03/01/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : MSIG  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No :  
Special Instruction to ARC, if any :  
TP: SKF2463Y  
LEFT REAR PORTION DAMAGED  
Prepared Date : 03/01/2018 02:54:24 PM



LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

Sebastian.

9/1/18.

- Lump Sum Repair.

- Photo After Paint.

90036121

Sebastianyang@lkkauto.com.

Chassis No :

Mileage :

0

Work Shop :

Repair Completed Date / Time :

### Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,325.00	0.00
Total Spray Painting Charges	786.00	0.00
Total Material Charges	0.00	0.00
Other Charges	0.00	0.00
<b>TOTAL</b>	<b>2,111.00</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>2,100.00</b>	<b>0.00</b>
No. of Repair Days	3.00	<del>0.00</del> 2 days
Prepared / Adjusted By		
Arc / Surveyor Sing Off Date	09/01/2018 01:16:29 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 09/01/2018 10:56:29 AM

### Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :  
Quotation Date :  
Invoice Amount :

Invoice No :  
Invoice Date :  
Prepared Date :

### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,325.00	<del>0.00</del> 1060
<b>Total Labour</b>	<b>1,325.00</b>	<b>0.00</b>

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	786.00	<del>0.00</del> 600
<b>Total Spray Painting &amp; Panel Beating</b>	<b>786.00</b>	<b>0.00</b>

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		