



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Identification Card

 **WORK PERMIT**
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
KL RESOURCES PTE. LTD.

Sector **MANUFACTURING**

 Name
YIN XIANZHANG
Occupation
HAND PACKER

Work Permit No.
D 73707102

Date of Application
15-07-2016

Date of Issue
11-08-2016

Date of Expiry
24-05-2018

 **L7112729**

Identification Card

VISIT PASS
Immigration Regulation

Name
YIN XIANZHANG

	Date of Birth	Sex	Nationality
	23-07-1983	M	CHINESE
	FIN	Date of Issue	Date of Expiry
	G6654119W	11-08-2016	24-05-2018

MULTIPLE JOURNEY VISA ISSUED


**YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED
OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.**



Driving License



Driving License



Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S66550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MBHH18000641 Vehicle Registration No: YN180T
Name(as shown in NRIC) : YIN XIAN ZHANG NRIC/FIN/Passport No : G6654119W
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore()
Contact (Tel) : _____ Mobile No. : 94297206
Email Address : vfixauto@gmail.com
Date of Accident : 30/12/2017 Time of Accident : 15:10 HRS
Place of Accident : ALONG SUNGEI KADUT AVE
Insurance Company: EQ INSURANCE COMPANY LIMITED

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

AMENDED REPORT TO OWN DAMAGED CLAIM.

Policyholder / Driver's Signature
Date:



Reporting Centre Personnel's Signature
Name: Lee Wan Qi
NRIC/FIN No.: S9245801F
Date: 09/01/2018

parts	
2350	4588
358	150
522	150
1225	450
654.2	281.5
650	155
265.2	285.2
1654.3	250
1885.3	422
526.8	485
1150	122
211	125.3
388	423.3
655	388.6
45	506.3
146.2	452
185	325
352.2	2352
210.5	1630
195	225.2
185	105
3250	185
236	198.3
250	1085
750.3	15339.7
980	
2218	37826.2
320	11347.86
322	26478.34
281.5	
65	
22486.5	

special nett	
220	
250	
1200	
1670	
LABOUR	
4000	
1500	
50	
100	
200	
120	
30	
6000	
TOTAL	
34148.34	

30%

check		
Parts	S/N	Labour
28540	1885	250
1120	1982	250
1985	350	500
285	90	1000
330.4	185	
290.6	188	
376	102	
376.4	36000	
458.2	40782	
185		
332.6		
201.3		
425		
155.2		
1251.3		
422.3		Total
650.3		83153.61
122.3		
422		
210		
506.4		
285		
8558		
6552		
856		
658		
1235		
958		
855		
500		
59102.3		
30% 17730.69		
41371.61		

M/S EQ INSURANCE CO LTD
5 MAXWELL ROAD MND COMPLEX
#17-00 TOWER BLOCK
SINGAPORE 069110
Attention: Motor Claim Department

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATE

DATE : 09/01/2018
ACC DATE : 30/12/2017
REF NO. : VFIX-TP20180048
POLICY NO : DMCHHQ17-000055

31155 \$5000

Not Authorized

22 day.

11/1/18 maybe 2019.1055

To repair to After repair

AMOUNT S\$

RE : VEHICLE NO : YN180T PKC37BN-00469

DESCRIPTION	LIST ITEM :		AMOUNT S\$
1	1 FRONT CABIN		28,540.00 ?
2	1 FRONT WINDSCREEN GLASS	<i>SAO</i>	2,350.00 ✓
3	1 FRONT WINDSCREEN GLASS WEATHERSTRIP	<i>To re</i>	358.00 ✓
4	1 FRONT CABIN LIFTER		1,120.00 ?
5	1 CABIN FRONT CROSS LINK		1,985.00 ?
6	2 CABIN FRONT CROSS LINK BRACKET R+L	<i>1/15 cr</i>	522.00 1,044.00 <i>1/15</i>
7	1 CABIN REAR BRIDGE LINK UPPER	<i>2nd/1st</i>	1,225.00 ✓
8	1 CABIN REAR BRIDGE LINK LOWER	<i>2nd</i>	654.20 ✓
9	2 CABIN REAR BRIDGE LINK LOCK	<i>2nd</i>	325.00 650.00 ✓
10	1 CABIN REAR BRIDGE LINK LOCK SWITCH		285.00 ?
11	2 CABIN REAR BRIDGE LINK STOPPER UPP R+L		165.20 330.40 ?
12	2 CABIN REAR BRIDGE LINK STOPPER LWR R+L		145.30 290.60 ?
13	2 CABIN REAR SHOCK ABSORBER		188.00 376.00 ?
14	1 CABIN LOCK LEVER	<i>2nd</i>	265.20 ✓
15	2 CABIN SHOCK ABSORBER REAR		188.20 376.40 ?
16	1 AIR FILTER HOUSING ASSY	<i>cr</i>	1,654.30 ✓
17	1 POWER STEERING OIL TANK		458.20 ?
18	1 FUSE BOX C/W FUSE / HARNESS WIRE	<i>cr</i>	1,885.30 ✓
19	1 FUSE BOX BRACKET		185.00 ?
20	1 BATTERY TRAY		526.80 ✓
21	1 FRONT MUD GUARD LH	<i>2nd</i>	332.60 ?
22	1 FRONT MUD GUARD BRACKET LH		201.30 ?
23	1 FRONT DASHBOARD	<i>2nd</i>	1,150.00 ✓
24	1 DASHBOARD RE-INFORCEMENT		425.00 ?
25	1 RADIO CONSOLE GARNISH	<i>cr</i>	211.00 ✓

26	1	SPEEDO METER COVER		155.20	7
27	1	SPEEDO METER		1,251.30	7
28	1	CENTER CONSOLE BOX	112	388.00	✓
29	1	WIPER GARNISH	Dis	655.00	✓
30	1	WIPER LINKAGE		422.30	7
31	1	WIPER LINKAGE MOTOR		650.30	7
32	3	WIPER BLADE	N/S Bent	45.00	135.00 12C
33	3	MIRROR ARM	N/S Bent	146.20	438.60 12C
34	1	MIRROR ARM HOLDER LWR	Bent		185.00 ✓
35	1	MIRROR ARM HOLDER UPP	Bent		352.20 ✓
36	1	SQUARE MIRROR	320		210.50 ✓
37	1	SIDE MIRROR LH	320		195.00 ✓
38	1	ROUND MIRROR	320		185.00 ✓
39	1	FRONT BONNET	Dis		3,250.00 ✓
40	1	FRONT BONNET EDGE GARNISH	11		122.30 ?
41	1	FRONT BONNET RUBBER	11		203.10 X
42	2	FRONT BONNET HINGE R+L	Bent	118.00	236.00 ✓
43	2	FRONT BONNET LOCK	107	125.00	250.00 ✓
44	2	FRONT BONNET CATCH	11	45.00	90.00 X
45	1	FRONT BONNET RUBBER	11		255.00 X
46	1	FRONT BONNET GRILLE	Bent		750.30 ✓
47	1	FRONT BONNET GRILLE LOGO	11		445.00 X
48	2	FRONT BONNET PULL HANDLE R+L		211.00	422.00 7
49	1	CORNER PANEL LH	Dis		980.00 ✓
50	2	HEADLAMP R+L	N/S 320	2218.00	4,436.00 12C
51	2	SIDE LAMP R+L	N/S 320	320.00	640.00 12C
52	2	HEADLAMP COVER R+L	N/S 320	322.00	644.00 12C
53	2	FRONT WHEEL MUD GUARD R+L	N/S Dis	281.50	563.00 12C
54	2	FRONT WHEEL MUD FLAG R+L	N/S 11	65.00	130.00 12C
55	2	FRONT DOOR R+L	N/S Bent 015 R	4,588.00	9,176.00 12C
56	2	DOOR STAY R+L		105.00	210.00 ?
57	2	DOOR HINGE UPP R+L	N/S Bent	150.00	300.00 12C
58	2	DOOR HINGE LWR R+L	N/S Bent	150.00	300.00 12C

59	2	DOOR LOCK L	N/S Jm	450.00	900.00	1pc
60	2	DOOR WEATHERSTRIP R+L		256.20	253.20	506.40 ?
61	2	DOOR MUD GUARD R+L	N/S D.J	281.50		563.00 1pc
62	2	DOOR MUD GUARD STEP RUBBER R+L	N/S D.J	155.00		310.00 1pc
63	1	FRONT DOOR GLASS LH	shotted		285.20	✓
64	1	WINDOW GLASS REGULATOR	N/S Bmt		250.00	✓
65	1	WINDOW GLASS REGULATOR MOTOR	N/S Jm		422.00	✓
66	1	DOOR INNER TRIM BOARD	D.J		485.00	✓
67	1	DOOR INNER TOP GARNISH	D.J		122.00	✓
68	1	DOOR FRAME LINING	D.J		125.30	✓
69	1	DOOR OUTER HANDLE			285.00	✓
70	1	STEP BOARD LH	D.J		423.30	✓
71	1	STEP BOARD GARNISH LH	D.J		388.60	✓
72	1	STEP BRACKET LH	Bmt		506.30	✓
73	1	STEP BOARD TOP GARNISH	D.J		452.00	✓
74	1	STEP BOARD LOWER GARNISH	D.J		325.00	✓
75	1	FRONT BUMPER	D.J		2,352.00	✓
76	2	FRONT BUMPER FOG LAMP R+L	N/S ene	652.00	1630	3,260.00 1pc
77	2	FRONT BUMPER SIGNAL LAMP R+L	N/S ene	225.20		450.40 1pc
78	2	FRONT BUMPER FOG LAMP RIM R+L	N/S ene	105.00		210.00 1pc
79	2	FRONT BUMPER BRACKET R+L	N/S Bmt	185.00		370.00 1pc
80	2	FRONT BUMPER END GARNISH R+L	N/S D.J	198.30		396.60 1pc
81	1	TURBO COOLER ASSY			8,558.00	?
82	1	AIR CON CONDENSER ASSY	Bmt/D.J		1,085.00	✓
83	1	RADIATOR ASSY			6,552.00	?
84	1	RADIATOR FAN BLADE			856.00	?
85	1	RADIATOR FAN SHROUD			658.00	?
86	1	ENGINE OIL COOLER			1,235.00	?
87	1	ENGINE ROCKER COVER			958.00	?
88	1	ENGINE GASKET TOP OH			855.00	?
89	2	ENGINE MOUNTING		250.00		500.00 ?
					110,150.50	
LESS 30%					33,045.15	
					\$ 110,039.50	

PARTICULAR	(SPECAIL NETT)	AMOUNT S\$
1 1 FRONT NUMBER PLATE	11	35.00 SN X
2 1 AIR CON BLOWER ASSY		1,885.00 SN ?
3 1 AIR CON EVAPERATOR UNIT ASSY		1,982.00 SN ?
4 1 AIR CON SUCTION HOSE		350.00 SN ?
5 1 RADIATOR COOLANT		90.00 SN ?
6 1 AIR CONDENSER ASSY	Repetd	950.00 SN X
7 1 AIR CONDENSER BRACKET	but	220.00 SN /
8 1 AIR CONDENSER MOTOR	20/yr	250.00 SN /
9 1 AIR CONDENSER FAN BLADE	complete	28.00 SN X
10 1 AIR CONDENSER PIPE		185.00 SN ?
11 1 AIR CONDENSER TUBE		188.00 SN ?
12 1 AIR CON DRIER		102.00 SN ?
13 2 BATTERY N150	11	210.00 - 420.00 SN X
14 1 SIDE GUIDE LH	213	1,200.00 SN
15 1 WASTE BEAN TANK	12	7,500.00 SN X
16 1 HYDROLIC HOOK BEAM c/w CYLINDER	20/rent	25,000/- 36,000.00 SN ?
		\$ 51,385.00

LABOUR & MISCELLANEOUS:

AMOUNT S\$

1	To remove damaged body parts with all necessary components/ attachments apply hot-works where necessary straighten repair, reshape, dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	4000	8,000.00
2	To spray paint replaced/repared body parts inclusive of preparatory works and painting materials	1500	4,000.00
3	To transfer door components with all necessary attachments	50	280.00
4	To remove,replace radiator assy with all necessary components	?	250.00
5	To remove replace air con cooling unit and recharge gas	100	250.00
6	To remove ,replace dashboard with all necessary components	200	250.00
7	To remove replace fuse box wire harnesss with all necessary components	?	250.00
8	To install front windscreen glass and water test	120	180.00
9	To conduct headlamp alignment	30	30.00
10	Towing charge	3.1/ ?	500.00
		\$	13,990.00

GRAND TOTAL : \$ 175,414.50

SINGAPORE DOLLARS : ONE HUNDRED SEVENTY FIVE THOUSAND
FOUR HUNDRED FOURTEEN & CENTS FIFTY ONLY

Vfix Auto Service Pte Ltd





Your Ref : DM18HO00030-EC

Date: 27th February 2018

Our Ref : CS/EQI18000618/Utd3s2

M/s EQ Insurance Company Ltd

5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE YN 180T
ACCIDENT ON 30/12/2017**

Instruction was received to inspect the vehicle Reg. No. YN 180T. The inspection was conducted on 11/01/2018 at the premises of M/s Vfix Auto Service Pte Ltd, 60 Kaki Bukit Ave 6 ARC @ KB Singapore 417892.

The following vehicle information was recorded:

Registration Number	: YN 180T
Make/Model	: Nissan PKC37BNHNP (M)
Year of Registration	: 2009
Body Colour	: White
Chassis Number	: PKC37BN00469
Engine Capacity	: 7684 cc
Speedometer Reading	: Battery Flat

The vehicle sustained damages at the front n/s portion and rooftop. The body structure affected due to collision. The Estimated repair cost of such vehicle is S\$34,148.34 (Sin Dollars: Thirty-Four Thousand One Hundred Forty-Eight and Thirty-Four Cents only.) (Exclude check items S\$83,153.61Nett) (Details see photographs enclosed)



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "**Total Loss**".

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 30,000.00

Less: LTA Reimbursement Value (RV)

(S\$ 674.00)

(S\$ 29,326.00)

Less: Excess

S\$ 5,000.00)

Nett Liability

S\$ 24,326.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 34,148.34

(Exclude check items S\$83,153.61 Nett)

Less: Excess

(S\$ 5,000.00)

Nett Liability

S\$ 29,148.34

(a) - (b) =

(S\$ 4,822.34)

The amount of estimated saving of S\$4,822.34 if the vehicle to be written off as "**Total Loss**" instead of to be repair.

Vehicle Inspected By:

CHUAH KANG SENG
Licensed Appraiser

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MII(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.