

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5940T - AXA**AAD1801-085***Not Authorised**Recovery B4 point*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD5940T - CANDY

VF1ABL15AUC281461

RENAULT

LATITUDE

07.01.2018

AXA**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bz</i> 1,108.46 —
2	1	BUMPER LOWER REAR	\$	<i>Nil/Nil</i> 768.84 —
3	1	BUMPER BRACKET CTR REAR	\$	<i>Nil</i> 113.47 —
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>cm</i> 44.99 —
9	1	BUMPER REFLECTOR LH	\$	<i>Bz</i> 43.61 —
10	1	BUMPER BEAM REAR	\$	<i>Bz</i> 777.52 —
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>Bz</i> 225.95 —
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1	BOOT REAR	\$	<i>R</i> 2,872.68 X
14	1	BOOT FINISHER	\$	<i>Sn</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05 X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35 X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35 X
18	1	BOOT BADGE 'RENAULT'	\$	<i>R</i> 225.36 —
19	1	BOOT BADGE	\$	<i>R</i> 225.36 —
20	1	BOOT STRUT LH	\$	<i>Sn</i> 276.08 X
21	1	BOOT STRUT RH	\$	<i>Sn</i> 276.08 X
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84 X
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84 X
24	1	BOOT INNER TRIM	\$	<i>Sn</i> 586.45 X
25	1	BOOT SWITCH	\$	<i>Sn</i> 168.13 X
26	1	BOOT LOCK	\$	<i>R</i> 202.67 X
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40 X
28	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52 X
29	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81 X
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45 X
31	1	FENDER PANEL REAR LH	\$	<i>Bz</i> 3,299.13 —
32	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47 X
33	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i> 671.45 X
34	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-085**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5940T - AXA

35	1	WHEELARCH REAR RH	\$	Sn	543.47	X
36	1	TAILLAMP RH	\$	Sn	552.55	X
37	1	TAILLAMP PANEL RH	\$	R	986.70	X
38	1	TAILLAMP LH	\$	Cur	552.55	✓
39	1	TAILLAMP PANEL LH	\$	R	986.70	X
40	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	Net	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	B71/Bu	2,189.88	✓
43	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
44	1	EXHAUST REAR	\$	R	7,489.05	X
45	1	EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Specical Nett

1	1SET	PARKING AID	\$	Short	700.00	✓
2	1SET	REAR BUMPER CLIP	\$	Na	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	Na	33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	Na	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	Na	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	Na	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	Na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	Na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	Na	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	Na	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	Na	30.00	—
13	1	BOOT STICKER "6555-3333"	\$	Na	30.00	—
14	1	BOOT INNER TRIM CLIP	\$	Na	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	Na	35.00	X
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	Na	35.00	X
17	1	FENDER INNER TRIM CLIP LH	\$	Na	28.00	X
18	1	FENDER INNER TRIM CLIP LH	\$	Na	28.00	X
19	1	TAILLAMP CLIP RH	\$	Na	5.00	X
20	1	TAILLAMP CLIP LH	\$	Na	5.00	X
21	2	REAR WINDSCREEN SELANT	\$	Na	80.00	40.00
22	1	WINDSCREEN MOULDING	\$	Na	100.00	—
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	Na	100.00	30.00
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	X
25	1	SPARE TYRE	\$	Sn	330.00	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-085

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5940T - AXA

TOTAL	\$	2,225.02
TOTAL PARTS	\$	34,507.07

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	1100
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	1800
To Rust-Proofing Of The Affected Areas.	\$	170.00	90
To reinstall rear bumper parking sensor.	\$	170.00	60
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 100
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	80
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
Towing Fees	\$	nn 120.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	120
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
TOTAL		\$	11,160.00
Over All Total		\$	45,667.07
Repair Days		15 Days	
		14 days	

LKK Auto Cons., limits hence notify the Repairer of the following:

- To resurvey Deformational spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Repair Days

Actual repair time