

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18000685/KPS3Q2

Date: 23/06/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant

Vehicle No : SGR6899G

Insured Vehicle No :

SHD33P

Date of Loss: 08/01/2018

Nature of Claim:

TP

Claim No: C0472625

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SGR6899G

Make & Model:

TOYOTA ALPHARD, 3.5 S (A)

Engine No:

2GR0588795

Reg. Date:

13/11/2008 (Man. Year: 2008)

Chassis No:

GGH208011405

Colour:

Metallic Pearl White

Odometer:

307604 km

Engine Capacity:

3456 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

235/50 R18

Rear Tyre Size:

235/50 R18

Front Left Side:

Pirelli 9 mm

Rear Left Side:

Pirelli 9 mm

Front Right Side:

Pirelli 9 mm

Rear Right Side:

Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,466.12	3,991.82	474.30	10.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,820.00	850.00	31.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,136.12	5,811.82	1,324.30	18.56
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	7,136.12	4,600.00	2,536.12	35.54
+ GST 7.00/7.00% (S\$)	499.53	322.00	177.53	35.54
Nett Amount (S\$)	7,635.65	4,922.00	2,713.65	35.54
+ Car Rental (8.0 x S\$180.00/day) (S\$)		1,440.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,369.45		

INSPECTION

Date of Assignment: 10/01/2018

Date Inspected: 11/01/2018 Inspected At:

Alans United Auto Pte Ltd (HQ)

BLK 7 SIN MING INDUSTRIAL

ESTATE #01-76

Singapore 575642

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2020)
Parts:	M1-MPV	TOYOTA ALPHARD 3.5 S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGR6899G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAIL GATE (CONSISTENT)	Bent	1,537.31 FL	*1,537.31 FL
2	1	*TAIL GATE ALPHARD EMBLEM (CONSISTENT)	Necessary	63.90 FL	*63.90 FL
3	1	*TAIL GATE V6 EMBLEM (CONSISTENT)	Necessary	39.80 FL	*39.80 FL
4	1	*TAIL GATE LOGO (CONSISTENT)	Necessary	66.15 FL	*66.15 FL
5	1	*O/S TAIL GATE SIDE GARNISH (CONSISTENT)	Dented	189.10 FL	*189.10 FL
6	1	*O/S TAILLAMP (CONSISTENT)	Dented / Cut	471.20 FL	*471.20 FL
7	1	*O/S TAILLAMP LOWER GARNISH (CONSISTENT)	Buckled	194.40 FL	*194.40 FL
8	1	*REAR END PANEL (CONSISTENT)	Bent	590.90 FL	*590.90 FL
9	1	*REAR BUMPER FASCIA (CONSISTENT)	Bent	680.50 FL	*680.50 FL
10	1	*REAR O/S BUMPER UNDER COVER (CONSISTENT)	Deformed	281.50 FL	*281.50 FL
11	1	*REAR BUMPER O/S REFLECTOR (CONSISTENT)	Cracked	66.90 FL	*66.90 FL
12	1	*REAR BUMPER SIDE RETAINER (CONSISTENT)	O/S Distorted	144.80 FL	*72.40 FL
13	1	*REAR O/S BUMPER BRACKET (CONSISTENT)	Bent	98.91 FL	*98.91 FL
14	1	*REAR EXHAUST SILENCER BOX (CONSISTENT)	Bent	773.50 FL	*773.50 FL
15	1	*REAR EXHAUST CHROME PIPE (CONSISTENT)	Dented	142.63 FL	*142.63 FL
16	1	*REAR W/ GLASS SEALANT (CONSISTENT)	Necessary	60.00 FS	*40.00 FS
17	4	*REAR BUMPER REVERSE SENSOR (CONSISTENT)	Serviceable	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,801.50	5,309.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,335.38	1,317.28
Total Parts (\$\$)	4,466.12	3,991.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	120.00
2	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	120.00	80.00
3	TO REMOVE AIR CON CONDENSER ,PIPES AND DRIER ,VACUUM AND TO RECHARGE GAS	New	120.00	0.00
4	TO APPLY UNDERSEALING	New	100.00	60.00
5	TO REMOVE AND RENEW EXHAUST SILENCER BOX	New	80.00	60.00
6	TO PUTTY AND SPRAY REPLACED PARTS	New	1,000.00	800.00
7	TO REMOVE, CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	1,100.00	700.00
Gross Labour Cost (\$)			2,670.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >