

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 8668K

MAKE :

MODEL : HYUNDAI i40

DATE 8/1/2018 14:47

AXA

REAR RIGHT

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Wheel Hup-Cap (RH) ✓			\$ 150.70
	<i>Rear bumper to 19.2</i>			
	SUB TOTAL			\$ 150.70
	LESS 20%			\$ 30.14
	DISCOUNTED TOTAL			\$ 120.56
	Rear Bumper Rubber Mat ✕			\$ 50.00
				Nett
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Rear Wheel Alignment			\$ 120.00
	TOTAL LABOUR			\$ 840.00
	ESTIMATE TOTAL			\$ 1,010.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental items must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental items must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

Ke LKK
11/1/18 100.4
2 PIP
PIR
After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.