

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG18000691/KHA3Q2

**Date:** 13/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100212262-07

**Claimant**  
**Vehicle No :** SHB9981D **Insured Vehicle No :** SJX3357G

**Date of Loss:** 07/01/2018 **Nature of Claim:** TP **Claim No:** 6216126103SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** SHB9981D  
**Make & Model:** RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) **Engine No:** M9R8839C000498  
**Reg. Date:** 30/09/2013 (Man. Year: 2013) **Chassis No:** VF1ABL15AUC273530  
**Colour:** Metallic White/Red **Odometer:** 720032 km  
**Engine Capacity:** 1995 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (S\$):** **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:**

### CONDITION OF TYRES

**Front Tyre Size:** 215/60 R16 **Rear Tyre Size:** 215/60 R16  
**Front Left Side:** Giti 9 mm **Rear Left Side:** Falken 8 mm  
**Front Right Side:** Giti 9 mm **Rear Right Side:** Falken 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	28,988.70	5,605.40	23,383.30	80.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,260.00	990.00	7,270.00	88.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>37,248.70</b>	<b>6,595.40</b>	<b>30,653.30</b>	<b>82.29</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,200.00</b>		
<b>(S\$)</b>	37,248.70	5,200.00	32,048.70	86.04
<b>+ GST 7.00/7.00% (S\$)</b>	2,607.41	364.00	2,243.41	86.04
<b>Nett Amount (S\$)</b>	<b>39,856.11</b>	<b>5,564.00</b>	<b>34,292.11</b>	<b>86.04</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$99.32/day) (S\$)</b>		297.96		
<b>+ Doc/Search Fee (S\$)</b>		5.35		
<b>Nett Liability (S\$)</b>		<b>6,017.31</b>		
<b>Global Sum Settlement (S\$)</b>		<b>6,000.00</b>		

### INSPECTION

**Date of Assignment:** 09/01/2018

**Date Inspected:** 09/01/2018 **Inspected At:**

Trans-cab Auto Services Pte Ltd  
No 2 Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 2.5 days

---

**Adjuster:** KENNETH KONG

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
21	1		*BOOT LOCK	Repair	202.67 FL	*- FL
22	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
23	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
24	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
25	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
26	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
27	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
28	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
29	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
30	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
31	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
32	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
33	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
34	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
35	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
36	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
37	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
38	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
39	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
40	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
41	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
42	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
43	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
44	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
45	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
46	1		*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*- FS
47	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
48	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
49	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
50	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
51	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
52	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
53	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
55	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
56	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
57	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
58	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>31,973.66</b>	<b>6,203.22</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	2,984.96	597.82
<b>Total Parts (\$)</b>	<b>28,988.70</b>	<b>5,605.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	2,800.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
11	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TOWING FEES	New	120.00	0.00
13	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
14	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,260.00</b>	<b>990.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >