

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17016118/SBS2
Date: 06/11/2017

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100179410
Claimant Vehicle No :	SJD2125X	Insured Vehicle No :	SJM594R
Date of Loss:	17/08/2017	Nature of Claim:	TP
		Claim No:	1622953979SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD2125X		
Make & Model:	HONDA FIT, 1.3 (A)	Engine No:	L13A4022463
Reg. Date:	13/03/2008 (Man. Year: 2008)	Chassis No:	GE61019656
Colour:	White	Odometer:	151039 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	21/09/2017		
Date Inspected:	22/08/2017	Inspected At:	Eng Soon Painting Services BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969
Estimated Period of Repair:	6.0 days		

Adjuster: Sebastian Yeang Wai Keen

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER BRACKET	Necessary	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	*Check	0.00 F	*- F
5	1		*FRT BUMPER SPONGE	*Check	0.00 F	*- F
6	1		*FRT BUMPER GRILLE LOWER	Deformed	0.00 F	*- F
7	1		*FRT BUMPER LOWER SPOILER	Cracked	0.00 F	*- F
8	1		*FRT GRILLE	Deformed	0.00 F	*- F
9	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
10	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
11	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Deformed	0.00 F	*- F
12	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
13	1		*FRT RH HEADLAMP ASSY	*Check	0.00 F	*- F
14	1		*BONNET	Bent	0.00 F	*- F
15	1		*BONNET LOCK	Bent	0.00 F	*- F
16	2		*BONNET HINGE	Bent	0.00 F	*- F
17	1		*AIR CON CONDENSER	*Check	0.00 F	*- F
18	1		*AIR CON SUCTION PIPE (LOW PRESSURE)	*Check	0.00 F	*- F
19	1		*AIR CON LIQUID PIPE	*Check	0.00 F	*- F
20	1		*RADIATOR	*Check	0.00 F	*- F
21	1		*RADIATOR COWLING	*Check	0.00 F	*- F
22	1		*RADIATOR FAN ASSY	*Check	0.00 F	*- F
23	1		*RADIATOR FAN CLUTCH	*Check	0.00 F	*- F
24	1		*FRT LH FENDER INNER SHIELD	*Check	0.00 F	*- F
25	1		*FRT RH FENDER INNER SHIELD	*Check	0.00 F	*- F
26	1		*FRT TOW HOOK COVER	Missing	0.00 F	*- F
27	1		*REAR BUMPER	Cracked	0.00 F	*- F
28	1		*REAR BUMPER LOWER GARNISH	Cut	0.00 F	*- F
29	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
30	1		*REAR BUMPER BRACKET	Necessary	0.00 F	*- F
31	1		*REAR BUMPER BEAM	*Check	0.00 F	*- F
32	1		*REAR BUMPER SPONGE	*Check	0.00 F	*- F
33	1		*TAILGATE	Dented	0.00 F	*- F
34	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
35	1		*TAILGATE MOULDING	Necessary	0.00 F	*- F
36	1		*REAR TOW HOOK COVER	Scratched	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$) **0.00** **0.00**

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/SJD2125X/06/11/2017 09:55
--

< END OF ESTIMATES >