## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

**VEHICLE NO: SHD 3069S** 

MAKE : MODEL : HYUNDAI i40

DATE 9/1/2018 8:41

por: 07.01.18 pp

MODEL	: HYUNDAI i40		TI 't Date	A	mount	
Qty	Parts Description/ Labour	Type	Unit Price	\$	603.60	
	Rear Bumper			\$	504.35	
	Rear Bumper Reinforcement		\$ 180.00	\$	360.00	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$	49.00	
	Rear Bumper Side Bracket ?			1	22.00	
	Rear Bumper Clips			\$		
	Rear Bumper Sponge 2			\$	143.40	
	Rear Bumper Under Cover X			\$	225.00	
	Rear Bumper Reflector Lamp (LH) 🔀			\$	32.00	
	SUB TOTAL			\$	1,939.35	1
	LESS 20%			\$	387.87	
	DISCOUNTED TOTAL			\$	1,551.48	1
	DISCOUNTED TOTAL					
	90					
	Rear Bumper Reverse Sensor 🗶			\$	135.70	Nett
	Rear Bumper Rubber Mat			\$	50.00	Nett
	Real Bumper Russer 11211					
				\$	185.70	
	Labour Charge				200	
	Panel Beating			\$	380.00	١,
	Spray Painting Charge			\$	200.00	18
	Wiring Charge			\$	50.00	1×
	R/Refix Reverse Sensor			\$	120.00	$\times$
	To Kenn Kennes Samuel					1
	TOTAL LABOUR	R		\$	750.00	4
	ESTIMATE TOTAL			\$	2,487.18	+
	ESTIMATE TOTAL	1			2,10112	1
	Kalin (C(K)  11/1/12 1400 hr.  2 Pa7x					
	Ka kin Citi	LKK	Auto Consultants hence r	L'E		
Fatty No	1 l. kg (4,00 hr.	1110	hapdile of the following.	220		
Paris		• To (	tesurve. Lutore after spray count	1		
	7 Put	• Par	ts prices are subject to or a series	esurvey	'	
		• Thir	digarty survey giornal V	udice	e" basis	
	PIP	• Sup	Leineria i maj le la la			
	PIP Before Parat photo	IS Su	DIP 110 Sun		om; my	
	Before Paral P	Acknow				
		Signate:	ure			
	This is an initial estimate based on a visual inspection of		vehicle. The final repair	quar	tum will	7
	he prepared after the vehicle is surveyed by a motor Surv	evor appoi	inted by the insurance co	ompa	ny.	
	be prepared after the vehicle is surveyed by a motor Surv	eyor appoi	nted by the insurance co	ompa	ny.	