

INVOICE

ASS. REQ. BY:

REF: CS/MSG18000733/Ktd302 Special Instructions

Kenneth
menimen ASSIGNMENT (Office)

From (Person): Monica chuney of MSIG Date/Time: 11/01/18 @ 5:31pm

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS1150B Insured: YMG428X

at Workshop m/s Automotive Collision Repair Tel: 6451 4958

of 81k176, Sin Ming Drive # 03-11

Policy No: 28957015MKC Claim No:

Sum Insured: Excess:

Make of Veh: DOA 09/01/18
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time: 9:38am @ 12/01/18 Person Contacted: Vehicle ☒ OUTDate/Time Action/Instructions ✓ ☒

SLS1150B - X

YMG428X - NA/MSG15000688/r3

DOA: 05/01/2015

All - Revert preli via menimen

854501 email Cred: 5520.84, 50%

MSIG

ASSIGNMENT

Date 12/01/2018

SLS 1150B 10 of 10

Estimated Cost

DD TP WIS TP RES CO RES EVAL INVT

To inspect vehicle for

SLS 1150B

at Workshop to

Automotive Collision Repair

Blk 176, Sin Ming Drive #03-11 575721

Insured

Policy No

Claims No

Sum Insured


Excess

(Client's Record)

Make of Ven

(Policy Condition)

Remark: The ven had commenced its repair at the time of inspection.



Est. of Market Value

IDAO Accident Report Consistent? Yes or No

GIA PR Green Consistent? Yes or No

Est. Repairs 08 days Res? Yes or No

Est. Sum 20 % G/Vail? Yes or No

CA REV / REP / 24 HRS 'wp'

Date Person Contacted

Vehicle IN/OUT

Type Motor M Cycle Bus Van Lorry Taxi Prime Mover

Truck Trailor

Make

Toy

Estimo

Wagon

2362

Color

M Silver

So-Feeding

7P093

Engine

C/Vol

ACR 50 01180P

Gen Cond Good Fair Poor Burnt

Steering In Order Jammed Leaked Burnt or

Brake In Order Jammed Leaked Burnt or

Mod N/S Rim STD or

Tyre Size

R Yokco

215/55R17

R Mic

BS DUN EXNOVA GY FS LIZA MID OHTSU PIR SLMI

TOYO INCHO or

Front

R Bal

6

Rear

R Bal

7

L Bal

6

L Bal

7

D/OA

9/1/18

D/OA

12/1/18

Surveyed at

Des of Damages Fr Rear D/S N/S U/O Rooftop or

N/S body

The U/O Chassis frame Body Structure affected must collect

Date Time Action Instruction

13/11 Take pass to Certificate

RECEIVED 14 DEC 2018

13/12/2018

Date Time File Pass to

13/12 Typist

☐

Preli. Report

☒

Final Report

Date Time File Result to

Days Of Repair 8

Resurvey No. of Trip 1

Add Fee

Steering

Braking

Tyre

Body

Survey Fee

Inspection

Paint

Welding

Other

Total

300

10

310

Report Format

Unit ①

TP 54501



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000733/Ktd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 12-01-2018



Code : MSG

1.

Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 6428X	Veh. Inspected	SLS 1150B
Policy No.	28957015MKC	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	12/01/2018

2.

Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

Description of Damages

5.

General Information

Accident Date	09/01/2018	Inspection Date	12/01/2018
Survey held at	AUTOMOTIVE COLLISION REPAIR SERVICES BLK 176 SIN MING DRIVE #03-11 SIN MING AUTOCARE, SINGAPORE 575721		

5a.

Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jan 2018		11 Jan 2018 17:31 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GARMCO (S) PTE LTD , Co. Reg. No.: 199304064Z		
Main Claimant:	TAN WEI AUTO PTE LTD , Co. Reg. No.: 201207059G		
Vehicle Reg. No.:	SLS1150B	Date of Loss:	09/01/2018 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	28957015MKC (Comprehensive) Coverage: 20/06/2017 - 19/06/2018
Vehicle Reg. No. (Insured):	YM6428X	Policy No. (Claimant):	
		Excess:	
Repairer:	Automotive Collision Repair Services (HQ) BLK 176 SIN MING DRIVE, #03-11 Sin Ming Autocare, 575721 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/01/2018]		
Driver/Custodian (Insured):	LIM KOK PING CHRISTOPHER (LIN GUOBIN) (/ Male), NRIC: S7722392D		
Adj Asg. Remarks:	PRI		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

1/17/2018

Adjuster Immediate Advice

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 17 Jan 2018

Preliminary Advice

Insured Vehicle No	: YM6428X	Accident Date	: 09/01/2018
TP Vehicle No	: SLS1150B	Assignment Date	: 11/01/2018
Make	: TOYOTA ESTIMA	Est. Duration of Repair	: 6.00
Date of Inspection	: 17/01/2018		
Inspection At	: AUTOMOTIVE COLLISION REPAIR SERVICES (HQ) BLK 176 SIN MING DRIVE, #03-11 SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,500.00
Revised Amount	:S\$	2,180.00 (Labour only)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,180.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/01/2018 14:57
Date Of Accident	09/01/2018 15:45
Exact Location Of Accident	PIE TOWARDS CHANGI NEAR EXIT 17
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS1150B
Insured/Policyholder	
Name Of Registered Owner	TAN WEI AUTO PTE LTD
Co Reg No	201207059G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88219191
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ESTIMA-2.4 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	8-V0008351-MVA R003
Cover Note Number	
Driver	
Name of Driver	ONG CHIN LIAT JOEL
NRIC No	S9133258B
Date Of Birth	28/08/1991
Occupation	INDOOR
Date Of Driving Pass	12/09/2011
Driving Experience	6 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88219191
Fax Number	
Contact Number	
EEmail Address	JOEL-ONG@HOTMAIL.COM

Address 216B COMPASSVALE DR #15-548
 Postcode 542216
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - EMPLOYEE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions RAINING
 Road Surface WET

Other information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YM6458X YM 6428X
 Vehicle Make/Model/Colour X ✓
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver CHRISTOPHER LIM KOK PING
 NRIC/Passport Number S7722392D
 Contact Number 98507059
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Signature



COMFORTDELGRO ENGINEERING PTE LTD
353 SIN MING DRIVE
SINGAPORE 575717

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Sketch Plan grid showing vehicle positions and details:

Left side labels: PTE, cheng, 17

Grid content:

- Top left: A
- Top middle: B
- Top right: A
- Middle left: A
- Middle middle: B
- Middle right: A
- Bottom left: A
- Bottom middle: B
- Bottom right: A

Right side labels:

- A: 3LSH50B
- B: 24YM6458X

The Circumstances of the Accident

I WAS DRIVING ALONG PIE TOWNED CHANGI NEAR EXIT 17, SUDDENLY A LORRY YN6458X WHICH WAS TRAVELLING ON MY LEFT SIDE, SWIRL INTO MY LANE.

THE SUDDEN CUTTING INTO MY LANE BY THE DRIVER OF VEHICLE YN6458X, LEFT ME LITTLE TIME TO REACT. HENCE THE REAR SECTION OF YN6458X COLLIDED INTO THE FRONT LEFT SECTION OF MY VEHICLE.

NO ONE WAS INJURED.

Declaration

10/01/2018 2:45 PM

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Handwritten Signature]



Driver's Signature (If driver is not the policyholder) / Date & Time

COMFORTDELGRO ENGINEERING PTE LTD
383 SIN MING DRIVE
SINGAPORE 5757

[Handwritten Signature]

Witnessed by Reporting Centre Personnel

Automotive Collision Repair Services
Blk 176, Sin Ming Drive, #03-11
Sin Ming Autocare
Singapore 575721
Tel: 6451 4958 Fax: 6451 3285

Vehicle No: SLS1150B
Our Ref: ACRS/18700/TP

Signature
18/1/18

Date: 11th Jan 2018

Make/ Model: Toyota estima 2.4
(AUG 2010)

*Not Authored
11th Jan 18
Penny After Penny
6 days*

Repair Estimate

Qty	Description	Amt (\$)
A) Replacement Of Parts		
1	Frt n/s headlamp <i>W</i>	
1	Frt n/s fender <i>B</i>	
1	Frt n/s door <i>B</i>	
1	Frt n/s door lower protector <i>W</i>	
1	Front n/s side view mirror complete <i>B</i>	
1	Rear n/s sliding door <i>B</i>	
Discount 25%		
After Discount		

B) Special Nett Items

1	Frt n/s door hinges (2pc) <i>B</i>	
1	Frt n/s door check <i>?</i>	
1	Frt n/s door weather rubber seal <i>?</i>	
1	Frt n/s door outer handle <i>B</i>	
1	Frt n/s door glass window inner weather rubber seal <i>?</i>	
1	Frt n/s door glass window outer moulding <i>B</i>	
1	Frt n/s door power-window Gear & motor (complete set) <i>?</i>	
1	Rear n/s left sliding door weather rubber seal <i>B</i>	
1	Rear n/s left sliding door handle <i>B</i>	
1	Frt n/s door lock & catch <i>?</i>	

C) Labour Charges

1)	To remove and replace the above damaged parts, straightening , to realign, repositioning-repairs, torching and etc.	\$2,300.00
2)	To conduct pre-paint preparation work, putty, spray painting, oven heating & hardening , polishing the repaired and replaced panels	\$2,500.00 <i>1100</i>
3)	Labour for remove refit power window motor & gear (front door)	\$160.00 <i>100</i>
4)	Labour for remove refit power window motor & gear (rear sliding door)	\$160.00 <i>100</i>
5)	Application of Tuffcoat rust-proofing	\$180.00 <i>100</i>
6)	Labour for electrical wiring	\$80.00 <i>300</i>
7)	Computerise wheel alignment	<i>22</i> \$120.00 X

\$5,500.00

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Grand Total

Acknowledged by Repairer

Signature:

Date:

Automotive Collision Repair Services
Blk 176, Sin Ming Drive, #03-11
Sin Ming Autocare
Singapore 575721

Tel: 6451 4958 Fax: 6451 3285

Vehicle No: SLS1150B
Our Ref: ACRS/18700/TP

Not Notified
L1 Prp @ 5450h
Arriving After Paint

Date: 11th Jan 2018

Make/ Model: Toyota estima 2.4
(AUG 2010)

Repair Estimate

Qty

Description

Amt (\$)

A) Replacement Of Parts

- 1 Frt n/s headlamp
- 1 Frt n/s fender
- 1 Frt n/s door
- 1 Frt n/s door lower protector
- 1 Front n/s side view mirror complete
- 1 Rear n/s sliding door

Gr	\$983.20	✓
Pr	\$527.55	✓
Pr	\$769.13	✓
Bu	\$513.16	✓
Bu	\$589.17	✓
Pr	\$1,124.90	✓
	<u>\$4,507.11</u>	
	<u>-\$1,126.77</u>	
	<u>\$3,380.34</u>	

Discount 25%
After Discount

B) Special Nett Items

- 2 Frt n/s door hinges (2pc)
- 1 Frt n/s door check
- 1 Frt n/s door weather rubber seal
- 1 Frt n/s door outer handle
- 1 Frt n/s door glass window inner weather rubber seal
- 1 Frt n/s door glass window outer moulding
- 1 Frt n/s door power-window Gear & motor (complete set)
- 1 Rear n/s left sliding door weather rubber seal
- 1 Rear n/s left sliding door handle
- 1 Frt n/s door lock & catch

Pr	\$170.80	✓
Gr	\$118.10	X
Gr	\$231.15	506h
Bu	\$312.90	✓
Gr	\$74.90	X
Gr	\$103.60	✓
n/s	\$526.30	✓
Gr	\$233.20	✓
Gr	\$231.15	✓
n	\$88.40	X
	<u>\$2,090.50</u>	

25%

C) Labour Charges

- 1) To remove and replace the above damaged parts, straightening , to realign, repositioning-repairs, torching and etc.
- 2) To conduct pre-paint preparation work, putty, spray painting, oven heating & hardening , polishing the repaired and replaced panels
- 3) Labour for remove refit power window motor & gear (front door)
- 4) Labour for remove refit power window motor & gear (rear sliding door)
- 5) Application of Tuffcoat rust-proofing
- 6) Labour for electrical wiring
- 7) Computerise wheel alignment

	\$2,300.00	90d
	\$2,500.00	110d
	\$160.00	60d
	\$160.00	60d
	\$180.00	90d
	\$80.00	20d
nn	\$120.00	X
	<u>\$5,500.00</u>	
	<u>\$10,970.84</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Grand Total

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jan 2018		11 Jan 2018 17:31 Edit Adj Rpt	S\$5,450.00 Edit Estimates	S\$5,450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GARMCO (S) PTE LTD , Co. Reg. No.: 199304064Z								
Main Claimant:	TAN WEI AUTO PTE LTD , Co. Reg. No.: 201207059G								
Vehicle Reg. No.:	SLS1150B	Date of Loss:	09/01/2018 15:00 - :59 [88 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 545499	Policy/Cover Note No.:	B28957015MKC(COMP) (Comprehensive) Coverage: 20/06/2017 - 19/06/2018						
Vehicle Reg. No. (Insured):	YM6428X	Policy No. (Claimant):							
		Excess:							
Repairer:	Automotive Collision Repair Services (HQ) BLK 176 SIN MING DRIVE, #03-11 Sin Ming Autocare, 575721 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/02/2018]								
Driver/Custodian (Insured):	LIM KOK PING CHRISTOPHER (LIN GUOBIN) (/ Male), NRIC: S7722392D								
Adj Asg. Remarks:	PR1								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS1150B (545499)
[YM6428X]
TP
TAN WEI AUTO PTE LTD
Jan 9 2018 3:00PM
[GARMCO (S) PTE LTD]
Automotive Collision Repair Services

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/18 12:03	Adjuster Immediate Advice	1 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
2	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
3	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
4	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
5	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
6	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
7	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
8	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
9	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
10	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
11	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
12	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
13	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
14	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
15	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
16	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
17	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
18	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
19	13/12/18 15:25	General View	1 Load JPG	<input checked="" type="checkbox"/>
20	13/12/18 15:27	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
21	13/12/18 15:27	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
22	13/12/18 15:27	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
23	13/12/18 15:27	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
24	13/12/18 15:27	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
25	13/12/18 15:27	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
26	13/12/18 15:27	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
27	13/12/18 15:27	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
28	13/12/18 15:27	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
29	13/12/18 15:27	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
30	13/12/18 15:27	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
31	13/12/18 15:27	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/01/18 17:32	TP GIA REPORT		Load PDF	
2	11/01/18 17:33	WE APPOINT LKK TO BE THE SJE		Load PDF	
3	11/01/18 17:34	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000733/KTD3E2

Date: 14/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B28957015MKC(COMP)

Claimant Vehicle No : SLS1150B

Insured Vehicle No : YM6428X

Date of Loss: 09/01/2018

Nature of Claim: TP

Claim No: 545499

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS1150B	Engine No:	HIDDEN
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Chassis No:	ACR500114097
Reg. Date:	10/08/2010 (Man. Year: 2010)	Odometer:	79093 km
Colour:	Metallic Silver		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,470.83	4,615.32	855.51	15.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,500.00	2,230.00	3,270.00	59.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,970.83	6,845.32	4,125.51	37.60
Approved Total (Overridden) (S\$)		5,450.00		
Nett Amount (S\$)	10,970.83	5,450.00	5,520.83	50.32

INSPECTION

Date of Assignment: 11/01/2018

Date Inspected: 12/01/2018 Inspected At:

Automotive Collision Repair Services (HQ)
BLK 176 SIN MING DRIVE, #03-11 Sin
Ming Autocare
Singapore 575721

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Dec 2018)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS1150B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT N/S HEADLAMP	Cut	983.20 FL	*983.20 FL
2	1		*FRT N/S FENDER	Bent	527.55 FL	*527.55 FL
3	1		*FRT N/S DOOR	Bent	769.13 FL	*769.13 FL
4	1		*FRT N/S DOOR LOWER PROTECTOR	Buckled	513.16 FL	*513.16 FL
5	1		*FRONT N/S SIDE VIEW MIRROR COMPLETE	Broken	589.17 FL	*589.17 FL
6	1		*REAR N/S SLIDING DOOR	Bent	1,124.90 FL	*1,124.90 FL
7	1		*FRT N/S DOOR HINGES (2PCS)	Bent-1pc only	170.80 F	*85.40 FN
8	1		*FRT N/S DOOR CHECK	Serviceable	118.10 F	*- FN
9	1		*FRT N/S DOOR WEATHER RUBBER SEAL (50%)	Cut	231.15 FS	*115.58 FS
10	1		*FRT N/S DOOR OUTER HANDLE	Broken	312.90 F	*312.90 FN
11	1		*FRONT N/S DOOR GLASS WINDOW INNER WEATHER RUBBER SEAL	Serviceable	74.90 F	*- FN
12	1		*FRT N/S DOOR GLASS WINDOW OUTER MOULDING	Cut	103.60 F	*103.60 FN
13	1		*FRT N/S DOOR POWER-WINDOW GEAR & MOTOR (COMPLETE SET)	Distorted / Jammed	526.30 F	*526.30 FN
14	1		*REAR N/S LEFT SLIDING DOOR WEATHER RUBBER SEAL	Cut	233.20 F	*233.20 FN
15	1		*REAR N/S LEFT SLIDING DOOR HANDLE	Cut	231.15 F	*231.15 FN
16	1		*FRT N/S DOOR LOCK & CATCH	Repair	88.40 F	*- FN

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	6,597.61	6,115.24
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,126.78	1,126.78
- Nett Item Discount on N Items 0.00/25.00% (\$\$)	0.00	373.14
Total Parts (\$\$)	5,470.83	4,615.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTENING, TO REALIGN, REPOSITIONING-REPAIRS, TORCHING AND ETC	New	2,300.00	900.00
2	TO CONDUCT PRE-PAINT PREPARATION WORK, PUTTY, SPRAY PAINTING, OVEN HEATING & HARDERNING, POLISHING THE REPAIRED AND REPLACED PANELS	New	2,500.00	1,100.00
3	LABOUR FOR REMOVE REFIT POWER WINDOW MOTOR & GEAR (FRONT DOOR)	New	160.00	60.00
4	LABOUR FOR REMOVE REFIT POWER WINDOW MOTOR & GEAR (REAR SLIDING DOOR)	New	160.00	60.00
5	APPLICATION OF TUFFCOAT RUST-PROOFING	New	180.00	90.00
6	LABOUR FOR ELECTRICAL WIRING	New	80.00	20.00
7	COMPUTERISE WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (S\$)			5,500.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >