

REF: 3831

REF CSB/LPC 17021158 / RJVb-1

Paper Survey

Rasul
Gerald Poh

ASSIGNMENT (Office)

LPC

Date Time 12/01/2018

From (Person)

Estimated Cost

OD (H) WS / TP RES / OD RES / EVA / ENV / MV / CE

To Inspect Vehicle No

SLG 6928 E

SGG 6505 B

at Workshop no

AMA Automotive

Tel 877 83636

of 36 Toh Guan Rd East # 01-36, 668580

Policy No

Claim No

17/17/17 / VP05 / 020199

Sum Insured

Excess

Make of Veh
(Client's Record)

Date 3/11/2017

CA / REV / REP. / REV 24 HRS 'wp'

Date Time 3:38pm @ 6/1/17

Person Conducted

Melvin

RAC Extension

RM (B) DET

Date Time

Actual Inspection X Estimate

SLG 6928 E / SGG 6505 B / 17/17/17 / VP05 / 020199 / 17/17/17 / VP05 / 020199

Disassemble: 7/11/17


After paint: 13/11/17 (Ti)

Rasul,

Pls see my remarks.

28/2/18 Submit LS \$ 13,300, 12 days
(Recd 5200, 28/2)

RECEIVED 28 FEB 2018



26/2/2018

45

RECEIVED 11/19/42



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC17021158/R1vb-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 12-01-2018



Code : LPC2

1. Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	SGG 6505B	Veh. Inspected	SLG 6928E
Policy No.		Coverage (\$)	0.00
Claim No.	17/17/17/VP05/020199	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	12/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	03/11/2017	Inspection Date	12/01/2018
Survey held at	AMA AUTOMOTIVE PTE. LTD. 36 TOH GUAN ROAD EAST #03-36 SINGAPORE 608580		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 12 January, 2018 1:09 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: PRE-REPAIR SURVEY - SLG6928E

Our Ref : 17/17/17/VP05/020199

Dear Catherine,

Kindly check with the surveyor if a re-inspection is required or a paper survey would suffice.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

S K AUTO CONSULTANTS

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference: TP/017/0448SK

Your Reference: TBA

Date: 8/12/2017

TO: Abdullah Hamid Bin Pakeer Mastan
C/o AMA Automotive Pte Ltd
Enterprise Hub #01-36
36 Toh Guan Road East
Singapore 608580

Assessment of Vehicle No : SLG 6928E

Date of Accident : 03/11/2017

Date of Inspection : 06/11/2017

We have carried out a physical assessment of SLG 6928E at AMA Automotive Pte Ltd according to your instructions on 06/11/2017 and are pleased to submit our report as follows;

1.VEHICLE PARTICULARS

Registration No.	:	SLG 6928E
Make & Model	:	HONDA SHUTTLE
Year of Registration	:	2016
Engine Capacity (cc)	:	1496
Chassis No.	:	GK81007497
Engine No.	:	L15B3538784
Colour	:	Red
Mileage (km)	:	19126

2.VEHICLE CONDITION

Body Paint:	:	Good
Steering	:	Serviceable
Foot Brake	:	Serviceable
Parking Brake	:	Serviceable

3.TYRE PARTICULARS & CONDITION

Front

RH Make/Size	:	Yokohama 185/60R15 - 80%
LH Make/Size	:	Yokohama 185/60R15 - 80%

Rear

RH Make/Size	:	Yokohama 185/60R15 - 80%
LH Make/Size	:	Yokohama 185/60R15 - 80%

Note: % denotes the remaining percentage of the tyre

S K AUTO CONSULTANTS

Our Reference TP/017/0448SK
Vehicle No. SLG 6928E

Page No. 2

4. DESCRIPTION OF DAMAGE

At the time of inspection observed that this vehicle had sustained damages to the FRONT AND REAR portion (BADLY DAMAGED)

Please see attached schedule for details.



Estimated Amount : S\$25,600.00
Adjusted Amount : S\$18,500/-
Estimated Repair Days : 14 days

Pursuant to your instruction, we have NOT AUTHORIZED repair.
The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within 14 Days from the date hereof, this report shall be treated as correct

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by S K AUTO CONSULTANTS for any reliance on this report by any third party.

S K AUTO CONSULTANTS

Page No. 3

Our Reference TP/017/0448SK
Vehicle No. SLG 6928E

x - serviceable

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	OUR ASSESSMENT(\$\$)
	PARTS (LIST ITEMS)			
1	Front Bumper	Deformed	1245.00	1245.00
2	Front Bumper Fog Lamp Cover L/R @\$72.40	Deformed	144.80	144.80
1	Front Bumper Lower Center Grille	Deformed	248.00	248.00
1	Front Bumper Lower Under Cover	Deformed	185.00	185.00
2	Front Bumper Side Retainer L/R @ \$78.00	Necessary	156.00	156.00
1	Bonnet	Distorted	1287.00	1287.00
1	Bonnet inner lock	Bent	242.00	242.00
1	Front Grille	Not cracked	218.80	218.80
1	Front Grille "Logo " Emblem	Necessary	24.00	24.00
1	Front Grille Chrome Garnish	Cracked	255.80	255.80
4	Front Grille Clips @ \$6.50	Necessary	26.00	26.00
2	RHS & LHS Headlamps @ 982.50	Grazed/inner	1965.00	1965.00
1	Front bumper reinforcement	Dented/Bent	478.00	478.00
1	Front support panel (centre)	Bent	342.00	342.00
1	Front support panel (right)	Bent	248.00	248.00
1	Front support panel (left)	Bent	248.00	248.00
1	Front lower cover	Deformed	198.00	198.00
2	RHS & LHS Support panel cover	Deformed	72.00	72.00
1	Radiator	Damaged	792.00	792.00
1	Air con condensor	Damaged	1274.00	1274.00
1	Air con condensor inlet pipe	Bent	98.00	98.00
1	Tailgate	Distorted	1600.70	1600.70
1	Tailgate centre chrome garnish	Damaged	525.80	525.80
1set	Tailgate centre chrome garnish clips	Necessary	40.00	40.00
1	Tailgate inner lock	Damaged	289.20	289.20
1	Tailgate keyless lock actuator	Damaged	342.00	342.00
1	Tailgate inner trim board	Deformed	547.00	547.00
1	Tailgate inner handle cover	Deformed	72.00	72.00
2	Tailgate damper @298.20 (stiffen)	Damaged	596.40	596.40
2	Tailgate rubber stopper @5.80	Necessary	11.60	11.60
1	Tailgate Honda badge	Necessary	92.00	92.00
1	Tailgate SHUTTLE emblem	Necessary	98.00	98.00
2	Tailgate reflectors	Reuse	421.00	0.00
1	Tailgate wiper motor	Re-use	375.20	0.00
1	Rear windscreen moulding	Necessary	172.00	172.00
1	Rear bumper	Deformed	1650.20	1650.20
1	Rear bumper centre bracket	Bent	211.00	211.00
2	Rear bumper side retainers @144.00	Necessary	288.00	288.00
2	Rear bumper reflector cover	Refix	98.00	0.00
	PARTS C/F		17177.50	16283.30

12,518

S K AUTO CONSULTANTS

Page No. 4

Our Reference TP/017/0448SK
Vehicle No. SLG 6928E

2041

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		OUR ASSESSMENT(S\$)	
	<u>PARTS (LIST ITEMS)</u>	PARTS B/F	17177.50		16283.30	
2	RHS & LHS Taillamp *inner side grazed	Damaged*	1357.00		1357.00	
1	Rear end panel	Distorted	762.00		762.00	
1	Rear end panel top garnish	Deformed	261.00		261.00	
1	Rear boot edge weatherstrip	Deformed	184.00		184.00	
1	Rear spare tyre panel tool box	Deformed	298.00		298.00	
1	RHS corner tool tray	Deformed	142.00		142.00	
2	Tool box corner sponge	Cracked	42.00		42.00	
2	RHS & LHS fender trims @342.00	Deformed	684.00		684.00	
1	Rear spare tyre panel	Distorted	798.00		798.00	
1	Exhaust silencer	Refix	782.00		0.00	
			22487.50		20811.30	
		less 20%	4497.50		4162.26	
			17990.00		16649.04	
	<u>SPECIAL NETT ITEMS</u>					
1 set	Rear Bumper clips	Necessary	60.00		40.00	
1	Rear windscreen sealant	Necessary	100.00		80.00	
1	Front number plate w/holder	Cracked	75.00		50.00	
1	Rear number plate w/holder	Dented	75.00		50.00	
1	Radiator coolant	Necessary	40.00		40.00	
1	Reverse camera	Damaged	480.00		480.00	
1 set	Reverse sensor	Damaged	280.00		250.00	
1 set	Tailgate inner trim clips	Necessary	60.00		40.00	
1	Rear spare tyre panel sealant	Necessary	100.00		80.00	
1	Rear end panel sealant	Necessary	100.00		80.00	
		TOTAL PARTS	19360.00		17839.04	

X

187

X

670

15,559

2026

12,447

60

35

X

X

2026

100

515

S K AUTO CONSULTANTS

Page No. 5

Our Reference TP/017/0448SK
Vehicle No. SLG 6928E

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
1	LABOUR To remove the affected parts & fittings to commence repairs; replace damaged parts and components (FRONT AND REAR)	2800.00	2400.00 1600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced (FRONT AND REAR) (includes - support panel, reinforcement, spare tyre panel)	2000.00	1600.00 1400
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions and focus headlamp beam	250.00	200.00 60
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear portion	200.00	180.00 80
5	To remove and refix rear exhaust, realign and check for system function	250.00	200.00 60
6	To remove and replace air con condensor; vacuum and refill gas	120.00	100.00 80
7	To remove and replace radiator; pressure test and refill coolant	100.00	80.00 60
8	To remove and replace reverse sensors & camera and check for proper function	140.00	120.00 60
9	To remove and refix rear tailgate windscreen	140.00	120.00 /
10	To provide anti-rust treatment on affected areas	240.00	210.00 120
Labour Total :		6240.00	5210.00
TOTAL (PARTS & LABOUR):		25600.00	23049.04

Note: (For Lump Sum Repair)

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or the use of ex stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements.

The final adjusted Lump Sum contract amount is S\$18,500/-



S. Kumanan
 Motor Surveyor

4/5-13,300

12 days

12,447.20
 515.00
 3640.00
 16,602.20
 282
 13,281.76



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC17021158/R1vbe2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 28-02-2018	
			Code : LPC2	
1. Policy Particulars - THIRD PARTY CLAIM				
Insured Veh.	SGG 6505B	Veh. Inspected	SLG 6928E	
Policy No.		Coverage (\$)	0.00	
Claim No.	17/17/17/VP05/020199	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	12/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE 1.5G A	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	GK81007497	Colour	RED	
Odometer	19127	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	YOKOHAMA	5 mm	
L/H Front Tyre	185/55 R16	YOKOHAMA	5 mm	
R/H Rear Tyre	185/55 R16	YOKOHAMA	5 mm	
L/H Rear Tyre	185/55 R16	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/11/2017	Inspection Date	06/11/2017	
Survey held at	AMA AUTOMOTIVE PTE. LTD. 36 TOH GUAN ROAD EAST #03-36 SINGAPORE 608580			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 6928E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	1,245.00	1,050.20
2	FRONT BUMPER FOG LAMP COVER L/R @\$72.40	SERVICEABLE	144.80	-
1	FRONT BUMPER LOWER CENTER GRILLE	DEFORMED	248.00	248.00
1	FRONT BUMPER LOWER UNDER COVER	DEFORMED	185.00	185.00
2	FRONT BUMPER SIDE RETAINER L/R @\$78.00	NECESSARY	156.00	156.00
1	BONNET	DISTORTED	1,287.00	1,050.00
1	BONNET INNER LOCK	SERVICEABLE	242.00	-
1	FRONT GRILLE	CRACKED	218.80	218.80
1	FRONT GRILLE "LOGO" EMBLEM	NECESSARY	24.00	24.00
1	FRONT GRILLE CHROME GARNISH	CRACKED	255.80	255.80
4	FRONT GRILLE CLIPS @\$6.50	NECESSARY	26.00	26.00
2	RHS & LHS HEADLAMPS @\$982.50	GRAZED / INNER	1,965.00	1,965.00
1	FRONT BUMPER REINFORCEMENT	DENTED / BENT	478.00	478.00
1	FRONT SUPPORT PANEL (CENTRE)	TO REPAIR SEE LABOUR	342.00	-
1	FRONT SUPPORT PANEL (RIGHT)	TO REPAIR SEE LABOUR	248.00	-
1	FRONT SUPPORT PANEL (LEFT)	TO REPAIR SEE LABOUR	248.00	-
1	FRONT LOWER COVER	DEFORMED	198.00	198.00
2	RHS & LHS SUPPORT PANEL COVER	DEFORMED	72.00	72.00
1	RADIATOR	DAMAGED	792.00	792.00
1	AIR CON CONDENSOR	DAMAGED	1,274.00	1,274.00
1	AIR CON CONDENSOR INLET PIPE	BENT	98.00	98.00
1	TAILGATE	DISTORTED	1,600.70	1,554.50
1	TAILGATE CENTRE CHROME GARNISH	SERVICEABLE	525.80	-
1	SET TAILGATE CENTRE CHROME GARNISH CLIPS	NECESSARY	40.00	40.00
1	TAILGATE INNER LOCK	DAMAGED	289.20	289.20
1	TAILGATE KEYLESS LOCK ACTUATOR	SERVICEABLE	342.00	-
1	TAILGATE INNER TRIM BOARD	DEFORMED	547.00	320.40
1	TAILGATE INNER HANDLE COVER	DEFORMED	72.00	72.00
2	TAILGATE DAMPER @\$298.20 (STIFFEC)	SERVICEABLE	596.40	-

Report Ref No. CS3/LPC17021158/R1vbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	TAILGATE RUBBER STOPPER @\$5.80	NECESSARY	11.60	11.60
1	TAILGATE HONDA BADGE	NECESSARY	92.00	92.00
1	TAILGATE SHUTTLE EMBLEM	NECESSARY	98.00	98.00
2	TAILGATE REFLECTORS	REUSE	421.00	-
1	TAILGATE WIPER MOTOR	REUSE	375.20	-
1	REAR WINDSCREEN MOULDING	NECESSARY	172.00	172.00
1	REAR BUMPER	DEFORMED	1,650.20	1,278.50
1	REAR BUMPER CENTRE BRACKET	BENT	211.00	211.00
2	REAR BUMPER SIDE RETAINERS @\$144.00	NECESSARY	288.00	288.00
2	REAR BUMPER REFLECTOR COVER	REFIX	98.00	-
2	RHS & LHS TAILLAMP INNER SIDE GRAZED	SERVICEABLE	1,357.00	-
1	REAR END PANEL	DISTORTED	762.00	762.00
1	REAR END PANEL TOP GARNISH	DEFORMED	261.00	187.00
1	REAR BOOT EDGE WEATHERSTRIP	DEFORMED	184.00	184.00
1	REAR SPARE TYRE PANEL TOOL BOX	DEFORMED	298.00	298.00
1	RHS CORNER TOOL TRAY	DEFORMED	142.00	142.00
2	TOOL BOX CORNER SPONGE	SERVICEABLE	42.00	-
2	RHS & LHS FENDER TRIMS @\$342.00	DEFORMED	684.00	670.00
1	REAR SPARE TYRE PANEL	DISTORTED	798.00	798.00
1	EXHAUST SILENCER	REFIX	782.00	-
	LESS 20% DISCOUNT		-4,497.50	-3,111.80
			17,990.00	12,447.20
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
1	FRONT NUMBER PLATE W/HOLDER (SN)	CRACKED	75.00	35.00
1	REAR NUMBER PLATE W/HOLDER (SN)	SERVICEABLE	75.00	-
1	RADIATOR COOLANT (SN)	NECESSARY	40.00	40.00
1	REVERSE CAMERA (SN)	SERVICEABLE	480.00	-
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	SET TAILGATE INNER TRIM CLIPS (SN)	NECESSARY	60.00	40.00
1	REAR SPARE TYRE PANEL SEALANT (SN) }	NECESSARY	100.00	100.00

Report Ref No. CS3/LPC17021158/R1vbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL SEALANT (SN) }	NECESSARY	100.00	-
			1,370.00	515.00
	LABOUR			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS (FRONT AND REAR).INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL (CENTRE),FRONT SUPPORT PANEL (RIGHT) AND FRONT SUPPORT PANEL (LEFT).		2,800.00	1,600.00
	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED (FRONT AND REAR).(INCLUDES-SUPPORT PANEL,REINFORCEMENT,SPARE TYRE PANEL).		2,000.00	1,400.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS AND FOCUS HEADLAMP BEAM.		250.00	60.00
	TO REMOVE AND REFIX/REPLACE REAR TRIMS,GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR PORTION.		200.00	80.00
	TO REMOVE AND REFIX REAR EXHAUST,REALIGN AND CHECK FOR SYSTEM FUNCTION.		250.00	60.00
	TO REMOVE AND REPLACE AIR CON CONDENSOR,VACUUM AND REFILL GAS.		120.00	80.00
	TO REMOVE AND REPLACE RADIATOR,PRESSURE TEST AND REFILL COOLANT.		100.00	60.00
	TO REMOVE AND REPLACE REVERSE SENSORS & CAMERA AND CHECK FOR PROPER FUNCTION.		140.00	60.00
	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN.		140.00	120.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.		240.00	120.00
			6,240.00	3,640.00
GRAND TOTAL			25,600.00	16,602.20

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,300.00
--	--	--	-----------

Report Ref No. CS3/LPC17021158/R1vbe2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.