



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKJ 9680U

| Qty                                | Description of Parts   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|---------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |  |               |                           |                   |
| 1                                  | FRONT BUMPER (WCP)   | BUCKLED       | 330.00                    | 330.00            |
| 1                                  | FRONT BUMPER REINFORCEMENT (WCP)                             | BENT          | 180.00                    | 180.00            |
| 2                                  | FRONT BUMPER RETAINER @\$13.00 (WCP)                         | N/S DISTORTED | 26.00                     | 13.00             |
| 1                                  | FRONT BUMPER SPONGE (WCP)                                    | TORN          | 50.00                     | 50.00             |
| 1                                  | FRONT BUMPER LOWER GRILLE (WCP)                              | DENTED        | 115.00                    | 115.00            |
| 1                                  | FRONT BUMPER EMBLEM (WCP)                                    | NECESSARY     | 18.00                     | 18.00             |
| 10                                 | FRONT BUMPER CLIPS @\$2.00 (WCP)                             | NECESSARY     | 20.00                     | 20.00             |
| 1                                  | FRONT SUPPORT PANEL (WCP)                                    | CRACKED       | 180.00                    | 180.00            |
| 1                                  | N/S HEADLAMP (WCP)   | MTG CRACKED   | 780.00                    | 780.00            |
| 1                                  | N/S HEADLAMP LOWER BRACKET (WCP)                             | DISTORTED     | 8.00                      | 8.00              |
| 1                                  | N/S FRONT FENDER (WCP)                                       | BUCKLED       | 140.00                    | 140.00            |
| 1                                  | BONNET (WCP)   | BUCKLED       | 320.00                    | 320.00            |
| 2                                  | BONNET TOP RUBBER SIDE @\$30.00 (WCP)                        | SERVICEABLE   | 60.00                     | -                 |
| 1                                  | BONNET TOP RUBBER CENTRE (WCP)                               | SERVICEABLE   | 25.00                     | -                 |
| 1                                  | BONNET INSULATOR (WCP)                                       | SERVICEABLE   | 90.00                     | -                 |
| 8                                  | BONNET INSULATOR CLIPS @\$2.00 (WCP)                         | NOT NECESSARY | 16.00                     | -                 |
| 1                                  | FRONT BUMPER GRILLE-LOWER (WCP)(ADDITIONAL)                  | CRACKED       | 90.00                     | 90.00             |
|                                    | COST PLUS 10%  |               | 244.80                    | 224.40            |
|                                    |  |               | 2,692.80                  | 2,468.40          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |  |               |                           |                   |
| 1                                  | FRONT NUMBER PLATE (SN)                                      | SERVICEABLE   | 40.00                     | -                 |
|                                    |  |               | 40.00                     | -                 |
| <b><u>LABOUR</u></b>               |  |               |                           |                   |
|                                    | TO PUTTY AND SPRAY PAINT.                                    |               | 800.00                    | 600.00            |
|                                    | TO REMOVE AND REFIT AIR-CON CONDENSER.VACUUM AND REFILL GAS. |               | 80.00                     | 80.00             |
|                                    | TO CHECK FRONT WIRE AND FOCUS HEADLAMP.                      |               | 30.00                     | 20.00             |
|                                    | LABOUR CHARGES.  |               | 650.00                    | 600.00            |
|                                    |  |               | 1,560.00                  | 1,300.00          |
| <b>GRAND TOTAL</b>                 |  |               | <b>4,292.80</b>           | <b>3,768.40</b>   |

Report Ref No. CS/ICS18000785/Ktd3n2



|                             |  |  |                 |
|-----------------------------|--|--|-----------------|
| RECOMMENDED COST OF REPAIRS |  |  | <b>3,768.40</b> |
| LESS EXCESS                 |  |  | <b>-750.00</b>  |
| NETT LIABILITY              |  |  | <b>3,018.40</b> |

Report Ref No. CS/ICS18000785/Ktd3n2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.