

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore (068811)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6338 7288 Fax : 6880 4838

DEAR SIR / MADAM :

*Not withstanding
1. B.1
Returning B4 pain*

ACCIDENT REPAIR ON: SKX208L

MODEL : BMW 318

POLICY NO : P1684166

CHASSIS NO : WBA8E36030NT38750

ENGINE NO : F3411196B38B15A

DATE / TIME OF ACCIDENT: 10/01/2018 Time: 2130Hrs ALONG FINLAYSON GREEN

THIRD PARTY VEHICLE NO: SHC5494P

Date: 15/01/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Boot Lid	1	1,175.00		<i>1</i> 1,175.00 X
2	Boot Lid Hinge LH	1	77.00		<i>1</i> 77.00 X
3	Boot Lid Hinge RH	1	77.00		<i>1</i> 77.00 X
4	Boot Lid Emblem	1	68.00		<i>1</i> 68.00 X
5	Boot Lid "318" Lettering	1	72.00		<i>1</i> 72.00 X
6	Boot Lid Lamp LH	1	270.00		<i>1</i> 270.00 X
7	Boot Lid Lamp RH	1	270.00		<i>1</i> 270.00 X
8	Rear Bumper	1	1,075.00		<i>1</i> 1,075.00 X
9	Rear Bumper Side Retainer LH	1	12.00		<i>1</i> 12.00 X
10	Rear Bumper Side Retainer RH	1	12.00		<i>1</i> 12.00 X
11	Rear Bumper Upper Centre Bracket	1	35.00		35.00 X
12	Rear Bumper Reinforcement	1	425.00		425.00 X
13	Rear Bumper Sponge	1			-
14	Rear Bumper Under Cover	1	65.00		<i>1</i> 65.00 X
15	Rear Bumper Tow Cover	1			-
16	Rear Bumper Sensor	1	235.00		235.00 X
17	Rear Bumper Sensor Ring	1	8.00		8.00 X
18	Rear Bumper Sensor Bracket	1	68.00		<i>1</i> 68.00 X
19	Rear Bumper Sensor Wiring Harness	1			-
20	Rear End Panel	1	595.00		<i>1</i> 595.00 X
21	Rear End Panel Garnish	1	81.00		<i>1</i> 81.00 X
22	Rear Tyre Panel	1	180.00		<i>1</i> 180.00 X
23	Front Bumper	1	960.00		960.00 X
24	Front Bumper Side Retainer LH	1	18.00		<i>1</i> 18.00 X
25	Front Bumper Side Retainer RH	1	18.00		<i>1</i> 18.00 X
26	Front Bumper Plate Garnish	1	68.00		<i>1</i> 68.00 X
27	Front Bumper Reinforcement	1	480.00		480.00 X
28	Front Bumper Sponge	1	53.00		53.00 X
Sub-Total:					6,397.00
Less 5% Discount					319.85
Total Parts:					6,077.15

Special Nett Items

1	Anti-rust coating	1	80.00	<i>1</i> 80.00 X
---	-------------------	---	-------	------------------

2	Rear Bumper Clips	10	3.50	nn 35.00
3	Front Bumper Clips	10	3.90	39.00
	Reverse Sensor	1	200.00	200.00
				354.00
Total Parts:				6,431.15

Labour Charges For Front Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	500	1,500.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	660	1,200.00
3	Provide skill labour to disconnect and check electrical wiring	30	60.00
4	Provide skill labour to check and re-adjust wheel alignment	nn	70.00 X
5	Provide skill labour to remove and replace wheel rim and tyre with balancing	nn	80.00 X
6	Provide skill labour to dismantle and transfer door fittings and mechanism to facilitate repair	nn	80.00 X
7	Remove and refit rear end panel lining and garnish to facilitate repair	nn	100.00 X
8	Remove and replace bumper sensors		100.00
Total Labour:			
			2,980.00
			9,421.15
			659.48
			10,080.63

Total Parts & Labour:

GST 7%

Grand Total:

Estimate Repair Duration

4 days **8 days**

ACCIDENT VEHICLE OF : SKX208L

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : Kenneth

Company : LKK

Date : 18/11/18

Time : 10.45am

Contact No : 96910663

Email : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification, cut & weld
- Supplementary estimate must be approved and is subject to final approval from insurance company

Acknowledged by Repairer:

Signature:

Date: