2/26/2018 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000822/KVD3N2

26/02/2018 Date:

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B80221537SMP

Claimant Vehicle SJH4215K Insured Vehicle No: SJS3788Y No:

Nature of Claim: Date of Loss: 10/01/2018 TP Claim No: 546008

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJH4215K Reg No:

Make & Model: HONDA STREAM, 1.7 (A) Engine No: R18A12803143 06/08/2008 (Man. Year: 2008) Chassis No: JHMRN68408S203158 Reg. Date:

Colour: Odometer: 137693 km

1799 cc **Engine Capacity:** Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: Nο

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16 Front Left Side: Continental 8 mm Rear Left Side: Continental 7 mm Front Right Side: Continental 8 mm Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,530.00	1,643.04	886.96	35.06
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,580.00	930.00	650.00	41.14
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,110.00	2,573.04	1,536.96	37.40
	Approved Total (Overridden) (S\$)		2,000.00		
	Nett Amount (S\$)	4,110.00	2,000.00	2,110.00	51.34

INSPECTION

Date of Assignment: 15/01/2018

V8 Motor Werkz Pte Ltd (HQ) Date Inspected: 15/01/2018 Inspected At:

BLK 8 #01-44 SIN MING IND EST SECTOR C

Singapore 575630

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

2/26/2018 Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Feb 2018)

Parts: M1-MPV HONDA STREAM 1.7 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: LKK Auto Consultants Pte Ltd/SJH4215K/26/02/2018 16:43

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	610.00 F	*610.00 FL
2	1		*REAR TAIL LAMP	Cracked	420.00 F	*420.00 FL
3	1		*BUMPER SIDE BRACKET	Distorted	120.00 F	*120.00 FL
4	1		*REAR BOOT	Bent	960.00 F	*903.80 FL
5	1		*SET REVERSE SENSOR	Serviceable	420.00 FS	*-FS
F=Fra	nchise	part. S=SpcNett.	L=ListItemDisc.			
				Sub Total (S\$)	2,530.00	2,053.80
			- List Item Discount o	n L Items 0.00/20.00% (S\$)	0.00	410.76
				Total Parts (S\$)	2,530.00	1,643.04

LKK Auto Consultants Pte Ltd/SJH4215K/26/02/2018 16:43. Not valid without Reference section.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO DISMANTLE AND REFIT THE BOOT, TAIL LAMP, BUMPER	New	300.00	300.00
2	TO TOWING	New	80.00	-
3	TO PUTTY AND SPRAY PAINT ON REAR BOOT, BUMPER	New	900.00	600.00
4	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	300.00	30.00
	Gross Labour Cost (S\$)		1,580.00	930.00

LKK Auto Consultants Pte Ltd/SJH4215K/26/02/2018 16:43. Not valid without Reference section. < END OF ESTIMATES >