

Meimen Rasul

ASSIGNMENT (Office)

From (Person): Jasmine Lick

of MSG1

Date/Time: 15/11/18 @ 11:50am

Estimated Cost:

Bill to:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XE1390G

Insured: YN804C

at Workshop in: Sng Ah Tee

Tel: 6268 6183

of B1K3, Pioneer Rd North # 01-18

Policy No: A28789287MKC

Claim No: 521879

Sum Insured:

Excess:

Make of Veh:

D.O.A. 04/07/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

R.O.D. Reference:

Date/Time: 12/11/18 @ 5:00pm

Person Contacted: Samantha

Vehicle: OUT

Date/Time: Action/Instructions ✓

XE1390G-X

YN804C-X

lump sum \$12,000. (Red. 636.75, 35%)






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18000824/R1td3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 15-01-2018	
		Code : CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	YN 804C	Veh. Inspected	XE 1390G
Policy No.	A28789287MKC	Coverage (\$)	0.00
Claim No.	521879	Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LIE)	Assign Date	15/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	04/07/2017	Inspection Date	15/01/2018
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jan 2018 13:36 <a href="#">Sendback Est</a>	12 Jan 2018 16:27 <b>S\$18,636.75</b>	15 Jan 2018 11:50 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	N/A, ID: N/A		
Main Claimant:	CHYE JOO CONSTRUCTION PTE LTD, Co. Reg. No.: 198800808K		
Vehicle Reg. No.:	XE1390G	Date of Loss:	04/07/2017 12:00 - :59
Claim Type:	TP / 521879	Policy/Cover Note No.:	A28789287MKC (TP, Fire & Theft) Coverage: 21/08/2016 - 20/08/2017
Vehicle Reg. No. (Insured):	YN804C	Policy No. (Claimant):	P1881926
		Excess:	
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lie]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/01/2018]		
Adj Asg. Remarks:	ON WP		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

## Denise Tay (LKKAUTO)

---

**From:** Sharon Sng <sharon@sngahtee.com>  
**Sent:** Wednesday, 31 October 2018 10:16 AM  
**To:** Denise Tay (LKKAUTO); Rasul (LKKAUTO)  
**Subject:** RE: XE1390G - FINALISE & AFTER PAINT

Hi all

confirm. pls submit.  
thanks.

Best Regards

---

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457  
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



---

**From:** Denise Tay (LKKAUTO) <denisetay@lkkauto.com>  
**Sent:** Tuesday, October 30, 2018 2:10 PM  
**To:** Rasul (LKKAUTO) <Rasul@lkkauto.com>; Sharon Sng <sharon@sngahtee.com>  
**Subject:** RE: XE1390G - FINALISE & AFTER PAINT

Dear Sharon,

Confirm?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Rasul (LKKAUTO)  
**Sent:** Thursday, 18 October 2018 10:35 AM  
**To:** Sharon Sng <sharon@sngahtee.com>  
**Cc:** Denise Tay (LKKAUTO) <denisetay@lkkauto.com>  
**Subject:** RE: XE1390G - FINALISE & AFTER PAINT

Hi Sharon,

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/07/2017 10:32
Date Of Accident	04/07/2017 12:15
Exact Location Of Accident	JALAN BAHAR FLYOVER TO TUAS
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE1390G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHYE JOO CONSTRUCTION PTE LTD
Co Reg No	198800808K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94514756
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	IVECO
Model	TRAKKER-12.9 D AT260T41 (EURO V) (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1881926
Cover Note Number	

### Driver

Name of Driver	NEHAL RUPINDER SINGH
Passport No/FIN	G8329684X
Date Of Birth	08/07/1986
Occupation	OUTDOOR
Date Of Driving Pass	09/02/2015
Driving Experience	2 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91365252
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address  
 Postcode  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

ON 04/07/2017 AT AROUND 1215HRS, I WAS TRAVELLING ALONG PIE TO TUAS AT JALAN BAHAR FLYOVER. WHILE DRIVING, SUDDENLY VEHICLE B CUT INTO MY LANE AND AND COLLIDED ONTO MY FRONT LEFT PORTION.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN804C  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver CHOO CHIANG HONG  
 NRIC/Passport Number S7523303E  
 Contact Number 97966654  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

#### Details of Witness

Name  
 Phone Number  
 Email Address



## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of thereport being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that :
  - (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involvedisclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

#### Sketch Plan

Alan Bahau  
Flyover





Sketch Plan Pg. 2

Describe Circumstances of the Accident

Refer to Accident Circumstances

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

<input type="checkbox"/> Claim own policy
<input checked="" type="checkbox"/> Claim third party
<input type="checkbox"/> Claim OD / TP at other workshop
<input type="checkbox"/> For record purpose
Policy No. <u>D1881976</u>
Insurer <u>AA</u> Veh. No. <u>XET370A</u>

Witnessed by Reporting Centre Personnel

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0808K
Vehicle Details	
Vehicle No.:	XE1390G
Vehicle to be Exported:	No
Intended De-registration Date:	31 Jan 2018
Vehicle Make:	IVECO
Vehicle Model:	TRAKKER AUTO AT260T41 (MY2013, EURO V)
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	F3BE3681DS451222149
Chassis No.:	WJME2NSS40C286054
Maximum Power Output:	-
Open Market Value:	\$123,291.00
Original Registration Date:	25 Jan 2016
First Registration Date:	25 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$6,165.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jan 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$5,262.00
COE Rebate Amount:	\$4,199.00
<b>Total Rebate Amount:</b>	<b>\$4,199.00</b>

The information contained herein is correct as at 11 Jan 2018

OK

**Sng Ah Tee Motor & Panel Service Pte Ltd** (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

**TP INSURER:** **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

N/A

N/A

Singapore

**Claimant Insurer:** **AXA Insurance Pte Ltd****PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	A28789287MKC	Date of Loss:	04/07/2017
Vehicle Reg. No.:	XE1390G	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	NEHAL RUPINDER SINGH		
Make/Model:	IVECO TRAKKER, 12.9 D AT260T41 (EURO V) (A)	Vehicle Reg. Date:	25/01/2016
Vehicle Colour:	WHITE	Chassis No:	WJME2NSS40C286054
Engine No:	F3BE3681DS451222149		
Odometer:	5 KM		
Paint Type:			
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	ON 04/07/2017 AT AROUND 1215HRS, I WAS TRAVELLING ALONG PIE TO TUAS AT JALAN BAHAR FLYOVER. WHILE DRIVING, SUDDENLY VEHICLE B CUT INTO MY LANE AND AND COLLIDED ONTO MY FRONT LEFT PORTION.		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	16,956.75
Miscellaneous Items	0.00
Labour	1,680.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>18,636.75</b>
<b>+ GST 7.00% (S\$)</b>	<b>1,304.57</b>
<b>Nett Amount (S\$)</b>	<b>19,941.32</b>

**This claim is handled by: SAMANTHA TAN YONG SING**

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

# REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 12 Jan 2018)  
 Parts: N/A IVECO TRAKKER 12.9 D AT260T41 (EURO V) (A) (Model not available in database)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/XE1390G/12/01/2018 16:27  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER (CENTER)	0.00	0.00	BT 1,450.00 F
2	1		*FRT BUMPER (LH)	0.00	0.00	BT 1,288.00 F
3	1		*FRT HEADLAMP LH	0.00	0.00	CRA 1,350.00 F
4	1		*FRT HEADLAMP OUTER GRILLE LH	0.00	0.00	BT 285.00 F
5	1		*FRT HEADLAMP BRACKET LH	0.00	0.00	CRA 364.50 F
6	1		*FRT HEADLAMP BRACKET COVER LH	0.00	0.00	MIS 230.00 F
7	1		*FRT SIGNAL LAMP LH	0.00	0.00	PRO 120.00 F
8	1		*FRT SIDE LAMP LH	0.00	0.00	PRO 75.00 F
9	1		*FRT CORNER PANEL TOP LH	0.00	0.00	MIS 2,580.00 F
10	1		*FRT CORNER PANEL RUBBER SEAL	0.00	0.00	MIS 102.50 F
11	1		*FRT SIDE MIRROR ASSY LH	0.00	0.00	PRO 1,150.00 F
12	1		*FRT STEP GARNISH (TOP)	0.00	0.00	MIS 1,050.00 F
13	1		*FRT STEP GARNISH PLATE (TOP)	0.00	0.00	MIS 150.00 F
14	1		*FRT STEP GARNISH PLATE (CENTER)	0.00	0.00	CRA 955.00 F
15	1		*FRT STEP GARNISH PLATE (LOWER)	0.00	0.00	Cut 405.00 F
16	1		*FRT WHEEL ARCH LH	0.00	0.00	1,400.00 F
17	1		*FRT DOOR TRAKKER LOGO LH	0.00	0.00	MIS 85.00 F
18	1		*FRT DOOR 410ES LOGO LH	0.00	0.00	MIS 105.00 F
19	1		*FRT DOOR LH	0.00	0.00	R 1,600.00 F
Sub Total (S\$)						14,745.00
+ Margin on L,N Items 15.00% (S\$)						2,211.75
Total Parts (S\$)						16,956.75

F=Franchise part.

Sng Ah Tee Motor & Panel Service Pte Ltd/XE1390G/12/01/2018 16:27. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING	New	30.00
2	TO APPLY ANTI RUST COATING	New	150.00
3	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	800.00
4	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	780.00
Gross Labour Cost (S\$)			1,680.00

Sng Ah Tee Motor & Panel Service Pte Ltd/XE1390G/12/01/2018 16:27. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

total \$12025 net  
OK? PLS confirm.  
Thanks. 27/4/2018

RASUL  
Hp 900/10068

7 days

4s or p/p?

12/01/18 @ 1810

Reg after or b/p paint

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

acknowledged by Repairer

Signature:

Date:

# REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 12 Jan 2018)  
 Parts: N/A IVECO TRAKKER 12.9 D AT260T41 (EURO V) (A) (Model not available in database)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/XE1390G/12/01/2018 16:27  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER (CENTER)	0.00	0.00	BT 1,450.00 F
2	1		*FRT BUMPER (LH)	0.00	0.00	BT 1,288.00 F
3	1		*FRT HEADLAMP LH	0.00	0.00	CRA 1,350.00 F
4	1		*FRT HEADLAMP OUTER GRILLE LH	0.00	0.00	TA 285.00 F
5	1		*FRT HEADLAMP BRACKET LH	0.00	0.00	CRA 364.50 F
6	1		*FRT HEADLAMP BRACKET COVER LH	0.00	0.00	MIS 230.00 F
7	1		*FRT SIGNAL LAMP LH	0.00	0.00	PRO 120.00 F
8	1		*FRT SIDE LAMP LH	0.00	0.00	PRO 75.00 F
9	1		*FRT CORNER PANEL TOP LH	0.00	0.00	MIS 2,580.00 F
10	1		*FRT CORNER PANEL RUBBER SEAL	0.00	0.00	NA 102.50 F
11	1		*FRT SIDE MIRROR ASSY LH	0.00	0.00	PRO 1,150.00 F
12	1		*FRT STEP GARNISH (TOP)	0.00	0.00	PRO 1,050.00 F
13	1		*FRT STEP GARNISH PLATE (TOP)	0.00	0.00	MIS 150.00 F
14	1		*FRT STEP GARNISH PLATE (CENTER)	0.00	0.00	CRA 955.00 F
15	1		*FRT STEP GARNISH PLATE (LOWER)	0.00	0.00	CRA 405.00 F
16	1		*FRT WHEEL ARCH LH	0.00	0.00	7 1,400.00 F
17	1		*FRT DOOR TRAKKER LOGO LH	0.00	0.00	NA 85.00 F
18	1		*FRT DOOR 410ES LOGO LH	0.00	0.00	NA 105.00 F
19	1		*FRT DOOR LH	0.00	0.00	R 1,600.00 F

F=Franchise part.

Sub Total (\$\$) 14,745.00  
 + Margin on L,N Items 15.00% (\$\$) 2,211.75  
 Total Parts (\$\$) 16,956.75

Sng Ah Tee Motor & Panel Service Pte Ltd/XE1390G/12/01/2018 16:27. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING	New	30.00
2	TO APPLY ANTI RUST COATING	New	150.00
3	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	800.00
4	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	700.00
Gross Labour Cost (S\$)			1,680.00

Sng Ah Tee Motor & Panel Service Pte Ltd/XE1390G/12/01/2018 16:27. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

RASUL

Hp 900/100 t8

7 days

4s or p/p ?

12/01/18 @ 1810

Reg after or b/p paint

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting





## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jan 2018 13:36 <a href="#">Sendback Est</a>	12 Jan 2018 16:27 <b>S\$18,636.75</b>	15 Jan 2018 11:50 <a href="#">Edit Adj Rpt</a>	<b>S\$12,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$12,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS

Insured:	SOLEX LOGISTICS (SINGAPORE) PTE LTD, Co. Reg. No.: 199701597H			
Main Claimant:	CHYE JOO CONSTRUCTION PTE LTD, Co. Reg. No.: 198800808K			
Vehicle Reg. No.:	XE1390G	Date of Loss:	04/07/2017 12:00 - :59 [17 Months and 9 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 521879	Policy/Cover Note No.:	A28789287MKC (TP, Fire & Theft) Coverage: 21/08/2016 - 20/08/2017	
Vehicle Reg. No. (Insured):	YN804C	Policy No. (Claimant):	P1881926	
		Excess:		
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]			
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 16/01/2018]			
Adj Asg. Remarks:	ON WP			

[View All](#)   [Compose Case Mail](#)

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

### ALL ASSOCIATED TASKS View All   Search Tasks   Create New Task   Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

XE1390G (521879)

[YN804C]

TP

CHYE JOO CONSTRUCTION PTE LTD

Jul 4 2017 12:00PM

[SOLEX LOGISTICS (SINGAPORE) PTE LTD]

Sng Ah Tee Motor & Panel Service Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

### Assessment Reports

1 per page ☒












































No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	05/07/17 17:01	<b>Accident Statement</b>	Load HTM	<input checked="" type="checkbox"/>
2	12/01/18 16:27	<b>Repairer Estimates</b>	Load HTM	<input checked="" type="checkbox"/>

### Photos/Images

3 per page ☒

No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	05/07/17 16:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	05/07/17 16:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	05/07/17 16:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	05/07/17 16:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	05/07/17 16:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	05/07/17 16:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	05/07/17 16:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	05/07/17 16:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	05/07/17 16:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	05/07/17 16:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	05/07/17 16:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	05/07/17 16:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	05/07/17 16:56	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/10/18 10:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	31/10/18 10:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	31/10/18 10:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	31/10/18 10:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	31/10/18 10:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	31/10/18 10:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	31/10/18 10:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	31/10/18 10:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	31/10/18 10:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	31/10/18 10:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	31/10/18 10:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	31/10/18 10:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	31/10/18 10:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
14	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
15	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
16	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
17	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
18	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
19	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
20	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
21	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
22	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
23	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
24	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
25	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
26	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
27	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
28	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
29	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
30	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
31	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
32	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
33	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
34	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
35	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
36	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
37	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
38	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
39	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
40	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
41	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
42	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
43	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
44	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
45	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
46	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
47	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
48	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
49	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
50	31/10/18 10:25	General View	 Load JPG	<input checked="" type="checkbox"/>
51	31/10/18 10:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	31/10/18 10:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	31/10/18 10:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	05/07/17 17:01	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	12/01/18 16:28	CI,IC,DL	 Load TIF	
3	12/01/18 16:28	E-filed GIA report	 Load PDF	

## Linked Accident Report Documents

			View	View in Browser
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	05/07/17 17:01	<b>Accident Statement</b>	Load HTM	
			3 per page	<input checked="" type="checkbox"/>
<b>Photos/Images</b>				
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	05/07/17 16:56	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
2	05/07/17 16:56	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
3	05/07/17 16:56	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
4	05/07/17 16:56	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
5	05/07/17 16:56	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
6	05/07/17 16:56	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
7	05/07/17 16:56	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
8	05/07/17 16:56	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
9	05/07/17 16:56	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
10	05/07/17 16:56	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
11	05/07/17 16:56	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
12	05/07/17 16:56	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
13	05/07/17 16:56	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
			1 per page	<input checked="" type="checkbox"/>
<b>Documentation</b>				
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	05/07/17 17:01	<b>Sketch Plan</b>	Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>				
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer				
Note: Remarks are private unless you show it to other parties.				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000824/R1TD3S2

Date: 05/11/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28789287MKC

Claimant Vehicle No: XE1390G

Insured Vehicle No: YN804C

Date of Loss: 04/07/2017

Nature of Claim: TP

Claim No: 521879

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: XE1390G

Make &amp; Model: IVECO TRAKKER, 12.9 D AT260T41 (EURO V) (A)

Engine No: F3BE3681DS451222149

Reg. Date: 25/01/2016 (Man. Year: 2013)

Chassis No: WJME2NSS40C286054

Colour: White

Odometer: 216308 km

Engine Capacity: 12882 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5

Rear Tyre Size: 315/80 R22.5 (D)

Front Left Side: Firemax 8 mm

Rear Left Side: Firemax 8/8 mm

Front Right Side: Firemax 8 mm

Rear Right Side: Firemax 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,956.75	10,695.00	6,261.75	36.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,330.00	350.00	20.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,636.75</b>	<b>12,025.00</b>	<b>6,611.75</b>	<b>35.48</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>12,000.00</b>		
<b>(S\$)</b>	18,636.75	12,000.00	6,636.75	35.61
<b>+ GST 7.00/7.00% (S\$)</b>	1,304.57	840.00	464.57	35.61
<b>Nett Amount (S\$)</b>	<b>19,941.32</b>	<b>12,840.00</b>	<b>7,101.32</b>	<b>35.61</b>

## INSPECTION

Date of Assignment: 15/01/2018

Date Inspected: 12/01/2018 Inspected At:

Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)  
Blk 3 Pioneer Road North, #01-18  
Singapore 628457

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

[https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\\_printpt&caseid=674303&extid=261899&CFID=43377494&C...](https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printpt&caseid=674303&extid=261899&CFID=43377494&C...) 1/4



*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 05 Nov 2018)

Parts: N/A IVECO TRAKKER 12.9 D AT260T41 (EURO V) (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XE1390G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (CENTER) (WCP)	Bent	1,450.00 F	*1,450.00 F
2	1		*FRT BUMPER (LH) (WCP)	Bent	1,288.00 F	*1,288.00 F
3	1		*FRT HEADLAMP LH (WCP)	Cracked	1,350.00 F	*1,350.00 F
4	1		*FRT HEADLAMP OUTER GRILLE LH (WCP)	Bent	285.00 F	*285.00 F
5	1		*FRT HEADLAMP BRACKET LH (WCP)	Cracked	364.50 F	*364.50 F
6	1		*FRT HEADLAMP BRACKET COVER LH (WCP)	Missing	230.00 F	*230.00 F
7	1		*FRT SIGNAL LAMP LH (WCP)	Broken	120.00 F	*120.00 F
8	1		*FRT SIDE LAMP LH (WCP)	Broken	75.00 F	*75.00 F
9	1		*FRT CORNER PANEL TOP LH (WCP)	Missing	2,580.00 F	*2,580.00 F
10	1		*FRT CORNER PANEL RUBBER SEAL (WCP)	Necessary	102.50 F	*102.50 F
11	1		*FRT SIDE MIRROR ASSY LH (WCP)	Broken	1,150.00 F	*1,150.00 F
12	1		*FRT STEP GARNISH (TOP) (WCP)	Serviceable	1,050.00 F	*- F
13	1		*FRT STEP GARNISH PLATE (TOP) (WCP)	Missing	150.00 F	*150.00 F
14	1		*FRT STEP GARNISH PLATE (CENTER) (WCP)	Cracked	955.00 F	*955.00 F
15	1		*FRT STEP GARNISH PLATE (LOWER) (WCP)	Cut	405.00 F	*405.00 F
16	1		*FRT WHEEL ARCH LH (WCP)	Serviceable	1,400.00 F	*- F
17	1		*FRT DOOR TRAKKER LOGO LH (WCP)	Necessary	85.00 F	*85.00 F
18	1		*FRT DOOR 410ES LOGO LH (WCP)	Necessary	105.00 F	*105.00 F
19	1		*FRT DOOR LH (WCP)	Repair	1,600.00 F	*- F

F=Franchise part.

<b>Sub Total (\$)</b>	<b>14,745.00</b>	<b>10,695.00</b>
<b>+ Margin on L,N Items 15.00/0.00% (\$)</b>	<b>2,211.75</b>	<b>0.00</b>
<b>Total Parts (\$)</b>	<b>16,956.75</b>	<b>10,695.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	30.00	30.00
2	TO APPLY ANTI RUST COATING	New	150.00	100.00
3	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	800.00	600.00
4	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	700.00	600.00
Gross Labour Cost (S\$)			1,680.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >