

ANF REC BY:

REF:

CS3 / SPF 18000833 / Wrb

Special Instruction:

Surveyor

Wilson

ASSIGNMENT (Office)

From (Person):

Abdul Rahman

of

SPF

Date/Time: 15/01/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No:

SKE 8227D

Insured:

Ym 4733C

at Workshop m/s

Huaf Hock motor

Tel:

8161 6788

of

Blk 302 Bedok Ind Park E #01-2054

Policy No:

Claim No:

AEMD / 105 / 009 / 2018 / 002.

Sum Insured

Excess:

Make of Veh:

D.O.A.

12.01.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

15/01/2018 134pm

Person Contacted:

David

Vehicle:

IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SKE 8227D - 006 / A16 15019457 / T1wb3g2
	Ym 8733C - X
	Dismantle photo 16 / 1 / 18
	After repair 17 / 1 / 18

DA: 15-11-15



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS3/SPF18000832/Wrb

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMY SINGAPORE 298333

Date : 15-01-2018



Code : SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YM 4733C	Veh. Inspected	SKE 8227D
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/002	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	15/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	12/01/2018	Inspection Date	15/01/2018
Survey held at	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SKE8227D

Our Ref : AEMD/105/009/2018/002

Date : 15 January 2018

Tel: 64784840

Fax: 64784848

Messrs LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

ACCIDENT ON 12 JANUARY 2018 INVOLVING GOVT VEHICLE YM4733C AND OTHER VEHICLE SKE8227D

We refer to the above matter.

- 2 Please arrange for an inspection of vehicle no. **SKE8227D** at **Messrs Huat Hock Motor Workshop of Blk 3012 Bedok Industrial Park E #01-2054, Singapore 489978.**
- 3 For appointment kindly contact **Mr David Mong** at **Tel: 64452934 / 81616988.**
- 4 Estimates were not provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for Assistant Director

cc : Messrs C Ramesh Law Practice

via Fax: 62913716 - (FYI, pls)

A FORCE FOR THE NATION

Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing
(13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (RH)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

Aug 2005

Vehicle No: **SKG 8227D**

Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door	BP30	BUC	
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror	780	NT	
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding	NEC		28
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber	150	DIS	
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender	389	BUC	
1107	991744	Frt RH Fender Lamp Inner Shield	DIS		108
1108	991752	Frt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door	DD	R	
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			

***Note: See attached for Labour.**

No of Items: _____

Assessor: _____

26/3/2018

Labour :

**Veh. No.
SKE8227D**

- | | |
|---|-------|
| 1) Replacing accident damaged parts, knock/jack & straighten accident affected areas. | \$500 |
| 2) Spray painting accident affected areas. | \$680 |
| 3) Carry out body cavity preservation on accident affected areas. | \$60 |
| 4) Checking electrical wiring & lighting system for proper function. | \$30 |
| 5) Transferring front RH door attachments to new door. | \$60 |


26/3/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref: CS3/SPF18000832/Wrbs2

ACCIDENT CLAIM SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMY SINGAPORE 298333

Date: 03-04-2018



ATTN: ABDUL RAHMAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YM 4733C	Veh. Inspected	SKE 8227D
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/002	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	15/01/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	MR053REE104132850	Colour	BLACK
Odometer	107644 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	BRIDGESTONE	3 mm
L/H Front Tyre	205/55R16	BRIDGESTONE	3 mm
R/H Rear Tyre	205/55R16	BRIDGESTONE	4 mm
L/H Rear Tyre	205/55R16	BRIDGESTONE	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/01/2018	Inspect Date / Time	15/01/2018 (10:18 AM)
Survey held at	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SKE 8227D

Qty	Description of Parts	Condition	Recommended (\$)
	REPLACEMENT OF PARTS		
1	FRT RH DOOR	BUCKLED	830.00
1	FRT RH DOOR WING MIRROR	CUT	750.00
1	FRT RH DOOR GLASS OUTER MOULDING	NECESSARY	128.00
1	FRT RH DOOR RUBBER	DISTORTED	150.00
1	FRT RH FENDER	BUCKLED	389.00
1	FRT RH FENDER INNER SHIELD	DISTORTED	186.00
1	REAR RH DOOR	TO REPAIR SEE LABOUR	-
	LESS 25% DISCOUNT		-608.25
			1,824.75
	LABOUR		
	REPLACING ACCIDENT DAMAGED PARTS, KNOCK / JACK & STRAIGHTEN ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR RH DOOR.		500.00
	SPRAY PAINTING ACCIDENT AFFECTED AREAS.		680.00
	CARRY OUT BODY CAVITY PRESERVATION ON ACCIDENT AFFECTED AREAS.		60.00
	CHECKING ELECTRICAL WIRING & LIGHTING SYSTEM FOR PROPER FUNCTION.		30.00
	TRANSFERRING FRONT RH DOOR ATTACHMENTS TO NEW DOOR.		60.00
			1,330.00
	GRAND TOTAL		3,154.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,500.00

Report Ref No. CS3/SPF18000832/Wrbs2

WILSON TEO CHENG MING

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.