



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2009 AUDI A6 2.0 T (SJU2026J)

Date of Loss

11 January 2018

Time of Loss

11.30

Loss Description

SJU2026J (INSD) C/W SJV8609H (TP)

Comment

Workshop Details

Total Rebate Amount

28457

Nett Loss Amount

\$14,543.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

15/05/2018



Days of work completion *

109



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SJU2026J

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

23/10/2009



Mileage

71648

Age of Vehicle

8

CATEGORY

Manufacturing Year

POLICY INFORMAT...

2009

ASSESSMENT INFO...

2009

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

ZHANG YU

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... AUDI

ASSESSMENT INFO...

CATEGORY Model

POLICY INFORMAT... A6 2.0 T

ASSESSMENT INFO...

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WAUZZZ4F3AN010667

CATEGORY Date of Birth

FNOL INFORMATI... 20 February 1981

POST SURVEY INF... 

CATEGORY Age

FNOL INFORMATI... 37

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

FNOL INFORMATI... 8

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... BPJ159386

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... 25 AKYAB ROAD, 309979, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Residential

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Married

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S8184711H

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

15/01/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

255/35R19

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

255/35R19

Front left side

PIRELLI6mm

Front right side

PIRELLI6mm

Rear left side

PIRELLI6mm

Rear right side

PIRELLI6mm



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART:
		1	1			FRONT BONNET			Damaged	1650				1650	Review
		2	1			FRONT BONNET HINGE - LH			Serviceable	0	0	0	0	0	Deny
		3	1			FRONT BONNET HINGE - RH			Serviceable	0	0	0	0	0	Deny
		4	1			FRONT BONNET ABSORBER - RH			Serviceable	0	0	0	0	0	Deny
		5	1			FRONT BONNET TOP HOOK - CENTRE			Serviceable	0	0	0	0	0	Deny
		6	1			FRONT BONNET BOTTOM LOCK - CENTRE			Damaged	80				80	Review
		7	1			FRONT BONNET INSULATOR			Serviceable	0	0	0	0	0	Deny
		8	15			FRONT BONNET INSULATOR CLIP			Necessary	1.5				22.5	Review
		9	1			FRONT BUMPER			Damaged	900				900	Review
		10	10			FRONT BUMPER CLIPS			Necessary	0.3				3	Review
		11	1			FRONT BUMPER SIDE HOLDER - LH			Necessary	18				18	Review
		12	1			FRONT BUMPER SIDE HOLDER - RH			Necessary	18				18	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART)
<input type="checkbox"/>		13	1			FRONT BUMPER REINFORCEMENT			Bent	265				265	Review
<input type="checkbox"/>		14	1			FRONT BUMPER BRACKET - LH			Damaged	75				75	Review
<input type="checkbox"/>		15	1			FRONT BUMPER BRACKET - RH			Damaged	75				75	Review
<input type="checkbox"/>		16	1			FRONT BUMPER TOW COVER - RH			Deformed	18				18	Review
<input type="checkbox"/>		17	1			FRONT BUMPER FOG LAMP CHROME W/COVER - LH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		18	1			FRONT BUMPER FOG LAMP CHROME W/COVER - RH			Damaged	85				85	Review
<input type="checkbox"/>		19	1			FRONT BUMPER FOG LAMP UNIT - LH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		20	1			FRONT BUMPER FOG LAMP UNIT - RH			Cracked	95				95	Review
<input type="checkbox"/>		21	1			FRONT BUMPER NOZZLE COVER - LH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		22	1			FRONT BUMPER NOZZLE COVER - RH			Damaged	25				25	Review
<input type="checkbox"/>		23	1			FRONT BUMPER NOZZLE - LH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		24	1			FRONT BUMPER NOZZLE - RH			Cracked	100				100	Review
<input type="checkbox"/>		25	1			FRONT BUMPER LOWER LIP - CENTRE			Damaged	150				150	Review

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
	26	1			FRONT BUMPER UNDER LOWER GARNISH			Damaged	300				300	Review
	27	1			FRONT FENDER - RH			Damaged	440				440	Review
	28	1			FRONT FENDER COWLING, REAR - RH			Serviceable	0	0	0	0	0	Deny
	29	1			FRONT FENDER COWLING, FRONT - RH			Deformed	15				15	Review
	30	20			FRONT FENDER CLIP			Serviceable	0	0	0	0	0	Deny
	31	1			FRONT NUMBER PLATE GARNISH			Damaged	65				65	Review
	32	1			GRILLE ASSY			Damaged	275				275	Review
	33	1			GRILLE LOGO			Serviceable	0	0	0	0	0	Deny
	34	1			POWER STEERING COOLER PIPE			Bent	220				220	Review
	35	1			SUPPORT PANEL			Cracked	320				320	Review
	36	1			RADIATOR			Damaged	350				350	Review
	37	1			RADIATOR, SMALL - RH FRONT			Serviceable	0	0	0	0	0	Deny
	38	1			CONDENSER			Bent	350				350	Review
	39	1			AIRCON CONDENSER SIDE GARNISH - LH			Deformed	15				15	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART)
<input type="checkbox"/>		40	1			AIRCON CONDENSER SIDE GARNISH - RH			Cracked	15				15	Review
<input type="checkbox"/>		41	1			AIRCON FAN MOTOR W/FAN BLADE			Damaged	360				360	Review
<input type="checkbox"/>		42	1			AIRCON FAN COWLING			Cracked	220				220	Review
<input type="checkbox"/>		43	1			RADIATOR FAN MOTOR, FAN BLADE & FAN COWLING			Damaged	320				320	Review
<input type="checkbox"/>		44	1			HEAD LAMP - RH			Cracked	1100				1100	Review
<input type="checkbox"/>		45	1			HEAD LAMP LOWER RETAINER - RH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		46	1			HEAD LAMP - LH			Cracked	1100				1100	Review
<input type="checkbox"/>		47	1			HEAD LAMP LOWER RETAINER - LH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		48	1			POWER STEERING COOLER PIPE			Bent	460				460	Review
<input type="checkbox"/>		49	1			RADIATOR TOP HOSE			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		50	1			RADIATOR BOTTOM HOSE			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		51	1			RADIATOR SPARE TANK			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		52	1			WIPER TANK ASSY			Serviceable	0	0	0	0	0	Deny

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PART)
	53	1			CHARCOAL TANK (PULSATION DAMAGE)			Serviceable	0	0	0	0	0	Deny
	54	1			CHARCOAL TANK BRACKET			Serviceable	0	0	0	0	0	Deny
	55	1			HEAD LAMP CONTROL UNIT - RH			Damaged	500				500	Review
	56	1			HEAD LAMP HID BULB - RH			Damaged	240				240	Review
	57	1			HEAD LAMP CONTROL UNIT - LH			Serviceable	0	0	0	0	0	Deny
	58	1			HEAD LAMP HID BULB - LH			Serviceable	0	0	0	0	0	Deny
	59	1			RADIATOR TOP HOSE (AMENDED)			Necessary	30				30	Review

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	R
	1		TO KNOCK OUT DENTS, RHF CHASSIS, CUT/WELD, SUPPORT PANEL, REMOVE & REPLACE ACCIDENT PARTS	1000	0	0	Reviewing		1
	2		TO RESPRAY PAINT ON ACCIDENT PORTIONS	900	0	0	Reviewing		1
	3		TO 4 WHEEL ALIGNMENT	0	0	0	Deny		1
	4		TO CHECK WIRING	20	0	0	Reviewing		1
	5		TO REMOVE, REPLACE CONDENSER AND REFILL GAS	100	0	0	Reviewing		1

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	R
		6		TO RESET ENGINE LIGHT	0	0	0	Deny		
		7		TO REMOVE, REPLACE POWER STEERING COOLER PIPE, CHARCOAL TANK, BRACKET AND RELATED PARTS	150	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	COOLANT	Reviewing	20	NECESSARY	
	2	FRONT NUMBER PLATE W/CASING	Reviewing	35	BENT	
	3	SUPPORT PANEL TOP GARNISH	Reviewing	65	(CRACKED) SUPPLEMENTARY 22/01/2018	
	4	ENGINE UNDER GARNISH CLIP, GRIP PIN X4PCS	Reviewing	20	(NECESSARY) SUPPLEMENTARY 22/01/2018	
	5	ENGINE UNDER GARNISH CLIP, PIN X4PCS	Reviewing	20	(NECESSARY) SUPPLEMENTARY 22/01/2018	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE	
<input type="checkbox"/>		6	FRONT FENDER SIDE STOPPER - RH	Reviewing	10	(NECESSARY) SUPPLEMENTARY 22/01/2018	
<input type="checkbox"/>		7	ENGINE MOUNTING - LH	Reviewing	165	(TORN) SUPPLEMENTARY 22/01/2018	
<input type="checkbox"/>		8	ENGINE MOUNTING - RH	Reviewing	165	(TORN) SUPPLEMENTARY 22/01/2018	
<input type="checkbox"/>		9	FRONT BUMPER NOZZLE PIPE JOINT - RH	Reviewing	15	(DEFORMED) SUPPLEMENTARY 22/01/2018	
<input type="checkbox"/>		10	POWER STEERING OIL	Reviewing	20	(NECESSARY) SUPPLEMENTARY 22/01/2018	
<input type="checkbox"/>		11	TO REMOVE, REPLACE RH, LH ENGINE MOUNTING	Reviewing	80	SUPPLEMENTARY 22/01/2018	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		12	DAYS OF REPAIR : 8 DAYS	Reviewing			
<input type="checkbox"/>		13	OIL STICK	Deny	0	NOT NECESSARY	
<input type="checkbox"/>		14	FOGLAMP SIDE COVER RH	Reviewing	35	MISSING	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$13,094.50

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,390.00	\$2,170.00
Spare Parts	\$12,570.50	\$10,274.50
Miscellaneous	\$55.00	\$650.00