

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD121T -*Not Authored**1/1 by \$ 2950*

Vehicle No.:	SHD121T - CANDY
Chassis No.:	KL1LA69RJBB089714
Vehicle Make:	CHEVROLET
Vehicle Model:	CHEVROLET EPICA 2.0
Date of Accident :	10.01.2018
Third Party Insurer :	AXA

PART		LIST
1	1 Front Bumper	\$ Bu 1,202.00 ✓
2	1 Front Bumper Lower Absorber	\$ S 180.00 X
3	1 Front Bumper Reinforcement	\$ R 356.00 X
4	1 Front Bumper Retainer LH	\$ R 102.00 ✓
5	1 Bumper Fog Lamp Cover LH	\$ S 32.40 X
6	1 Front Fender LH	\$ Bu 837.60 ✓
7	1 Front Fender Liner LH	\$ S 47.00
8	1 Front Shock Absorber Assy LH	\$ S 216.17
9	1 Front Lower Arm LH	\$ S 283.00
10	1 Front Knuckle Arm LH	\$ S 230.00
11	1 Front Door LH	\$ R 1,133.00
12	1 Front Door Glass Guide LH Chrome Moulding	\$ S 60.00
13	1 Front Door Outer Handle LH	\$ S 125.00
14	1 Front Door Hinge Upper LH	\$ R 65.00
15	1 Front Door Hinge Lower LH	\$ R 65.00
16	1 Front Side View Mirror LH	\$ Pdl Bu 939.00 ✓
17	1 Side Rocker Panel Garnish LH	\$ S 236.40 X
18	1 Rear Door LH	\$ R 1,133.00 X
19	1 Rear Door Guide LH Chrome Moulding	\$ S 60.00 X
20	1 Rear Door Outer Handle LH	\$ S 125.00 X
21	1 Rear Door Weatherstrip LH	\$ S 138.79 X
22	1 Rear Fender LH	\$ R 1,145.00 X

TOTAL	\$	8,711.36
10%	\$	871.14
	\$	7,840.22

Special Nett

1	1 Set Front Fender Liner Clip LH	\$	R 30.00 X
2	1 Door Sticker "Trans-cab" LH	\$	R 80.00 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-130

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD121T -

3	1	Door Sticker "6555-3333" LH	\$	<i>na</i>	80.00 ✓
4	1set	Side Rocker Panel Garnish Clip LH	\$	<i>na</i>	60.00 ✓
5	1	Frt Tyre LH	\$	<i>na</i>	360.00 X
6	1	Frt Wheel Rim LH	\$	<i>na</i>	254.00 X
TOTAL			\$		864.00
TOTAL PARTS			\$		8,704.22

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,700.00	<i>400</i>
To Rust-Proofing Of The Affected Areas.	\$	220.00	<i>300</i>
Putty and Spray Painting Of The Affected Portion.	\$	2,800.00	<i>4500</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>200</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>na</i> 380.00	X
Towing Fees	\$	<i>na</i> 120.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00	X

LKK Auto Consultants hence notify the Repairer of the following:	TOTAL	\$	7,120.00
• To resurvey before/after spray painting	Over All Total	\$	15,824.22
• To display damaged part (s) (if any)			
• Parts prices are subject to confirmation			
• Third party survey is on a "Without Prejudice" basis			
• All work done (s) is allowed			
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
REPAIR DAYS			
10 DAYS <i>2 1/2 days</i>			
Acknowledged by Repairer			
Signature:			
Date:			