

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18000860/GPS3N2

Date: 20/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJL1576S	Insured Vehicle No :	SHC8851Y
Date of Loss: 09/01/2018	Nature of Claim: TP	Claim No: MCT18010244

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL1576S		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	3ZZ4805374
Reg. Date:	17/11/2008 (Man. Year: 2008)	Chassis No:	MR053ZEE106121758
Colour:	Silver	Odometer:	157625 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	919.50	386.32	533.18	57.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	480.00	380.00	100.00	20.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	1,399.50	766.32	633.18	45.24
Approved Total (Overridden) (\$\$)		600.00		
(\$\$)	1,399.50	600.00	799.50	57.13
+ GST 7.00/7.00% (\$\$)	97.97	42.00	55.97	57.13
Nett Amount (\$\$)	1,497.47	642.00	855.47	57.13
+ Car Rental (2.0 x \$S100.00/day) (\$\$)		200.00		
Nett Liability (\$\$)		842.00		

INSPECTION

Date of Assignment:	11/01/2018		
Date Inspected:	12/01/2018	Inspected At:	Allswell Motor Traders (HQ) 25 Defu Lane 9 Singapore 539266
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL1576S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	891.20 F	*486.80 FL
2	1		*CLIP	Necessary	28.30 F	*28.30 FL
					Sub Total (\$)	919.50
					- List Item Discount on L Items 0.00/25.00% (\$)	515.10
						128.78
					Total Parts (\$)	919.50
						386.32

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DISMANTLE & ASSEMBLY	New	120.00	180.00
2	RESPRAYING OF BUMPER & POLISHING	New	360.00	200.00
Gross Labour Cost (\$)			480.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >