



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 8068B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR REINFORCEMENT (SN)	NOT NECESSARY	552.34	-
1	BUMPER BRACKET LHS (SN)	NOT NECESSARY	35.37	-
1	BUMPER BRACKET RHS (SN)	NOT NECESSARY	35.37	-
1	REAR BUMPER (SN)	DEFORMED	1,123.30	1,123.30
1	REAR SPOILER (SN)	CUT	313.65	313.65
1	REAR BUMPER CTR BRACKET (SN)	DEFORMED	84.97	84.97
1	REVERSE SENSOR (ADDITIONAL)(SN)	CUT	400.00	400.00
1	B&P NUMBER PLATE (SN)	BENT	80.00	80.00
			2,625.00	2,001.92
	<u>LABOUR</u>			
	ELECT WIRING & MECH COMPO.		280.00	280.00
	LABOUR.		2,520.00	1,680.00
	SPRAY PAINT.		2,400.00	1,600.00
	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC.		480.00	480.00
			5,680.00	4,040.00
	GRAND TOTAL		8,305.00	6,041.92
	RECOMMENDED COST OF REPAIRS			6,041.92

Report Ref No. CS/FCI18000909/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.