

ASS. REQ. BY:

REF:

CS/msg18000921/Kopezi

Special Instruction:

SUPERVISOR:

Kenneth

ASSIGNMENT (Office)

From (Person):

Fivel Foo

of

msgh

Date/Time:

16012018 10:40am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 3636T

Insured:

SJG 2669C

at Workshop m/s

Hui Yang Motor

Tel:

6451 5782

of

176 Sin Ming Drive #04-02

Policy No:

A27116787 QMX

Claim No:

545768

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12012018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

12012018 11:27am

Person Contacted:

Bil

Vehicle: IN OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SLU 3636T - x

SJG 2669C - x

18/1/18 @

9.34am revised to Fivel Foo via Messenger

1/3

867001 email, not agree.

8/1/18 86725 Confirm by email. Parts plus labour only.  
(Red \$ 7136.20 24%)

ASS. REC. BY:

REF: MSG 1

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_ 1 to 1 year

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: 3646 8087 Yr Regn: 06, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: M/ 9220d c.c. 1950

Colour: M/ Black A/C: Insured / Std / NI / NA

Sp. Reading: 46 P84 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDD 21300 4 2A 21 26 P5

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 12/1/18

D.O.A. 16/1/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/1 15h post to Catherine

  
22/3/2018

RECEIVED

Date/Time, File Pass to?

17/3 15h

Date/Time, File Return to?

2)

☐: Prell. Report☐: Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech Invs (\$)☐: Weekend (\$)

Survey Fee: 200

Transportation: S - RS SI

Photos: 10

Others:

TOTAL: 210

Report Format: MER-TF

Lump Sum / I.B.I. (\$): 6725



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18000921/Kqb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 16-01-2018	
		Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJG 2669C	Veh. Inspected	SLU 3636T
Policy No.	A27116787QMX	Coverage (\$)	0.00
Claim No.	545768	Excess (\$)	0.00
Assign From	MERIMEN (FIEVEL FOO)	Assign Date	16/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	12/01/2018	Inspection Date	16/01/2018
Survey held at	HUI YANG MOTOR SERVICE BLOCK 176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jan 2018		16 Jan 2018 10:40 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

<b>Insured:</b>	CHUA GUAT, ID: S0156045Z, Tel: +6596163833, Email: NOEMAIL		
<b>Main Claimant:</b>	ACE FLEET MANAGEMENT PTE. LTD., Co. Reg. No.: 201710914N		
<b>Vehicle Reg. No.:</b>	SLU3636T	<b>Date of Loss:</b>	12/01/2018 13:00 - :59
<b>Claim Type:</b>	TP / 545768	<b>Policy/Cover Note No.:</b>	A27116787QMX (Comprehensive) Coverage: 25/06/2017 - 24/06/2018
<b>Vehicle Reg. No. (Insured):</b>	SJG2669C	<b>Policy No. (Claimant):</b>	
		<b>Excess:</b>	
<b>Repairer:</b>	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Imm.Advice due 17/01/2018]</b>		
<b>Driver/Custodian (Insured):</b>	CHUA GUAT (63 / Female), NRIC: S0156045Z, Tel: +6596163833		
<b>Adj Asg. Remarks:</b>	Car in survey today 16/01/2018		

**ASSOCIATED MAIL RECEIVED** View All Compose Case Mail

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 18 Jan 2018

**Preliminary Advice**

Insured Vehicle No	: SJG2669C	Accident Date	: 12/01/2018
TP Vehicle No	: SLU3636T	Assignment Date	: 16/01/2018
Make	: MERCEDES-BENZ E220D SE	Est. Duration of Repair	: 3.00
Date of Inspection	: 16/01/2018		
Inspection At	: HUI YANG MOTOR PTE LTD (HQ) 176 SIN MING DRIVE #04-02, SIN MING AUTOCARE SINGAPORE 575721		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,861.20
Revised Amount	:S\$	3,648.50
Check Items (Estimated)	:S\$	4,643.70
Total	:S\$	8,292.20

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/01/2018 10:07
Date Of Accident	12/01/2018 12:50
Exact Location Of Accident	ALONG HOLLAND VILLAGE CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU3636T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ACE FLEET MANAGEMENT PTE. LTD.
Co Reg No	201710914N
Email Address	SQUARECAR123@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-86667800
<b>Vehicle Particulars</b>	
Manufacturer	MERCEDES-BENZ
Model	E220D AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5090853610-01
Cover Note Number	
<b>Driver</b>	
Name of Driver	LEE KUM WOH
NRIC No	S7170448C
Date Of Birth	27/09/1971
Occupation	OUTDOOR
Date Of Driving Pass	25/11/1993
Driving Experience	24 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91411836
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2 Pg. 1

SKETCH PLAN



veh A: SLU36367

veh B: SJG2669C

Holland Village car park

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*Pls refer to attached police report*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



T/20180112/2136

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

2 of 3

Report No. T/20180112/2136

## CONTINUATION OF REPORT

Name	Chua Guat		ID No.	S0156045Z
Related Vehicle	SJG2669C (Car)		Contact No.	96163833
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
<b>Driver:</b>				
Name	LEE KUM WOH		ID No.	S7170448C
Related Vehicle	SLU3636T (Car)		Contact No.	91411836
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	12/01/2018		Date Discharge	12/01/2018
No. of Days granted Medical Leave	07		Degree of Injury	NIL

**Brief Details.**

On the above mentioned date and time, I was at the carpark of Holland Village. A car(SJG2669C) was in front of me. The said car suddenly reverses very fast and hit onto my car. I then make a check and discover that my front portion was damaged.

I then took photo of the accident and exchange particulars of the driver. I would like to inform that have the footage from my in-car camera.

After the accident, I felt unwell and went to Mount Alvernia to seek medical attention. I was given 7days medical leave.

21  
10

119  
輝陽汽車有限公司  
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

12/01/2018

Owner: ACE FLEET MANAGEMENT PTE LTD

**ESTIMATE TO REPAIR MERCEDES BENZ E220D - SLU3636T**

1pc	front RH headlamp
1pc	front RH headlamp lower bracket
1pc	front bumper
1pc	front bumper reinforcement
1pc	front bumper sponge
1pc	front bumper lower centre grille
1pc	front bumper lower RH grille
1pc	front bumper number plate garnish
1pc	front bumper centre RH parking sensor
1pc	front centre grille base
1pc	front centre grille centre garnish
1pc	front centre grille frame chrome
2pcs	front centre grille centre RH chrome @\$65.00
1pc	front support panel centre garnish

Not within  
11 Sep @ \$100  
Running After Repair  
3 days

18/1/18  
\$ 2,900.00 ✓  
\$ 113.00 X  
\$ 1,500.00 ✓  
\$ 460.00 X  
\$ 130.00 ✓  
\$ 85.00 ✓  
\$ 60.00 X  
\$ 105.00 ✓  
\$ 250.00 ✓  
\$ 285.00 ✓  
\$ 235.00 ✓  
\$ 250.00 ✓  
\$ 130.00 ✓  
\$ 185.00 ✓

cost + 15%

\$ 6,688.00  
\$ 1,003.20  
\$ 7,691.20

1set front number plate & casing

See s.nett \$ 50.00 ✓

wiring  
spray painting  
labour charges  
Total

\$ 120.00 2d  
\$ 500.00 30d  
\$ 500.00 30d  
\$ 8,861.20

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jan 2018		16 Jan 2018 10:40 <a href="#">Edit Adj Rpt</a>	<b>S\$6,725.00</b> <a href="#">Edit Estimates</a>	<b>S\$6,725.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by Insurer]
Insured:	CHUA GUAT, ID: S0156045Z, Tel: +6596163833, Email: NOEMAIL	
Main Claimant:	ACE FLEET MANAGEMENT PTE. LTD., Co. Reg. No.: 201710914N	
Vehicle Reg. No.:	SLU3636T	Date of Loss: 12/01/2018 13:00 - :59
Claim Type:	TP / 545768	Policy/Cover Note No.: A27116787QMX (Comprehensive) Coverage: 25/06/2017 - 24/06/2018
Vehicle Reg. No. (Insured):	SJG2669C	Policy No. (Claimant):
		Excess:
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 15/02/2018]	
Driver/Custodian (Insured):	CHUA GUAT (63 / Female), NRIC: S0156045Z, Tel: +6596163833	
Adj Asg. Remarks:	Car in survey today 16/01/2018	

























ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

**\*SLU3636T (545768)**  
**[SJG2669C]**  
**TP**  
**ACE FLEET MANAGEMENT PTE. LTD.**  
**Jan 12 2018 1:00PM**  
**[CHUA GUAT]**  
**Hui Yang Motor Pte Ltd**

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	15/01/18 10:12	<b>Accident Statement</b> From: SC - Reg. No: SJG2669C, Claimant: CHUA GUAT		Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	18/01/18 09:49	<b>Adjuster Immediate Advice</b>		Load HTM			
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	22/03/18 14:07	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
2	22/03/18 14:07	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
3	22/03/18 14:07	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
4	22/03/18 14:07	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
5	22/03/18 14:07	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
6	22/03/18 14:07	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
7	22/03/18 14:07	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
8	22/03/18 14:07	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
9	22/03/18 14:07	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
10	22/03/18 14:07	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
11	22/03/18 14:07	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
12	22/03/18 14:07	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
13	22/03/18 14:07	<b>Odometer Reading</b>		Load JPG	<input checked="" type="checkbox"/>		
14	22/03/18 14:07	<b>Chassis Number</b>		Load JPG	<input checked="" type="checkbox"/>		
15	22/03/18 14:08	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
16	22/03/18 14:08	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
17	22/03/18 14:08	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
18	22/03/18 14:08	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
19	22/03/18 14:08	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
20	22/03/18 14:08	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	15/01/18 10:12	<b>SLU3636T E-file &amp; Police report</b> From: SC - Reg. No: SJG2669C, Claimant: CHUA GUAT		Load PDF			
2	15/01/18 10:19	<b>Estimate</b>		Load PDF			

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

^

v

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000921/KQBE2

Date: 26/03/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A27116787QMX

Claimant Vehicle No : SLU3636T

Insured Vehicle No : SJG2669C

Date of Loss: 12/01/2018

Nature of Claim: TP

Claim No: 545768

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLU3636T

Make &amp; Model: MERCEDES-BENZ E220D SE, 2.0 (A)

Engine No: 65492080096580

Reg. Date: 14/06/2017 (Man. Year: 2017)

Chassis No: WDD2130042A212695

Colour: Metallic Black

Odometer: 46984 km

Engine Capacity: 1950 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,741.20	6,105.00	1,636.20	21.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	620.00	500.00	44.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>8,861.20</b>	<b>6,725.00</b>	<b>2,136.20</b>	<b>24.11</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>620.28</b>	<b>470.75</b>	<b>149.53</b>	<b>24.11</b>
<b>Nett Amount (\$\$)</b>	<b>9,481.48</b>	<b>7,195.75</b>	<b>2,285.73</b>	<b>24.11</b>

## INSPECTION

Date of Assignment: 16/01/2018

Date Inspected: 16/01/2018 Inspected At:

Hui Yang Motor Pte Ltd (HQ)

176 Sin Ming Drive #04-02, Sin Ming

AutoCare

Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 26 Mar 2018)  
**Parts:** 143      MERCEDES-BENZ E220D SE 2.0 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SLU3636T)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH HEADLAMP (WCP)	MTG Cracked	2,900.00 F	*2,900.00 F
2	1		*FRONT RH HEADLAMP LOWER BRACKET (WCP)	Repair	113.00 F	*- F
3	1		*FRONT BUMPER (WCP)	Bent	1,500.00 F	*1,500.00 F
4	1		*FRONT BUMPER REINFORCEMENT (WCP)	Repair	460.00 F	*- F
5	1		*FRONT BUMPER SPONGE (WCP)	Cracked	130.00 F	*130.00 F
6	1		*FRONT BUMPER LOWER CENTRE GRILLE (WCP)	Cracked	85.00 F	*85.00 F
7	1		*FRONT BUMPER LOWER RH GRILLE (WCP)	Serviceable	60.00 F	*- F
8	1		*FRONT BUMPER NUMBER PLATE GARNISH (WCP)	Dented	105.00 F	*105.00 F
9	1		*FRONT BUMPER CENTRE RH PARKING SENSOR (WCP)	Shorted	250.00 F	*250.00 F
10	1		*FRONT CENTRE GRILLE BASE (WCP)	Distorted	285.00 F	*285.00 F
11	1		*FRONT CENTRE GRILLE CENTRE GARNISH (WCP)	Dented	235.00 F	*235.00 F
12	1		*FRONT CENTRE GRILLE FRAME CHROME (WCP)	Cracked	250.00 F	*250.00 F
13	2		*FRONT CENTRE GRILLE CENTRE RH CHROME (WCP)	Cracked	130.00 F	*130.00 F
14	1		*FRONT SUPPORT PANEL CENTRE GARNISH (WCP)	Deformed	185.00 F	*185.00 F
15	1		*SET FRONT NUMBER PLATE & CASING	Scratched	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>6,738.00</b>	<b>6,105.00</b>
<b>+ Margin on L,N Items 15.00/0.00% (\$\$)</b>	<b>1,003.20</b>	<b>0.00</b>
<b>Total Parts (\$\$)</b>	<b>7,741.20</b>	<b>6,105.00</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	WIRING	New	120.00	20.00
2	SPRAY PAINTING	New	500.00	300.00
3	LABOUR CHARGES	New	500.00	300.00
Gross Labour Cost (S\$)			<b>1,120.00</b>	<b>620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >