

ASS REC BY: REF: CS3 / LPC17019554 / Trb-1⁰² Special Instruction

ASSIGNMENT (Office)

From (Person): Taufik of Gerald Poh of LPC Date/Time: 15-01-2018

Rate/Rate & Cost: Bill to:

OD / ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJG 8394 E Insured: GBC 47364

at Workshop no: Kok Wang Car Grooming Tel: 9183 9633

of 1 Sooh Lee street #06-40 pioneer centre, 627 605

Policy No: Claim No: 17/17/17/VCOO/020161

Sum Insured: Excess:

Make of Veh: DOA 9/10/17

(Client's Record):

CA / REV / REF: REV 24 HRS 'wp'

Date/Time: 11/10/17 @ 9:58am Person Contacted: Mr. Kok Vehicle: IN OUT

Date/Time: Action/Remarks: X FEAR

SJG 8394 E x

GBC 47364 07/07/12/0000000000/0000000000 24-150812

Taufik

Pls see my remarks

Submit LIS \$7400, 7 days

Red: \$1200, 14%.

MV: \$20K, LTA: \$13,215.00, NV: 6725

mbout
22/2/2018
4/5 \$7400, 7 days

RECEIVED 20 FEB 2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC17019554/T1rb-1

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 16-01-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 4736U	Veh. Inspected	SJG 8394E
Policy No.		Coverage (\$)	0.00
Claim No.	17/17/17/VC00/020151	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	15/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/10/2017	Inspection Date	16/01/2018
Survey held at	KOK WANG CAR GROOMING (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE SINGAPORE 627605		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 15 January, 2018 8:47 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: PRE-REPAIR SURVEY - SJG8394E
Attachments: 15012018084318.pdf

Our Ref : 17/17/17/VC00/020151

Dear Catherine,

Kindly let us know if a re-inspection is required or a paper survey would suffice.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #03-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0415 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Tan Bing Hua James
C/o: 1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605

Date of report: 30.10.2017
Date of request: 11.10.2017
Date of inspection: 11.10.2017
Date of accident: 09.10.2017
Claim type: Third Party Claim

Report No: AAS/2017/382

Particulars of affected vehicle:

Registration no: SJG8394E
Make/Model: Volkswagen Jetta TSI (A)
Year of registration: 2008
Colour: Metallic Black

Odometer: 213188 km
Engine Capacity: 1390 cc
Engine no: BLG038823
Chassis no: WVVZZZ1KZ8M176039

Condition of tires:

Front Left: 5mm
Make: Dunlop
Rear Left: 5mm
Make: Dunlop

Front Right: 5mm
Make: Dunlop
Rear Right: 5mm
Make: Dunlop

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

The Assignment

The inspection was conducted at M/s. Kok Wang Car Grooming
1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605

(Subsequent inspection was conducted)

Assessment

Repairer's estimate: \$ 14,088.00
Revised estimate: \$ 10,757.60
Recommended reserve: \$ 8,600.00 (Lump sum)

Estimated normal duration of repairs : 8 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #03-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0418 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SJG8394E

Report No: AAS/2017/382

W/O PREJUDICE

Point of impact

At the front portion.

General description of damages

The bonnet, front grille, front bumper, headlamps, LHF fender, lock carrier, aircon condenser, radiator, air charger, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Koh Wang Car Grooming as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$10,757.60

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$8,600.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 8 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 98 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #03-16 Sin Ming AutoCity (S) 575722.
Mobile: 9858-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SJG8394E

Report No: AAS/2017/382

Appraisal Schedule

/N Parts Description	Qty	Condition		Repairer's Est	Revised Est
1 Bonnet	1	Dented		\$ 958.20	\$ 958.20
2 Bonnet hinge LH/RH	2	Serviceable	\$ 71.20	\$ 142.40	-
3 Bonnet insulator	1	Deformed		\$ 100.00	\$ 100.00 XNN
4 Bonnet insulator clips	1set	Necessary		\$ 50.00	\$ 30 50.00 Δ
5 Bonnet seal	1	Necessary		\$ 25.30	\$ 25.30
6 Bonnet stopper	2	Necessary	\$ 6.00	\$ 12.00	\$ 12.00
7 Bonnet hook	1	Bent		\$ 61.30	\$ 61.30
8 Bonnet lock	1	Distorted		\$ 165.60	\$ 165.60
9 Front grille	1	Cracked		\$ 282.10	\$ 282.10
10 Front grille emblem	1	Necessary		\$ 64.80	\$ 64.80
11 Headlamp LH/RH	2	Cracked	\$ 649.90	\$ 1,299.80	\$ 1,299.80
12 Front bumper	1	Dented		\$ 868.70	\$ 868.70
13 Front bumper license finisher	1	Dented		\$ 51.30	\$ 51.30
14 Front bumper centre grille	1	Cracked		\$ 163.20	\$ 163.20
15 Front bumper fog lamp LH/RH	2	Cracked	\$ 150.20	\$ 300.40	\$ 300.40
16 Front bumper fog lamp grille LH/RH	2	Cracked	\$ 75.40	\$ 150.80	\$ 150.80
17 Front bumper moulding LH/RH	2	Serviceable	\$ 53.60	\$ 107.20	-
18 Front bumper chrome moulding LH/RH	2	Necessary	\$ 162.30	\$ 324.60	\$ 324.60
19 Front bumper absorber	1	Dented/Cracked		\$ 63.50	\$ 63.50
20 Front bumper reinforcement	1	Cracked		\$ 474.60	\$ 474.60
21 Front bumper bracket LH/RH	2	Cracked	\$ 29.00	\$ 58.00	\$ 58.00
22 LHF fender	1	Distorted/Repair		\$ 581.20	-
23 Lock carrier	1	Cracked		\$ 817.40	\$ 817.40
24 Air intake channel	1	Serviceable		\$ 24.40	-
25 Air intake duct	1	Serviceable		\$ 18.00	-
26 Air intake cover	1	Serviceable		\$ 16.00	-
27 Aircon condenser	1	Bent/Punctured		\$ 781.10	\$ 781.10
28 Radiator	1	Dented		\$ 682.90	\$ 682.90
29 Air charger cooler	1	Dented		\$ 541.30	\$ 541.30
30 Fan cowl	1	Cracked		\$ 190.70	\$ 190.70
31 Electric fan 1	1	Serviceable		\$ 755.60	-
32 Electric fan 2	1	Serviceable		\$ 755.60	-
List total:				\$ 10,888.00	\$ 8,487.60
1 Front number plate	1	Dented		\$ 70.00	\$ 70.00 45
2 Radiator coolant	1	Necessary		\$ 40.00	\$ 40.00 85
Special nett total:				\$ 110.00	\$ 110.00
Parts Total:				\$ 10,998.00	\$ 8,597.60

8357.60
10% - 7521.84



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #03-16 Sin Ming AutoCity (S) 575722
Mobile: 9685-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SJG8394E

Report No: AAS/2017/382

Labour Description

Repairer's Est

Revised Est

1 Rust proofing on front affected & replacement panels.

\$ 60.00

\$ 40.00 30

2 To check front lightings & wirings.

\$ 60.00

\$ 40.00 30

3 To replace aircon condenser. Top up aircon gas.

\$ 150.00

\$ 120.00 100

4 To replace radiator & cooling fan assy.

\$ 120.00

\$ 80.00 700

5 Spray painting on affected & replacement panels.

\$ 1,200.00

\$ 1,000.00 200

6 Renew front damaged parts. Re-align all affected area.

\$ 1,500.00

\$ 880.00

Labour Total:

\$ 3,090.00

\$ 2,160.00 1640

Grand Total:

\$ 14,088.00

\$ 10,757.60

The final adjusted lump sum amount is \$8,600.00

Under normal circumstances, the repair should be completed within a reasonable period of 8 working days.

8 Photographs were taken at the time of inspection.

9246.84
4/5 \$74.00
7 days

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	47161

Vehicle Details

Vehicle No.	SJG8394E
Vehicle to be Exported	No
Intended De-registration Date	04 Dec 2017
Vehicle Make	VOLKSWAGEN
Vehicle Model	JETTA 1.4 TSI 170 COMFORTLINE
Primary Colour	Black
Manufacturing Year	2008
Engine No.	BLG038823
Chassis No.	WWWZZZ1KZ8M176039
Maximum Power Output	125.0 kW (167 bhp)
Open Market Value	\$24,695.00
Original Registration Date	17 Jul 2008
First Registration Date	17 Jul 2008
Transfer Count	2
Actual ARF Paid	\$24,695.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	16 Jul 2018
PARF Rebate Amount	\$12,347.00

Intended COE Rebate Details

COE Expiry Date	16 Jul 2018
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$14,101.00
COE Rebate Amount	\$868.00
Total Rebate Amount	\$13,215.00

The information contained herein is correct as at 04 Dec 2017

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS3/LPC17019554/T1rbe2-1		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 27-02-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 4736U	Veh. Inspected	SJG 8394E	
Policy No.		Coverage (\$)	0.00	
Claim No.	17/17/17/VC00/020151	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	15/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	WWWZZZ1KZ8M176039	Colour	BLACK	
Odometer	213188	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	DUNLOP	6 mm	
L/H Front Tyre	225/45 R17	DUNLOP	6 mm	
R/H Rear Tyre	225/45 R17	DUNLOP	6 mm	
L/H Rear Tyre	225/45 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/10/2017	Inspection Date	11/10/2017	
Survey held at	KOK WANG CAR GROOMING (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE SINGAPORE 627605			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJG 8394E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	DENTED	958.20	958.20
2	BONNET HINGE LH / RH @\$71.20	SERVICEABLE	142.40	-
1	BONNET INSULATOR	NOT NECESSARY	100.00	-
1	SET BONNET INSULATOR CLIPS	NECESSARY	50.00	30.00
1	BONNET SEAL	NECESSARY	25.30	25.30
2	BONNET STOPPER @\$6.00	NECESSARY	12.00	12.00
1	BONNET HOOK	BENT	61.30	61.30
1	BONNET LOCK	DISTORTED	165.60	165.60
1	FRONT GRILLE	CRACKED	282.10	282.10
1	FRONT GRILLE EMBLEM	NECESSARY	64.80	64.80
2	HEADLAMP LH / RH @\$649.90	CRACKED	1,299.80	1,299.80
1	FRONT BUMPER	DENTED	868.70	868.70
1	FRONT BUMPER LICENSE FINISHER	DENTED	51.30	51.30
1	FRONT BUMPER CENTRE GRILLE	CRACKED	163.20	163.20
2	FRONT BUMPER FOG LAMP LH / RH @\$150.20	CRACKED	300.40	300.40
2	FRONT BUMPER FOG LAMP GRILLE LH / RH @\$75.40	CRACKED	150.80	150.80
2	FRONT BUMPER MOULDING LH / RH @\$53.60	SERVICEABLE	107.20	-
2	FRONT BUMPER CHROME MOULDING LH / RH @\$162.30	NECESSARY	324.60	324.60
1	FRONT BUMPER ABSORBER	DENTED / CRACKED	63.50	63.50
1	FRONT BUMPER REINFORCEMENT	CRACKED	474.60	474.60
2	FRONT BUMPER BRACKET LH / RH @\$29.00	CRACKED	58.00	58.00
1	LHF FENDER	TO REPAIR SEE LABOUR	581.20	-
1	LOCK CARRIER	CRACKED	817.40	817.40
1	AIR INTAKE CHANNEL	SERVICEABLE	24.40	-
1	AIR INTAKE DUCT	SERVICEABLE	18.00	-
1	AIR INTAKE COVER	SERVICEABLE	16.00	-
1	AIRCON CONDENSER	BENT / PUNCTURE	781.10	781.10
1	RADIATOR	DENTED	682.90	682.90
1	AIR CHARGER COOLER	DENTED	541.30	541.30

Report Ref No. CS3/LPC17019554/T1rbe2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FAN COWLING	CRACKED	190.70	190.70
1	ELECTRIC FAN 1	SERVICEABLE	755.60	-
1	ELECTRIC FAN 2	SERVICEABLE	755.60	-
	LESS 10% DISCOUNT		-	-836.76
			10,888.00	7,530.84
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	DENTED	70.00	45.00
1	RADIATOR COOLANT (SN)	NECESSARY	40.00	40.00
			110.00	85.00
	LABOUR			
	RUST PROOFING ON FRONT AFFECTED & REPLACEMENT PANELS.		60.00	30.00
	TO CHECK FRONT LIGHTINGS & WIRINGS.		60.00	30.00
	TO REPLACE AIRCON CONDENSER. TOP UP AIRCON GAS.		150.00	100.00
	TO REPLACE RADIATOR & COOLING FAN ASSY.		120.00	80.00
	SPRAY PAINTING ON AFFECTED & REPLACEMENT PANELS.		1,200.00	700.00
	RENEW FRONT DAMAGED PARTS. RE-ALIGN ALL AFFECTED AREA. INCLUSIVE OF THE REPAIR OF LHF FENDER.		1,500.00	700.00
			3,090.00	1,640.00
	GRAND TOTAL		14,088.00	9,255.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,400.00

Report Ref No. CS3/LPC17019554/T1rbe2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.