

23/03/2018

ASS. REC. BY:

REF 33/mcun00 9815/C96-1

Special Instruction:

Surveyor: Richard ASSIGNMENT (Office)From (Person): Lundt of MISC Date/Time 15-01-2018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SBE 2332D Insured: YM6751Lat Workshop m/s Bunel Automatic Tel: 67452088of 1 km Bukit Aue 6 # 1 - 78 AntbergPolicy No: 18780601 MEC Claim No: 55964

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 20/5/2017  
(Client's Record)CA / REV / REP. / REV 24 HRS <sup>(MP)</sup> H.O.D Endorsement: \_\_\_\_\_Date/Time 20/1/2017 1:33pm Person Contacted: Sally Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	SBE 2332D	
	11/1/2017	
20/5/2017 @ 5:13pm	Send email inform Bunel Sunday with estimate by afternoon	
	Sunday: 20/5/2017, dismantle. 5/6/2017 offer repair. 11/6/2017	
23/1/18	Submit LS \$6000, 9 days (Red \$3150, 34%)	

RECEIVED 15-01-2018



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17009815/qb-1

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 16-01-2018



Code : MSG

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	YM 6751L	Veh. Inspected	SBE 2332D
Policy No.	28780601MKC	Coverage (\$)	0.00
Claim No.	515464	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	15/01/2018

**2. Vehicle Particulars & Condition**

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--	--

**5. General Information**

Accident Date	20/05/2017	Inspection Date	16/01/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2017		22 May 2017 13:16 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
<b>Insured:</b>		<b>CHIAN TECK REALTY PTE.LTD., Co. Reg. No.: 200905590Z</b> <span>[Created by insurer]</span>							
<b>Main Claimant:</b>		<b>TAN JOO CHENG, ID: S11605058</b>							
<b>Vehicle Reg. No.:</b>		<b>SBE2332D</b>							
<b>Claim Type:</b>		<b>TP / 515463</b>							
<b>Vehicle Reg. No. (Insured):</b>		<b>YM6751L</b>							
<b>Repairer:</b>		<b>Bluwel Automotive Service Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 (UNIT B) #01-28, 417883 Kaki Bukit - Tel:</b>							
<b>Handling Insurer:</b>		<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]</b>							
<b>Adjuster:</b>		<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Richard Harjanto] ... [Final Rpt due 11/01/2018]</b>							
<b>Adj Asg. Remarks:</b>		<b>Please contact Ms Sally @ 6745 2088 to arrange for survey.</b>							
<b>ASSOCIATED MAIL RECEIVED</b>									
<a href="#">View All</a> <a href="#">Compose Case Mail</a>									
<ul style="list-style-type: none"> <li>MSIG_SG (09/01/2018): Report Send Back Alerts - SBE2332D (TP)</li> </ul>									
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 Kaki Bukit Ave 6 Blk C #01-28/53/55/56 Singapore 417883

Tel: 67452088 Fax: 68412088

E-mail: bluwel2088@yahoo.com.sg

GST Reg No.: 200704951N

Co Reg No.: 200704951N

Date: 30/06/2017

Vehicle No.: SBE2332D

Model: HYUNDAI ACCENT

Name: TAN JOO CHENG

Address: BLK 13 SURIN ROAD SINGAPORE 535534

## Repair Bill For SBE2332D

NO	DESCRIPTION	AMOUNT
	LUMP SUM REPAIR	\$ 9,150.00

TOTAL: \$ 9,150.00

7% GST: \$ 640.50

GRAND TOTAL: \$ 9,790.50





## PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers  
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779  
Tel : 62934822 Fax : 62963283

Messrs. Tan Joo Cheng  
13, Surin Road  
Singapore 535534

Bill No. DN/TP/17/0087/BLU  
22/06/2017

		Dr.
To		
Survey Fee (S \$) :		
Photographs (S \$) :		
Transport (S \$) :		
Resurvey (S \$) :		
Site-Survey (S \$) :		
Services rendered including photographs and transport charges		(S \$) 797.00
Our reference	: TP/0050/01/17	
Insured	:	
Policy / Cert. No.	:	
Your Claim No.	: Third Party Claim	
Vehicle :	: Hyundai Accent (A) - SBE 2332 D	
Dollars :	: Seven Hundred Ninety Seven Only	
Checked by	for PRIORITY SERVICES	
	E. & O. E. 	

Only our official receipt will be recognised for payment made on this account

Text Size

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type Singapore NRIC

Owner ID 0505B

**Vehicle Details**

Vehicle No SBE2332D

Vehicle to be Exported No

Intended De-registration Date 22 May 2017

Vehicle Make HYUNDAI

Vehicle Model ACCENT (RB) 5DR 1.4 CVT ABS D/AB 2WD

Primary Colour Red

Manufacturing Year 2015

Engine No G4LCFU388094

Chassis No KMHCT51BTFU229707

Maximum Power Output 73.6 kW (98 bhp)

Open Market Value \$11,242.00

Original Registration Date 17 Apr 2015

First Registration Date 17 Apr 2015

Transfer Count 0

Actual ARF Paid \$6,242.00

**Intended PARF Rebate Details**

PARF Eligibility Yes

PARF Eligibility Expiry Date 16 Apr 2025

PARF Rebate Amount \$4,681.00

**Intended COE Rebate Details**

COE Expiry Date 16 Apr 2025

COE Category A - Car up to 1800cc &amp; 97kW (130bhp)

COE Period(Years) 10

QP Paid \$67,749.00

COE Rebate Amount \$53,535.00

**Total Rebate Amount: \$58,216.00**

The information contained herein is correct as at 22 May 2017

OK

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#)  
 Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.  
 Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution  
 Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)



## PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers  
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779  
Tel : 62934822 Fax : 62963283

### VEHICLE INSPECTION REPORT

Report No. TP/0050/01/17	Date of Report	: 22 June 17
To : Tan Joo Cheng	Date of Request	: 22 May 17
13, Surin Road	Report requested by	: Tan Joo Cheng
Singapore 535534	Date of Accident	: 20 May 17
	Date of Inspection	: 22 May 17
	Claim No.	: Third Party Claim

### PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: SBE 2332 D	Odometer Reading	: 23,913 km
Make	: Hyundai	Carrying Capacity	: 4
Model	: Accent (A)	Radio / Cassette / CD	: Yes
Year of Manufacture	: 2015	Air-Conditioner	: Yes
Colour	: Red	Wing Mirror	: Yes
Engine Capacity	: 1,368 cc	Clock	: Yes
Engine No	: --	Seat Belts	: Yes
Chassis / Frame No	: KMHCT51BTFU229707	Others	: Nil

### TYRE CONDITION

Front Left	: 7mm	Front Right	: 7mm
Make	: Kumho	Make	: Kumho
Rear Left	: 7mm	Rear Right	: 7mm
Make	: Kumho	Make	: Kumho
Spare	:	Road Wheels Type	: Alloy

(The above represents the approximate remaining life of tyre treads)

Jack & Tools	: Intact	Spare Tyre	: Intact
--------------	----------	------------	----------

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work	: Good
Paint Work	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

*This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.*

## ASSESSMENT

	<u>Repairer's Estimate (S \$)</u>	<u>Our Recommendation (S \$)</u>
Spare Parts :	11,003.60	7,225.72
Labour Charges :	2,700.00	1,860.00
Paint Work :	2,000.00	1,700.00
Towing Charges :	0.00	0.00
Others :	0.00	0.00
Totals :	15,703.60	10,785.72

Reduction (S \$) : 6,553.60

Recommended Reserve (S \$) : 9,150.00 (Lump Sum)

Estimated Normal Period of Repairs : 12 working days

## CONTRIBUTIONS BY INSURED

Excess (S \$) : N/A

Others : --

## GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

### The Assignment

The survey was conducted at M/s. Bluwel Automotive Services Pte Ltd., Block 1, Kaki Bukit Avenue 6, (Unit B) #01-28, (Unit C) #01-51/53/55, Singapore 417883.

Follow-up inspection has been conducted.

### Point of Impact

At the front and rear portion.

### Damages

Front portion: The front bonnet, front bumper grille, headlamps assembly, etc.

Rear portion: The tailgate, rear bumper, rear bumper reinforcement, tail-lamps assembly, end panel, etc.

Other parts were also found damaged. (see schedule for details)

### Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$10,785.72

### Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$9,150.00

We now revert to you for your decision on repairs.

Very truly yours

**PRIORITY SERVICES**



**JIMMY S. T. LEE** AMSOE, AMIRTE, AMSAE-AUS, MSAAA  
Motor Appraiser



**LAWRENCE NG**  
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Vehicle No : SBE 2332 D Hyundai Accent (A)  
Workshop : Bluwel Automotive Services Pte Ltd.

TP/0050/01/17

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
To Supply :					
1pc. Bonnet	Dented	1,177.40		1,177.40	20 XR
1pc. Bonnet RH hinge	Serviceable	45.90		--	20
1pc. Bonnet LH hinge	Serviceable	45.90		--	20
1pc. Front bumper	Dented	418.30		418.30	20
1pc. Front bumper top rubber seal	Necessary	41.60		41.60	20
1pc. Front bumper inner sponge	Cracked	110.70		110.70	20
1pc. Front bumper lower grille	Cracked	47.90		47.90	20
1pc. Front bumper reinforcement	Refit	261.60		--	20
1pc. Front grille	Cracked	62.50		62.50	20
1pc. Front grille emblem	Necessary	25.60		25.60	20
2pcs. Front grille chrome mouldings	Refit	92.70		--	20
1pc. RH headlamp	Cracked	517.70		517.70	20 XN1
1pc. LH headlamp	Cracked	527.70		527.70	20
1pc. Support panel	Dented / Repair	781.80		--	20
1pc. Support panel top garnish	Deformed	47.80		47.80	20
1pc. Tailgate	Dented	1,303.20		1,303.20	20
1pc. Tailgate 'Accent' emblem	Necessary	31.20		31.20	20
1pc. Tailgate centre' emblem	Necessary	23.30		23.30	20
1pc. Tailgate outer handle	Dented	72.50		72.50	20
1pc. Tailgate lock	Bent	166.80		166.80	20
1pc. Tailgate lock catch	Bent	11.30		11.30	20 XSV
1pc. Tailgate weatherstrip	Bent	52.60		52.60	20
1pc. Tailgate inner trim board	Cracked	58.20		58.20	20 XNN
1pc. Tailgate windscreen glass	Refit	377.10		--	20
1pc. Tailgate windscreen glass wiper motor	Malfunction / Bent	249.80		249.80	20 XSV
1pc. Rear bumper	Dented	406.40		406.40	20
1pc. Rear bumper LH reflector	Cracked	53.40		53.40	20
1pc. Rear bumper RH reflector	Cracked	53.40		53.40	20 XN1
1pc. Rear bumper number plate lamp	Refit	35.20		--	20
1pc. Rear bumper reinforcement	Dented	365.40		365.40	20
1pc. Rear bumper reinforcement RH stay	Dented	84.40		84.40	20 XSV
1pc. Rear bumper reinforcement LH stay	Dented	84.40		84.40	20
2pcs. Rear bumper reinforcement lower brackets	Bent	21.40		21.40	20
2pcs. Rear bumper reinforcement upper brackets	Bent	21.40		21.40	20
1pc. RH tail-lamp	Cracked	302.80		302.80	20 XN1
1pc. LH tail-lamp	Cracked	302.80		302.80	20
1pc. End panel	Dented	499.30		499.30	20
1pc. End panel inner garnish	Deformed	115.10		115.10	20
1pc. Rear fender RH inner trim board	Cracked	98.70		98.70	20 XN1
1pc. Rear fender LH inner trim board	Cracked	98.70		98.70	20
1pc. Spare tyre panel top board	Cracked	339.00		339.00	20
1pc. Exhaust silencer	Dented/ Bent	560.70		560.70	20 XSV

Vehicle No : SBE 2332 D Hyundai Accent (A)  
Workshop : Bluwel Automotive Services Pte Ltd.

TP/0050/01/17

Replacement of Parts	Condition	Repairer's Estimate (\$)	Dist. %	Our Recommendation (\$)	Dist. %
Sub-Total :-		9,993.60		8,353.40	
Total Discount :-		--		1,670.68	
		9,993.60		6,682.72	
Special Nett Items :-					
1pc. Front number plate	Dented	70.00		35.00	
1set. Front bumper clips	Necessary	60.00		40.00	
1set. Support panel top garnish clips	Necessary	50.00		23.00	
1pc. Tailgate windscreen glass inner seal	Necessary	70.00		20.00	
1tube. Tailgate windscreen glass sealant	Necessary	70.00		40.00	
1set. Tailgate inner trim board clips	Necessary	70.00		34.00	
1pc. Rear number plate	Dented	70.00		35.00	
1set. Rear bumper clips	Necessary	70.00		40.00	
1set. Rear bumper reverse sensor	Dented	320.00		200.00	
1set. End panel inner garnish clips	Necessary	60.00		20.00	
1set. Rear fender RH inner trim board clips	Necessary	50.00		28.00	
1set. Rear fender LH inner trim board clips	Necessary	50.00		28.00	
Total For Parts :-		11,003.60		7,225.72	
Labour Charges :					
To remove & replace the above listed parts, knock, straighten & reshape, cut & weld body panel parts where necessary, re-position & re-align, replacement of parts to the original position including adjustment.		1,700.00		1,300.00 1,000	
Apply rust coating on the replaced & repaired panels.		120.00		60 80.00	
Check wiring & lighting system on affected areas.		70.00		40.00	
Remove, re-install & replace rear inner garnishes, trims & boards to assist repairs.		200.00		60 120.00	
Remove, replace & re-adjust rear bumper reverse sensor.		70.00		40.00	
Remove, replace & re-install exhaust silencer & rubber hangers to assist repairs.		150.00		80.00	
Remove & re-install tailgate windscreen glass.		240.00		120.00	

Vehicle No : SBE 2332 D Hyundai Accent (A)  
Workshop : Bluwel Automotive Services Pte Ltd.

TP/0050/01/17

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
Transfer & replace tailgate mechanism to new tailgate.		150.00		60 80.00	
Spray Painting :					
To putty & spray repaired & replaced body panels.		2,000.00		1,300 1,700.00	
Grand Total :-		15,703.60		10,785.72	

Surveyed By : Lawrence Ng

9 days

Reference No. : 93MSG17009815 Cqb-1  
Policy Type: OD / TP / TP RES / TL / EVA

SBE 2332D

**(1) Office Assign Form**

C	Reference No.
C	Customer Code
N	Assign From
C	Assign Date
C	Veh No (Inspected)
C	Veh No (Insured)
C	D.O.A
C	Policy No
C	Claim No
C	Insurance Authorisation (CA /REV/REP)
C	Report Type
C	Weekend Charges
N	Survey held at/Repairer
C	Excess

[illegible]

**Surveyor** ( *Simon* ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

- |   |                        |
|---|------------------------|
| C | Vehicle No             |
| C | Regn Month/Year        |
| N | Vehicle Type           |
| N | Make & Model           |
| C | Engine Capacity. (C.C) |
| N | Colour                 |
| C | Odometer. (Sp.Reading) |
| C | Chassis No             |
| N | General Condition      |
| N | Steering               |
| N | Brake                  |
| N | Modification (Modi)    |
| C | Tyre Size              |
| N | Tyre Make              |
| C | Tyre Balance           |
| C | Date of Inspection     |
| N | Survey held            |
| N | Des.of Damages         |

[illegible]

## (2) System - (Views/Merimen)

- ### C Damaged Vehicle Photographs Uploaded

--	--	--	--

### (3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓	
✓	


#### (4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

**Check By:**

## Case Handler

Date \_\_\_\_\_

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 May 2017		22 May 2017 13:16 <a href="#">Edit Adj Rpt</a>	<b>S\$6,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$6,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	CHIAN TECK REALTY PTE.LTD., Co. Reg. No.: 200905590Z		
Main Claimant:	TAN JOO CHENG, ID: S1160505B		
Vehicle Reg. No.:	SBE2332D	Date of Loss:	20/05/2017 12:00 - :59
Claim Type:	TP / 515463	Policy/Cover Note No.:	28780601MKC (Comprehensive) Coverage: 13/07/2016 - 12/07/2017
Vehicle Reg. No. (Insured):	YM6751L	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	Bluwel Automotive Service Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 (UNIT B) #01-28, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/01/2018]		
Adj Asg. Remarks:	Please contact Ms Sally @ 6745 2088 to arrange for survey.		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- MSIG\_SG (09/01/2018): Report Send Back Alerts - SBE2332D (TP)

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SBE2332D (515463)**  
**[YM6751L]**  
**TP**  
**TAN JOO CHENG**  
**May 20 2017 12:00PM**  
**[CHIAN TECK REALTY PTE.LTD.]**  
**Bluwel Automotive Service Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Letters/Correspondences								1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print		
1	22/05/17 13:14	Non Reporting Letter to OI						<div>1</div> Load HTM			
Assessment Reports								1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print		
1	19/12/17 13:57	Accident Statement From:OD - Reg. No: YM6751L, Claimant: CHIAN TECK REALTY PTE LTD						<div>1</div> Load HTM			
Photos/Images								3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
2	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
3	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
4	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
5	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
6	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
7	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
8	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
9	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
10	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
11	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
12	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
13	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
14	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
15	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
16	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
17	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
18	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
19	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
20	23/05/17 08:49	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
21	23/05/17 08:51	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
22	23/05/17 08:51	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
23	23/05/17 08:51	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
24	23/05/17 08:51	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
25	23/05/17 08:51	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
26	23/05/17 08:51	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
27	23/05/17 08:51	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		
28	23/05/17 08:51	General View						<div>1</div> Load JPG	<input checked="" type="checkbox"/>		

29	23/05/17 08:51	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	23/05/17 08:51	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
32	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
33	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
59	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
60	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
61	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
62	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
63	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
64	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
65	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
66	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
67	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
68	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
69	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
70	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
71	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
72	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
73	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
74	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
75	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
76	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
77	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
78	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

79	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
80	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
81	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
82	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
83	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
84	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
85	05/06/17 18:02	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
86	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
87	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
88	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
89	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
90	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
91	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
92	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
93	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
94	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
95	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
96	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
97	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
98	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
99	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
100	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
101	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
102	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
103	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
104	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
105	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
106	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
107	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
108	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
109	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
110	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
111	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
112	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
113	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
114	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
115	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
116	15/06/17 14:20	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>					<input checked="" type="checkbox"/>
			1 per page	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/05/17 13:12	Pre-Repair Survey	1	Load PDF	
2	19/12/17 14:56	LOD	1	Load PDF	
3	19/12/17 14:56	FINAL REPAIR BILL	1	Load PDF	
4	19/12/17 14:58	SURVEY REPORT	1	Load PDF	
5	16/01/18 11:40	SBE2332D COLOUR PHOTOGRAPHS (1/2)	1	Load PDF	
6	16/01/18 11:40	SBE2332D COLOUR PHOTOGRAPHS (2/2)	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/01/18 11:02	Invoice	1	Load PDF	
2	26/01/18 11:02	PHOTO	1	Load PDF	

Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17009815/CQBE2-1

Date: 26/01/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28780601MKC

Claimant Vehicle No : SBE2332D

Insured Vehicle No : YM6751L

Date of Loss: 20/05/2017

Nature of Claim: TP

Claim No: 515463

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBE2332D

Make &amp; Model: HYUNDAI ACCENT, 1.4 (A)

Engine No: G4LCFU388094

Reg. Date: 17/04/2015 (Man. Year: 2015)

Chassis No: KMHCT51BTFU229707

Colour: Red

Odometer: 23913 km

Engine Capacity: 1368 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size: 175/70 R14

Front Left Side: Kumho 5 mm

Rear Left Side: Kumho 5 mm

Front Right Side: Kumho 5 mm

Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,003.60	4,734.20	6,269.40	56.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	2,760.00	1,940.00	41.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,703.60</b>	<b>7,494.20</b>	<b>8,209.40</b>	<b>52.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,000.00</b>		
<b>(S\$)</b>	<b>15,703.60</b>	<b>6,000.00</b>	<b>9,703.60</b>	<b>61.79</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,099.25</b>	<b>420.00</b>	<b>679.25</b>	<b>61.79</b>
<b>Nett Amount (S\$)</b>	<b>16,802.85</b>	<b>6,420.00</b>	<b>10,382.85</b>	<b>61.79</b>

### INSPECTION

Date of Assignment: 22/05/2017

Date Inspected: 22/05/2017 Inspected At:

BLUWEL AUTOMOTIVE SERVICE PTE LTD  
BLK 1 KAKI BUKIT AVE 6  
#01-28/51/53/55(MAIN OFFICE)  
SINGAPORE 417883

Estimated Period of Repair: 9.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 26 Jan 2018)

**Parts:** 143      **HYUNDAI ACCENT 1.4 (A) (Catalogue:Merimen Singapore 1.0)**

**Labour:** Repairer's      **(Price-denominated Standard List)**

**Print Code:** (Unsubmitted, no print-code for SBE2332D)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Repair	1,177.40 F	*- FL
2	1	*BONNET RH HINGE	Serviceable	45.90 F	*- FL
3	1	*BONNET LH HINGE	Serviceable	45.90 F	*- FL
4	1	*FRONT BUMPER	Dented	418.30 F	*418.30 FL
5	1	*FRONT BUMPER TOP RUBBER SEAL	Necessary	41.60 F	*41.60 FL
6	1	*FRONT BUMPER INNER SPONGE	Cracked	110.70 F	*110.70 FL
7	1	*FRONT BUMPER LOWER GRILLE	Cracked	47.90 F	*47.90 FL
8	1	*FRONT BUMPER REINFORCEMENT	Refit	261.60 F	*- FL
9	1	*FRONT GRILLE	Cracked	62.50 F	*62.50 FL
10	1	*FRONT GRILLE EMBLEM	Necessary	25.60 F	*25.60 FL
11	2	*FRONT GRILLE CHROME MOULDINGS	Refit	92.70 F	*- FL
12	1	*RH HEADLAMP	Not Necessary	517.70 F	*- FL
13	1	*LH HEADLAMP	Cracked	527.70 F	*527.70 FL
14	1	*SUPPORT PANEL	Repair	781.80 F	*- FL
15	1	*SUPPORT PANEL TOP GARNISH	Deformed	47.80 F	*47.80 FL
16	1	*TAILGATE	Dented	1,303.20 F	*1,303.20 FL
17	1	*TAILGATE ACCENT EMBLEM	Necessary	31.20 F	*31.20 FL
18	1	*TAILGATE CENTRE EMBLEM	Necessary	23.30 F	*23.30 FL
19	1	*TAILGATE OUTER HANDLE	Dented	72.50 F	*72.50 FL
20	1	*TAILGATE LOCK	Bent	166.80 F	*166.80 FL
21	1	*TAILGATE LOCK CATCH	Serviceable	11.30 F	*- FL
22	1	*TAILGATE WEATHERSTRIP	Bent	52.60 F	*52.60 FL
23	1	*TAILGATE INNER TRIM BOARD	Not Necessary	58.20 F	*- FL
24	1	*TAILGATE WINDSCREEN GLASS	Refit	377.10 F	*- FL
25	1	*TAILGATE WINDSCREEN GLASS WIPER MOTOR	Serviceable	249.80 F	*- FL
26	1	*REAR BUMPER	Dented	406.40 F	*406.40 FL
27	1	*REAR BUMPER LH REFLECTOR	Cracked	53.40 F	*53.40 FL
28	1	*REAR BUMPER RH REFLECTOR	Not Necessary	53.40 F	*- FL
29	1	*REAR BUMPER NUMBER PLATE LAMP	Refit	35.20 F	*- FL
30	1	*REAR BUMPER REINFORCEMENT	Dented	365.40 F	*365.40 FL
31	1	*REAR BUMPER REINFORCEMENT RH STAY	Serviceable	84.40 F	*- FL
32	1	*REAR BUMPER REINFORCEMENT LH STAY	Dented	84.40 F	*84.40 FL
33	2	*REAR BUMPER REINFORCEMENT LOWER BRACKETS	Bent	21.40 F	*21.40 FL
34	2	*REAR BUMPER REINFORCEMENT UPPER BRACKETS	Bent	21.40 F	*21.40 FL
35	1	*RH TAIL-LAMP	Not Necessary	302.80 F	*- FL
36	1	*LH TAIL-LAMP	Cracked	302.80 F	*302.80 FL
37	1	*END PANEL	Dented	499.30 F	*499.30 FL
38	1	*END PANEL INNER GARNISH	Deformed	115.10 F	*115.10 FL
39	1	*REAR FENDER RH INNER TRIM BOARD	Not Necessary	98.70 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR FENDER LH INNER TRIM BOARD	Cracked	98.70 F	*98.70 FL
41	1		*SPARE TYRE PANEL TOP BOARD	Cracked	339.00 F	*339.00 FL
42	1		*EXHAUST SILENCER	Serviceable	560.70 F	*- FL
43	1		*FRONT NUMBER PLATE	Dented	70.00 FS	*35.00 FS
44	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*40.00 FS
45	1		*SET SUPPORT PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*23.00 FS
46	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	70.00 FS	*20.00 FS
47	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*40.00 FS
48	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	70.00 FS	*34.00 FS
49	1		*REAR NUMBER PLATE	Dented	70.00 FS	*35.00 FS
50	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*40.00 FS
51	1		*SET REAR BUMPER REVERSE SENSOR	Dented	320.00 FS	*200.00 FS
52	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	60.00 FS	*20.00 FS
53	1		*SET REAR FENDER RH INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*28.00 FS
54	1		*SET REAR FENDER LH INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*28.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,003.60</b>	<b>5,782.00</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>1,047.80</b>
<b>Total Parts (\$\$)</b>	<b>11,003.60</b>	<b>4,734.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	APPLY RUST COATING ON THE REPLACED & REPAIRED PANELS	New	120.00	60.00
2	CHECK WIRING & LIGHTING SYSTEM ON AFFECTED AREAS	New	70.00	40.00
3	REMOVE, RE-INSTALL & REPLACE REAR INNER GARNISHES, TRIMS & BOARDS TO ASSIST REPAIRS	New	200.00	60.00
4	REMOVE, REPLACE & RE-ADJUST REAR BUMPER REVERSE SENSOR	New	70.00	40.00
5	REMOVE, REPLACE & RE-INSTALL EXHAUST SILENCER & RUBBER HANGERSR TO ASSIST REPAIRS	New	150.00	80.00
6	REMOVE & RE-INSTALL TAILGATE WINDSCREEN GLASS	New	240.00	120.00
7	TRANSFER & REPLACE TAILGATE MECHANISM TO NEW TAILGATE	New	150.00	60.00
8	TO PUTTY & SPRAY REPAIRED & REPLACED BODY PANELS	New	2,000.00	1,300.00
9	TO REMOVE & REPLACE THE ABOVE LISTED PARTS, KNOCK, STRAIGHTEN & RESHAPE, CUT & WELD BODY PANEL PARTS WHERE NECESSARY, RE-POSITION & RE-ALIGN, REPLACEMENT OF PARTS TO THE ORIGINAL POSITION INCLUDING ADJUSTMENT	New	1,700.00	1,000.00
<b>Gross Labour Cost (S\$)</b>			<b>4,700.00</b>	<b>2,760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >