

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore (068811)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6338 7288 Fax : 6880 4838

DEAR SIR / MADAM :

*Not Authorised
Running After Police*

ACCIDENT REPAIR ON: SKR5995X

MODEL : TOYOTA ESTIMA AERAS 2.4 CVT

POLICY NO : GA163006/1

CHASSIS NO : ACR500185480

ENGINE NO : 2AZJ119907

DATE / TIME OF ACCIDENT: 09/01/2017 Time: 1915Hrs along THOMSON RD (B4 THOMSON FLYOVER)

THIRD PARTY VEHICLE NO: FBC8024P

Date: 15/01/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Rear Fender RH	1	901.50		901.50 ✓
2	Rear Fender Shield	1	189.65		189.65 ✓
3	Rear Fender Quarter Glass Moulding w/Glass	1			-
4	Rear Tail Lamp Assy RH	1	402.40		402.40 ✓
5	Rear Bumper	1	586.20		586.20 X
6	Rear Bumper Side Retainer (Short) LH	1	56.71		56.71 X
7	Rear Bumper Side Retainer (Short) RH	1	56.71		56.71 X
8	Rear Bumper Side Retainer (Long) LH	1	67.80		67.80 X
9	Rear Bumper Side Retainer (Long) RH	1	67.80		67.80 X
10	Rear Bumper Reflector RH	1	60.70		60.70 X
11	Tailgate	1	1,701.70		1,701.70 X
12	Tailgate Weatherstrip	1	376.40		376.40 X
13	Tailgate Lettering "Estima"	1	66.95		66.95 ✓
14	Tailgate Lettering "Aeras"	1	57.80		57.80 ✓
15	Tailgate Emblem	1	66.70		66.70 ✓
16	Rear Windscreen Moulding Set	1	127.30		127.30 X

Sub-Total: 4,786.32
Less 25% Discount 1,196.58
Total Parts: 4,786.32

Special Nett Items

1	Anti-rust coating	1	80.00		80.00 X
2	Rear Bumper Clips	10	3.89		38.90 X
3	Front Fender Shield Clips RH	10	3.89		38.90 X
4	Reverse sensor set	1	300.00		300.00 X
5	Wheel Rim	1			- X
	Windscreen Sealant	1	100.00		100.00 X
					457.80

Total Parts: 5,244.12

Labour Charges For Rear/RH Side Portion

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	4001 1,250.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	6601 1,000.00
3	Provide skill labour to disconnect and check electrical wiring	60.00 201
4	Provide skill labour to check and re-adjust wheel alignment	80.00 X
5	Provide skill labour to remove and replace wheel rim and tyre with balancing	80.00 X
6	Provide skill labour to remove and refit rear windscreen	200.00 X
7	Provide skill labour to dismantle and transfer tailgate and mechanism to facilitate repair	120.00 X
	Provide skill labour to remove and replace bumper sensors	120.00 X
Total Labour:		2,910.00
Total Parts & Labour:		8,154.12
GST 7%		570.79
Grand Total:		8,724.91

Estimate Repair Duration7 days

ACCIDENT VEHICLE OF : 'SKR5995X'

Page : 2 of 2

4 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : Kenneth
Company : LKK
Date : 15/1/18
Time : 1.05pm
Contact No : 96910663
Email : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: