

ASS. REC. BY:

REF: CS3 / MS618000954 / WB57

range
Special Instruction:

Supervisor: Wilson ASSIGNMENT (Office)

From (Person): Catherine Thica of MS61 Date/Time: 16012018 11:25am

Estimated Cost: _____ Bill to: _____

OD / ~~FF~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKW 979H Insured: SKP 956C

at Workshop m/s N-51 Automotive Tel: 6847 0051

of 2 Kaki Buldt Ave 2 #01-17

Policy No: B27760954 SMP Claim No: 546016

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13012018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP' H.O.D. Endorsement: _____

Date/Time: 16012018 11:44 am Person Contacted: Zynn Vehicle IN OUT

| Date/Time | Action/Instruction (- X) Estimate |
|-----------|--|
| | SKW 979H - NA / EQ218000317 / R3 DOA: 13012018 |
| | SKP 956C - NA / MS618000823 / R3 DOA: 13012018 |
| | Dismantle part: 17012018 |
| | After repair: 19012018 |
| | |
| | |

PRS

REF: MSEL

3 YEARS
MILWAUKEE

ASSIGNMENT

From: _____ Date: 16.01.2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKW 9179H

at Workshop m/s: N-51 Automotiva

of: 2 Kaki Bukit Ave 2 #01-17

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SKW 9179H Yr Regn: 20/11/2015

Type: M.C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Tryster Harrier o.c. 1986

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 26321 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Z3460-0056472

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Mod: NI / S/Rim / STD A/Rim or _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|----------|----------|
| N/S | O/S |
| <u>X</u> | <u>X</u> |

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

Tyre Size: F: 225/65R17

R: 225/65R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GEOLANDAR (F) (CR)

Front 4 mm R/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 13/1/18 D.O.I. 16/1/2018

Survey held at: As Above

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Des. of Damages: Frt Rear O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|------------------------------|
| | <u>Range \$3900 - \$4900</u> |
| | <u>4 Days</u> |

RECEIVED 08 APR 2018

Date/Time: File Pass to? : Preli. Report

1) 06.01.2018 : Final Report

Date/Time: File Return to? _____

2) _____

Report Format: PRS

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Other: _____

ADD Fee: Site Insp (\$ _____)

Inter/ew (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

Photos: _____

Other: _____

TOTAL: _____

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---------|---------------|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 15 Jan 2018 | | 16 Jan 2018 11:25 Assign | | | | New Assignment Cancel Case |

| | | | | |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

CLAIM SUBFOLDER DETAILS [Created by insurer]

| | | | |
|------------------------------------|---|-------------------------------|---|
| Insured: | HU YUEQI, ID: S2667843I, Tel: +6598301365, Email: NOEMAIL | | |
| Main Claimant: | WEI QINFENG, ID: G1528288L | | |
| Vehicle Reg. No.: | SKW9179H | Date of Loss: | 13/01/2018 17:00 - :59 |
| Claim Type: | TP / 546016 | Policy/Cover Note No.: | B27760954SMP (Comprehensive) Coverage: 13/08/2017 - 12/08/2018 |
| Vehicle Reg. No. (Insured): | SKP956C | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051 | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/01/2018] | | |
| Driver/Custodian (Insured): | HU YUEQI (52 / Male), NRIC: S2667843I, Tel: +6598301365 | | |

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

| | | | |
|-----------------------------------|--|--------------|----------------|
| Vehicle No. | SKW 9179 H | Model / Make | TOYOTA HARRIER |
| Date of Accident | 13/01/18 | | |
| Time of Accident | 1730 HRS | | |
| Location of Accident | CHINA TOWN EU TOWN SEN ST | | |
| Exact purpose use during accident | PRIVATE USE | | |
| Name of Owner | Wei Ginfeng | | |
| Telephone No. | H/P: 98102389 Home: 96678693 Office: | | |
| NRIC | x 95292082 | | |
| Address | 29, Fernvale Close # 22-19 Rivertrees Residence S'79746x | | |
| Claim type | OD THIRD PARTY REPORTING ONLY | | |
| Insurance Company | EC2 | | |
| Type of Coverage | Comprehensive Third Party Third Party / Fire / Theft | | |
| Policy No. | DMP5HQ17-000015 / | | |
| Name of Driver | As Above If No, Lin Xiang | | |
| NRIC | F2560936X Any Passengers: 0 | | |
| Date of birth | 19 July 1966 | | |
| Occupation | Outdoor / Indoor | | |
| Driving License Pass Date | 26 April 2017 | | |
| Gender | Male / Female | | |
| Contact No. | H/P: 98102389 Home: 96678693 Office: | | |
| Address | 29, Fernvale Fernvale close # 22-19 Rivertrees Residence S'797464 | | |
| Driver have any own vehicle | No, If yes, Reg No. | | |
| Relationship | Employee, If no, state Husband | | |
| Weather condition | Clear Raining Other DRIZZLE | | |
| Road Surface | Dry Wet Other | | |
| Any Injuries | No, If Yes, Who? | | |
| Name And Contact No. | | | |
| Name And Contact No. | | | |
| Police Report | No, If Yes, Where? | | |
| Vehicle B No. | SKP 956C Any Passengers: 0 | | |
| Name of Driver | Contact No.: | | |
| Vehicle C No. | Any Passengers: | | |
| Vehicle D No. | Any Passengers: | | |
| Vehicle E no. | Any Passengers: | | |
| Vehicle F No. | Any Passengers: | | |
| Vehicle G No. | Any Passengers: | | |
| Witness Name | Witness Contact: | | |
| Accident Portion | REAR | | |
| Camera Recorder | Yes / No | | |
| Email Address | weiqinfeng21@163.com | | |
| PARTICULAR WORKSHOP | N-51 AUTOMOTIVE PTE LTD | | |
| CONTACT NO. | 6842 0051 / 6744 0510 | | |
| CONTACT PERSON | Jen | | |
| FAX NO | 6741 0510 | | |
| WORKSHOP EMAIL ADDRESS | sales@n51.com.sg | | |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

EU TONG SEN ST (WARRANT OF PEOPLE'S PARK COMPLEX

VEHICLE A - SKW 9179M

4 →

VEHICLE B - SKP 956C

3 →

2 →

1 →



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG EU TONG SEN ST, ON THE THIRD LANE TOWARDS KALLANG DIRECTION.

WHILE DRIVING FORWARD, DUE TO VEHICLE INFRONT BRAKE TO COMPLETE STOP, AND SO I TOO APPLIED BRAKE TO COMPLETE STOP. SUDDENLY AFTER A FEW SECONDS I FELT A GREAT IMPACT FROM THE REAR OF MY VEHICLE.

ALIGHTED AND REALIZED IT WAS A VEHICLE BEARING (SKP 956C) HAD COLLIDED TO THE REAR OF MY VEHICLE.

VEHICLE A - SKW 7179M
VEHICLE B - SKP 956C


DECLARATION

I/We declare the foregoing particulars are true in every respect.

* 

Policyholder's Signature

Date & Time:



Driver's Signature
(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
|------|-------------|---------------|--|--|--|-------------|---|
| Main | 15 Jan 2018 | | 16 Jan 2018 11:25 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

| | | | |
|-----------------------------|---|------------------------|--|
| Insured: | HU YUEQI, ID: S26678431, Tel: +6598301365, Email: NOEMAIL | | |
| Main Claimant: | WEI QINFENG, ID: G1528288L | | |
| Vehicle Reg. No.: | SKW9179H | Date of Loss: | 13/01/2018 17:00 - :59 [25 Months and 24 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / 546016 | Policy/Cover Note No.: | B27760954SMP (Comprehensive) Coverage: 13/08/2017 - 12/08/2018 |
| Vehicle Reg. No. (Insured): | SKP956C | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051 | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 17/01/2018] | | |
| Driver/Custodian (Insured): | HU YUEQI (52 / Male), NRIC: S26678431, Tel: +6598301365 | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

*SKW9179H (546016)
 [SKP956C]
 TP
 WEI QINFENG
 Jan 13 2018 5:00PM
 [HU YUEQI]
 N-51 Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

| Assessment Reports | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------------|-----------------|---|--------------|-------------------------------------|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 16/01/18 10:24 | Accident Statement From:SC - Reg. No: SKP956C, Claimant: HU YUEQI | Load HTM | <input type="checkbox"/> |
| Photos/Images | | | 3 per page ▼ | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 20 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 21 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 22 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 23 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 24 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 25 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 26 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 27 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 28 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 29 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 30 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 31 | 05/04/18 18:42 | General View | Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--|-------------------------------------|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 32 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 05/04/18 18:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--|-------------------------------------|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 80 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 84 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 85 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 86 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 87 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 88 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 89 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 90 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 91 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 92 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 93 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 94 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 95 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 96 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 97 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 98 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 99 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 100 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 101 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 102 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 103 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 104 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 105 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 106 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 107 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 108 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 109 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 110 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 111 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 112 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 113 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 114 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 115 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 116 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 117 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 118 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 119 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 120 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 121 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 122 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 123 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 124 | 06/04/18 15:01 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 125 | 06/04/18 15:01 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 126 | 06/04/18 15:01 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 127 | 06/04/18 15:01 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|------------|-------------------------------------|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 128 | 06/04/18 15:01 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 129 | 06/04/18 15:01 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 130 | 06/04/18 15:01 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 131 | 06/04/18 15:01 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 132 | 06/04/18 15:01 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 133 | 06/04/18 15:01 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 134 | 06/04/18 15:01 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |
| 135 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 136 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 137 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 138 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 139 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 140 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 141 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 142 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 143 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 144 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 145 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 146 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 147 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 148 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 149 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 150 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 151 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 152 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 153 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 154 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 155 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 156 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 157 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 158 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 159 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 160 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 161 | 06/04/18 15:02 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |

| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|---|------------|-------------------------------------|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 16/01/18 10:24 | Fax From Third Party | Load PDF | |
| 2 | 16/01/18 10:24 | Email from Third Party | Load PDF | |
| 3 | 16/01/18 10:24 | TP GIA Rep - SKW9179H From:SC - Reg. No: SKP956C, Claimant: HU YUEQI | Load PDF | |
| 4 | 16/01/18 11:24 | Disagree on SJE | Load PDF | |
| 5 | 16/01/18 11:24 | Reply on Disagree of SJE | Load PDF | |
| 6 | 16/01/18 11:31 | Fax frm Third Party on Survey | Load PDF | |

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18000954/WBS2
Date: 10/04/2018

REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | B27760954SMP |
| Claimant Vehicle No : | SKW9179H | Insured Vehicle No : | SKP956C |
| Date of Loss: | 13/01/2018 | Nature of Claim: | TP |
| | | Claim No: | 546016 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--------------------------------------|-------------|--------------|
| Reg No: | SKW9179H | Engine No: | 3ZRB632554 |
| Make & Model: | TOYOTA HARRIER, 2.0 ELEGANCE CVT (A) | Chassis No: | ZSU600056472 |
| Reg. Date: | 20/11/2015 (Man. Year: 2015) | Odometer: | 26321 km |
| Colour: | Black | | |
| Engine Capacity: | 1986 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition: | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size: | 225/65R17 | Rear Tyre Size: | 225/65R17 |
| Front Left Side: | GEOLANDAR 4 mm | Rear Left Side: | GEOLANDAR 4 mm |
| Front Right Side: | GEOLANDAR 4 mm | Rear Right Side: | GEOLANDAR 4 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 16/01/2018 | |
| Date Inspected: | 16/01/2018 Inspected At: | N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921 |
| Estimated Period of Repair: | 0.0 days | |

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/10/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,900.00 - \$4,900.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Apr 2018)

Parts: M1-SUV TOYOTA HARRIER 2.0 ELEGANCE CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKW9179H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >