

INS. CASE OWNER:

Jms

CC 4/AXA1800 0957, K hb3

LKK: IDAC:

Surveyor: Kenneth DOI: 16/1/18 Date/Time: 16/1/18

ASSIGNMENT

Registered in Merimen: 58M00570

Pre-assign / CCU / FTE



Insured Vehicle No.: SKU 6099K
Name of Insured: KUA ZHI YONG
Insured Tel No.: HP: 94375084
Excess Sec II :S\$
Is driver the owner? (YES / NO)

Claim No.: 58M00570 / 24596
Policy No.: VPA/P1950982
Make / Model: 2010 TM
Place of Accident: SUE NEAR EXIT 8A

If NO, Driver Name / Age: OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO
Driver Tel No.: (V/L) YES / NO Insured Liability: % Final? Yes / No

SUE 3030M



INSRS: WSP: Tel: Liability: RMKS: AUTOWORK



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Table with columns for Date/Time, Description, STAGE, and DATE / PIC. Includes sections for PRELIMINARY ADVICE, FINALIZATION, FINAL SETTLEMENT, and FINAL PAYMENT.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18000957/Khb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 16-01-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKU 6099K	Veh. Inspected	SLL 3030M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	16/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/01/2018	Inspection Date	16/01/2018
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

kh

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

*Not authorized
6/1/18 @ 3750/-
Penny After Paint
Sday*

THAMAINDRAN
c/o 46 Lentor Plain
Singapore 786548

Date: 16/01/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
RE : TOYOTA COROLLA ALTIS / SLL3030M		
1 pc	rear bumper	<i>Bu</i> 564.10
1 pc	rear bumper reinforcement	<i>Bu</i> 365.40
2 pcs	rear bumper reflector @ 173.20	<i>Sm</i> 346.40
2 pcs	rear bumper side retainer @ 63.40	<i>N/S</i> 126.80
2 pcs	rear bumper reinforcement bracket @ 147.10	<i>N/S</i> 294.20
2 pcs	rear bumper corner retainer @ 61.40	<i>Sm</i> 122.80
1 pc	rear boot lid	<i>Bu</i> 765.20
1 pc	rear boot lock	<i>R</i> 164.40
1 pc	rear boot lock catch	<i>R</i> 73.20
2 pcs	rear boot lamp <i>295.00</i> @ 357.10	<i>N/S</i> 714.20
1 pc	rear boot weathership	<i>Sm</i> 279.60
1 pc	rear boot emblem	<i>Sm</i> 74.10
1 pc	rear boot emblem "COROLLA"	<i>Sm</i> 64.30
1 pc	rear boot emblem "ALTIS"	<i>Sm</i> 65.70
1 pc	rear end panel	<i>Bu</i> 571.40
1 pc	rear end panel garnish <i>240.00</i>	<i>Mg/Du</i> 331.90
2 pcs	reverse sensor <i>282.00</i> @ 346.40	<i>Shat</i> 692.80
1 pc	rear lock sensor receiver	<i>Shat</i> 275.00
2 pcs	rear tail lamp <i>499.60</i> @ 564.70	<i>N/S</i> 1,129.40
1 pc	rear spare tyre panel top board	<i>Sm</i> 356.10
1 pc	rear exhaust silencer	<i>R</i> 974.80
sub-total		8,351.80
less 25%		2,087.95
sub-total		6,263.85

LKK Auto Consultants hence notify the Repairor of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurer's Company

Authorised by Repairor:
Signature:
Date:

balance brought forward.	6,263.85	
To remove and replace the parts mentioned above, above, panel beat and realign the necessary affected areas.	1,000.00	<i>600</i>
To check wiring system.	50.00	<i>200</i>
To apply putty and spray painting on affected areas.	750.00	<i>600</i>
To install reverse sensor & reverse camera.	120.00	<i>600</i>
To apply rust proofing on affected areas.	200.00	<i>600</i>
To apply water proof sealant on affected areas.	200.00	<i>300</i>
To carry out exhaust works.	120.00	<i>na</i> X
Total	8,703.85	

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

THAMAINDRAN

c/o 46 Lentor Plain
Singapore 786548

*Not withstanding
1/16/18
Purvey After Pains
5 days*

Date: 16/01/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
RE : TOYOTA COROLLA ALTIS / SLL3030M		
1 pc	rear bumper	<i>Pr</i> 564.10 ✓
1 pc	rear bumper reinforcement	<i>Pr</i> 365.40 ✓
2 pcs	rear bumper reflector @ 173.20	<i>Sm</i> 346.40 X
2 pcs	rear bumper side retainer @ 63.40	<i>n/s</i> 126.80 ✓
2 pcs	rear bumper reinforcement bracket @ 147.10	294.20 ✓
2 pcs	rear bumper corner retainer @ 61.40	122.80 ✓
1 pc	rear boot lid	<i>Pr</i> 765.20 ✓
1 pc	rear boot lock	<i>n</i> 164.40 X
1 pc	rear boot lock catch	<i>n</i> 73.20 X
2 pcs	rear boot lamp <i>n/s</i> @ 357.10	714.20 ✓
1 pc	rear boot weathership	<i>So</i> 279.60 ✓
1 pc	rear boot emblem	<i>rec</i> 74.10 ✓
1 pc	rear boot emblem "COROLLA"	<i>rec</i> 64.30 ✓
1 pc	rear boot emblem "ALTIS"	<i>rec</i> 65.70 ✓
1 pc	rear end panel	571.40 ✓
1 pc	rear end panel garnish	331.90 ✓
2 pcs	reverse sensor @ 346.40	692.80 ✓
1 pc	rear lock sensor receiver	275.00 ✓
2 pcs	rear tail lamp <i>n/s</i> @ 564.70	<i>cl/s</i> 1,129.40 X
1 pc	rear spare tyre panel top board	<i>Sm</i> 356.10 X
1 pc	rear exhaust silencer	<i>n</i> 974.80 X
	sub-total	8,351.80
	less 25%	2,087.95
	sub-total	6,263.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	<p>balance brought forward.</p> <p>To remove and replace the parts mentioned above, above, panel beat and realign the necessary affected areas.</p> <p>To check wiring system.</p> <p>To apply putty and spray painting on affected areas.</p> <p>To install reverse sensor & reverse camera.</p> <p>To apply rust proofing on affected areas.</p> <p>To apply water proof sealant on affected areas.</p> <p>To carry out exhaust works.</p>	<p>6,263.85</p> <p>1,000.00 ?</p> <p><i>200</i> 50.00</p> <p><i>600</i> 750.00</p> <p><i>600</i> 120.00</p> <p>200.00 ?</p> <p>200.00 ?</p> <p><i>na</i> 120.00 X</p> <hr/> <p>Total 8,703.85</p>
--	--	---

Vic (LKKAuto)

From: admin@supreme.sg
Sent: Tuesday, 16 October, 2018 10:55 AM
To: Vic (LKKAuto)
Cc: Admin A; 'Dylan Chew'
Subject: DV
Attachments: 16102018_102609_BRN3C2AF46F4866_000634.pdf

Hi Vic,

DV attached for your settlement.

Best regards,
Yuki Ho
Supreme Auto Service Pte Ltd
No.176 Sin Ming Drive
#02-01 Singapore 575721
Tel: 64528211
Fax: 64517423

◀ **Re:SEEK QUANTUM MANDATE S8M0084O**

Type

🗨 Question

Message

hi, we will not compensate for LOU. please offer 4 days LOR and COR as advised.

Reply

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKU 6099K (Insd veh)	Model:	TOYOTA COROLLA ALTIS 1.6 CVT
	SLL 3030M (TP veh)		
Date of Accident:	15/01/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	8,703.85
Final Repair Cost	:	\$	3,750.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	428.00 4 days
LTA / GIA Search Fee	:	\$	2.00

Others: : \$

: \$

Final Settlement Sum : \$ 4,180.00

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	AUTOWORX HOUSE	: \$ 4,180.00

NUR SHAQILAH BTE ABDOL
WAHAB

02/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18000957/Khb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: JAS TAN		Date : 02-11-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKU 6099K	Veh. Inspected	SLL 3030M
Policy No.	VPA/P1950982	Coverage (\$)	0.00
Claim No.	S8M00840	Excess (\$)	0.00
Assign From	JAS TAN	Assign Date	16/01/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MR053REH104551098	Colour	METALLIC SILVER
Odometer	27448	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/45R17	MICHELIN	6 mm
L/H Front Tyre	215/45R17	MICHELIN	6 mm
R/H Rear Tyre	215/45R17	MICHELIN	7 mm
L/H Rear Tyre	215/45R17	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/01/2018	Inspection Date	16/01/2018
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 3030M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	BUCKLED	564.10	564.10
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	365.40	365.40
2	REAR BUMPER REFLECTOR @ \$173.20 (CONSISTENT)	SERVICEABLE	346.40	-
2	REAR BUMPER SIDE RETAINER @ \$63.40 (CONSISTENT)	N/S DISTORTED	126.80	63.40
2	REAR BUMPER REINFORCEMENT BRACKET @ \$147.10 (CONSISTENT)	N/S DENTED	294.20	147.10
2	REAR BUMPER CORNER RETAINER @ \$61.40 (CONSISTENT)	SERVICEABLE	122.80	-
1	REAR BOOT LID (CONSISTENT)	BENT	765.20	765.20
1	REAR BOOT LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	164.40	-
1	REAR BOOT LOCK CATCH (CONSISTENT)	TO REPAIR SEE LABOUR	73.20	-
2	REAR BOOT LAMP @ \$357.10 (CONSISTENT)	N/S CUT	714.20	295.00
1	REAR BOOT WEATHERSTRIP (CONSISTENT)	SERVICEABLE	279.60	-
1	REAR BOOT EMBLEM (CONSISTENT)	NECESSARY	74.10	74.10
1	REAR BOOT EMBLEM "COROLLA" (CONSISTENT)	NECESSARY	64.30	64.30
1	REAR BOOT EMBLEM "ALTIS" (CONSISTENT)	NECESSARY	65.70	65.70
1	REAR END PANEL (CONSISTENT)	BENT	571.40	571.40
1	REAR END PANEL GARNISH (CONSISTENT)	MTG DISTORTED	331.90	240.00
2	REVERSE SENSOR @ \$346.40 (CONSISTENT)	SHORTED	692.80	282.00
1	REAR LOCK SENSOR RECEIVER (CONSISTENT)	SHORTED	275.00	275.00
2	REAR TAIL LAMP @ \$564.70 (CONSISTENT)	N/S MTG CRACKED / O/S SERVICEABLE	1,129.40	499.60
1	REAR SPARE TYRE PANEL TOP BOARD (CONSISTENT)	SERVICEABLE	356.10	-
1	REAR EXHAUST SILENCER (CONSISTENT)	TO REPAIR SEE LABOUR	974.80	-
	LESS 25% DISCOUNT		-2,087.95	-1,068.08
			6,263.85	3,204.22

Report Ref No. CC4/ASM18000957/Khb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE, ABOVE PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR BOOT LOCK, REAR BOOT LOCK CATCH AND REAR EXHAUST SILENCER.		1,000.00	600.00
	TO CHECK WIRING SYSTEM.		50.00	20.00
	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS.		750.00	600.00
	TO INSTALL REVERSE SENSOR & REVERSE CAMERA.		120.00	60.00
	TO APPLY RUST PROOFING ON AFFECTED AREAS.		200.00	60.00
	TO APPLY WATER PROOF SEALANT ON AFFECTED AREAS.		200.00	30.00
	TO CARRY OUT EXHAUST WORKS.	NOT NECESSARY	120.00	-
			2,440.00	1,370.00
	GRAND TOTAL		8,703.85	4,574.22
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,750.00

Report Ref No. CC4/ASM18000957/Khb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.