

15th January 2018

AXA Insurance Pte Ltd
8 Shenton Way,
#24-01 AXA Tower
Singapore 068811

LKK Auto Consultants here notify
the Repairer of the following:

- To repair before after spray painting
- To display damaged parts during repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

杨通国际



ROC / CR / GST Reg No: 200004370R

Quotation No.: Q18-OPS-0041

Dear Sir

Estimated Cost of Repair Job for PC5550R & GBA9419M on 08/01/2018

S/n	Description	Qty	UOM	Unit Price	Total Price
1	To supply passenger door frame rubber	1	pc	\$108.75	\$108.75
2	To supply front bumper	1	pc	\$1,220.27	\$1,220.27
3	To supply front head lamp LHS	1	pc	\$448.20	\$448.20
4	To repair front wall fibre LHS	1	job	\$1,650.00	\$1,650.00
5	Labour to remove and install passenger door frame rubber				
6	Labour to remove and install front bumper cum alignment	2	days	\$360.00	\$720.00
7	labour to remove and install front head lamp LHS				
8	To supply Labour and material to spray painting front bumper, front wall LHS portion, passenger door	2	days	\$360.00	\$720.00
SUB-TOTAL					4,867.22
GST					340.71
Total					5,207.93

Terms and Conditions:

Price quoted subject to 7% GST

Yours faithfully

Elson Lim

Elson Lim
Operation Manager
hp : 91114480

556.95
10% = 501.25
950
1451.25
2% = 1160

Guo Qiang - 82880282.
lumpsum repair.
After repair photos.
Guo Qiang@lkkauto.com
17/4/18. 3 days.

Total: 1160

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com | Email: claims@LexBuild.com

