

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFA 3588A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (SN)	DEFORMED	1,630.57	1,630.57
1	LEFT CHROME MOULDING (SN)	NECESSARY	128.17	128.17
1	RIGHT CHROME MOULDING (SN)	NECESSARY	128.17	128.17
1	REAR BOTTOM TRIM BUMPER (SN)	CUT	241.49	241.49
1	REAR BUMPER LOWER CTR MOULDING (SN)	NECESSARY	158.78	158.78
1	REAR SWITCHING BRACKET (SN)	SERVICEABLE	46.06	-
1	DISTANCE SENSOR (SN)	SERVICEABLE	172.07	-
1	REAR CROSS MEMBER (SN)	BENT	789.45	789.45
1	COVER (ADDITIONAL)(SN)	CUT	38.15	38.15
1	RIGHT BOTTOM BRACKET (ADDITIONAL)(SN)	CUT	17.36	17.36
1	LEFT BOTTOM BRACKET (ADDITIONAL)(SN)	CUT	17.36	17.36
1	BASIC MOUNTING FOR BUMPER (ADDITIONAL)(SN)	CRACKED	211.58	211.58
			3,579.21	3,361.08
	<u>LABOUR</u>			
	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANFARD.		380.00	380.00
	RESPRAY REAR BUMPER.		840.00	840.00
	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.		1,920.00	1,920.00
	DISASSEMBLE AND ADJUST HEAD REST & REFINISH.		240.00	240.00
			3,380.00	3,380.00
	GRAND TOTAL		6,959.21	6,741.08
	RECOMMENDED COST OF REPAIRS			6,741.08

Report Ref No. CS/FC118000969/R1vd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.