

ASS. REC. BY:

REF: CS/ms618000977/T/rbz

Special Instruction:

Subval: Merinun

Tawfik

ASSIGNMENT (Office)

From (Person):

Monira Chung

of

MSTK

Date/Time: 16/01/2018 3:18 pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 3087X

Insured:

SDD 2928S

at Workshop m/s

Ding Auto

Tel:

9733 5832

of

219 Jln Boon Lay

Policy No:

27802090MY

Claim No:

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 13-01-2018

CA / REV / REP. / REV 24 HRS WPI

17-01-2018

H.O.D. Endorsement:

Date/Time:

16-01-2018 3:57pm

Person Contacted:

Jing Feng

Vehicle IN / OUT

Date/Time	Action/Instruction (✓): Estimate
	<u>SLH 3087X - X</u>
	<u>SDD 2928S - X</u>
<u>15.1.2018</u>	<u>Sent preli through merinun</u>

Touyuh

MSIG

Date: 17/10/2018

SLH 3087X

2x6 out

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLH 3087X

At Workshop: Ding Auto

of 249 jln Boon Lay

Insured:

Policy No:

Claim No:

Sum Insured:

Excess:

(Client's Record)

Jin Feng

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	
NS	OS
X	

Sal. or Market value:

DAC Accident Report Consistent? : Yes or No

GIA PR Seen Consistent? : Yes or No

Est. Repairs days Res: Yes or No

Lum Sum % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date Person Contacted

Vehicle IN / OUT  
Jin Feng

Type: 11 Cycles / Bus / Van / Long / Taxi / Home Mover

Truck / Trailer

Make: Toyota A/Ts 1578

Color: Blue. Insured / Std. N / NA

So. Reg. No: 84242 Insured / Std. N / NA

Eng. No:

Cyl: MK053REH/04550710

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S / R / STD A / Rim or

Tyre Size: R 205/55R16  
R 2 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / RIR / SUMI

TOYO / YOKO or Achilles

Front: 6 Rear: 6

RBa: 6 LBa: 6

D.O.A. DO: 17/11/18 @ 1345

Survey held at: Ding Auto Boon Lay

Class of Damages: (P) (R) OS / NS / UC / Rock or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Confirm LIs 88450. 10 days  
Red: 8576.42, 50%

RECEIVED 2 APR 2018

Date / Time File Pass /

typist

Prelim. Report  
 Final Report

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee

300

Date / Time File Return /

Add Fee:  Stamped 5

Man. print 5  
 Faxing 5  
 Red. 5

Transporter

Light / Fuel

Food

Other

10

Report Format: TP

Lum. Sum: 8450

310



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000977/T1rb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 16-01-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDD 2928S	Veh. Inspected	SLH 3087X
Policy No.	27802019QMY	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	16/01/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	13/01/2018	Inspection Date	17/01/2018
Survey held at	249 JLN BOON LAY		
Repairer	DING AUTO PTE LTD		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Jan 2018 09:35 <a href="#">Sendback Est</a>	16 Jan 2018 11:13 <b>S\$17,026.42</b>	16 Jan 2018 15:18 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
<b>Insured:</b>	QUEK SWEE SIANG, ID: S0014176C								
<b>Main Claimant:</b>	LCRF PTE LTD, Co. Reg. No.: 201624597K								
<b>Vehicle Reg. No.:</b>	SLH3087X	<b>Date of Loss:</b>	13/01/2018 01:00 - :59						
<b>Claim Type:</b>	TP	<b>Policy/Cover Note No.:</b>	27802019QMY (Comprehensive) Coverage: 07/11/2017 - 06/11/2018						
<b>Vehicle Reg. No. (Insured):</b>	SDD2928S	<b>Policy No. (Claimant):</b>	999995061						
		<b>Excess:</b>							
<b>Repairer:</b>	Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208								
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]								
<b>Claimant's Insurer:</b>	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [ <b>Imm.Advice</b> due 17/01/2018]								
<b>Driver/Custodian (Insured):</b>	QUEK ZHEN YUAN ( / Male), NRIC: S9310960J								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 18 Jan 2018

**Preliminary Advice**

Insured Vehicle No	: SDD2928S	Accident Date	: 13/01/2018
TP Vehicle No	: SLH3087X	Assignment Date	: 16/01/2018
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 10.00
Date of Inspection	: 17/01/2018		
Inspection At	: DING AUTO PTE LTD (HQ) BLK 10, #01-20, SIN MING INDUSTRIAL ESTATE SECTOR C SINGAPORE 575645		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,026.42
Revised Amount	:S\$	8,811.37
Check Items (Estimated)	:S\$	1,976.20
Total	:S\$	10,787.57

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

### SINGAPORE ACCIDENT STATEMENT

#### NOTICE

1. This Form is intended to speed up the claims process.  
 2. This Form is to be completed by the Policyholder and/or the Authorised Driver.  
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurers to deny liability.  
 4. The use and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.  
 5. Information reporting may be referred to the Police for investigation.  
 6. This Form is provided by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore for publishing and that copies of this report will for a fee be made available upon application by interested parties.  
 7. By providing part of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available.

#### ACCIDENT STATEMENT

Date Of Report: 15/01/2018 18:21  
 Date Of Accident: 13/01/2018 01:40  
 Exact Location Of Accident: CLEMENCEAU AVE  
 Country/State of Loss: SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number: SLH3087X  
 Insured/Policyholder:  
 Name Of Registered Owner: LCRF PTE LTD  
 Co Reg No: 201624597K  
 Email Address: NOEMAIL  
 Mobile Phone No:  
 Alternative Phone No: OFFICE-31584255  
 Vehicle Particulars:  
 Manufacturer: TOYOTA  
 Model: COROLLA ALTIS CLASSIC 1.6 CVT  
 Exact Purpose for which vehicle was being used at time of accident: PRIVATE HIRER  
 Are you claiming under your own insurance policy for repair to your vehicle?: NO  
 If No, Please state action to be taken: THIRD PARTY  
 Vehicle Category: PRIVATE CAR  
 Insurance Company:  
 Name of Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.  
 Type Of Coverage: COMPREHENSIVE  
 Fleet Policy: NO  
 Policy Number: 999995061  
 Cover Note Number:  
 Driver:  
 Name of Driver: TAY PENG LEONG  
 NRIC No: S8541615D  
 Date Of Birth: 21/12/1985  
 Occupation: OUTDOOR  
 Date Of Driving Pass: 07/08/2009  
 Driving Experience: 8 YEARS AND 5 MONTHS  
 Gender: MALE  
 Mobile Number: (LOCAL) +65-92394128  
 Fax Number:  
 Contact Number:  
 Email Address: NOEMAIL

Is driver an employee of the Insured's Company? NO

Relationship of the Driver with the Insured OTHER - HIRER

Registration Number of Driver's Own Vehicle -

Make/Model of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions RAINING

Road Surface WET

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

Have I been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name TAMPINES EAST NPP

Police Station Address ROAD: 263 TAMPINES STREET 21 #01-138 , POSTCODE: 520263 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-7839999 - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT T/20180113/2131

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDD2928S

Vehicle Make/Model/Colour

#### Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver QUEK ZHEN YUAN

NRIC/Passport Number S9310960J

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SDQ8887T  
Year/Make/Model/Colour  
Type of Property:  
Vehicle Category PRIVATE CAR  
Name of Driver MOHD ROSLAN BIN MAHMOOD  
Licence/Passport Number S1385543I  
Licence Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SLH3087X  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time: \_\_\_\_\_

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

  
Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

SKETCH PLAN

Attach sketch plan


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Attach Police Report T/20180113/2131


DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:




Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Clemenceau Ave



1 - C - SDQ - 8887-T

2 - A - SLH - 3087-X

3 - B - SDD - 2928-S





**SINGAPORE  
POLICE FORCE**



T/20180113/2131

Police Station Of Origin:  
Tampines East NPP  
253 Tampines Street 21 #01-138  
SINGAPORE 520263  
Tel No. 1800-7839999

Report No. T20180113/2131

**REPORT OF A TRAFFIC ACCIDENT**

Time Report Made: 13/01/2018 18:22	Vide Report No.:	Station Diary No. 18
---------------------------------------	------------------	-------------------------

**Informant's Particulars**

Name of Informant: TAY PENG LEONG		Address: APT BLK 278C COMPASSVALE BOW #06-569 SINGAPORE 543278	
ID Type / ID No.: NRIC NO / S8541615D		Contact No.: Home/Office: Mobile: 86869755	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 32	Date of Birth: 21/12/1985	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: UBER		Driving Licence Information: Class: 3 Date of Expiry:	

**General Information of the Accident**

Type of Accident: Non-Injury Others	Drink Drive: No	Date/Time of Accident: 13/01/2018 01:40	Type of Location: Straight Road
---	--------------------	--	------------------------------------

Location:  
Along Road 1  
CLEMENCEAU AVENUE

TOWARDS HAVELOCK ROAD

Weather: Heavy rain	Road Surface: Wet	Road Speed Limit:
Traffic Flow: Two Way	Traffic Control: Not Controlled	Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear		Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SDD2928S	Car				Seriously Damaged	0
SDQ8887T	Car				Seriously Damaged	0
SLH3087X	Car				Seriously Damaged	0



Police Station Of Origin:  
Singapore East NPP  
83 Tampines Street 21 #01-138  
SINGAPORE 520263  
Tel No 1800-7839999

CONTINUATION OF REPORT

Details of Person Involved

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Driver Name		ID No.	S8541615D
TAY PENG LEONG		Contact No.	86869755
Related Vehicle	SLH3087X (Car)	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Date Discharge	13/01/2018
Date Treatment	13/01/2018	Degree of Injury	Slight
No. of Days granted Medical Leave	05		

Brief Details:

On the 13/01/2018 at about 0139hrs, I was driving along Clemenceau Avenue towards Havelock Road in my vehicle bearing the registration plate number SLH3087X. I was driving along the second lane at that point of time.

Subsequently, I stopped my car before approaching the traffic light as it was turning red. I stopped my vehicle behind a car bearing the plate number SDQ8887T (Car A). The traffic light then turned green and Car A slowly started moving as it was raining heavily.

As I was about to move off, I felt a strong impact coming from the rear and I realised that a car bearing the plate number SDD2928S (Car C) had collided with me from the rear. As a result, my car skidded and collided the rear bumper of Car A due from the impact from behind.

All the drivers then went out to exchange particulars. No one was injured at that point of time. All the cars did suffer some serious damages to the collision. Driver of Car C admitted that it was his fault for colliding with my car.

Subsequently, I felt some strain on my back and neck thus I seek medical treatment and were given 5 days MC.



**SINGAPORE  
POLICE FORCE**



Police Station Of Origin:  
Tampines East NPP  
443 Tampines Street 21 #01-138  
SINGAPORE 520263  
Tel no: 1800-7838999

3 of 3  
Report No. T/20180113/2131

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report:  
G/  
Sgt 2 MOHAMAD IZWAN BIN MOHAMAD ISHAK

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
13/01/2018 18:22

Officer In Charge Of Case:  
TP / GIA /  
Staff Sgt TANG SIEW PING  
Contact No: 65476430



Classification Of Case:

Authentication Stamp  
SR158

SIGNATURE

**Ding Auto Pte Ltd** (Co.Reg.No:201311788Z)

Blk 10, #01-20, Sin Ming Industrial Estate Sector C  
Singapore 575645

Tel: 64521208 Fax: 64520614 Email: admin@dingauto.sg;ding@dingauto.sg;kenneth.ding@dingauto.sg

**TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

**QUEK ZHEN YUAN**

NIL

Singapore

**Claimant Insurer: AIG Asia Pacific Insurance Pte. Ltd.**

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	13/01/2018
Vehicle Reg. No.:	SLH3087X	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (TP):	TAY PENG LEONG		

Make/Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC	Vehicle Reg. Date:	28/10/2016
	CVT (A)		
Vehicle Colour:	GREY	Chassis No:	MR053REH104558710
Engine No:	1ZR593437		
Odometer:	84292 KM		

Paint Type:  
Total Loss? **NO**  
Est. Duration of Repair (day) 18

*Tay Peng Leong 97495749  
- wr -  
Resing before paint  
chng 4/5 10 days*

Description of Accident/Loss: REFER TO POLICE REPORT T/20180113/2131  
Present Location: DING AUTO PTE LTD (JALAN BOON LAY)

*sure (klau) on  
17/1/18*

COST OF CLAIMS	Amount
Parts	9,976.42
Miscellaneous Items	0.00
Labour	7,050.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>17,026.42</b>
<b>+ GST 7.00% (S\$)</b>	<b>1,191.85</b>
<b>Nett Amount (S\$)</b>	<b>18,218.27</b>

This claim is handled by: **YOU JING FENG**

### REPAIR DETAILS

#### Reference

Part Source: MRM-SG      Version: 1.0 (Last Synchronised: 16 Jan 2018)  
 Parts: 143      TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's      (Price-denominated Standard List)  
 Print Code: Ding Auto Pte Ltd/SLH3087X/16/01/2018 11:13  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

#### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID	0.00	0.00	bl 335.00F
2	1		*BOOTLID EMBLEM LOGO	0.00	0.00	al 25.00F
3	1		*BOOTLID EMBLEM COROLLA	0.00	0.00	al 24.00F
4	1		*BOOTLID EMBLEM ALTIS	0.00	0.00	al 24.00F
5	1		*BOOTLID CHROME	0.00	0.00	al 120.00F
6	1		*BOOTLID PLATE LAMP RHS	0.00	0.00	z 60.00F HN
7	1		*BOOTLID PLATE LAMP LHS	0.00	0.00	z 60.00F HN
8	1		*BOOTLID LAMP LHS	0.00	0.00	al 140.00F
9	1		*BOOTLID LAMP RHS	0.00	0.00	al 140.00F
10	1		*BOOTLID INSULATOR	0.00	0.00	z 180.00F <i>size different</i>
11	1		*BOOTLID INSULATOR CLIP	0.00	0.00	al 185.00F <i>SVC X</i>
12	1		*BOOTLID LOCK	0	0.00	dis 35.00FS
13	1		*NUMBER PLATE	0	0.00	bl 40.00FS
14	1		*REAR BUMPER	0.00	0.00	de 215.00F
15	1		*REAR BUMPER REINF	0.00	0.00	bt 145.00F
16	1		*REVERSE SENSOR	0.00	0.00	mu 156.00F
17	1		*REAR BUMPER REFLECTOR RHS	0.00	0.00	x 36.00F <i>SVC X</i>
18	1		*REAR BUMPER REFLECTOR LHS	0.00	0.00	x 36.00F <i>SVC X</i>
19	1		*REAR BUMPER RETAINER LONG LHS	0.00	0.00	neu 42.00F
20	1		*REAR BUMPER RETAINER LONG RHS	0.00	0.00	neu 42.00F
21	1		*REAR BUMPER RETAINER SHORT RHS	0.00	0.00	ne 36.00F
22	1		*REAR BUMPER RETAINER SHORT LHS	0.00	0.00	ne 36.00F
23	1		*REAR BUMPER REINF ARM LHS	0.00	0.00	z 45.00F <i>SVC SVC X</i>
24	1		*REAR BUMPER REINF ARM RHS	0.00	0.00	z 45.00F <i>SVC X</i>
25	1		*REAR END PANEL	0.00	0.00	bl 240.00F
26	1		*REAR END PANEL SEALANT	0	0.00	neu 50.00FS
27	1		*REAR END PANEL TOP GARNISH	0.00	0.00	cl 110.00F
28	1		*REAR END PANEL TOP GARNISH CLIP	0	0.00	neu 35.00FS
29	1		*SPARE TYRE PANEL	0.00	0.00	Ry 360.00F
30	1		*SPARE TYRE BOARD	0.00	0.00	neu 145.00F
31	1		*TAIL LAMP LHS	0.00	0.00	z 150.00F <i>SVC</i>
32	1		*TAIL LAMP RHS	0.00	0.00	neu 150.00F
33	1		*TAIL LAMP CLIP LHS	0.00	0.00	neu 2.40F
34	1		*TAIL LAMP CLIP RHS	0.00	0.00	neu 2.40F
35	1		*TAIL LAMP PANEL LHS	0.00	0.00	Ry 72.00F
36	1		*TAIL LAMP PANEL RHS	0.00	0.00	Ry 72.00F

Ding Auto Pte Ltd/SLH3087X/16/01/2018 11:13. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS



No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
37.	1		*REAR FENDER LHS	0.00	0.00	Ry *450.00 F
38	1		*REAR FENDER LHS TRIM	0.00	0.00	X *205.00 F
39	1		*REAR FENDER RHS TRIM	0.00	0.00	X *205.00 F
40	1		*REAR FENDER RHS	0.00	0.00	Ry *450.00 F
41	1		*BONNET	0.00	0.00	bt *360.00 F
42	1		*BONNET SEAL	0.00	0.00	we *24.00 F
43	1		*BOONET HINGE LHS	0.00	0.00	Ry *35.00 F
44	1		*BOONET HINGE RHS	0.00	0.00	Ry *35.00 F
45	1		*RADIATOR GRILLE	0.00	0.00	ae *180.00 F
46	1		*RADIATOR GRILLE TOP GARNISH	0.00	0.00	de *45.00 F?
47	1		*RADIATOR GRILLE TOP GARNISH CLIP	0	0.00	de *35.00 FS?
48	1		*HEAD LAMP LHS	0.00	0.00	ae *280.00 F
49	1		*HEAD LAMP RHS	0.00	0.00	ae *280.00 F
50	1		*FRONT BUMPER	0.00	0.00	de *215.00 F
51	1		*FRONT BUMPER SPONGE	0.00	0.00	crw *55.00 F
52	1		*FRONT BUMPER REINF	0.00	0.00	bt *120.00 F
53	1		*FRONT BUMPER REINF ARM LHS	0.00	0.00	? *45.00 F
54	1		*FRONT BUMPER REINF ARM RHS	0.00	0.00	? *45.00 F
55	1		*NUMBER PLATE	0	0.00	bt *40.00 FS
56	1		*BRACE PANEL	0.00	0.00	bt *42.00 F
57	1		*CONDENSER	0.00	0.00	? *360.00 F
58	1		*RADIATOR	0.00	0.00	bt *455.00 F
59	1		*SUPPORT PANEL	0.00	0.00	bt *250.00 F
60	1		*FRONT FENDER LHS	0.00	0.00	X *215.00 F
61	1		*FRONT FENDER LHS EMBLEM	0.00	0.00	X *24.00 F
62	1		*FRONT FENDER RHS EMBLEM	0.00	0.00	we *24.00 F
63	1		*FRONT FENDER RHS	0.00	0.00	bt *215.00 F
64	1		*FRONT BUMPER RETIANER LHS	0.00	0.00	X *24.00 F
65	1		*FRONT BUMPER RETIANER RHS	0.00	0.00	we *24.00 F
66	1		*FAN COWLING	0.00	0.00	? *85.00 F
67	1		*FAN BLADE	0.00	0.00	crw *65.00 F
68	1		*FAN MOTOR	0.00	0.00	crw *180.00 F
69	1		*RADIATOR UPPER GUILDE	0.00	0.00	? *48.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	8,705.80
+ Margin on L,N Items 15.00% (\$\$)	1,270.62
<b>Total Parts (\$\$)</b>	<b>9,976.42</b>

Ding Auto Pte Ltd/SLH3087X/16/01/2018 11:13. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	1600 2,800.00
2	R&R BOOTLID COMPONENTS	New	50 100.00
3	R&R SPARE TYRE /BOARD/CARPET/TRIM	New	60 150.00
4	R&R REVERSE SENSOR AND SPRAY PAINTING	New	30 100.00
5	R&R FUEL TANK	New	X 200.00
6	R&R CONDENSER AND REFILL AIRCON GAS	New	7 100 150.00
7	R&R RADAITOR AND REFILL COOLANT	New	80 400 150.00
8	ALIGNMENT REAR CHASSIS	New	7 200 350.00
9	ALIGNMENT FRONT CHASSIS	New	X 350.00
10	SPRAY REAR BUMPER	New	200 250.00
11	SPRAY REAR FENDER LHS & RHS	New	400 500.00
12	SPRAY BOOTLID	New	200 300.00
13	SPRAY REAR END PANEL AND SPARE TYRE PANEL	New	300 450.00
14	SPRAY FRONT BUMPER ,REINF,BRACE PANEL	New	250 450.00
15	SPRAY BONNET	New	200 300.00
16	SPRAY FRONT FENDER LHS & RHS	New	200 450.00
Gross Labour Cost (S\$)			7,050.00

Ding Auto Pte Ltd/SLH3087X/16/01/2018 11:13. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

### Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New 1600	2,800.00
2	R&R BOOTLID COMPONENTS	New 50	100.00
3	R&R SPARE TYRE /BOARD/CARPET/TRIM	New 60	150.00
4	R&R REVERSE SENSOR AND SPRAY PAINTING	New 30	100.00
5	R&R FUEL TANK	New X	200.00 HH
6	R&R CONDENSER AND REFILL AIRCON GAS	New 2, 100	150.00
7	R&R RADAITOR AND REFILL COOLANT	New 80, 100	150.00
8	ALIGNMENT REAR CHASSIS	New 200	350.00 HH X
9	ALIGNMENT FRONT CHASSIS	New X	350.00 HH
10	SPRAY REAR BUMPER	New 200	250.00
11	SPRAY REAR FENDER LHS & RHS	New 400	500.00
12	SPRAY BOOTLID	New 200	300.00
13	SPRAY REAR END PANEL AND SPARE TYRE PANEL	New 300	450.00
14	SPRAY FRONT BUMPER ,REINF,BRACE PANEL	New <del>250</del> 200	450.00
15	SPRAY BONNET	New 200	300.00
16	SPRAY FRONT FENDER LHS & RHS	New 200	450.00
<b>Gross Labour Cost (S\$)</b>			<b>7,050.00</b>

Ding Auto Pte Ltd/SLH3087X/16/01/2018 11:13. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Survey 17/1/18  
10 day

**Ding Auto Pte Ltd** (Co.Reg No: 201311788)  
 Blk 10, #01-20, Sin Ming Industrial Estate Sector  
 Singapore 575645  
 Tel: 64521208 Fax: 64520614 Email: admin@dingauto.sg; ding@dingauto

0 \* C  
 335 \* +  
 25 \* +  
 26 \* +

**TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)**  
**QUEK ZHEN YUAN**  
 NIL  
 Singapore

**Claimant Insurer: AIG Asia Pacific Insurance Pte. Ltd.**

**PARTICULARS OF CLAIM**

Claim Type: THIRD PARTY  
 Policy No:  
 Vehicle Reg. No.: SLH3087X  
 Party At Fault: THIRD PARTY  
 Driver (TP): TAY PENG LEONG

Ref. N  
 Date c  
 Drive

Make/Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) **Vehicle**  
 Vehicle Colour: GREY  
 Engine No: 1ZRX593437 **Chas**  
 Odometer: 84292 KM

1710

Paint Type:  
 Total Loss? **NO**  
 Est. Duration of Repair (day) 18

Tay  
 R

Description of Accident/Loss: REFER TO POLICE REPORT T/20180113/213  
 Present Location: DING AUTO PTE LTD (JALAN BOON LAY)

**COST OF CLAIMS**

Parts  
 Miscellaneous Items  
 Labour  
 Paintwork Labour  
 Towing

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**Amount**  
 176.42  
 0.00  
 150.00  
 0.00  
 0.00  
**Gross Total 026.42**  
 + GST 7.00% 191.85  
**Nett Amount 218.27**

This claim is handled by: **YOU JING FENG**



## REPAIR DETAILS

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Jan 2018)  
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Ding Auto Pte Ltd/SLH3087X/16/01/2018 11:13  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID	0.00	0.00	bt 335.00F
2	1		*BOOTLID EMBLEM LOGO	0.00	0.00	ne 25.00F
3	1		*BOOTLID EMBLEM COROLLA	0.00	0.00	ne 24.00F
4	1		*BOOTLID EMBLEM ALTIS	0.00	0.00	ne 24.00F
5	1		*BOOTLID CHROME	0.00	0.00	an 120.00F
6	1		*BOOTLID PLATE LAMP RHS	0.00	0.00	? 60.00F
7	1		*BOOTLID PLATE LAMP LHS	0.00	0.00	? 60.00F
8	1		*BOOTLID LAMP LHS	0.00	0.00	an 140.00F
9	1		*BOOTLID LAMP RHS	0.00	0.00	an 140.00F
10	1		*BOOTLID INSULATOR	0.00	0.00	x 180.00F
11	1		*BOOTLID INSULATOR CLIP	0.00	0.00	de 185.00F
12	1		*BOOTLID LOCK	0	0.00	dis 35.00FS
13	1		*NUMBER PLATE	0	0.00	bt 40.00FS
14	1		*REAR BUMPER	0.00	0.00	de 215.00F
15	1		*REAR BUMPER REINF	0.00	0.00	bt 145.00F
16	1		*REVERSE SENSOR	0.00	0.00	an 156.00F
17	1		*REAR BUMPER REFLECTOR RHS	0.00	0.00	x 36.00F
18	1		*REAR BUMPER REFLECTOR LHS	0.00	0.00	x 36.00F
19	1		*REAR BUMPER RETAINER LONG LHS	0.00	0.00	an 42.00F
20	1		*REAR BUMPER RETAINER LONG RHS	0.00	0.00	an 42.00F
21	1		*REAR BUMPER RETAINER SHORT RHS	0.00	0.00	an 36.00F
22	1		*REAR BUMPER RETAINER SHORT LHS	0.00	0.00	an 36.00F
23	1		*REAR BUMPER REINF ARM LHS	0.00	0.00	? 45.00F
24	1		*REAR BUMPER REINF ARM RHS	0.00	0.00	? 45.00F
25	1		*REAR END PANEL	0.00	0.00	bt 240.00F
26	1		*REAR END PANEL SEALANT	0	0.00	an 50.00FS
27	1		*REAR END PANEL TOP GARNISH	0.00	0.00	de 110.00F
28	1		*REAR END PANEL TOP GARNISH CLIP	0	0.00	an 35.00FS
29	1		*SPARE TYRE PANEL	0.00	0.00	Ry 360.00F
30	1		*SPARE TYRE BOARD	0.00	0.00	an 145.00F
31	1		*TAIL LAMP LHS	0.00	0.00	? 150.00F
32	1		*TAIL LAMP RHS	0.00	0.00	an 150.00F
33	1		*TAIL LAMP CLIP LHS	0.00	0.00	an 2.40F
34	1		*TAIL LAMP CLIP RHS	0.00	0.00	an 2.40F
35	1		*TAIL LAMP PANEL LHS	0.00	0.00	Ry 72.00F
36	1		*TAIL LAMP PANEL RHS	0.00	0.00	Ry 72.00F

Ding Auto Pte Ltd/SLH3087X/16/01/2018 11:13. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	
Main	16 Jan 2018 09:35 <a href="#">Sendback Est</a>	16 Jan 2018 11:13 <b>S\$17,026.42</b>	16 Jan 2018 15:18 <a href="#">Edit Adj Rpt</a>	<b>S\$8,450.00</b> <a href="#">Edit Estimates</a>	<b>S\$8,450.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS									
Insured:	<b>QUEK SWEE SIANG</b> , ID: S0014176C								
Main Claimant:	<b>LCRF PTE LTD</b> , Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	<b>SLH3087X</b>								
Claim Type:	<b>TP / 546162</b>								
Vehicle Reg. No. (Insured):	<b>SDD29285</b>								
Repaired:	<b>Ding Auto Pte Ltd (HQ)</b> Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]								
Claimant's Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... <b>[Final Rpt due 15/02/2018]</b>								
Driver/Custodian (Insured):	QUEK ZHEN YUAN ( / Male), NRIC: S93109603								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

### Claim Documents

SLH3087X (546162)  
 [SDD2928S]  
 TP  
 LCRF PTE LTD  
 Jan 13 2018 1:00AM  
 [QUEK SWEE SIANG]  
 Ding Auto Pte Ltd

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			<b>View</b> <input type="button" value="View in Browser"/>	
<b>Assessment Reports</b>			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print
1	15/01/18 18:30	<b>Accident Statement</b>	Load HTM	<input type="checkbox"/>
2	16/01/18 11:13	<b>Repairer Estimates</b>	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/01/18 16:09	<b>Adjuster Immediate Advice</b>	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
27	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
28	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
29	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
30	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
31	03/04/18 17:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print
32	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
33	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
34	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
35	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
36	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
37	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
38	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
60	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
61	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
62	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
63	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
64	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
65	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
66	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
67	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
68	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
69	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
70	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
71	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
72	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
73	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
74	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
75	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
76	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
77	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
78	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
79	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
80	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>
81	03/04/18 17:12	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print
82	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
83	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
84	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
85	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
86	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
87	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
88	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
89	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
90	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
91	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
92	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
93	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
94	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
95	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
96	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
97	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
98	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
99	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
100	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
101	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
102	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
103	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
104	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
105	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
106	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
107	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
108	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
109	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
110	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
111	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
112	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
113	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
114	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
115	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
116	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
117	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
118	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
119	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
120	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
121	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
122	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
123	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
124	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
125	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
126	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
127	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
128	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
129	03/04/18 17:12	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/01/18 11:47	OI GIA REPORT	Load PDF	

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print
1	15/01/18 18:30	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print
1	15/01/18 18:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	15/01/18 18:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	15/01/18 18:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	15/01/18 18:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	15/01/18 18:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	15/01/18 18:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	15/01/18 18:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	15/01/18 18:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	15/01/18 18:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	15/01/18 18:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	15/01/18 18:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	15/01/18 18:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	15/01/18 18:29	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print
1	15/01/18 18:30	Sketch Plan	Load TIF	
2	15/01/18 18:30	Sketch Plan #2	Load TIF	
3	15/01/18 18:30	Sketch Plan #3	Load TIF	
4	15/01/18 18:30	Sketch Plan #4	Load TIF	
5	15/01/18 18:30	Sketch Plan #5	Load TIF	
6	15/01/18 18:30	Sketch Plan #6	Load TIF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000977/T1RBE2  
Date: 04/04/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A27802019QMY  
**Claimant Vehicle No :** SLH3087X **Insured Vehicle No :** SDD2928S  
 Date of Loss: 13/01/2018 Nature of Claim: TP Claim No: 546162

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH3087X**  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRX593437  
 Reg. Date: 28/10/2016 (Man. Year: 2016) Chassis No: MR053REH104558710  
 Colour: Blue Odometer: 84292 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Achilles 6 mm Rear Left Side: Achilles 6 mm  
 Front Right Side: Achilles 6 mm Rear Right Side: Achilles 6 mm

*The above values represent the remaining tyre treads depth*

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,976.42	6,894.42	3,082.00	30.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,050.00	3,670.00	3,380.00	47.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,026.42</b>	<b>10,564.42</b>	<b>6,462.00</b>	<b>37.95</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,450.00</b>		
(S\$)	17,026.42	8,450.00	8,576.42	50.37
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,191.85</b>	<b>591.50</b>	<b>600.35</b>	<b>50.37</b>
<b>Nett Amount (S\$)</b>	<b>18,218.27</b>	<b>9,041.50</b>	<b>9,176.77</b>	<b>50.37</b>

### INSPECTION

Date of Assignment: 16/01/2018  
 Date Inspected: 17/01/2018 Inspected At: Ding Auto Pte Ltd (HQ)  
 Estimated Period of Repair: 10.0 days Repairer : Ding Auto Pte Ltd (HQ)

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2018)
<b>Parts:</b> 143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLH3087X)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID (WCP)	Bent	335.00 F	*335.00 F
2	1		*BOOTLID EMBLEM LOGO (WCP)	Necessary	25.00 F	*25.00 F
3	1		*BOOTLID EMBLEM COROLLA (WCP)	Necessary	24.00 F	*24.00 F
4	1		*BOOTLID EMBLEM ALTIS (WCP)	Necessary	24.00 F	*24.00 F
5	1		*BOOTLID CHROME (WCP)	Cracked	120.00 F	*120.00 F
6	1		*BOOTLID PLATE LAMP RHS (WCP)	Not Necessary	60.00 F	*- F
7	1		*BOOTLID PLATE LAMP LHS (WCP)	Not Necessary	60.00 F	*- F
8	1		*BOOTLID LAMP LHS (WCP)	Cracked	140.00 F	*140.00 F
9	1		*BOOTLID LAMP RHS (WCP)	Cracked	140.00 F	*140.00 F
10	1		*BOOTLID INSULATOR (WCP)	Deformed	180.00 F	*180.00 F
11	1		*BOOTLID INSULATOR CLIP (WCP)	Serviceable	185.00 F	*- F
12	1		*BOOTLID LOCK	Distorted	35.00 FS	*35.00 FS
13	1		*NUMBER PLATE	Bent	40.00 FS	*40.00 FS
14	1		*REAR BUMPER (WCP)	Deformed	215.00 F	*215.00 F
15	1		*REAR BUMPER REINF (WCP)	Bent	145.00 F	*145.00 F
16	1		*REVERSE SENSOR (WCP)	Necessary	156.00 F	*156.00 F
17	1		*REAR BUMPER REFLECTOR RHS (WCP)	Serviceable	36.00 F	*- F
18	1		*REAR BUMPER REFLECTOR LHS (WCP)	Serviceable	36.00 F	*- F
19	1		*REAR BUMPER RETAINER LONG LHS (WCP)	Necessary	42.00 F	*42.00 F
20	1		*REAR BUMPER RETAINER LONG RHS (WCP)	Necessary	42.00 F	*42.00 F
21	1		*REAR BUMPER RETAINER SHORT RHS (WCP)	Necessary	36.00 F	*36.00 F
22	1		*REAR BUMPER RETAINER SHORT LHS (WCP)	Necessary	36.00 F	*36.00 F
23	1		*REAR BUMPER REINF ARM LHS (WCP)	Serviceable	45.00 F	*- F
24	1		*REAR BUMPER REINF ARM RHS (WCP)	Serviceable	45.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*REAR END PANEL (WCP)	Bent	240.00 F	*240.00 F
26	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
27	1		*REAR END PANEL TOP GARNISH (WCP)	Deformed	110.00 F	*110.00 F
28	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	35.00 FS	*35.00 FS
29	1		*SPARE TYRE PANEL (WCP)	Repair	360.00 F	*- F
30	1		*SPARE TYRE BOARD (WCP)	Cracked	145.00 F	*145.00 F
31	1		*TAIL LAMP LHS (WCP)	Cracked	150.00 F	*150.00 F
32	1		*TAIL LAMP RHS (WCP)	Cracked	150.00 F	*150.00 F
33	1		*TAIL LAMP CLIP LHS (WCP)	Necessary	2.40 F	*2.40 F
34	1		*TAIL LAMP CLIP RHS (WCP)	Necessary	2.40 F	*2.40 F
35	1		*TAIL LAMP PANEL LHS (WCP)	Repair	72.00 F	*- F
36	1		*TAIL LAMP PANEL RHS (WCP)	Repair	72.00 F	*- F
37	1		*REAR FENDER LHS (WCP)	Repair	450.00 F	*- F
38	1		*REAR FENDER LHS TRIM (WCP)	Not Necessary	205.00 F	*- F
39	1		*REAR FENDER RHS TRIM (WCP)	Not Necessary	205.00 F	*- F
40	1		*REAR FENDER RHS (WCP)	Repair	450.00 F	*- F
41	1		*BONNET (WCP)	Bent	360.00 F	*360.00 F
42	1		*BONNET SEAL (WCP)	Necessary	24.00 F	*24.00 F
43	1		*BOONET HINGE LHS (WCP)	Repair	35.00 F	*- F
44	1		*BOONET HINGE RHS (WCP)	Repair	35.00 F	*- F
45	1		*RADIATOR GRILLE (WCP)	Cracked	180.00 F	*180.00 F
46	1		*RADIATOR GRILLE TOP GARNISH (WCP)	Deformed	45.00 F	*45.00 F
47	1		*RADIATOR GRILLE TOP GARNISH CLIP	Necessary	35.00 FS	*35.00 FS
48	1		*HEAD LAMP LHS (WCP)	Cracked	280.00 F	*280.00 F
49	1		*HEAD LAMP RHS (WCP)	Deformed	280.00 F	*280.00 F
50	1		*FRONT BUMPER (WCP)	Deformed	215.00 F	*215.00 F
51	1		*FRONT BUMPER SPONGE (WCP)	Cracked	55.00 F	*55.00 F
52	1		*FRONT BUMPER REINF (WCP)	Bent	120.00 F	*120.00 F
53	1		*FRONT BUMPER REINF ARM LHS (WCP)	Serviceable	45.00 F	*- F
54	1		*FRONT BUMPER REINF ARM RHS (WCP)	Serviceable	45.00 F	*- F
55	1		*NUMBER PLATE	Bent	40.00 FS	*40.00 FS
56	1		*BRACE PANEL (WCP)	Bent	42.00 F	*42.00 F
57	1		*CONDENSER (WCP)	Bent	360.00 F	*360.00 F
58	1			Bent	455.00 F	*455.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
			<b>*RADIATOR</b> (WCP)				
59	1		<b>*SUPPORT PANEL</b> (WCP)	Bent	250.00 F	*250.00 F	
60	1		<b>*FRONT FENDER LHS</b> (WCP)	Repair	215.00 F	*- F	
61	1		<b>*FRONT FENDER LHS EMBLEM</b> (WCP)	Not Necessary	24.00 F	*- F	
62	1		<b>*FRONT FENDER RHS EMBLEM</b> (WCP)	Necessary	24.00 F	*24.00 F	
63	1		<b>*FRONT FENDER RHS</b> (WCP)	Bent	215.00 F	*215.00 F	
64	1		<b>*FRONT BUMPER RETIANER LHS</b> (WCP)	Necessary	24.00 F	*24.00 F	
65	1		<b>*FRONT BUMPER RETIANER RHS</b> (WCP)	Necessary	24.00 F	*24.00 F	
66	1		<b>*FAN COWLING</b> (WCP)	Distorted	85.00 F	*85.00 F	
67	1		<b>*FAN BLADE</b> (WCP)	Distorted	65.00 F	*65.00 F	
68	1		<b>*FAN MOTOR</b> (WCP)	Damaged	180.00 F	*180.00 F	
69	1		<b>*RADIATOR UPPER GUILDE</b> (WCP)	Deformed	48.00 F	*48.00 F	
					<b>Sub Total (S\$)</b>	<b>8,705.80</b>	<b>6,025.80</b>
					<b>+ Margin on L,N Items 15.00/15.00% (S\$)</b>	<b>1,270.62</b>	<b>868.62</b>
					<b>Total Parts (S\$)</b>	<b>9,976.42</b>	<b>6,894.42</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	2,800.00	1,600.00
2	R&R BOOTLID COMPONENTS	New	100.00	50.00
3	R&R SPARE TYRE /BOARD/CARPET/TRIM	New	150.00	60.00
4	R&R REVERSE SENSOR AND SPRAY PAINTING	New	100.00	30.00
5	R&R FUEL TANK	New	200.00	0.00
6	R&R CONDENSER AND REFILL AIRCON GAS	New	150.00	100.00
7	R&R RADAITOR AND REFILL COOLANT	New	150.00	80.00
8	ALIGNMENT REAR CHASSIS	New	350.00	0.00
9	ALIGNMENT FRONT CHASSIS	New	350.00	0.00
10	SPRAY REAR BUMPER	New	250.00	200.00
11	SPRAY REAR FENDER LHS & RHS	New	500.00	400.00
12	SPRAY BOOTLID	New	300.00	200.00
13	SPRAY REAR END PANEL AND SPARE TYRE PANEL	New	450.00	300.00
14	SPRAY FRONT BUMPER ,REINF,BRACE PANEL	New	450.00	250.00
15	SPRAY BONNET	New	300.00	200.00
16	SPRAY FRONT FENDER LHS &RHS	New	450.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>7,050.00</b>	<b>3,670.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >