Carrier Carm

REF: NS/INC18000980/Rlqbe2

ASSIGNMENT

From: Date:	Ven No. SHB 1892E Yr Pegn. Doly June
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyota PRIMS c.c 1798
at Workshop m/s	Colour MARGON A.C Insured / Std / NI / NA
of	Sp.Reading 347621 TRadio: Insured / Std / NI / NA
Insured: SFY 6726Y	Eng/No:
Policy No. 5094786021 0610.17 - 0510.18	C/No: JTOKN 3642057472236
Claims No. M 0978056-002	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Increer / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Morder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rith / STD A/Rim or
	Tyre Size: F: 195/65815
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! /
repair at the time of inspection.	TOYO/YOKO OF FALKEN .
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R.Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: 13 days Res.: Yes or No	D.O.A. 12/01/18 D.O.I. 15/01/18
Lum Sum: % 3 Val.: Yes or No	Survey held at SMAT
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	NS FM
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction 9 (B 1571E - 1273 / Nyfi 1200 (304 / Ring	392 0(A:)7(B)2 01/18/2016
51/ MFF: 321 JM/ M / M / TJCFD YTE	20h: 1616:15
	Mone
4 & 11350, 13 days Cled	\$ (1425.90,50/s)
	SFY 67264
	
N.A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1.	2
Cate/Time, File Pass to? : Preli. Report	Days Of Repair: 13
	Resurvey No. of Trip: 2 Survey Fee: 160
Date/Time. File Return to?	Transconation (\$ 5.70.0)
Add Fee	the state of the s
7P	rinten, evi (\$ Proces 35)
Report Format:	t Tech. In ya. 5
Lump Sum / 12/13 (350)	Wesken: \$



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







			Mark Constant and the	A PARTIE AND THE PARTY OF THE P
NTUC INCOME INSUF	RANCE CO-OPERATIVE LTD	Ref:	NS/INC18000980	/R1qb
73 BRAS BASAH ROA #05-01 NTUC TRADE 189556	D UNION HOUSESINGAPORE	Date:	16-01-2018	
		Code:	INC4	
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	Policy Particulars	:- THIRI	PARTY CLAIM	
Insured Veh.	SFY 6726Y	Veh. Ir	spected	SHB 1892E
Policy No.	5094786021	Cover	age (\$)	0.00
Claim No.		Exces	s (\$)	0.00
Assign From		Assign	Date	15/01/2018
2.50 ************************************	Vehicle Parti	culars 8	Condition	· · · · · · · · · · · · · · · · · · ·
Make & Model		c.c	 	Ó
Engine No.	HIDDEN	Year o	f Reg.	
Chassis No.		Coloui	•	
Odometer	-	Steeri	ng	
Brakes		Modifi	cation	
General			· · · · · · · · · · · · · · · · · · ·	
	Conditi	ons of 1	yres-	SCALARAMAN PLANTS NEW YORK
	Size	Make		Balance
R/H Front Tyre				mm
L/H Front Tyre				mm
R/H Rear Tyre				mm
L/H Rear Tyre				mm
4	Description	on of Da	mages 🕌 🗀	
5.	Genera	l inform	ation	
Accident Date	12/01/2018	Inspec	tion Date	15/01/2018
Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE LI	D	· ·
	60 WOODLANDS INDUSTRIAL	PARK E4	SINGAPORE 75770	5
	R			
	ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W			REPAIRS

Reference No.: NS/NC/8000 980/R/g/s
Policy Type: OD /TP/TP RES / TL / EVA **Typist** Case Handler Admin (Catha): Case handler to make sure all Information created by the assignment team are ACCURATE. Y-Date N-Date Y-Date N-Date (1) Office Assign Form C Reference No. C **Customer Code** Assign From Ν C Assign Date Veh No (Inspected) C Veh No (Insured) C C D.O.A C Policy No Claim No C Insurance Authorisation (CA /REV/REP) C C Report Type C Weekend Charges Survey held at/Repairer Ν C **Excess**): Case handler to make sure the surveyor completed all required information. Surveyor ((1) Assignment Form C Vehicle No C Regn Month/Year Ν. Vehicle Type Ν Make & Model C Engine Capacity. (C.C) Colour Ν C Odometer. (Sp.Reading) C Chassis No Ν **General Condition** Ν Steering Brake N Modification (Modi) Ν C Tyre Size Tyre Make Ν C Tyre Balance C Date of Inspection Ν Survey held Ν Des.of Damages (2) System - (Views/Merimen) Damaged Vehicle Photographs Uploaded (3) Workshop Estimate/Assignment Form ALL Parts condition Ν C Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) C C Days of repair C **Finalised Amount** Re-inspection Cases to Finalize within 5 Days (4) System - (Views/Merimen) Resurvey photo Uploaded

Survey Department Check List (Case Handler)

Check By:

Case Handler

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
-	MT/0980348-002	SMRT TAXIS	SHB 1220U	SGB 4394T	30/1/2018
2	MT/0971146-002	SMRT BUS	SG 5580Y	SJS 5536U	25/11/2017
1 6	MT/0982534-001	COMFORT TRANSPORTATION PTE LTD	SHC 3146H	S1L 8920L	10/2/2018
4	MT/0982203-002	CITYCAB	SHA 9342D	SDD 8298L	12/2/2018
5	MT/0978056-002	SMRT TAXIS	SHB 1892E	SFY 6726Y	12/1/2018
9	MT/0982536-001	COMFORT TRANSPORTATION PTE LTD	SHC 2230D	PC 7662M	13/2/2018
7	MT/0980412-002	SMRT TAXIS	SHF 248B	SKD 6621S	31/1/2018
. ∞	MT/0980980-002	SMRT TAXIS	SHD 6289D	SJH 7534U	3/2/2018
6	MT/0980928-002	SMRT TAXIS	SHB 1319U	FBC 5857Y	4/2/2018
10	MT/0982537-001	SMRT TAXIS	SHB 628J	FBH 2102K	4/2/2018
11	MT/0981878-002	COMFORT TRANSPORTATION PTE LTD	SHC 7245D	SJF 9837T	11/2/2018
12	MT/0982037-002	COMFORT TRANSPORTATION PTE LTD	SHC 8089G	GBG 9309R	10/2/2018

e Bao Tech	oTech ****								Gene	eralClaim
Hello, NAC_PAYA_UBI_80	0601		Dar Calabor Albana			,	Change La	nguage	· Change Passwo	ord • Log Out
My Desktop	Polic	y Query								
Notice of Loss	Policy N	o.				Date of Accident		12/01/2018 16:36		
	Vehiçle	No.(Far Motor)	SFY6726Y							
						Search 1				
	Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	න	5094786021	LIZAIANTO ENTERPRISE	B170130329	GPC	Third Party, Fire & Theft	SFY6726Y	SFY6726Y	06/10/2017	05/10/2018
						Continue			•	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB1892E
Vehicle to be Exported:	No
Intended De-registration Date:	28 Feb 2018
Vehicle Make:	ТОУОТА
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR6100900
Chassis No.:	JTDKN36U205747236
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	23 Jul 2014
First Registration Date:	23 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jul 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jul 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$53,269.00
COE Rebate Amount:	\$29,247.00
Total Rebate Amount:	\$35,313.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renev	ved. The vehicle must be de-registered upon COE expiry or wh

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be developed a distribution of the control of the vehicle must be developed a distribution of the vehicle must be developed and t

The information contained herein is correct as at 28 Feb 2018

MSR118006529 / SMRT Automotive Services Pte Ltd - Woodlands ENTRY DATE & TIME: 13/01/2018 11:11 SUBMITTED BY: B. Thaiyal Nayagi

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCII	DENT	STAT	EMEN	U
-------	------	------	------	---

13/01/2018 11:11 **Date Of Report** 12/01/2018 17:15 **Date Of Accident**

WODDLANDS AVE 7 /WOODLANDS AVE 2 **Exact Location Of Accident**

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHB1892E

Insured/Policyholder

SMRT TAXIS PTE LTD Name Of Registered Owner

198905369K Co Reg No **NOEMAIL** Email Address

Mobile Phone No

OFFICE-80000000 Alternative Phone No

Vehicle Particulars

TOYOTA Manufacturer

PRIUS TAXI-1.8 (A) Model

Exact Purpose for which vehicle was being used at

time of accident

HIRER AND REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

Insurance Company

FIRST CAPITAL INSURANCE LTD Name of Insurance Company THIRD PARTY FIRE AND/OR THEFT Type Of Coverage

YES Fleet Policy

D-17087562MFSH **Policy Number**

Cover Note Number

Driver > *** Signal Signal

MOHAMMED SHAHLAN BIN ISMAIL Name of Driver

S7418673D NRIC No 11/06/1974 Date Of Birth **OUTDOOR** Occupation 18/11/1994 **Date Of Driving Pass**

23 YEARS AND 1 MONTH **Driving Experience**

MALE Gender

Mobile Number Fax Number

Contact Number

NOEMAIL EMail Address

785A WOODLANDS RISE

731785 Postcode

04-104

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Address

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CROSS JUNCTION

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged? I have been approached by unknown person(s) YES

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Passenger 1

NAME:

: UNKNOWN

GENDER:

: FEMALE

Passenger 2

NAME:

: UNKNOWN

GENDER:

: FEMALE

Passenger 3

NAME:

: UNKNOWN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG WOODLANDS AVE 2 TURNING RIGHT TOWARDS WOODLANDS MRT WITH THREE PASSENGERS (FEMALE 2 MALAY 1 INDIAN) ON BOARD. TRAFFIC WAS IN MY FAVOUR AND THE GREEN ARROW APPEARED, AS SUCH I PROCEEDED TO TURN. SUDDENLY A VEHICLE SFY6726Y DID NOT STOP AT THE RED LIGHT AND COLLIDED ONTO THE LEFT FRONT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE TOO BIG

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SFY6726Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SOEHARKIANTO BIN ABDUL KADER \$1541283F

	Sketch Pl	g. ·		
		Hecklowls A PR 2	1	
vicodlands Ave 7	1.	THE PERSON NAMED IN COLUMN TO THE PE		> 75.
		Ø.		
1-SHB 1892E B-SFY 6726Y	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	7		
Julie 13/01/2018			·	
	·			
DECLARATION— I/We declare the foregoing particulars : S/XV1 Policyholder's Signature	are true th every respect. Driver's Signature	1/2018	tling Centre Personnel's Sig	Zoi8

Sketch Plan Pg. 2

SKETCH PLAN



IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Date & Time:

SIXAT S

Policyholder's Signature Date & Time: Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.:



60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHB1892E

Ref. No

TAX/01/18/2076

Reg. Date

23/07/2014

Vehicle Type

TAXI

Make

TOYOTA PRIUS

Model

PRIUS

Name of Driver

MOHAMMED SHAHLAN BIN

ISMAIL

Type of Accident

SIDE SWIPE

Date / Time of Accident

12/01/2018 05:15:00 PM

Accident Reported Date / Time :

13/01/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

Towed Back Date/Time

12/01/2018

Replacement Vehicle issued? :

Yes

Accident Repair Job Card No :

000024094073


Special Instruction to ARC, if any

TOWED \$50 /SFY6726Y

Prepared Date

13/01/2018 11:29:00 AM

Presury after repair /wine







we completed by pervice Advisor, Accident Repair Centre

Chassis No :

JTDKN36U205747236

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

1,521.00

0.00

Total Spray Painting Charges

2,592.00

Total Material Charges

10,689.70

0.00

1,335.00

10,689.70

Other Charges

0.00

TOTAL

16,137.70

Lum Sum Total

16,150.00

0.00

No. of Repair Days

0.00

10.00

Odays Lunpsun

Prepared / Adjusted By

Arc / Surveyor Sing Off Date

: 15/01/2018 10:54:16 AM

01/01/1900 12:00:00 AM

15/01/1881440

Prepared / Adjusted Date

Remarks

Prepared Date : 15/01/2018 10:54:16 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

LKK Auto Consultants hence notify

the Repairer of the following: To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO REPAIR LH FRONT PORTION	1,521.00	0.00			
「otal Labour	1,521.00	0.00			

Part 2 - Spray Painting & Panel Beating Related Works

lob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY FRONT DOOR LH	378.00	0.00 200
O RESPRAY FRONT FENDER LH	378.00	0.00
O RESPRAY APRON PANEL LH	180.00	0.00
O RESPRAY FRONT WHEEL HOUSE LH	180.00	0.00 150
O RESPRAY FRT MEMBER,LH	180.00	0.00
O REPSRAY FRONT BUMPER	378.00	0.00 200
O SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0.00 150
O REPSRAY FRONT HOOD	378.00	0.00 200
O RESPRAY FRONT SUPPORT PANEL	180.00	0.00 (س
O RESPRAY FRONT PILLAR LH	180.00	0.00
otal Spray Painting & Panel Beating	2,592.00	0.00

art 3 - Other Costs - Accident and Accident Repair Related Expenses

ob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
OWING CHARGE	80.00	0.00
O CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 60
O APPLY RUST-PROOFING ON AFFECTED REA	100.00	0.00
O DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
O REMOVE AND REFIT ENGINE WIRE ROOM	200.00	0.00
O REPLACE SUNDRY PARTS	100.00	0.00 20
O WASH AND VACUUM	60.00	0.00 40
O ALIGN CHASSIS	350.00	0.00 /50
O REMOVE & REFIX FRONT LHS/RHS QUATER LASS	120.00	0.00 60
O PROVIDE LABOUR & MATERIAL FOR SOLAR LM (NET)	125.00	0.00 /25
otal Other Costs	1,335.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommer d	Surveyor Approved	Photos Attached
7002- 7070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No
3802- 7050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace	No
537 4- 7051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
3876- 7030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace	No
3852- 7020			FENDER LINER PAD, FR WHEEL. LH	1	49.30	25.00	36.97	Replace	Replace	No
3702- 7050			FENDER APRON SUB FRT/LH	1	637.80	25.00	478.35	Replace	Replace	No
2120- 7021			QUARTER GLASS FRT/LH	1	234.90	25.00	176.17	Replace	Replace	No
2111- 7772			WIRE, ENGINE ROOM	1	5,567.10	10.00	5,010.39	Replace 1	Replace ?	No
2113- 7180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace	Replace	No
1170- 7500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace	No
7028120 0			MEMBER SUB-ASSY, FR LH	1	810.70	25.00	608.02	Replace	Replace	, No
2119- 7930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No
2161- 3010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No
2116- 7040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace	No
2611- 7080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace	No
2021- 7023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace	No
⁷ 014- ⁷ 030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace		No
'013- '030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace	No
3294- '030		6505561	DEFLECTOR, RADIATOR LH	1	77.00	25.00	57.75	Replace	Replace ?	No
			NUMBER PLATE		15.00	0.00	15.00	Replace	Replace	
1444			NUMBER PLATE FRAME		12.00	0.00	12.00	Replace	Replace CP4	M 6
!114- '140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace	Nο
102-		6505541	BUMPER GRILLE SUB-ASSY, LOWER		311.10	25.00	233.32	Replace	Replace	-No
220- 230		6505438	FOG LAMP LH	1	280.10	10.00	252.09	Replace	Replace	No
521- 050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Replace	No
529- 040			BRACKET, FR TURN UPPER LH	1	24.40	25.00	18.30	Replace	Replace /	No
529- 060			BRACKET, FR TURN CENTER LH	1	58.20	25.00	43.65	Replace	Replace	No
529- 050			BRACKET, FR TURN LOWER LH	1	26.00	25.00	19.50	Replace	Replace /	No

Page:

Number	,	OLOGR THE	r arc (famile	GLI	(\$)	பரையா (%)	(\$)	Recommen d	Approved	Attached
52618- 47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace 7	No
53301- 17060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace	No
53420- 17070			HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace	No
53410- 17070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace	No
53201- 17902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace	No
31132- 17030			PILLAR, FR BODY, LH	1	363.10	25.00	272.32	Replace	Replace Pegent	_No
		Т	OTAL MATERIALS					13,362.18	13,362.12	_
TOTAL MATERIALS(Discounted)								10,689.70	10,689.70	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	TOTAL SUPPLEMENTARY MATERIALS								

1867 P

REQUEST FOR SUPPLYMENT PARTS

Contractor		WEG	A ENGINEERING	PTE LTD			7
Accident Case Number	TAX 0	118/2076	Date of Co	Hection	15 (1)	18 (الر
Vehicle No	SHB 1	892E	Day of R	(equest	18 (1)	18	24/0
Vehicle Modei	TOYOTA	frius	Number of Da (If ar	- 1	3 Days V	ok/	1
5/N 4434,3	5,36,37	wire Engina Room		Quantity -	45567.18		/
4391		Front Freder Name)) RH 1.	\$ 51.90	ru/	<i> </i>
4486,1	87,88	wire Engine Room		1.	# 242.00	out!	
4391,4	439,90	To Respory Front Fe	nder RH		# 378.00	200	/
	m. enggle (lygg) v (lyt) sakkayamanını	To Remove & Refix		Roplace &	#350-00	150	
Made	1 7 7	WITE Figure Room	<u> </u>))	\$ 400.00		CLE
Анно, 4	1 + 2	To Espair Front Chas	SIS MUMBUR	LHAKN	4 350-60	(m)	
4395,	96	To Roset & Diagnose	System Luni	tion -	\$ 33500	(00	
1, (Name) <u>Gu</u>	an	Pagene subata) etionage	igus fin tumiggét padse	· ·	· · · · · · · · · · · · · · · · · · ·		
(Position)							
	e declaration is t	e that - Supplementary Parts i	Signaturu 176	or regret its fr	ing this declaration ont of an authorise	d withess)	
Fo: SMRT Sizil							
Acknowledge B	}	ARC Executive Supervis	arasa [reserved and some	· war and the state of the stat		
Approval By		Surveyor - In-house S					
Parts Ordering	S	MRT Store / Contractor Suppl WOC	y : Form 22 /	2 ann 22 / PO :	WOC/ Reservation (Ngrape	
Photo Scounie	4	73.5 50) }	ر: معالم المسالم	aic of submissible	: !	

0 Antenna	Time I and a great
Iness Date (5-1-1)	Vehicle to Wega Date Int 601 Towing: Pury
1000-	Time In: 1655 Driver
Date	Wega Joh No: 010038
E 1/2 F	1//2
KM 347620	Vehicle sent to SMRT Date In 27/1/1 Towing: Time In: / 220 Driver / Driver
DT1020	Duveiv
	Received by (SMRT) :

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No :

JTDKN36U205747236

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

1,521.00

Total Spray Painting Charges

2,970.00

Total Material Charges

6,699.92

Other Charges

1,955.00

TOTAL

13,145.92

Lum Sum Total

0.00

No. of Repair Days

14.00

Prepared / Adjusted By Arc / Surveyor Sing Off Date

: 15/01/2018 10:54:16 AM

13.00

0.00

1,200.00

1,600.00

10,468.63

-1,918.63

11,350.00

RASUL (LKK)

15/01/2018 02:55:56 AM

Prepared / Adjusted Date

Remarks

Prepared Date :

15/01/2018 10:54:16 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

an-1801-0839

Invoice No

Quotation Date

30/1

Invoice Date :

Invoice Amount

Prepared Date:

Section u - Details of Repair Estimates

Part 1 - Labour Works

Pail 1 - Labout 1 - Comments	Quotation from ARC	Adjusted by Surveyor, if applicable.
Job Scope TO REPAIR LH FRONT PORTION	1,521.00	1,200.00
Total Labour	1,521.00	1,200.00

Part 2 - Spray Painting & Panel Beating Related Works

	Quotation from ARC	Adjusted by Surveyor, if applicable
lob Scope		200.00
TO RESPRAY FRONT DOOR LH	378.00	200.00
O RESPRAY FRONT FENDER LH	378.00	100.00
TO RESPRAY APRON PANEL LH	180.00	
TO RESPRAY FRONT WHEEL HOUSE LH	180.00	100.00
TO RESPRAY FRT MEMBER,LH	180.00	100.00
	378.00	200.00
TO REPSRAY FRONT BUMPER	180.00	100.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	070.00	200.00
TO REPSRAY FRONT HOOD	378.00	100.00
TO RESPRAY FRONT SUPPORT PANEL	180.00	
TO RESPRAY FRONT PILLAR LH	180.00	100.00
TO RESPRAY FRONT FENDER RH	378.00	200.00 5
Total Spray Painting & Panel Beating	2,970.00	1,600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

	Quotation from ARC	Adjusted by Surveyor, if applicable
ob Scope	80.00	60.00
O CHECK WIRING AND SYSTEM FUNCTION		80.00
O APPLY RUST-PROOFING ON AFFECTED	100.00	
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00
O REMOVE AND REFIT ENGINE WIRE ROOM	200.00	100.00
	100.00	20.00
TO REPLACE SUNDRY PARTS	60.00	40.00
O WASH AND VACUUM		150.00
TO ALIGN CHASSIS	350.00	
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120.00	60.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR	125.00	125.00
FILM (NET) TO REMOVE AND REFIX DASHBOARD	350.00	150.00 S
	350.00	100.00 5
TO CHECK & RESET SYSTEM FUNCTION	<u> </u>	-2,863.63
Lump Sum Adjustment by Surveyor	0.00	
Total Other Costs	1,955.00	-1,918.63


Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	•	Photos . Attached
7002-		6505529	DOOR FRT/LH	1	1 894.40	100.00	0.00	Replace	Repair	No R
7070			STICKER DECAL	1	1 60.00	0.00	60.00	Replace	Replace	No nu
3802-		6505558	SMRT (DOOR) FENDER FRT/LH		1 723.40	25.00	542.55	Replace	Replace	No BUL
7050			NAME PLATE	-	1 51.90	25.00	38.92	Replace	Replace	No suc
7051	 	6505554	(HYBRID) FENDER LINER	-	1 171.70	25.00	128.77	Replace	Replace	No DE
3876- 17030		650555-	FENDER CINER FRT/LH FENDER LINER PAD,	<u>L</u>	1 49.30	25.00	36.97	Replace	Replace	No nee
53852- 17020			FR WHEEL. LH		1 637.80	100.00	0.00	Replace	Repair	Non
53702- 47050			FENDER APRON SUB FRT/LH	<u> </u>			176.17	Replace	Replace	No
52120- 47021			QUARTER GLASS FRT/LH		1 234.90	25.00				rec
32111-			WIRE, ENGINE ROOM		1 5,567.10	10.00	5,010.39	Replace	Replace	
47772 82113-	-	+	WIRE, ENGINE ROOM, NO.3		1 242.00	10.00	217.80	Replace	Replace 5	
47180 81170-		6505436	HEAD LAMP LH	+	1 945.20	10.00	850.68	Replace	Replace	No BRI
47500 57028120)	-	MEMBER SUB-ASSY,	+-	1 810.70	100.00	0.00	Replace	Repair	Nap
20 52119-	-	6505517	BUMPER FRT	+	1 482.00	25.00	361.50	Replace	Replace	No DE
47930 52161-	-		BUMPER CLIPS	+	10 1.61	25.00	12.07	Replace	Replace	No net
16010 52116-		6505516	BUMPER SUPPORT	+-	1 76.40	25.00	57.30	Replace	Replace	No res
47040	-	6505518	F/LH BUMPER ENERGY	+	1 78.80	25.00	59.10	Replace	Replace	1º m
52611- 47080			ABSORBER FRT BUMPER		1 498.40	100.00	0.00	Replace	Repair	No
52021- 47023		6505539	REINFORCEMENT FRT						- I nivor	I K
57014- 47030			ARM SUB-ASSY, FR BUMPER LH		0 250.40		0.00	Replace		1 7 SNO
57013-	-		ARM SUB-ASSY, FR BUMPER RH		0 250.40	25.00	0.00	Replace		7.94
47030 53294-		6505561	DEFLECTOR, RADIATOR LH		1 77.00	25.00	57.75	Replace		NoXsv
47030	+		NUMBER PLATE	_	1 15.00	0.00	15.00	Replace		
	+		NUMBER PLATE FRAME		1 12.00	0.00	12.00	Replace		
52114-			BRACKET, FR		1 110.40	25.00	82.80	Replace		
47140 53102-		6505541		,	1 311.10	25.00	233.32	Replace		
47020 81220-	_	6505438		1	1 280.10	10.00	252.09	Replace	Replace	E
12230 81521-	-	-	LENS & BODY, FR	1	1 511.80	0 10.00) 460.62	Replace	e Replace	No.
47050 81529-			TURN LH BRACKET, FR TURN	N	1 24.40	25.00	18.30	Replace	e Replace	No /
47040 81529-			BRACKET, FR TURN	N	1 58.20	25.00	43.65	Replace	e Replace	e Na
47060			CENTER LH BRACKET, FR TURI		1 26.00	25.00	19.50	Replace	e Replace	e No
81529- 47050			LOWER LH							

Number	- cutuon	SIOUK NO	rart name	cuty	List Price (\$)	Discount (%)	Final Price (\$)	ARG Recommen d	Surveyor Approved	Photos Attached
52618- 47050		6505540	BUMPER FRT ABSORBER LOWER	0	127.70	25.00	0.00	Replace	Not given	No XSV
53301- 47060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace	No let
53420- 47070			HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace	No CB+
53410-			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace	No JET
47070 53201-		 	SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace	No By
47902 61132-		 	PILLAR, FR BODY, LH	1	363.10	100.00	0.00	Replace	Repair	No /Z
47030 75374-			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No rec
47051	<u> </u>	1	TOTAL MATERIALS	<u></u>					10,468.63	
TOTAL MATERIALS(Discounted)							Τ	6,699.92	10,468.63	

Added Spare Parts / Material Usage After Surveyor Signed off

Part	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
Number 75374-		NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS 38.92									



Celine Fong (LKKAuto)

From:

Celine Fong (LKKAuto)

Sent:

Monday, 12 February 2018 6:13 PM

To:

'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)'

Cc:

Rasul (LKKAuto)

Subject:

RE: SHB1892E

Dear Poh Suan,

Confirmed lump sum \$11,350.00, 13 days.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,

#02-25 | S(408933)

----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]

Sent: Friday, 2 February 2018 3:16 PM To: Rasul (LKKAuto) < Rasul@lkkauto.com>

Cc: Celine Fong (LKKAuto) <celinefong@lkkauto.com>; 'Leong Chee kwong' <cheekwongwega@gmail.com>

Subject: SHB1892E

Hi Rasul,

Attached herewith the repair estimate of SHB 1892E having Case No: TAX/01/18/2076.

There is no change to the approved amount of \$11,350 @ 13 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: 02 February 2018 10:36

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Thatcham escribe

1 200	<u>natcham esc</u>		S. N. Jack Wald		
NTU	C INCOME INSUF	RANCE CO-OPERATIVE LTD	Ref:	NS/INC18000980	D/R1gbe2
					Bi (1883) \$1819 \$20 \$183 \$251 \$16 \$18
		D UNION HOUSESINGAPORE	Date:	05-03-2018	
			Code:	INC4	
13		Policy Particulars	:- THIR	D PARTY CLAIM	
	Insured Veh.	SFY 6726Y	Veh. I	nspected	SHB 1892E
	Policy No.	5094786021	Cover	age (\$)	0.00
	Claim No.	MT/0978056-002	Exces	s (\$)	0.00
	Assign From		Assig	n Date	15/01/2018
2.		Vehicle Parti	culars &	Condition	
	Make & Model	TOYOTA PRIUS	c.c		1798
	Engine No.	HIDDEN	Year o	of Reg.	2014
	Chassis No.	JTDKN36U205747236	Colou	r	MAROON
	Odometer	347621	Steeri	ng	IN ORDER
	Brakes	IN ORDER	Modifi	ication	SPORTS RIM
	General	FAIR			
3.		Conditi	ons of	Tyres	
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	FALKE	N	5 mm
	L/H Front Tyre	195/65 R15	FALKE	N	5 mm
	R/H Rear Tyre	195/65 R15	FALKE	N	5 mm
	L/H Rear Tyre	195/65 R15	FALKE	N	5 mm
4.		Descripti	on of D	amages 🗰 🕶 🌬	Expression (Control of Control of
	THE VEHICLE SU	STAINED DAMAGES AT THE N/S	FRONT	PORTION.	
	DAMAGES SEE D	ETAILS.			
5.		Genera	l Inform	ation	
	Accident Date	· · · · · · · · · · · · · · · · · · ·	1	ction Date	15/01/2018
	Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE L	TD	
		60 WOODLANDS INDUSTRIAL	PARK E	4 SINGAPORE 7577	05
5a.		R	emarks		
	A)THE INSPECTION	ON WAS CONDUCTED ON A'WIT	HOUT P	REJUDICE" BASIS. NOT AUTHORISED	REPAIRS.
5b.		Estimate	Days o	Repair	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1892E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FENDER FRT/LH (DISC 25%)	BUCKLED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	FENDER LINER FRT / LH (DISC 25%)	DEFORMED	171.70	128.77
1	FENDER LINER PAD, FR WHEEL LH (DISC 25%)	NECESSARY	49.30	36.97
1	QUARTER GLASS FRT / LH (DISC 25%)	NECESSARY	234.90	176.17
1	BUMPER FRT (DISC 25%)	DEFORMED	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.07
1	BUMPER SUPPORT F/LH (DISC 25%)	NECESSARY	76.40	57.30
1	BUMPER ENERGY ABSORBER FRT (DISC 25%)	CUT	78.80	59.10
1	BRACKET, FR BUMPER (DISC 25%)	NECESSARY	110.40	82.80
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	CRACKED	311.10	233.32
1	BRACKET, FR TURN UPPER LH (DISC 25%)	CRACKED	24.40	18.30
1	BRACKET, FR TURN CENTER LH (DISC 25%)	DISTORTED	58.20	43.65
1	BRACKET, FR TURN LOWER LH (DISC 25%)	DISTORTED	26.00	19.50
1	HOOD PANEL (DISC 25%)	BENT	748.10	561.07
1	HOOD HINGE LH (DISC 25%)	BENT	55.90	41.92
1	HOOD HINGE RH (DISC 25%)	BENT	55.90	41.92
1	SUPPORT SUB-ASSY (DISC 25%)	BENT	1,460.40	1,095.30
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	WIRE, ENGINE ROOM (DISC 10%)	CUT	5,567.10	5,010.39
1	WIRE, ENGINE ROOM, NO.3 (DISC 10%)	CUT	242.00	217.80
1	HEAD LAMP LH (DISC 10%)	BROKEN	945.20	850.68
1	FOG LAMP LH (DISC 10%)	BROKEN	280.10	252.09
1	LENS & BODY, FR TURN LH (DISC 10%)	CRACKED	511.80	460.62
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	NUMBER PLATE (SN)	CRACKED	15.00	15.00
1	NUMBER PLATE FRAME (SN)	CRACKED	12.00	12.00
1	ARM SUB-ASSY, FR BUMPER LH	SERVICEABLE	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	SERVICEABLE	250.40	-
1	DEFLECTOR, RADIATOR LH	SERVICEABLE	77.00	-[

Report Ref No. NS/INC18000980/R1qbe2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

41,350.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Gur Adjusted
1	BUMPER FRT ABSORBER LOWER	SERVICEABLE	127.70	-
1	DOOR FRT / LH	TO REPAIR	894.40	-
1	FENDER SPRON SUB FRT / LH	TO REPAIR	637.80	-
1	MEMBER SUB-ASSY, FR LH	TO REPAIR	810.70	-
1	BUMPER REINFORCEMENT FRT	TO REPAIR	498.40	-
1	PILLAR, FR BODY, LH	TO REPAIR	363.10	-
			16,329.90	10,468.63
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		3,216.00	2,005.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		3,070.00	1,680.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.		60.00	40.00
			6,446.00	3,745.00
	GRAND TOTAL		22,775.90	14,213.63

(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) Report Ref No. NS/INC18000980/R1qbe2

RECOMMENDED COST OF LUMP SUM REPAIRS

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

h

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tori, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.