



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CS/EQI18001011/Atd3e2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 08-05-2018	
			Code : EQI	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SFL 6080U	
Policy No.	DMPPHQ17-000896	Coverage (\$)	0.00	
Claim No.	DM18HO00134	Excess (\$)	3,500.00	
Assign From	BAZLIN AHMAD	Assign Date	17/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C 180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WDD2040312A823243	Colour	BROWN	
Odometer	92309	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	PIRELLI	6 mm	
L/H Front Tyre	225/45 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/01/2018	Inspection Date	17/01/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD NO : 320 UBI ROAD 3 SINGAPORE 408649			
5a. Remarks				
A)THE MARKET VALUE IS S\$90,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8191B

Vehicle Details

Vehicle No.: SFL6080U

Vehicle to be Exported: No

Intended De-registration Date: 18 Jan 2018

Vehicle Make: MERCEDES BENZ

Vehicle Model: C 180 BLUEEFFICIENCY

Primary Colour: Brown

Manufacturing Year: 2012

Engine No.: 27491030036714

Chassis No.: WDD2040312A823243

Maximum Power Output: 115.0 kW (154 bhp)

Open Market Value: \$31,873.00

Original Registration Date: 08 Mar 2013

First Registration Date: 08 Mar 2013

Transfer Count: 0

Actual ARF Paid: \$26,873.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 07 Mar 2023

PARF Rebate Amount: \$20,154.00

Intended COE Rebate Details

COE Expiry Date: 07 Mar 2023

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$78,301.00

COE Rebate Amount: \$40,183.00

Total Rebate Amount: \$60,337.00

The information contained herein is correct as at 18 Jan 2018

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFL 6080U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET (WCP)	DENTED	1,050.00	1,050.00
10	BONNET INSULATOR CLIPS (WCP)	NECESSARY	40.00	40.00
1	LOGO EMBLEM (WCP)	NECESSARY	42.00	42.00
2	"STAR" LOGO (WCP)	NOT NECESSARY	90.00	-
1	BONNET LOCK (WCP)	NOT NECESSARY	45.00	-
1	FRONT BUMPER (WCP)	DEFORMED	740.00	740.00
1	FRONT BUMPER SPONGE (WCP)	DEFORMED	65.00	65.00
1	FRONT BUMPER REINFORCEMENT (WCP)	BENT	155.00	155.00
1	FRONT BUMPER SIDE BRACKET LH (WCP)	NECESSARY	45.00	45.00
1	FRONT BUMPER SIDE BRACKET RH (WCP)	NECESSARY	45.00	45.00
10	FRONT BUMPER CLIPS (WCP)	NECESSARY	40.00	40.00
1	FRONT SUPPORT PANEL (WCP)	BUCKLED	66.00	66.00
1	SUPPORT PANEL TOP GARNISH (WCP)	CRACKED	35.00	35.00
1	HEAD LAMP ASSY LH (WCP)	CRACKED	540.00	540.00
1	HEAD LAMP ASSY RH (WCP)	CRACKED	540.00	540.00
1	HEAD LAMP BRACKET LH (WCP)	NOT NECESSARY	125.00	-
1	HEAD LAMP BRACKET RH (WCP)	NOT NECESSARY	125.00	-
1	FRONT BUMPER LOWER CENTRE (CTR) (WCP)	NOT NECESSARY	80.00	-
1	FRONT BUMPER LOWER GRILLE (LH) (WCP)	NOT NECESSARY	30.00	-
1	FRONT BUMPER LOWER GRILLE (RH) (WCP)	NOT NECESSARY	30.00	-
1	FOG LAMP - CHROME (LH) (WCP)	NOT NECESSARY	62.00	-
1	FOG LAMP - CHROME (RH) (WCP)	NOT NECESSARY	62.00	-
1	CONDENSOR (WCP)	DENTED	650.00	650.00
1	RADIATOR (WCP)	NOT NECESSARY	680.00	-
1	RADIATOR GRILLE (WCP)	CRACKED	320.00	320.00
1	TOWING COVER (WCP)	NOT NECESSARY	40.00	-
1	FRONT FENDER (ADDITIONAL) (WCP)	BUCKLED	420.00	420.00
1	FRONT NUMBER PLATE GARNISH (ADDITIONAL) (WCP)	DEFORMED	60.00	60.00
1	BONNET STOPPER LH (ADDITIONAL) (WCP)	NECESSARY	18.00	18.00
1	BONNET STOPPER RH (ADDITIONAL) (WCP)	NECESSARY	18.00	18.00
1	FRONT BUMPER BRACKET LH (ADDITIONAL) (WCP)	DAMAGED	24.00	24.00
1	FRONT BUMPER BRACKET RH (ADDITIONAL) (WCP)	DAMAGED	24.00	24.00

Report Ref No. CS/EQ18001011/Atd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUPPORT PANEL LH HEADLAMP (ADDITIONAL) (WCP)	BENT	130.00	130.00
8	RIVET (ADDITIONAL) (WCP)	NECESSARY	8.00	8.00
2	RADIATOR CLIPS (ADDITIONAL) (WCP)	NECESSARY	14.00	14.00
4	FRONT BUMPER RIVET (ADDITIONAL) (WCP)	NECESSARY	8.00	8.00
1	HEADLAMP PANEL RH (ADDITIONAL) (WCP)	BENT	130.00	130.00
1	AIR GUIDE BAFFLE (ADDITIONAL) (WCP)	DEFORMED	35.00	35.00
1	RAD GRILLE BRACKET (ADDITIONAL) (WCP)	BENT	12.00	12.00
1	SUPPORT HOOK (ADDITIONAL) (WCP)	BENT	48.00	48.00
1	LOWER GRILLE CTR (ADDITIONAL) (WCP)	DEFORMED	95.00	95.00
2	ROD BEAM CLIPS (ADDITIONAL) (WCP)	NECESSARY	32.00	32.00
1	BONNET LOCK CATCH (ADDITIONAL) (WCP)	BENT	24.00	24.00
	COST PLUS 15%		1,026.30	820.95
			7,868.30	6,293.95
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN) (ADDITIONAL)	NECESSARY	45.00	45.00
			45.00	45.00
	<u>LABOUR</u>			
	TO KNOCK, STRAIGHTEN, REMOVE & REFIX DAMAGE PARTS.		1,800.00	800.00
	TO PUTTY & SPRAY PAINTING ON THE BONNET, FRONT BUMPER FRONT SUPPORT PANEL & AFFECTED AREAS.		1,800.00	600.00
	TO CHECK WIRING.		100.00	30.00
	TO REMOVE & REFIX CONDENSOR TO ASSIST WORKLOAD.		100.00	100.00
			-	-
			-	-
			3,800.00	1,530.00
	GRAND TOTAL		11,713.30	7,868.95
	RECOMMENDED COST OF REPAIRS			7,868.95
	LESS EXCESS			-3,500.00
	NETT LIABILITY			4,368.95

Report Ref No. CS/EQI18001011/Atd3e2

Report Ref No. CS/EQI18001011/Atd3e2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQ18001011/ATD3E2

Date: 13/07/2018

REFERENCE

Insured/Claimant: GAN CHENG HUAN Policy No: DMPPHQ17000896
Date of Loss: 13/01/2018 Nature of Claim: OD Claim No: DM18HO00134

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFL6080U**
Make & Model: MERCEDES-BENZ C180, 1.6 (A) Engine No: 27491030036714
Reg. Date: 08/03/2013 (Man. Year: 2012) Chassis No: WDD2040312A823243
Colour: Brown Odometer: 92309 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,338.95	6,338.95	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,530.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,868.95	7,868.95	0.00	0.00
- Excess (S\$)	0.00	3,500.00	-3,500.00	
(S\$)	7,868.95	4,368.95	3,500.00	44.48
+ GST 7.00/7.00% (S\$)	550.83	305.83	245.00	44.48
Nett Amount (S\$)	8,419.78	4,674.78	3,745.00	44.48

INSPECTION

Date of Assignment: 13/07/2018 Present Location: ComfortDelGro Engineering Pte Ltd (Ubi)
Date Inspected: 17/01/2018 Inspected At: 320 UBI ROAD 3
Singapore 408649
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2018)
Parts:	M1-COUPE	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFL6080U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	1,050.00 F	*1,050.00 F
2	10		*BONNET INSULATOR CLIPS	Necessary	40.00 F	*40.00 F
3	1		*LOGO EMBLEM	Necessary	42.00 F	*42.00 F
4	1		*FRONT BUMPER	Deformed	740.00 F	*740.00 F
5	1		*FRONT BUMPER SPONGE	Deformed	65.00 F	*65.00 F
6	1		*FRONT BUMPER REINFORCEMENT	Bent	155.00 F	*155.00 F
7	1		*FRONT BUMPER SIDE BRACKET LH	Necessary	45.00 F	*45.00 F
8	1		*FRONT BUMPER SIDE BRACKET RH	Necessary	45.00 F	*45.00 F
9	10		*FRONT BUMPER CLIPS	Necessary	40.00 F	*40.00 F
10	1		*FRONT SUPPORT PANEL	Buckled	66.00 F	*66.00 F
11	1		*SUPPORT PANEL TOP GARNISH	Cracked	35.00 F	*35.00 F
12	1		*HEAD LAMP LH	Cracked	540.00 F	*540.00 F
13	1		*HEAD LAMP RH	Cracked	540.00 F	*540.00 F
14	1		*CONDENSOR	Dented	650.00 F	*650.00 F
15	1		*RADIATOR GRILLE	Cracked	320.00 F	*320.00 F
16	1		*FRONT NUMBER PLATE	Necessary	45.00 FS	*45.00 FS
17	1		*FRONT FENDER	Buckled	420.00 F	*420.00 F
18	1		*FRONT NUMBER PLATE GARNISH	Deformed	60.00 F	*60.00 F
19	1		*BONNET STOPPER LH	Necessary	18.00 F	*18.00 F
20	1		*BONNET STOPER RH	Necessary	18.00 F	*18.00 F
21	1		*FRONT BUMPER BRACKET LH	Damaged	24.00 F	*24.00 F
22	1		*FRONT BUMPER BRACKET RH	Damaged	24.00 F	*24.00 F
23	1		*FRONT SUPPORT PANEL LH	Bent	130.00 F	*130.00 F
24	8		*RIVET	Necessary	8.00 F	*8.00 F
25	2		*RADIATOR CLIPS	Necessary	14.00 F	*14.00 F
26	4		*FRONT BUMPER RIVET	Necessary	8.00 F	*8.00 F
27	1		*HEADLAMP PANEL RH	Bent	130.00 F	*130.00 F
28	1		*AIR GUIDE BAFFLE	Deformed	35.00 F	*35.00 F
29	1		*RADIATOR GRILLE BRACKET	Bent	12.00 F	*12.00 F
30	1		*SUPPORT HOOK	Bent	48.00 F	*48.00 F
31	1		*LOWER GRILL CTR	Deformed	95.00 F	*95.00 F
32	2		*ROD BEAM CLIPS	Necessary	32.00 F	*32.00 F
33	1		*BONNET CATCH	Bent	24.00 F	*24.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	5,518.00	5,518.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	820.95	820.95
Total Parts (\$\$)	6,338.95	6,338.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN,PANEL BEAT AND REMOVE & REPLACE DAMAGE PARTS	New	800.00	800.00
2	TO PUTTY & SPRAY PAINT ON BONNET,FRONT BUMPER,FRONT SUPPORT PANEL & AFFECTED AREA	New	600.00	600.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO REMOVE & REFIT CONDENSER TO ASSIST WORKLOAD	New	100.00	100.00
Gross Labour Cost (S\$)			1,530.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >