

22/03/2002

ASS. REC. BY:

REF: CS/MSH/800102L/6965

Special Instruction:

SUPERVISOR:

60

ASSIGNMENT (Office)

From (Person):

monica chung

of

MSH

Date/Time: 17/01/2018 10:12am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHP 1846C

Insured:

SKD 1348P

at Workshop m/s

SMRT

Tel:

6555 5556

of

60 Woodlands Ind Park Rd

Policy No:

27278411 QMY

Claim No:

846220

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13-01-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time:

17/01/2018 10:15am

Person Contacted:

Esther

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHP 1846C - CC3 / ALH 16000162 / M12C392

DA: 31215

SKD 1348P - X

19/1/18 @ 3:33pm Revised to Monica Chung via Merimen.

Smile *xpd.*

REF: mslh

Melimen

ASSIGNMENT

From: _____ Date: 17.01.2018
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SGP 1846C
at Workshop m/s: SMRT
of: 60 Woodlands Ind Park Et
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: Esther - 6555 5556

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 7 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Wp.

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGP 1846C Yr Regn: 08 Jul 2016
Type: M.Cas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Sienta C.O. 1496
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 26182 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: NSP1707016 . 146
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In Order / Jammed / Leaked / Burnt or
Brake: In Order / Jammed / Leaked / Burnt or
Mod: Nil / S.Rip / STD A/Rim or
Tyre Size: F: 185 / 60 R15
R: 11
ES DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 17-01-18
Survey held at w/s 3pm
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
07/2 Finalized \$ 6150 with Gsther. (Red to 8708.15, 59%)

RECEIVED 27 FEB 2018

[Signature]
27/2/2018

Date/Time File Pass to? ☐ : Prel. Report
11/2/18 *[Signature]* ☐ : Final Report
Date/Time File Return to? _____

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee: _____
Transportation: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

\$ - R\$ - \$
Photos
Others

300
10

Report Format: MEMO

Lump Sum / I.B.I: (\$ 6150)

TOTAL

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.				
C Customer Code				
N Assign From				
C Assign Date				
C Veh No (Inspected)				
C Veh No (Insured)				
C D.O.A				
C Policy No				
C Claim No				
C Insurance Authorisation (CA /REV/REP)				
C Report Type				
C Weekend Charges				
N Survey held at/Repairer				
C Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No				
C Regn Month/Year				
N Vehicle Type				
N Make & Model				
C Engine Capacity. (C.C)				
N Colour				
C Odometer. (Sp.Reading)				
C Chassis No				
N General Condition				
N Steering				
N Brake				
N Modification (Modi)				
C Tyre Size				
N Tyre Make				
C Tyre Balance				
C Date of Inspection				
N Survey held				
N Des.of Damages				

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded				
--	--	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition				
C Market Value for OD cases				
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C Days of repair				
C Finalised Amount				
C Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C Resurvey photo Uploaded				
---------------------------	--	--	--	--

Check By:

Case Handler

Date



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18001024/Gqb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 17-01-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKD 1348P	Veh. Inspected	SGP 1846C
Policy No.	27278411QMY	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	17/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/01/2018	Inspection Date	17/01/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2018		17 Jan 2018 10:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		CHEW SOON BENG @ TEO SOON BENG, ID: S0070369I							
Main Claimant:		GOH LIM HENG, ID: S0021293H							
Vehicle Reg. No.:		SGP1846C	Date of Loss:	13/01/2018 00:00 - :59					
Claim Type:		TP	Policy/Cover Note No.:	27278411QMY (Comprehensive) Coverage: 21/03/2017 - 20/03/2018					
Vehicle Reg. No. (Insured):		SKD1348P	Policy No. (Claimant):						
		Excess:							
Repairer:		Smrt Automotive Service Pte Ltd (HQ) 60 WOODLANDS INDUSTRIAL PARK E4, 757705 Woodlands - Tel:							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/01/2018]							
Adj Asg. Remarks:		ON WP							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
<TeyChorKeng@smrt.com.sg>
Sent: Wednesday, 14 February 2018 12:13 PM
To: Denise Tay (LKKAUTO); Guo Qiang (LKKAUTO)
Cc: Shiau Chan (LKKAUTO); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: FW: SGP1846C TP MSIG - After repair photo
Attachments: estimate.pdf

Hi Denise,

We have confirm the finalise amount at \$6,150.00 before GST @ 7 working days.

Can I have the adjusted report?

Thanks.
Regards,
Esther

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: 14 February 2018 09:57
To: Guo Qiang (LKKAUTO); Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Cc: Shiau Chan (LKKAUTO)
Subject: RE: SGP1846C TP MSIG - After repair photo

Sorry miss out one more page

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 14 February 2018 9:55 AM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <TeyChorKeng@smrt.com.sg>
Cc: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: SGP1846C TP MSIG - After repair photo

Hi Esther,

Confirmed total amount \$6150 before GST @ 7 working days..

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 14 February 2018 9:55 AM
To: Guo Qiang (LKKAUTO); Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Cc: Shiao Chan (LKKAUTO)
Subject: RE: SGP1846C TP MSIG - After repair photo
Attachments: estimate.pdf

Hi Esther,

Confirmed total amount \$6150 before GST @ 7 working days..

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) [<mailto:TeyChorKeng@smrt.com.sg>]
Sent: Thursday, 25 January, 2018 3:03 PM
To: Guo Qiang (LKKAUTO)
Subject: RE: SGP1846C TP MSIG - After repair photo

Hi Guo Qiang,

Can finalise this case ASAP?

Thanks.

Regards,
Esther

From: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Sent: 25 January 2018 14:58
To: 'guoqiang@lkkauto.com'
Subject: SGP1846C TP MSIG - After repair photo

Hi Guo Qiang,

Attached is the After repair photo for SGP1846C.

Regards,
Esther

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 19 Jan 2018

Preliminary Advice

Insured Vehicle No : SKD1348P
TP Vehicle No : SGP1846C
Make : TOYOTA SIENTA
Date of Inspection : 17/01/2018
Inspection At : SMRT

Accident Date : 13/01/2018
Assignment Date : 17/01/2018
Est. Duration of Repair : 6

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,858.15
Revised Amount	:S\$	4,581.81
Check Items (Estimated)	:S\$	5,336.37
Total	:S\$	9,918.18
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2018 13:46
Date Of Accident	13/01/2018 16:15
Exact Location Of Accident	BUKIT TIMAH RD BEFORE NAMLY AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGP1846C
Insured/Policyholder	
Name Of Registered Owner	GOH LIM HENG
NRIC No	S0021293H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96356296
Alternative Phone No	OFFICE-96356296

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092022506
Cover Note Number	CLASSIC

Driver

Name of Driver	WU YIPENG
NRIC No	S9118592Z
Date Of Birth	28/05/1991
Occupation	INDOOR
Date Of Driving Pass	19/07/2011
Driving Experience	6 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91150291
Fax Number	
Contact Number	OTHERS-91157089
Email Address	YEEPUNG@NAVER.COM

Insurance Company Name


Nature Of Damage

No. Of Passenger (Including Driver)

2

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving our family car, SGP1846C, on 13/1/2018 at approximately 16:15hrs along Bukit Timah Road nearby Hwa Chong Institution. I had two passengers who were my sisters, one at the front seat, and one in the middle seats behind me. It was rainy and the road was wet.

There were 3 lanes; on the right lane was a queue for U-turn. Our car was traveling at approximately 40kmh. A car from the right lane swerved into the middle lane which is the same lane as where our family car was driving along; it had cut-in abruptly to take the front of the other car in front of us, most likely doing so to avoid the U-turn queue.

At this instance, the car in front of us hit the brakes and decelerated very quickly. As a result, I had to stop quickly too. In a short interval, the middle lane was cramped up with vehicles on the right swerving in, and traffic lights ahead turning red. We came to a complete stop and we were within a safe distance from the car in front.

Things happened quickly. At the next moment, my sisters and I heard a loud bang, three of us flung forward but were thankfully held back by our seatbelts. Due to the impact, along with the restraints from our seatbelts, we had suffered from sudden flexion-extension neck movements but thankfully none of us suffered significant injury.

We soon realised that we had been hit on the rear. We got off the car and communicated with Mr Chew Soon Beng (owner of SKD1348P). We also took photographs at the consent of Mr Chew.

Declaration

I/We declare the foregoing particulars are true in every respect.

1/15/2018 13:43
Policyholder's Signature / Date & Time

[Signature]
Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]
Thomas Chew (S098890)
Customer Care Executive
Motor Service Centre
Witnessed by Reporting Centre Personnel


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1293H
Vehicle Details	
Vehicle No.:	SGP1846C
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5G A
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	2NR8565615
Chassis No.:	NSP1707016146
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$21,527.00
Original Registration Date:	08 Jul 2016
First Registration Date:	08 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$12,138.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jul 2026
PARF Rebate Amount:	\$9,103.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$44,292.00
Total Rebate Amount:	\$53,395.00


The information contained herein is correct as at 18 Jan 2018

OK

Accident Photo



Accident Photo



Accident Photo



SMRT Vehicle Repair Estimate

Group : Buses / Taxis / Private Car
Reg. No. : SGP 1846 C
Make / Model : TOYOTA SIENTA
Chassis No : NSP1707016146
Name of Driver : GOH LIM HENG

Ref. No. : _____
Reg. Date : 8/7/2016
Mileage : _____
Rental/Replacement Vehicle : Yes / No

Date/Time of Accident : 13/01/2018 16:15

Surveyor is Required ? YES / NO

If Yes, VICOM / LKK / AIS / Others MSIG : MSIG

Vehicle is Towed Back ? YES / NO Date / Time : _____


Accident reporting date : 15/01/2018 13:46

Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others

Special Instruction to ARC, if any : _____

MISG THIRD PARTY CLAIM

The damages on the vehicle are as indicated in the following diagram :



Signed : _____ Date : _____

Accident Repair Job Card No : _____ Date Prepared : _____

Summary of Repair Estimates Repair Completed : _____

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charges	\$	2,200.00	\$	-
Total Spray Painting Charges	\$	1,800.00	\$	-
Total Material Charges	\$	9,798.15	\$	-
Other Charges	\$	1,060.00	\$	-
TOTAL	\$	14,858.15	\$	7713.48

Lump Sum Repair, if any : 20% : 6150

No. of Repair Days : [10] days

Signature : _____ Prepared by : _____ Adjusted by : Guo Qiang - 82880282
Guo Qiang@lkk auto. com

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Part prices at subject confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QN No. : _____ Invoice No. : _____ Invoice Date : 17/1/2018

Signed : _____ Date : _____

19/1/18 tumpsum Repair - After repair photos.

Part 1 - Labour Works

Job Scope	Quotation from ARC	
To renew damaged parts, replace and realign support panels, and aligned all parts	\$ 2,200.00	8pc 1000
Total Labour	\$ 2,200.00	\$ -

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray affected areas	\$ 1,800.00	900
Spray Painting	\$ 1,800.00	\$ -

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page ()

Job Scope	Quotation from ARC	
Towing		
to transfer of door mechanism		
To tuffcoat affect areas	\$ 250.00	60
To remove & refit /rear windscreen glass	\$ 120.00	100
To Conduct water leakage test	\$ 100.00	X
To remove /refit upholstery and cushion seat	\$ 80.00	60
To Transfer bootlid mechanism	\$ 120.00	60
To perform wiring check on accident damaged area	\$ 150.00	30
To remove and replace roof-top lining		
To check/adjust computer 4 wheel alignment (before/after)		
To adjust chassiss alignment on car-o-liner		
To remove/replace exhaust silencer box and straighten centre pipe	\$ 120.00	X 60
To remove/replace front sensors	\$ 120.00	40
To remove/replace Steering wheel Airbag Module		
To remove /replace SRS system and decode system		
Total Other Costs	\$ 1,060.00	\$ 2310

Part 4 - Spare Parts / Material Usage

Ref No.:

To be completed by Service Advisor, ARC

Part Number	Parts Description	Qty	list Price (\$)	Parts discount	Final Price (\$)	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
	TAIL GATE / buc	1	\$ 1,455.60	25%	\$ 1,091.70	/	
	TAIL GATE TOP LOCK ? / le	1	\$ 381.40	25%	\$ 286.05	/	
	TAIL GATE INNER TRIM X NN	1	\$ 164.70	25%	\$ 123.53		
	TAIL GATE WEATHERSTRIP ? / Twi	1	\$ 325.20	25%	\$ 243.90	/	
	TAIL GATE WINDSCREEN MOULDING / mcl	2	\$ 69.80	25%	\$ 52.35	/	
	TAIL GATE LOGO / mcl	1	\$ 69.50	25%	\$ 52.13	/	
	TAIL GATE REFLECTOR X / NN	2	\$ 330.70	25%	\$ 248.03		
	TAIL GATE SHOCKABSOBER X / NN	2	\$ 458.60	25%	\$ 343.95		
	TAIL GATE CENTRAL LOCKING SENSOR ? / DM	1	\$ 205.80	25%	\$ 154.35	/	
	TAIL GATE SIDE RUBBER X NN	2	\$ 55.40	25%	\$ 41.55		
	REAR NUMBER PLATE GARNISH ? / le	1	\$ 295.60	25%	\$ 221.70	/	
	REAR NUMBER PLATE LAMP X NN	2	\$ 89.60	25%	\$ 67.20		
	REAR BUMPER / le	1	\$ 445.20	25%	\$ 333.90	/	
	REAR BUMPER SIDE < RH - le	2	\$ 305.10	25%	\$ 228.83	114.42	
	REAR BUMPER TOWING COVER X NN	1	\$ 58.50	25%	\$ 43.88		
	REAR BUMPER BRACKET X X NN	2	\$ 185.30	25%	\$ 138.98		
	REAR BUMPER REFLECTOR ? / CPA	2	\$ 75.40	25%	\$ 56.55	/	
	REAR BUMPER SPONGE ? / CPA	1	\$ 49.30	25%	\$ 36.98	/	
	REAR BUMPER SIDE RETAINER < RH - le	2	\$ 68.30	25%	\$ 51.23	25.62	
	REAR TAIL LAMP ? < RH - CPA	2	\$ 695.70	25%	\$ 521.78	260.89	
	REAR TAIL LAMP LOWER BRACKET ? / CWT	2	\$ 58.90	25%	\$ 44.18	/	
	REAR TAIL LAMP PANEL X NN	2	\$ 422.50	25%	\$ 316.88		
	REAR END PANEL OUTER / buc	1	\$ 455.60	25%	\$ 341.70	/	
	REAR END PANEL INNER ? / buc	1	\$ 547.20	25%	\$ 410.40	/	
	REAR END PANEL TOP GARNISH ? / CPA	1	\$ 205.20	25%	\$ 153.90	/	
	REAR FLOOR PANEL X Repair	1	\$ 945.60	25%	\$ 709.20		
	REAR FLOOR PANEL SPONGE X NN	1	\$ 504.20	25%	\$ 378.15		
	REAR FLOOR PANEL TOP BOARD COVER X NN	1	\$ 358.30	25%	\$ 268.73		
	REAR FLOOR PANEL TOOLS BOARD ? / le	1	\$ 494.70	25%	\$ 371.03	/	
	REAR FENDER INNER TRIM ? / le	2	\$ 618.60	25%	\$ 463.95	/	
	REAR FENDER SPLASHIELD X NN	2	\$ 79.90	25%	\$ 59.93		
	REAR FENDER AIR VENT ? / CPA	2	\$ 82.40	25%	\$ 61.80	/	
	REAR SILENCER BOX X Repair	1	\$ 898.60	25%	\$ 673.95		
	REAR SILENCER BOX MOUNTING X / NN	2	\$ 58.30	25%	\$ 43.73		477.5
	REAR SILENCER TOP SEAL X	1	\$ 189.50	25%	\$ 142.13		
Special Nett Items	REAR NUMBER PLATE / SCR	1	\$ 50.00		\$ 50.00	40	
	REAR BUMPER CLIP / mcl	1SET	\$ 30.00		\$ 30.00	/	
	REAR END PANEL TOP GARNISH CLIP / mcl	1SET	\$ 40.00		\$ 40.00	20	
	REAR FENDER SPLASHIELD CLIP X NN	1SET	\$ 50.00		\$ 50.00	X	
	REAR WINDSCREEN SEALANT / mcl	2	\$ 120.00		\$ 120.00	50	
	REAR REVERSE SENSOR / DM	1SET	\$ 280.00		\$ 280.00	200	
	REAR REVERSE CAMERA X NN	1SET	\$ 450.00		\$ 450.00	X	
						340	
TOTAL MATERIALS			\$ 12,724.20		\$ 9,798.15		

Contractor:			
Reference Number		Date of Collection	/ /
Vehicle No	SGP 1846 C	Date of Request	18/01/2018
Vehicle Model	TOYOTA SIENTA	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price
1		REAR BUMPER CENTER / CRA	1	\$315.60
2		TAIL GATE INNER HANDLE / CRA	1	\$65.70
3				381.3
4				25%: 285.98

<<< Please submit photographs for damaged parts >>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this
declaration

(to be signed in front of an authorised

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	LKK AUTO
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
Photo Submitted	YES / NO	Date of submission

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jan 2018		17 Jan 2018 10:12 Edit Adj Rpt	S\$6,150.00 Edit Estimates	S\$6,150.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHEW SOON BENG @ TEO SOON BENG, ID: S00703691		
Main Claimant:	GOH LIM HENG, ID: S0021293H		
Vehicle Reg. No.:	SGP1846C	Date of Loss:	13/01/2018 16:00 - :59
Claim Type:	TP / 546220	Policy/Cover Note No.:	B27278411 (Comprehensive) Coverage: 21/03/2017 - 20/03/2018
Vehicle Reg. No. (Insured):	SKD1348P	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	SMRT Automotive Service Pte Ltd (Kaki Bukit) 23 Kaki Bukit Ave 4 #02-03B./04-01, (South Wing) Vicom Building, 415933 Kaki Bukit - Tel: 6866 2677		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 16/02/2018]		
Adj Asg. Remarks:	ON WP		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SGP1846C (546220)**
[SKD1348P]
TP
GOH LIM HENG
Jan 13 2018 4:00PM
[CHEW SOON BENG @ TEO SOON BENG]
SMRT Automotive Service Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/01/18 15:33	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/02/18 17:40	General View	 Load JPG	☒
2	14/02/18 17:40	General View	 Load JPG	☒
3	14/02/18 17:40	General View	 Load JPG	☒
4	14/02/18 17:40	General View	 Load JPG	☒
5	14/02/18 17:40	General View	 Load JPG	☒
6	14/02/18 17:40	General View	 Load JPG	☒
7	14/02/18 17:40	General View	 Load JPG	☒
8	14/02/18 17:40	General View	 Load JPG	☒
9	14/02/18 17:40	General View	 Load JPG	☒
10	14/02/18 17:40	General View	 Load JPG	☒
11	14/02/18 17:40	General View	 Load JPG	☒
12	14/02/18 17:40	General View	 Load JPG	☒
13	14/02/18 17:40	General View	 Load JPG	☒
14	14/02/18 17:40	General View	 Load JPG	☒
15	14/02/18 17:40	General View	 Load JPG	☒
16	14/02/18 17:40	General View	 Load JPG	☒
17	14/02/18 17:40	General View	 Load JPG	☒
18	14/02/18 17:40	General View	 Load JPG	☒
19	14/02/18 17:40	General View	 Load JPG	☒
20	14/02/18 17:40	General View	 Load JPG	☒
21	14/02/18 17:40	General View	 Load JPG	☒
22	14/02/18 17:40	General View	 Load JPG	☒
23	14/02/18 17:40	General View	 Load JPG	☒
24	14/02/18 17:40	General View	 Load JPG	☒
25	14/02/18 17:40	General View	 Load JPG	☒
26	14/02/18 17:40	General View	 Load JPG	☒
27	14/02/18 17:40	General View	 Load JPG	☒
28	14/02/18 17:40	General View	 Load JPG	☒
29	14/02/18 17:40	General View	 Load JPG	☒
30	14/02/18 17:40	General View	 Load JPG	☒

31	14/02/18 17:40	General View	1	Load JPG	✓
32	14/02/18 17:40	General View	1	Load JPG	✓
33	14/02/18 17:40	General View	1	Load JPG	✓
34	14/02/18 17:40	General View	1	Load JPG	✓
35	14/02/18 17:40	Chassis Number	1	Load JPG	✓
36	14/02/18 17:40	Odometer Reading	1	Load JPG	✓
37	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
38	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
39	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
40	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
41	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
42	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
43	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
44	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
45	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
46	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
47	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
48	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
49	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
50	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
51	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
52	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
53	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
54	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
55	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
56	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
57	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
58	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
59	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
60	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
61	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
62	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
63	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
64	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
65	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
66	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
67	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
68	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
69	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
70	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
71	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
72	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
73	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
74	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
75	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
76	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
77	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
78	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓

79	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
80	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
81	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
82	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
83	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
84	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
85	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
86	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
87	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
88	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
89	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
90	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
91	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
92	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
93	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
94	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
95	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
96	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
97	14/02/18 17:41	Reinspection Photo	1	Load JPG	✓
98	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
99	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
100	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
101	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
102	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
103	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
104	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
105	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
106	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
107	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
108	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
109	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
110	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
111	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
112	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
113	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
114	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
115	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
116	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
117	14/02/18 17:42	Reinspection Photo	1	Load JPG	✓
118	14/02/18 17:42	Photo After Spray	1	Load JPG	✓
119	14/02/18 17:42	Photo After Spray	1	Load JPG	✓
120	14/02/18 17:42	Photo After Spray	1	Load JPG	✓
121	14/02/18 17:42	Photo After Spray	1	Load JPG	✓
122	14/02/18 17:42	Photo After Spray	1	Load JPG	✓
123	14/02/18 17:42	Photo After Spray	1	Load JPG	✓

Documentation

1 per page



No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	17/01/18 10:14	TP GIA REPORT	1	Load PDF	

2	17/01/18 10:14	ESTIMATE	i	Load PDF	
3	17/01/18 10:15	OI GIA REPORT	i	Load PDF	
4	17/01/18 10:16	EMAIL TO TP WORKSHOP, WE APPOINT LKK TO SURVEY	i	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/03/18 09:25	SUPPLEMENTARY	i	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001024/GQBS2

Date: 01/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B27278411

Claimant Vehicle No : SGP1846C

Insured Vehicle No : SKD1348P

Date of Loss: 13/01/2018

Nature of Claim: TP Claim No: 546220

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGP1846C

Make & Model: TOYOTA SIENTA, 1.5 (A)

Engine No: 2NR8565615

Reg. Date: 08/07/2016 (Man. Year: 2015)

Chassis No: NSP1707016146

Colour: White

Odometer: 26182 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 185/60R15

Rear Tyre Size: 185/60R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,105.50	5,403.47	7,702.03	58.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,060.00	2,310.00	2,750.00	54.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,165.50	7,713.47	10,452.03	57.54
Approved Total (Overridden) (S\$)		6,150.00		
(S\$)	18,165.50	6,150.00	12,015.50	66.14
+ GST 7.00/7.00% (S\$)	1,271.59	430.50	841.09	66.14
Nett Amount (S\$)	19,437.09	6,580.50	12,856.59	66.14

INSPECTION

Date of Assignment: 17/01/2018

Date Inspected: 17/01/2018 Inspected At:

SMRT Automotive Service Pte Ltd
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printpt&caseid=675650&extid=262156&CFID=29441406&C... 1/5

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2018)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGP1846C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAIL GATE (DISC 25%)	Buckled	1,455.60 F	*1,091.70 F
2	1	*TAIL GATE TOP LOCK (DISC 25%)	Deformed	381.40 F	*286.05 F
3	1	*TAIL GATE INNER TRIM	Not Necessary	164.70 F	*- F
4	1	*TAIL GATE WEATHERSTRIP (DISC 25%)	Twisted	325.20 F	*243.90 F
5	1	*TAIL GATE WINDSCREEN MOULDING 2pcs (DISC 25%)	Necessary	69.80 F	*52.35 F
6	1	*TAIL GATE LOGO (DISC 25%)	Necessary	69.50 F	*52.13 F
7	2	*TAIL GATE REFLECTOR	Not Necessary	330.70 F	*- F
8	2	*TAIL GATE SHOCKABSORBER	Not Necessary	458.60 F	*- F
9	1	*TAIL GATE CENTRAL LOCKING SENSOR (DISC 25%)	Damaged	205.80 F	*154.35 F
10	2	*TAIL GATE SIDE RUBBER	Not Necessary	55.40 F	*- F
11	1	*REAR NUMBER PLATE GARNISH (DISC 25%)	Deformed	295.60 F	*221.70 F
12	2	*REAR NUMBER PLATE LAMP	Not Necessary	89.60 F	*- F
13	1	*REAR BUMPER (DISC 25%)	Deformed	445.20 F	*333.90 F
14	1	*REAR BUMPER SIDE (DISC 25%)	N/s Not Necessary/O/s Deformed	305.10 F	*114.42 F
15	1	*REAR BUMPER TOWING COVER	Not Necessary	58.50 F	*- F
16	2	*REAR BUMPER BRACKET	Not Necessary	185.30 F	*- F
17	1	*REAR BUMPER REFLECTOR 2pcs (DISC 25%)	Cracked	75.40 F	*56.55 F
18	1	*REAR BUMPER SPONGE (DISC 25%)	Cracked	49.30 F	*36.98 F
19	1	*REAR BUMPER SIDE RETAINER (DISC 25%)	N/s Not Necessary/O/s Deformed	68.30 F	*25.62 F
20	1	*REAR TAIL LAMP (DISC 25%)	N/s Not Necessary/O/s Cracked	695.70 F	*260.89 F
21	2	*REAR TAIL LAMP LOWER BRACKET (DISC 25%)	Cut	58.90 F	*44.18 F
22	2	*REAR TAIL LAMP PANEL	Not Necessary	422.50 F	*- F
23	1	*REAR END PANEL OUTER (DISC 25%)	Buckled	455.60 F	*341.70 F
24	1	*REAR END PANEL INNER (DISC 25%)	Buckled	547.20 F	*410.40 F
25	1	*REAR END PANEL TOP GARNISH (DISC 25%)	Cracked	205.20 F	*153.90 F
26	1	*REAR FLOOR PANEL	Repair	945.60 F	*- F
27	1	*REAR FLOOR PANEL SPONGE	Not Necessary	504.20 F	*- F
28	1	*REAR FLOOR PANEL TOP BOARD COVER	Not Necessary	358.30 F	*- F
29	1	*REAR FLOOR PANEL TOOLS BOARD (DISC 25%)	Deformed	494.70 F	*371.03 F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
30	1	*REAR FENDER INNER TRIM 2pcs (DISC 25%)	Deformed	618.60 F	*463.95 F
31	2	*REAR FENDER SPLASHIELD	Not Necessary	79.90 F	*- F
32	2	*REAR FENDER AIR VENT (DISC 25%)	Cracked	82.40 F	*61.80 F
33	1	*REAR SILENCER BOX	Repair	898.60 F	*- F
34	2	*REAR SILENCER BOX MOUNTING	Not Necessary	58.30 F	*- F
35	1	*REAR SILENCER TOP SEAL	Not Necessary	189.50 F	*- F
36	1	*REAR NUMBER PLATE	Scratched	50.00 FS	*40.00 FS
37	1	*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
38	1	*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*20.00 FS
39	1	*SET REAR FENDER SPLASHIELD CLIP	Not Necessary	50.00 FS	*- FS
40	2	*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*50.00 FS
41	1	*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
42	1	*SET REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
43	1	*REAR BUMPER CENTER (DISC 25%)	Cracked	315.60 F	*236.70 F
44	1	*TAIL GATE INNER HANDLE (DISC 25%)	Cracked	65.70 F	*49.27 F

F=Franchise part. S=SpcNett.

Total Parts (S\$)	13,105.50	5,403.47
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS, REPLACE AND REALIGN SUPPORT PANELS, AND ALIGNED ALL PARTS.	New	2,200.00	1,000.00
2	TO RESPRAY AFFECTED AREAS.	New	1,800.00	900.00
3	TOWING. (NPA)	New	0.00	0.00
4	TO TRANSFER OF DOOR MECHANISM. (NPA)	New	0.00	0.00
5	TO TUFFCOAT AFFECT AREAS.	New	250.00	60.00
6	TO REMOVE & REFIT / REAR WINDSCREEN GLASS.	New	120.00	100.00
7	TO CONDUCT WATER LEAKAGE TEST.	New	100.00	0.00
8	TO REMOVE / REFIT UPHOLSTERY AND CUSHION SEAT.	New	80.00	60.00
9	TO TRANSFER BOOTLID MECHANISM.	New	120.00	60.00
10	TO PERFORM WIRING CHECK ON ACCIDENT DAMAGED AREA.	New	150.00	30.00
11	TO REMOVE AND REPLACE ROOF-TOP LINING. (NPA)	New	0.00	0.00
12	TO CHECK / ADJUST COMPUTER 4 WHEEL ALIGNMENT (BEFORE / AFTER) (NPA)	New	0.00	0.00
13	TO ADJUST CHASSIS ALIGNMENT ON CAR-O-LINER. (NPA)	New	0.00	0.00
14	TO REMOVE / REPLACE EXHAUST SILENCER BOX AND STRAIGHTEN CENTRE PIPE.	New	120.00	60.00
15	TO REMOVE / REPLACE FRONT SENSORS.	New	120.00	40.00
16	TO REMOVE / REPLACE STEERING WHEEL AIRBAG MODULE. (NPA)	New	0.00	0.00
17	TO REMOVE / REPLACE SRS SYSTEM AND DECODE SYSTEM. (NPA)	New	0.00	0.00
Gross Labour Cost (S\$)			5,060.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >