

TRANS-CAB AUTO SERVICES PTE LTD

NO.58 DEFU LANE 1 SINGAPORE 539498

TEL NO.6287 6666 FAX NO.6281 1400

CO/GST REG NO.201019626G

SHC5406U -

LI DAN

Not Authorised
L1 Reg B 5001

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5406U - LI DAN

LXS12-00021359*

TOYOTA

CROWN TAXI

08.01.2013

AXA

PART			LIST	
1	1	Front Bumper Assembly	\$	B/LM 417.40 ✓
2	1	Front Bumper Reinforcement / Beam	\$	R 269.35 X
3	1	Front Side Lamp RH	\$	CM 170.60 ✓
4	1	Front Headlamp RH	\$	SM 411.54 X
5	1	Front Support Panel Assy	\$	R 626.30 ✓
6	1	Front Fender RH	\$	R 732.83 X
			\$	2,628.02
			25% \$	657.01
TOTAL			\$	1,971.02

Specical Nett

1 Set	Front Bumper Fastener Clip	\$	MM 12.00 ✓
TOTAL		\$	12.00
TOTAL PARTS		\$	1,983.02

Panel Beating, Knocking And Straightening
The Necessary Portion, Remove And
Renewal Of Parts, Adjust And Realign The
Same

\$ 1,000.00 1801

To Rust-Proofing Of The Affected Areas.

\$ MM 200.00 X

To Check Electrical Lighting Concerned.

\$ 100.00 201

Putty And Spray Painting Of The Affected
Portion.

\$ MM 720.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.58 DEFU LANE 1 SINGAPORE 539498

TEL NO.6287 6666 FAX NO.6281 1400

CO/GST REG NO.201019626G

SHC5406U -

LI DAN

*To Remove And Refit Interior Fittings,
Trimings, Garnish, Fittings And Other, To
Enable repair.*

\$ *nn* 250.00 X

*To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.*

\$ *nn* 150.00 X

Towing Fees.

\$ *nn* 100.00 X

TOTAL \$ 2,520.00

Over All Total \$ 4,503.02

Total Repair Days

04 Days

1 day