

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5406U

Page No.:1 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER ASSEMBLY (CONSISTENT)	BENT/CRACKED	417.40	417.40
1	FRONT BUMPER REINFORCEMENT/BEAM (CONSISTENT)	TO REPAIR SEE LABOUR	269.35	-
1	FRONT SIDE LAMP RH (CONSISTENT)	CRACKED	170.60	170.60
1	FRONT HEADLAMP RH (CONSISTENT)	SERVICEABLE	411.54	-
1	FRONT SUPPORT PANEL ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	626.30	-
1	FRONT FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	732.83	-
	LESS 25% DISCOUNT		-657.00	-147.00
			1,971.02	441.00
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER FASTENER CLIP (SN) (CONSISTENT)	NECESSARY	12.00	12.00
			12.00	12.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT/BEAM, FRONT SUPPORT PANEL ASSY AND FRONT FENDER RH.		1,000.00	180.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	200.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		100.00	20.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	NOT NECESSARY	720.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	250.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	150.00	-
	TOWING FEES.	NOT NECESSARY	100.00	-
			2,520.00	200.00
	GRAND TOTAL		4,503.02	653.00



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		500.00
(101101 RE-ACCIDENT CONDITION)		

Report Ref No. CC3/AXA13001447/Keb3y

KONG SENG CHEONG Licensed Appraiser