



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/AXA13001447/Keb3y

8 SHENTON WAY #27-01 SINGAPORE 068811

Date : 07-10-2013



ATTN: BELLIANA LIM

Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJA 6778B	Veh. Inspected	SHC 5406U
Policy No.	P1111186	Coverage (\$)	0.00
Claim No.	C0259268	Excess (\$)	0.00
Assign From		Assign Date	21/01/2013

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CROWN	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	LXS120021359	Colour	WHITE / RED
Odometer	920767	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/80R14	WEST LAKE	8 mm
L/H Front Tyre	175/80R14	WEST LAKE	8 mm
R/H Rear Tyre	175/80R14	WEST LAKE	2 mm
L/H Rear Tyre	175/80R14	WEST LAKE	2 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/01/2013	Inspection Date	21/01/2013
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD 58 DEFU LANE 1 SINGAPORE 539498		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------