

Pam

REF: EQI

1790c

From: Date 18/01/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKB 9800H
at Workshop: Mova Automotive
15 Fan Yong Road

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Vehicle:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 23K

DAI Accident Report: Consistent? : Yes or No

GA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: Person Contacted:

Vehicle: IN / OUT

Date Time Action Instruction

Date Time File Pass to?

☐ : Preli. Report
☐ : Final Report

Date Time File Return to?

Report Format:

Lum Sum / MV

Ver No: SKB 9800H Page: 2011 MUY

Type: C Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: B.M.W 523 I

cc: 2497

Colour: Black

Bo Reading: 10 0091

Eng No:

Q No: WBAFP 320X0 C 86 4098

Gen Cond: Good / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Mod: Nil / S/R / STD A/Rim or

Tyre Size: R: 225 / 55 R 17

R: V V

CS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front:

R.Bal:

L.Bal:

D.O.A:

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Accident Fee

Storage

Other

Add Fee:

☐ Site fee
☐ Transport
☐ Test
☐ Other

Site fee

Transport

Test

Other

