

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







| NTUC INCOME INSURANCE CO-OPERATIVE LTD                                 |  |                         |         | NS/INC18001055/R1vbe2 |            |  |
|--|--|-------------------------|---------|-----------------------|------------|--|
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556 |  |                         | Date:   | 02-03-2018<br>INC4    |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                             |  |                         |         |                       |            |  |
|  | Insured Veh.   | SKK 7897U               | Veh. lı | nspected              | SHC 4018M  |  |
|  | Policy No.   | 5093905148              | Cover   | age (\$)              | 0.00       |  |
|  | Claim No.  | MT/0977790-003          | Exces   | s (\$)                | 0.00       |  |
|  | Assign From  |                         | Assig   | n Date                | 16/01/2018 |  |
| 2. Vehicle Particulars & Condition                                     |  |                         |         |                       |            |  |
|  | Make & Model   | TOYOTA PRIUS            | c.c     |                       | 1798       |  |
|  | Engine No.   | HIDDEN                  | Year o  | f Reg.                | 2017       |  |
|  | Chassis No.  | JTDKB3FU703576147       | Colou   | •                     | MAROON     |  |
|  | Odometer   | 15074                   | Steeri  | ng                    | IN ORDER   |  |
|  | Brakes   | IN ORDER                | Modifi  | cation                | NIL        |  |
|  | General  | FAIR                    |         |                       |            |  |
| 3. Conditions of Tyres   |  |                         |         |                       |            |  |
|  |  | Size                    | Make    |                       | Balance    |  |
|  | R/H Front Tyre   | 195/65 R15              | YOKO    | HAMA                  | 5 mm       |  |
|  | L/H Front Tyre   | 195/65 R15              | YOKO    | HAMA                  | 5 mm       |  |
|  | R/H Rear Tyre  | 195/65 R15              | YOKO    | HAMA                  | 5 mm       |  |
|  | L/H Rear Tyre  | 195/65 R15              | YOKO    | HAMA                  | 5 mm       |  |
| 4.   | . Description of Damages   |                         |         |                       |            |  |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.   |                         |         |                       |            |  |
|  | DAMAGES SEE DETAILS.   |                         |         |                       |            |  |
| 5.   | General Information  |                         |         |                       |            |  |
|  | Accident Date  | 13/01/2018              | Insped  | ction Date            | 16/01/2018 |  |
|  | Survey held at   | SMRT AUTOMOTIVE SERVICE | S PTE L | TD                    |            |  |
|  | 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705   |                         |         |                       |            |  |
| 5a.  | 5a. Remarks  |                         |         |                       |            |  |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                         |         |                       |            |  |
| 5b.  | . Estimate Days of Repair  |                         |         |                       |            |  |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days   |                         |         |                       |            |  |