

3

FRONT NUMBER PLATE

Reviewing

35

SCRATCHED



TO SPRAY PAINT ON REPLACED, REPAIRED

600

0

0

Reviewing



60

Reviewing



Labour



1

TO INSPECT FRONT LIGHTING WATER &
LEAKAGE TEST

40

0

0

Reviewing



2

0

Reviewing



17

1

WASHER TANK

Deformed

90

90

Reviewing



60

Reviewing



14

1

SUPPORT PANEL

Bent

495

495

Reviewing



Reviewing



11

20

FRONT BUMPER CLIPS

Necessary

3

60

Reviewing



12



8

1

FRONT BUMPER LOGO

Necessary

35

35

Reviewing



9

2



5

1

FRONT BUMPER SPONGE

Damaged

60

60

Reviewing



6

1

2

1

FRONT BUMPER LOWER SPOILER

Deformed

450

450

Reviewing



3

1

FOG LAMP COVER RH

Handbrake (Serviceable)

Engine Modification

Pre-accident condition

Excellent

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

4

Driver License #

License Type

License Issue Date

January 1, 2014

License Expiration Date

Address

BLK 51 STRATHMORE AVENUE, #20-191, 140051,
Singapore

Address type

Personal Correspondence

LATIU 1.5

Type

Listed on policy ▼

Type of Paint

Chassis No

JN1BAAC11Z0004088

Engine No

HR15078386A

Engine Capacity

Sum Insured

0

January 18, 2018

IC & DL (OWNER).pdf

Forms / Claim Documents

Driver's License / IDP

MOVA AUTOMOTIVE PTE LTD

January 18, 2018

Model
LATIO 1.5

Service Address

Blk 1008, , , 159722

Primary Contact/Insured

VINAYAK PRAVIN
BLK 51 STRATHMORE AVENUE, 140051, Singapore
91456740
VPRAVIN@GMAIL.COM

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions
Pend estimate Excess to be confirm

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

Document Type

Document SubType

[Upload Documents](#)

RESURVEY PHOTOS.pdf

Evidence

Photos

LKK AUTO CONSULTANTS PTE LTD (OD)

January 26, 2018

SURVEY PHOTOS.pdf