

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 9919R

DA

MAKE :

MODEL : HYUNDAI i40

L/Sum
General In

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>X succ</i>			\$ 294.35	
	Radiator Grille H Emblem <i>X succ</i>			\$ 113.65	
	Front Bumper Cover <i>cm</i>			\$ 562.30	
	Front Bumper Sponge <i>X succ</i>			\$ 142.20	
	Front Bumper Reinforcement <i>X succ</i>			\$ 526.10	
	Front Bumper Centre Grille <i>cm</i>			\$ 176.90	
	Front Bumper Bracket Top (LH/RH) <i>X succ</i>		\$ 22.40	\$ 44.80	
	Front Bumper Retainer Mounting <i>X succ</i>		\$ 9.20	\$ 18.40	
	SUB TOTAL			\$ 1,878.70	
	LESS 20%			\$ 375.74	
	DISCOUNTED TOTAL			\$ 1,502.96	
	Front Number Plate <i>cm</i> <i>200g</i>			\$ 25.00	Nett
	Front No Plate Trim Cover <i>cm</i> <i>200g</i>			\$ 30.00	Nett
				\$ 55.00	
	Labour Charge			200	
	Panel Beating			\$ 350.00	
	Spray Painting Charge			\$ 200.00	
				180	
	TOTAL LABOUR			\$ 550.00	
	ESTIMATE TOTAL			\$ 2,107.96	
<i>Ka/ur LKK</i> <i>18/1/8 1030 hrs.</i> <i>2 Days</i> <i>4/5</i> <i>After Repair photo</i>					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.