

ASS. SEC. BY

REF CS3/AXA18001109/Gd30v

Menimen

GQ

ASSIGNMENT (Office)

From Person

Cynthia Loh

AXA

18/01/2018 @ 11:27am

Estimated Cost

B/W

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

JQM 2057

Insured

SHB 7682E

at Workshop no

Gold Auto Works

Tel

96199144

at 48 Toh Guan Rd East #01-119

Policy No P1680520

Claim No

C0467261

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

29/12/2017

CA / REV / REP. / REV 24 HRS 'wp'

MOD Endorsement

Date/Time 12:07pm @ 18/01/2018

Person Contacted

Mr. Zoron

Status IN/OUT

Date/Time

Action/Inspection (X) Estimate

JQM 2057 -X

SHB 7682E - CS/TP18000283/Kqb

D.O.A: 29/12/2017

After repair: 1/2/2018 (Paul Kh)

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s Gold Auto

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: JQM2057 Yr Regn: -

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha 135 LC C.C. 135

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 35071 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: -

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80/90-17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 19-01-18

Survey held at W/S 3pm

Des. of Damages ☒ Frt / Rear / ☒ O/S / ☒ N/S UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Submit PR5

RECEIVED 12 APR 2018

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation

_____ \$ - RS _____ \$

) _____ Photos

) _____ Others

TOTAL

100
100

...CLAIM SUBFOLDER...(New Assignment)

RI Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jan 2018		18 Jan 2018 11:27 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Main Claimant:	-		
Vehicle Reg. No.:	JQM2057	Date of Loss:	29/12/2017 00:00 - :59
Claim Type:	TP / C0467261	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHB7682E	Policy No. (Claimant):	
		Excess:	S\$5,000.00
Repairer:	Gold Auto Works Pte Ltd (HQ) 48 Toh Guan Rd East #01-119, Enterprise Hub, 608586 Jurong East - Tel: 96199144/ 87789382		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/01/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AXA_SG (18/01/2018): C0467261/P1680520

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SG AXA Insurance SM AXA SGP - Motor Survey

From: claims@goldautoworks.com.sg
Sent: Wednesday, January 17, 2018 11:40 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: Requesting Pre-Repair Inspection for Vehicle no.: JQM2057
Attachments: img-117112659-0001.pdf

Categories: Kushal

Our Ref : 2018-01-007

Date : 17/1/2018

Attention Motor Claims Department

Dear Sir/Mdm,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PERSUANT TO PARAGRAPHS 6.2 OF PRE-ACTION FOR NIMA CASES.

Accident involving JQM2057 and SHB7682E at/along Toh Guan Rd Easr (towards Toh Guan Rd) on 29.12.2017; 17:30H.

We act for motor vehicle no. JQM2057 with instruction to repair the same.

Please be informed that the said vehicle can be inspected at the following address;-

Venue: 48 Toh Guan Rd East
Enterprise Hub
01-119, Gold Auto Works
Singapore 608586

Contact Person : Mr Zoron Koh (HP: 9619-9144) and/or myself at 8778-9382.

Note: Kindly contact us to arrange for Pre-Repair Inspection.

If you fail to conduct the Pre-Repair Inspection within the next 2 working days excluding any intervening Saturday, Sunday and Public Holiday, the said workshop will commence repairs thereafter without further notice to you.

Warmest Regards,
jess Chua
Gold Auto Works Pte Ltd



**SINGAPORE
POLICE FORCE**



T/20180103/2078

1 of 3

Police Station Of Origin:
Tiong Bahru NPP
128 Kim Tian Road #01-123 SINGAPORE
160128
Tel No: 1800-2739999

Report No. T/20180103/2078

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/01/2018 14:09	Vide Report No.:	Station Diary No.: 17
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: LIM JIAN CHONG		Address: No.10 Jalan SS 6/13 Taman Seri Saujana 81900 Kota Tinggi Johor	
ID Type / ID No.: FIN NO / G2622051W		Contact No.: Home/Office: Mobile: 93929410	
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 21	Date of Birth: 21/08/1996	Type of Informant: Rider
Race: Chinese		Language: Malay	Institution / School Name:
Occupation: Storekeeper		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 29/12/2017 17:30	Type of Location: Straight Road
Location: Along Road 1 TOH GUAN ROAD EAST (TOWARDS TOH GUAN RD)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JQM2057	Motorcycle				Slightly Damaged	0
SHB7682E	Taxi				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180103/2078

3 of 3

Report No. T/20180103/2078

Police Station Of Origin:
Tiong Bahru NPP
128 Kim Tian Road #01-123 SINGAPORE
160128
Tel No: 1800-2739999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

A /

Sr Staff Sgt JURAIMI BIN MOHAMED AMIN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Contact No.:

Authentication Stamp


NP168

Signature Of Informant:

Date/Time:

03/01/2018 14:09

Classification Of Case:



On 29 Dec 2017 at about 5.30pm, I was riding my motorcycle JQM 2057 along Toh Guan Road East towards Toh Guan Road. I saw a red taxi SHB 7682E was stationary on the left side of the road with the hazard light on. As I was about to overtake the taxi, it suddenly swerved right across my path. I immediately applied brake and swerved to the right but was unable to avoid colliding onto the right side of the taxi. On collision, I was flung from my motorcycle and landed a few meters away.

Passerby assisted me to the side of the road and also pushed my motorcycle to the road side.

I was injured and was conveyed by ambulance to Ng Teng Fong General Hospital.

My handphone was also damaged in the accident.



...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI BI Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jan 2018		18 Jan 2018 11:27 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		[Created by insurer]	
Main Claimant:	-			
Vehicle Reg. No.:	JQM2057	Date of Loss:	29/12/2017 00:00 - :59	
Claim Type:	TP / C0467261	Policy/Cover Note No.:	P1680520 (Third Party Only)	
Vehicle Reg. No. (Insured):	SHB7682E	Policy No. (Claimant):		
		Excess:	S\$5,000.00	
Repairer:	Gold Auto Works Pte Ltd (HQ) 48 Toh Guan Rd East #01-119, Enterprise Hub, 608586 Jurong East - Tel: 96199144/ 87789382			
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 29/01/2018]			

ASSOCIATED MAIL RECEIVED

- AXA_SG (18/01/2018): C0467261/P1680520

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Claim Documents

*JQM2057 (C0467261)
[SHB7682E]
TP
-

Dec 29 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]
Gold Auto Works Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	12/04/18 10:18	General View		Load PDF
2	12/04/18 13:38	Photo After Spray		Load PDF
Documentation			1 per page <input checked="" type="checkbox"/>	
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail Print
1	17/01/18 12:23	EMAIL		Load PDF
2	17/01/18 12:24	img-117112659-0001		Load PDF
3	18/01/18 11:24	E-filed GIA report - INSD		Load PDF
4	18/01/18 11:56	Emailed to Transcab		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AXA18001109/R1D3E2
Date: 18/04/2018

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	JQM2057	Insured Vehicle No :	SHB7682E
Date of Loss:	29/12/2017	Nature of Claim:	TP
		Claim No:	C0467261

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JQM2057	Engine No:	HIDDEN
Make & Model:	YAMAHA 135LC, 135cc ES	Chassis No:	HIDDEN
Reg. Date:	(Man. Year:)	Odometer:	35071 km
Colour:	Red		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	18/01/2018	
Date Inspected:	19/01/2018 Inspected At:	Gold Auto Works Pte Ltd (HQ) 48 Toh Guan Rd East #01-119, Enterprise Hub Singapore 608586
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:**Parts:** N/A YAMAHA 135LC 135cc ES (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for JQM2057)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >