

Surveyor
Maimun

REF: CS3 / msh 18001112 / mlgd3e2

Special Instruction:

US \$ 8200.00

ASSIGNMENT (Office)

From (Person): Katherine Wong of msh Date/Time: 02042018

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: OH Appraisal

Workshop: Hiap Lek

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: SLN 9483P Insured: SLR 17533

at Workshop m/s Hiap Lek Tel: 8453 1743

of 160 Sin Ming Dr #05-17

Policy No: A28795104mcx Claim No: 544671

Sum Insured: Excess:

Make of Veh: D.O.A. 05012018

(Client's Record)

Do Not Finalize
H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 8 days)

Date/Time: 12/4/18 Submit Final Fig 4150, 5 days (Red \$ 4050 / 49%; Original 8 days)

Date/Time	Action/Instruction
	SLN 9483P - CCL 174613000579 / mlgd3
	SLR 17533 - " "
	* Billing PRS + PS
	RECEIVED 12 APR 2018
	9/4/2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1) Date/Time 12/4/18 File Pass to [Signature]

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to

REF: CS3/MSG18001112/Mld3

range

ASSIGNMENT (Office)
 Menimen Katherine Wong of MSIG Time 18/01/2018 @ 10:25am
 Estimated Cost:
 OD (TP) WS / TP RES / OD RES / EVA / EV / MV / CS
 To Inspect Vehicle No: SLN 9483P Insured: SLR 1753S
 at Workshop no: Hiap Teek Automobile Tel: 6453 1743
 of 160 Sin Ming Drive # 05-17
 Policy No: A28795104MCX Claim No: 544671
 Sum Insured:
 Make of Veh:
 (Client's Record)
 CA / REV / REP. / REV 24 HRS 'wp'
 Date/Time: 12:03pm @ 18/01/18 Person Contacted: Hanwei
 Vehicle ID: (OUT)

Date/Time	Action/Inspection	Estimate
	SLN 9483P - CC1/AIG18000579/Mlud3	D.O.A: 05/01/2018
	SLR 1753S - CC1/AIG18000579/Mlud3	D.O.A: 05/01/2018

REF: MSLH.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: NIAP LK

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLH9483P Yr Regn: MAY 2017Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: KIA NIRO cc 1580Colour: WHITE A/C: _____ Insured / Std / NI / NASp. Reading: 12673 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNACC81CVH5661391Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60/RL6

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 05/01/2017 D.O.I. 19/1/2017

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

OS BODY

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ Site Insp. (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

Photo: _____

Chart: _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2018		18 Jan 2018 10:25 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N		
Main Claimant:	TEO POH SENG, ID: S7640219A		
Vehicle Reg. No.:	SLN9483P	Date of Loss:	05/01/2018 17:00 - :59
Claim Type:	TP / 544671	Policy/Cover Note No.:	A28795104MCX (Comprehensive) Coverage: 08/08/2017 - 07/08/2018
Vehicle Reg. No. (Insured):	SLR1753S	Policy No. (Claimant):	
		Excess:	
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/01/2018]		
Driver/Custodian (Insured):	TEO CHENG SEONG (), NRIC: S7239043A, Tel: +6596324332		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/01/2018 11:21
Date Of Accident 05/01/2018 18:10
Exact Location Of Accident BARTLEY ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLN9483P
Insured/Policyholder
Name Of Registered Owner TEO POH SENG
NRIC No S7640219A
Email Address DINO_TEO@YAHOO.COM
Mobile Phone No (LOCAL) +65-90489667
Alternative Phone No OFFICE-90489667

Vehicle Particulars

Manufacturer KIA
Model NIRO-1.6 HYBRID GDI DCT SUNROOF (A)
Exact Purpose for which vehicle was being used at time of accident PERSONAL USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 1700006254
Cover Note Number

Driver

Name of Driver TEO POH SENG
NRIC No S7640219A
Date Of Birth 03/12/1976
Occupation INDOOR
Date Of Driving Pass 30/11/1999
Driving Experience 18 YEARS AND 1 MONTH
Gender MALE
Mobile Number (LOCAL) +65-90489667
Fax Number
Contact Number OFFICE-90489667
EMail Address DINO_TEO@YAHOO.COM

Address	BLK 6 TELOK BLANGAH CRESCENT #03-422
Postcode	090006
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHMENTS.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR1753S
Vehicle Make/Model/Colour	TOYOTA/C-HR/WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEO CHENG SEONG
NRIC/Passport Number	S7239043A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT LEFT BUMPER DAMAGED
No. Of Passenger (Including Driver)	

Sketch Plan #2

SKETCH PLAN



A = SANCUR3P

B = SLR17535

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I am travelling to home along Bentley Road Traffic was heavy. I was trying to change lane from 3rd lane to 2nd lane. As there is a double white line marked on the road, I couldn't do so. After the double white line ended, I signalled right to indicate I am going right. I checked my blind spot and there was a good distance between the vehicle behind me. When I got into the lane, vehicle SLR17535 also decided to change lane from 1st to 2nd and hit my rear right rear door.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 6/1/18 9.35 am

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

OH APPRAISAL SERVICES

BLK 34,#02-309,TOA PAYOH,LORONG 5
SINGAPORE (310034)
Mobile : 97982959 Fax : 63975857 email : oh3434@yahoo.com.sg

VEHICLE DAMAGE INSPECTION REPORT

Mr. Teo Poh Seng
Blk 6 Telok Blangah Crescent
#03-422
Singapore 090006

Our Ref : SLN9483P/TP5022
Date : 26 February 2018

REFERENCES

Claim Type	: Third Party	Date of Accident	: 05 January 2018
Vehicle No.	: SLN9483P	Date of Assignment	: 17 January 2018
Make	: Kia	Date of Inspection	: 17 January 2018
Model	: Niro Hybrid 1.6	Date of Re-inspn.	: 22 January 2018
Reg. Date	: 23 May 2017	Chassis No	: KNACC81CVH5061391
Color	: White	Engine No	: Blocked
Odometer	: 12566 km		

TYRE CONDITION

	<u>Front near side</u>	<u>Front off side</u>	<u>Rear near side</u>	<u>Rear off side</u>
Make	Michelin	Michelin	Michelin	Michelin
Size	205/60 R16	205/60 R16	205/60 R16	205/60 R16
Thread Balance	5 mm	5 mm	6 mm	6 mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at Rear,Rh side and Rh undercarriage portion

INSPECTION AND ADJUSTMENT

Original Quotation : \$12,261.00 Revised Assessment \$8,200.00 Lump sum

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
(8) days to complete.(Survey at Hiap Lek Automobile Trading.)

This survey was conducted on a "WITHOUT PREJUDICE" basis.

S/N	Description	Qty	Condition	Original Quotation	Revised Quotation	
	<u>Material</u>					
1	Rear bumper	1	Deformed	451.00	451.00	X nn
2	Rear bumper bracket	1	Dislodge Rh	28.00	28.00	X nn
3	Rear bumper side retainer	1	Bent Rh	22.00	22.00	X nn
4	Rear Rh fender	1	Dented/bent	1,465.00	1,465.00	X nn
5	Rear Rh fender mudflap	1	Grazed	28.00	28.00	X nn
6	Rear Rh fender inner shield	1	Grazed	75.00	75.00	X nn
7	Rear Rh fender 1/4 glass moulding	1	Necessary	65.00	65.00	X nn
8	Rear Rh fender 1/4 glass garnish	1	Grazed	35.00	35.00	X nn
9	Rear Rh wheel arc (Front)	1	Grazed	95.00	95.00	✓
10	Rear Rh wheel arc (Rear)	1	Grazed	45.00	45.00	✓
11	Rear Rh door	1	Dented/bent	1,190.00	1,190.00	✓
12	Rear Rh door outer handle	1	Grazed	55.00	55.00	X nn
13	Rear Rh door lock	1	Bent	209.00	209.00	✓
14	Rear Rh door checker	1	Bent	52.00	52.00	X nn
15	Rear Rh door weatherstrip	1	Necessary	124.00	124.00	✓
16	Rear Rh door speaker	1	Faulty	150.00	150.00	X nn
17	Rear Rh door inner trim board	1	Deformed	782.00	782.00	✓
18	Rear Rh door window glass regulator	1	Bent	240.00	240.00	✓
19	Rear Rh door window glass regulator motor	1	Malfunction	244.00	244.00	✓
20	Rear Rh door protector	1	Grazed	174.00	174.00	✓
21	Rocker panel Rh	1	Repair	1,409.00	0.00	X }
22	Rocker panel garnish Rh	1	Grazed	220.00	220.00	X }
23	Rear Rh top arm	1	Bent	270.00	270.00	X }
24	Rear Rh lower arm	1	Bent	152.00	152.00	X }
25	Rear Rh disc plate	1	Bent	110.00	110.00	X }
26	Rear Rh shock absorber	1	Bent	236.00	236.00	X }
27	Rear Rh stabilizer bar (Short)	1	Bent	67.00	67.00	X }
28	Rear Rh trailing arm (Top)	1	Bent	220.00	220.00	X }
29	Rear Rh trailing arm (Bottom)	1	Bent	240.00	240.00	X }
30	Rear Rh knuckle arm	1	Bent	337.00	337.00	X }
31	Rear Rh knuckle arm bearing	1	Bent	300.00	300.00	X }
				9,090.00	7,681.00	
			Less 10 % discount	909.00	768.10	
				8,181.00	6,912.90	

<u>Special nett items</u>				
32	Rear Rh fender 1/4 glass sealant	1 Necessary	40.00	40.00 Xnn
33	Rear Rh sport rim	1 Dented/bent	650.00	550.00
34	Rear Rh mudflap clip	1 set Necessary	14.00	14.00 Xnn
35	Rear Rh fender inner shield clip	1 set Necessary	18.00	18.00 Xnn
36	Rear Rh door inner trim board clip	1 set Necessary	28.00	28.00
Parts total			8,931.00	7,562.90
<u>Labour & Misc.</u>				
1)	Labour charge to remove-refit, panel beat, straighten, re-align and repair of rear bumper, rear Rh fender, rear wheel arch panel, rear Rh door and others relevant accident damages.		1,400.00	1,200.00 800
2)	To remove-refit rear Rh under carriage damage parts.		300.00	250.00 x
3)	To conduct computerise wheel alignment test.		80.00	60.00 -
4)	To check wirings, lightings and remove/refix rear bumper reverse sensor		100.00	80.00 30
5)	To supplied and applied anti rust treatment to affected panels.		150.00	120.00 40
6)	Towing charges		80.00	60.00 -
7)	To transfer rear Rh doors fittings and attachments.		100.00	60.00 -
8)	Remove/replace quarter glass.		120.00	80.00 -
9)	To putty and spray painting charges.		1,000.00	800.00 700
Total			12,261.00	10,272.90
Lump sum repair adjustment				8,200.00

5-7 days

OH APPRAISAL SERVICES

Vehicle No: SLN9483P

Our Ref: SLN9483P/TP5022

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.



For Oh Appraisal Services






























...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2018		18 Jan 2018 10:25 Edit Adj Rpt	S\$4,150.00 Edit Estimates	S\$4,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SKYWAY MOTOR PTE LTD , Co. Reg. No.: 199904194N									
Main Claimant: TEO POH SENG , ID: S7640219A									
Vehicle Reg. No.: SLN9483P		Date of Loss: 05/01/2018 17:00 - :59 [7 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 544671		Policy/Cover Note No.: A28795104MCX (Comprehensive) Coverage: 08/08/2017 - 07/08/2018							
Vehicle Reg. No. (Insured): SLR1753S		Policy No. (Claimant):							
		Excess:							
Repairer: Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Imm.Advice due 19/01/2018]									
Driver/Custodian (Insured): TEO CHENG SEONG () , NRIC: S7239043A, Tel: +6596324332									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN9483P (544671)
[SLR1753S]
TP
TEO POH SENG
Jan 5 2018 5:00PM
[SKYWAY MOTOR PTE LTD]
Hiap Lek Automobile Trading

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Video						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail		Print	
1	17/01/18 17:03	Video - Accident (TP) From:SC - Reg. No: SLR1753S, Claimant: SKYWAY MOTOR PTE LTD				 Load MP4			
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail		Print	
1	17/01/18 17:03	Accident Statement From:SC - Reg. No: SLR1753S, Claimant: SKYWAY MOTOR PTE LTD				 Load HTM			
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
2	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
3	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
4	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
5	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
6	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
7	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
8	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
9	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
10	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
11	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
12	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
13	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
14	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
15	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
16	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
17	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
18	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
19	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
20	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
21	19/01/18 17:10	General View				 Load JPG		<input checked="" type="checkbox"/>	
22	12/04/18 14:03	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
23	12/04/18 14:03	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
24	12/04/18 14:03	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
25	12/04/18 14:03	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
26	12/04/18 14:03	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
27	12/04/18 14:03	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
28	12/04/18 14:03	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	
29	12/04/18 14:03	Reinspection Photo				 Load JPG		<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
30	12/04/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	12/04/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	12/04/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	12/04/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	12/04/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	12/04/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	12/04/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	12/04/18 14:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	12/04/18 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/01/18 17:03	SLN9483P E-FILE REPORT From: SC - Reg. No: SLR1753S, Claimant: SKYWAY MOTOR PTE LTD	Load PDF	
2	18/01/18 10:24	TP PRI Request	Load PDF	
3	18/01/18 10:24	TP reject SJE - assign LKK	Load PDF	
4	18/01/18 10:24	TP workshop repairer	Load PDF	
5	02/04/18 09:12	Survey Report	Load PDF	
6	02/04/18 09:12	Survey Photo part 1	Load PDF	
7	02/04/18 09:12	Survey Photo part 2	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18001112/M1QD3

Date: 13/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28795104MCX

Claimant Vehicle No : SLN9483P

Insured Vehicle No : SLR1753S

Date of Loss: 05/01/2018

Nature of Claim: TP

Claim No: 544671

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN9483P

Make & Model: KIA NIRO, 1.6 HYBRID GDI DCT SUNROOF (A)

Engine No: G4LEHS183206

Reg. Date: 23/05/2017 (Man. Year: 2017)

Chassis No: KNACC81CVH5061391

Colour: White

Odometer: 12673 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,931.00	3,370.70	5,560.30	62.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	1,830.00	1,500.00	45.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,261.00	5,200.70	7,060.30	57.58
Approved Total (Overridden) (S\$)		4,150.00		
Nett Amount (S\$)	12,261.00	4,150.00	8,111.00	66.15

INSPECTION

Date of Assignment: 18/01/2018

Date Inspected: 19/01/2018 Inspected At:

Hiap Lek Automobile Trading (HQ)
160 Sin Ming Drive, #05-17 Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Apr 2018)	
Parts:	N/A	KIA NIRO 1.6 HYBRID GDI DCT SUNROOF (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN9483P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Not Necessary	451.00 FL	*- FL
2	1	*REAR BUMPER BRACKET	Not Necessary	28.00 FL	*- FL
3	1	*REAR BUMPER SIDE RETAINER	Not Necessary	22.00 FL	*- FL
4	1	*REAR RH FENDER	Not Necessary	1,465.00 FL	*- FL
5	1	*REAR RH FENDER MUDFLAP	Not Necessary	28.00 FL	*- FL
6	1	*REAR RH FENDER INNER SHIELD	Not Necessary	75.00 FL	*- FL
7	1	*REAR RH FENDER 1/4 GLASS MOULDING	Not Necessary	65.00 FL	*- FL
8	1	*REAR RH FENDER 1/4 GLASS GARNISH	Not Necessary	35.00 FL	*- FL
9	1	*REAR RH WHEEL ARC (FRONT)	Grazed	95.00 FL	*95.00 FL
10	1	*REAR RH WHEEL ARC (REAR)	Grazed	45.00 FL	*45.00 FL
11	1	*REAR RH DOOR	Dented / Bent	1,190.00 FL	*1,190.00 FL
12	1	*REAR RH DOOR OUTER HANDLE	Not Necessary	55.00 FL	*- FL
13	1	*REAR RH DOOR LOCK	Bent	209.00 FL	*209.00 FL
14	1	*REAR RH DOOR CHECKER	Not Necessary	52.00 FL	*- FL
15	1	*REAR RH DOOR WEATHERSTRIP	Necessary	124.00 FL	*124.00 FL
16	1	*REAR RH DOOR SPEAKER	Not Necessary	150.00 FL	*- FL
17	1	*REAR RH DOOR INNER TRIM BOARD	Deformed	782.00 FL	*782.00 FL
18	1	*REAR RH DOOR WINDOW GLASS REGULATOR	Bent	240.00 FL	*240.00 FL
19	1	*REAR RH DOOR WINDOW GLASS REGULATOR MOTOR	Malfunction	244.00 FL	*244.00 FL
20	1	*REAR RH DOOR PROTECTOR	Grazed	174.00 FL	*174.00 FL
21	1	*ROCKER PANEL RH	Repair	1,409.00 FL	*- FL
22	1	*ROCKER PANEL GARNISH RH	Not Necessary	220.00 FL	*- FL
23	1	*REAR RH TOP ARM	Not Necessary	270.00 FL	*- FL
24	1	*REAR RH LOWER ARM	Not Necessary	152.00 FL	*- FL
25	1	*REAR RH DISC PLATE	Not Necessary	110.00 FL	*- FL
26	1	*REAR RH SHOCK ABSORBER	Not Necessary	236.00 FL	*- FL
27	1	*REAR RH STABILIZER BAR (SHORT)	Not Necessary	67.00 FL	*- FL
28	1	*REAR RH TRAILING ARM (TOP)	Not Necessary	220.00 FL	*- FL
29	1	*REAR RH TRAILING ARM (BOTTOM)	Not Necessary	240.00 FL	*- FL
30	1	*REAR RH KNUCKLE ARM	Not Necessary	337.00 FL	*- FL
31	1	*REAR RH KNUCKLE ARM BEARING	Not Necessary	300.00 FL	*- FL
32	1	*REAR RH FENDER 1/4 GLASS SEALANT	Not Necessary	40.00 FS	*- FS
33	1	*REAR RH SPORT RIM	Dented / Bent	650.00 FS	*550.00 FS
34	1	*SET REAR RH MUDFLAP CLIP	Not Necessary	14.00 FS	*- FS
35	1	*SET REAR RH FENDER INNER SHIELD CLIP	Not Necessary	18.00 FS	*- FS
36	1	*SET REAR RH DOOR INNER TRIM BOARD CLIP	Necessary	28.00 FS	*28.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,840.00	3,681.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	909.00	310.30

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					8,931.00	3,370.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE TO REMOVE-REFIT, PANEL BEAT, STRAIGHTEN, RE-ALIGN AND REPAIR OF REAR BUMPER, REAR RH FENDER, REAR WHEEL ARCH PANEL, REAR RH DOOR AND OTHERS RELEVANT ACCIDENT DAMAGES	New	1,400.00	800.00
2	TO REMOVE-REFIT REAR RH UNDER CARRIAGE DAMAGE PARTS	New	300.00	0.00
3	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST	New	80.00	60.00
4	TO CHECK WIRINGS, LIGHTINGS AND REMOVE/ REFIX REAR BUMPER REVERSE SENSOR	New	100.00	30.00
5	TO SUPPLIED AND APPLIED ANTI RUST TREATMENT TO AFFECTED PANELS	New	150.00	40.00
6	TOWING CHARGES	New	80.00	60.00
7	TO TRANSFER REAR RH DOORS FITTINGS AND ATTACHMENTS	New	100.00	60.00
8	REMOVE / REPLACE QUARTER GLASS	New	120.00	80.00
9	TO PUTTY AND SPRAY PAINTING CHARGES	New	1,000.00	700.00
Gross Labour Cost (\$\$)			3,330.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >