

AH Catherine Chong

**MCWELL VENTURES PTE LTD**

51 Ubi Ave 1 #01-05
 Paya Ubi Industrial Park
 Singapore 408933
 : (65) 6844 4640 / 9838 7743
 : (65) 6844 4641
 : international@mcwellventures.com
 : www.mcwellventures.com
 Co. / GST Reg. No.: 200103711R

To. LKK

DATE: 22/01/2018

51 ubi ave 1 paya ubi industrial park #01-25 S(408933)

Vehicle No. : GBF1158S
 Make/Model : Nissan NV350
 Chassis No. : JN1MC2E26Z0006689
 Policy No. :
 D.O.A. :

ESTIMATE COST OF REPAIRS TO VEHICLE GBF1158S

No.	QTY	ITEMS	AMOUNTS (\$S)
-----	-----	-------	---------------

PARTS LIST

1	1 pc	Frt panel / <i>Inc</i>	\$ 1,160.90
2	2 pcs	Frt corner panel R/L <i>< LH - Inc</i>	\$ 505.20
3	1 pc	Frt grille assy <i>- CHA</i>	\$ 438.70
4	1 pc	Frt bumper <i>- CHA</i>	\$ 892.70
5	2 pcs	Frt bumper bracket R/L <i>?</i>	\$ 165.60
6	1 pc	Frt bumper reinforcement <i>?</i>	\$ 667.10
			\$ 4,501.00
			Less 30% \$ 1,350.30
List Parts Sub-Total :			\$ 3,150.70

PARTS NETT

1	1 pc	Frt windscreen <i>- CHA</i>	\$ 995.60
2	1 pc	Frt windscreen moulding <i>- MC</i>	\$ 53.20
3	1 pc	Frt wiper garnish <i>?</i>	\$ 420.40
4	2 pcs	Headlamp R/L <i>- CHA</i>	\$ 324.50
5	1 pc	Frt grille emblem (Logo) <i>- mis</i>	\$ 71.60
6	1 pc	Frt bumper tow cover <i>X</i>	\$ 31.20
7	2 pcs	Frt bumper fog lamp R/L <i>?</i>	\$ 257.50
8	2 pcs	Frt bumper fog lamp grille R/L <i>?</i>	\$ 91.90
			\$ 2,919.80
			Less 10% \$ 291.98
Nett Parts Sub-Total :			\$ 2,627.82

PARTS S/NETT

1	1 pc	Frt no.plate <i>- CHA</i>	\$ 50.00
2	1 pc	Air inlet duct (A/c) <i>?</i>	\$ 300.00
3	1 pc	A/c suction pipe <i>?</i>	\$ 268.20
4	1 pc	A/c discharge pipe <i>?</i>	\$ 237.40
5	1 pc	A/c liquid pipe <i>?</i>	\$ 242.50
6	1 pc	A/c receiver drier <i>?</i>	\$ 151.10
7	1 pc	A/c cooling coil assy <i>?</i>	\$ 2,181.50

8	1 pc	A/c blower assy ?	\$	813.60
9	1 pc	Frt windscreen sealant	\$	50.00
10	1 pc	Frt windscreen inner seal	\$	50.00
11	1 pc	Frt windscreen I.U. bracket	\$	30.00
12	1 pc	Frt panel sealant	\$	50.00
13	1 pc	Frt panel sticker (Co. logo)	\$	150.00

Special Nett Sub-Total : \$ 4,574.30

\$ 10,352.82Labour Charge

To check electrical system, repair wire harness and focus headlamp.	\$	80.00	30
To remove, replace and reinstall front windscreen.	\$	150.00	100
To remove and reinstall dashboard for necessary repairs.	\$	400.00	200
To remove, replace and reinstall a/c blower and a/c cooling coil assy. (Include vacuum & recharge a/c gas)	\$	150.00	?
To straighten, repair, realign on affected area and replace damaged parts.	\$	1,200.00	600
To conduct chassis alignments.	\$	350.00	X
To spray painting on affected area.	\$	1,000.00	500
Total	\$	3,330.00	

Tota \$ 13,682.82

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7 Days .

Lumpsum Repair .

After repair photos:

Guo Qiang - 82880282

Guo Qiang @lkkauto.com

Excess \$500

Not Authorised

22/1/18.