

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joel Goh

Date: 23 Jan 2018

Preliminary Advice

Vehicle No	: GBF1158S	Accident Date	: 15/01/2018
Make	: NISSAN NV350	Policy No.	: DMCVSN1642021701
Assignment Date	: 17/01/2018	Excess	: S\$500.00
Date of Inspection	: 22/01/2018	Est. Duration of Repair	: 7.00
Inspection At	: MCWELL VENTURES PTE LTD (HQ) 51 UBI AVE 1, #01-05 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,682.82
Revised Amount	:S\$	5,300.71
Check Items (Estimated)	:S\$	6,050.39
Total	:S\$	11,351.10
Lump Sum Repair (Estimated)	:S\$	9,100.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	39,172.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,828.00

Remarks

Brake System : In Order
Steering System : In Order
Tyre Condition (Front) : 6/6 mm
Tyre Condition (Rear) : 6/6 mm

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :